Released From Confidential Status

Case Number: 07-478-GA-UNC

Date: 11/16/2007

Ohio Consumers' Counsel
Third Set Production of Documents
Duke Energy Ohio, Inc.
PUCO Case No. 07-589-GA-AIR
PUCO Case No. 07-590-GA-ALT
PUCO Case No. 07-591-GA-AAM
Date Received: August 14, 2007
Response Due: September 4, 2007

OCC-POD-03-027

REQUEST:

27. Please provide copies of all workpapers, data, source documents, and/or other information DE-Ohio relied upon in responding to OCC Interrogatory No. 51 pertaining to the reportable incidents related to the repair or replacement of defective or prone to leak natural gas risers over the past 5, 10, and 20 years.

RESPONSE:

See Attachment OCC-POD-03-027.

WITNESS RESPONSIBLE: Gary J. Hebbeler

RECEIVED

NOV 1 8 2007

DOCKETING DIVISION
Public Utilities Commission of Ohio



December 12, 2001

Information Resources Manager (DPS-34)
Office of Pipeline Safety
Research and Special Programs Administration
U.S. Department of Transportation
Room 7128
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Sir or Madam:

Reference:

Pipeline Safety Incident - Fire; 1278 McGuffey Lane, Clermont County, Ohio

Report I.D. 525231

This letter is to update your files regarding the telephonic notice you received on April 6, 2000. This is in reference to the explosion that occurred at 1278 McGuffey Ln. in Clermont County, Ohio.

This incident is reportable as prescribed under 49 CFR 191.3 and 191.5. The property damage exceeded the level specified by the Rules.

Enclosed is the final Incident Report for Gas Distribution Systems, Form RSPA F 7100.1 regarding this incident.

This will be the final correspondence that you will receive regarding this incident. If you have any questions, I may be contacted at (513) 287-3921.

Sincerely,

THE CINCINNATI GAS & ELECTRIC COMPANY

Randall L. Suttles
Regulatory Compliance Specialist
Gas Operations Department

Enclosure

cc: file





December 12, 2001

Mr. Edward M Steele
Chief, Gas Pipeline Safety Section
The Public Utilites Commission of Ohio
The Borden Building, 7th Floor
180 East Broad Street
Columbus, Ohio 43215-3793

Dear Mr. Steele:

Reference:

Pipeline Safety Incident - Fire; 1278 McGuffey Lane, Clermont County, Ohio

D.O.T. Report I.D. 525231

This letter is to update your files regarding the telephonic notice you received on April 1, 2000 regarding the fire that occurred at 1278 McGuffey Ln. Clermont County, Ohio.

This incident is reportable to the State of Ohio as prescribed under OAC 4901:1-16 and the Department of Transportation as prescribed under 49 CFR 191.3 and 191.5. The property damage exceeded the level specified by the Rules.

Cinergy is required to submit a final report stating the cause of the incident and the actions taken to minimize the possibility of a recurrence of such an incident. As for the cause of the incident, Cinergy has determined it to be inconclusive. Please refer to the DOT Final Report form 7100.1 in Part 3. As for the actions taken, please refer to the Final Stipulation and Recommendation and The Final Corrective Action Plan, which both the Public Utilities Commission of Ohio has approved.

Enclosed is the final Incident Report for Gas Distribution Systems, Form RSPA F 7100.1 regarding this incident.

This will be the final correspondence that you will receive regarding this incident. If you have any questions, I may be contacted at (513) 287-3921.

Sincerely,

THE CINCINNATI GAS & ELECTRIC COMPANY

Randall L. Suttles
Regulatory Compliance Specialist
Gas Operations Department

Enclosure

cc: file





U.S. Department of Transportation	INCIDENT REPOR	RT - GAS DISTRIBUTION SYSTEM	Report Date 04/27/00
Research and Special Programs Administration		**Final Reports	No. 525231
			(RSPA)
PART 1 - GENERAL REPORT INFO	RMATION	'SEE INSTRUCTIONS'	(1-47 A)
1. a. Operator's 5 digit identification		4. Reason for reporting	
10 12 13 1 6 1		☐ Fatelity	Number / / / / pers
b. Name of Operator Cincinnati		☐ Injury requiring Impa	tient
c. 139 East Fourth Street	AND IN CHANGE AND	hospitalization	Number / / / pers
Number and Street		•	
d. Cincinnați : Hamilton: Ohi	0 45202	🔲 Property demage/lo	ss Estimate \$ 250,000
City, County, State and Zip C	ode	<u> </u>	
2. Location of incident		Operator judgment/	· •
 1278 McGuffey Lane 		🔲 Supplemental Repo	ert '
Number and Street B Batavia, Clermont County		5. Eleosed time until area	
City and County		was made safe	(<u> </u>
c. Ohio 45238		6. Telephone Report	
State and Zip Code		/ 0 / 4 / mo.	10/5/day [0/0/
d. Class location	1 🗆 2 🗆 3 🗆 4	7. a. Estimated pressure a	t point and time of incident (PSI)
•		<i>50</i>	
e. Incident on Federal land	☐ Yes ☐ No	b. Maximum allowable o	perating pressure MAOP)(PSIG
		60	
Time and date of incident		c. MAOP established by	
1015/1/1/hr. /0	/4 / mo. / 0 / 1 / day / 0 / 0 / yr.	(1) Test pressure	(PS/G)
	· 	(2) 49 CFR § 192.6	19 (a)(3)
PART 2 - APPARENT CAUSE		_	
☐ Corresion	Damage by Outside Forces	☐ Construction/Operating error	Other <u>under investigation</u>
(Continue in Part A)	(Continue in Part 8)	(Continue in Part C)	
Accidentally caused by operato	or .		
(Continue in Parts 8 and/or C)	ION OF FACTORS CONTRIBUTING TO	THE INCIDENT	(Attach additional sheet(s) as
PART 3 - WARRY THE DESCRIPT			necessary)
Explosion still under investigat	ion;e		
PART 4 - ORIGIN OF THE INCIDE	III		
1. Part of system where incident of		2. Component which falls	d
	Meter Set Assembly	a. Part	
	Olher	☐ Body of pipe	☐ Valve
3. Material involved:		☐ Joint type	☐ Regulator/meter
☐ Steel ☐	Cast iron	☐ Fitting	☐ Weld(Specify)
İ		•	(girth, longitudina
☐ Polyathylene plastic ☐	Other plastic:	☐ Drip/Riser	☐ Other
Other		•	
	PS) <u>[</u>	Wall thickness [] in.	
	Vanufacturer Yr	Manufactured / / / / Yr Installed /	1 1 1 1
PART 5 - ENVIRONMENT			
Area of Incident	<u>_</u>	_	
	pavement	☐Under ground or Under water	ÜQther
PART 6 - PREPARER AND AUTI Randall L. Suttles / Regula	HORIZED SIGNATURE Nory Compliance Specialist		513 / 287-3921
(type or print) Prepared	's Name and Title		
1			Area Code and Telephone Nu









Information Resources Manager (DPS-34)
Office of Pipeline Safety
Research and Special Programs Administration
U.S. Department of Transportation
Room 2103
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Sir or Madam:

Reference:

Final Report; Pipeline Safety Incident Explosion; 6955 Lakota Ridge Dr. Liberty Township, Ohio

Report I.D. 625073

This letter is to update your files regarding the telephonic notice you received on October 6, 2002. This is in reference to the explosion that occurred at 6955 Lakota Ridge Dr. Liberty Twp., Ohio.

This incident is reportable as prescribed under 49 CFR 191.3 and 191.5. Estimated property damage exceeded \$50,000.

Enclosed is the final Incident Report for Gas Distribution Systems, Form RSPA F 7100.1 regarding this incident.

This will be the final correspondence that you will receive regarding this incident. If you have any questions, I may be contacted at (513) 287-3921...

Sincerely,

THE CINCINNATI GAS & ELECTRIC COMPANY

Randall L. Suttles Regulatory Compliance Specialist Gas Operations Department

Enclosure





October 4, 2004

Mr. Edward M Steele Chief, Gas Pipeline Safety Section The Public Utilites Commission of Ohio The Borden Building, 7th Floor 180 East Broad Street Columbus, Ohio 43215-3793

Dear Mr. Steele:

Reference:

Final Report; Pipeline Safety Incident Explosion; 6955 Lakota Ridge Br. Liberty Township, Ohio

Report I.D. 625073

This letter is to update your files regarding the telephonic notice you received on October 6, 2002. This is in reference to the explosion that occurred at 6955 Lakota Ridge Dr. Liberty Twp., Ohio.

This incident is reportable as prescribed under 49 CFR 191.3 and 191.5. Estimated property damage exceeded \$50,000.

Enclosed is the final Incident Report for Gas Distribution Systems, Form RSPA F 7100.1 regarding this incident.

Cinergy is required to submit a final report stating the cause of the incident and the actions taken to minimize the possibility of a recurrence of such an incident. As for the cause of the incident, Cinergy has determined it to be inconclusive. Please refer to the DOT Final Report form 7100.1 in Part 3. As for the actions taken, please refer to the Final Stipulation and Recommendation and The Final Corrective Action Plan, which both the Public Utilities Commission of Ohio has approved.

Should you have any questions in the interim, I may be contacted at 513-287-3921.

Sincerely,

THE CINCINNATI GAS & ELECTRIC COMPANY

Randall L. Suttles
Regulatory Compliance Specialist
Gas Operations Department

Enclosure





NOTICE: This report is required by 49 CFR Part 191. Feiture to report can result in a civil penalty not to exceed \$1,000 for each violation for each day that such violation penalts except that the maximum civil penalty shall not exceed \$200,000 as provided in 49 USC 1676.

ONAS No. 2137-0522

MOSON OF A Character 1 A Character 1	DISTRIBUTION SYSTEM Report Date 10/4/2004 625073 (RSPA)
Administration PART 1 - GENERAL REPORT INFORMATION	'SEE INSTRUCTIONS'
1. a. Operator's 5 digit Identification Number	4. Reason for reporting
10 12 13 16 14 1	Fatality Number / / persons
b. Name of Operator Cincinnati Gas & Electric Company	Injury requiring inpatient hospitalization Number / / / persons
c. 139 East Fourth Street Number and Street	, , , , , , , , , , , , , , , , , , , ,
d. Cincinnati; Hamilton, Ohio 45202	Property damage/loss Estimate \$
City, County, State and Zip Code 2. Location of incident	Operator judgment/emergency action
a. 6955 Lakota Ridge Drive	Supplemental Report
Number and Street	The state of the s
b. Liberty Twp.; Butler County City and County	5. Elapsed time until area was made safe (_ / _ / hr / _ /
עוש שיוש עיש ניש	min.
c. Ohio 45011	6. Telephone Report
State and Zip Code d. Class location	7. s. Estimated pressure at point and time of incident
d. Class location	(P\$IG)
e. Incident on Federal land Yes X No	b. Maximum allowable operating pressure
3. Time and date of incident	(MAOP)(PSIG) c. MAOP established by:
/ 0 / 8 / 1 / 3 / hr. / 1 / 0 / mo. / 0 / 6 / day	(1) Test pressure(PSIG)
1 0/ 21 yr.	(2) 49 CFR § 192.619 (a)(3)
PART 2 - APPARENT CAUSE	
☐ Corrosion ☐ Damage by Outside Forces	Construction/Operating error X Other Inconchaire
(Continue in Part A) (Continue in Part B)	(Continue in Part C)
☐ Accidentally caused by operator	•
(Continue in Parts B and/or C) PART 3 - NARRATIVE DESCRIPTION OF FACTORS CONTRIBUTION	ING TO THE (Attach additional sheet(s) as necessary)
INCIDENT	HIP 15 III
Various factors possibly contributed to the cause of the incident, ins	
review of records available to CG&E to date fail to identify the speci	nc controuting tectors.
PART 4 - ORIGIN OF THE INCIDENT	
Part of system where incident occurred	2. Component which failed
☐ Main ☐ Meter Set Assembly	a. Part
Service Line Other	Body of pipe
3. Material involved:	☐ Joint type ☐ Regulator/meter ☐ Fitting ☐ Weld(Specify)
Li Steel Li Cascinon	☐ Fitting ☐ Weld(Specify)
☐ Polyethylene plastic ☐ Other plastic:	☐ Drlp/Riser ☐ Other
☐ Other	•
Nominal pipe size (NPS) / / / / / / / / / / / / / / / / / / /	/ in, Wall thickness / / / / in. Yr Manufactured / / / / Yr Installed / / / /
4. Operation wanufacturer	11 Manulactured [/ / / IT #15/8#80 []
PART 5 - ENVIRONMENT	
Area of Incident	
□Within/Under bldg □Under pavement □Above ground	☐Under ground or Under water XOtherThe fitting was
	installed above ground while the
	<u>damage event was in the</u> building
PART 6 - PREPARER AND AUTHORIZED SIGNATURE	
The state of the s	
Randall L. Suttles/ Regulatory Compliance Specialist	513/287-3921
Randall L. Suttles/ Regulatory Compliance Specialist (type or print) Preparer's Name and Title	
Randall L. Suttles/ Regulatory Compliance Specialist	513/287-3921 Area Code and Telephone Number
Randall L. Suttles/ Regulatory Compliance Specialist	





PART A - CORROSION		
1. Where did the corrosion occur?	2. Visual Description	3. Cause
☐ Internally	☐ Localized pitting	☐ Galvanic
	General compsion	
□ =		D Other
☐ Externally	Other	
. Pipe coating information		
☐ Bare ☐ Coated		فالمسائدة ما ماليان
 Was corroded part of pipeline considered 		CASCOVERING AFCHORATE
Yes Year protection started		
□ No		
Additional Information:		
AII/A		
N/A		
PART B - DAMAGE BY OUTSIDE FORCES		
Primary cause of incident		
Damage resulted from action of oper	ator or his agent.	
. Damage resulted from action by outs	•	
. Damage by earth movement	······································	
Subsidence	•	
☐ Landslide/washout		
Frost		
Damage by lightning or fire		
2. Locating information (for damage resulting	ng from action of outside party/third part	(y)
a. Did operator get prior notification that		
☐ Yes Date receive	d <u>(/_f</u> mo <u>//_f</u> day_(_	
□ N₀		
 b. Was pipeline location marked either 	as a result of notification or by markers	already in place?
☐ Yes ☐ Permane	nt markers	Other
□ No		
c. Does statute or ordinance require the	e outside party to determine whether un	derumund facility (ies) exist?
☐ Yes		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
3. Additional Information:		
See part O		
PART C - CONSTRUCTION DEFECT		
1. Cause		
Poor workmanship during	 Operating procedure inappropri 	riate D Error in operating procedure application
construction		
☐ Physical damage during	C) Other	
construction		
		•
2. Additional information:		
2. Additional information:	•	•
		•
2. Additional information:		•
2. Additional information:		
2. Additional information: See part D		
2. Additional information: See part D PART D - OTHER	•	
2. Additional information: See part D PART D - OTHER Brief Description:	cause of the incident: the cause believe	ed to be a riser failure. These possible factors include, by
Additional information: See part D PART D - OTHER Brief Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the Incident; the cause believe	ed to be a riser failure. These possible factors include, by
2. Additional information: See part D PART D - OTHER Brief Description: Various factors possibly contributed to the	cause of the incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, by natructions, acts of God (i.e, extreme weather conditions:
Additional information: See part D PART D - OTHER Brief Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, but instructions, acts of God (i.e., extreme weather conditions:
Additional information: See part D PART D - OTHER Briel Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, but instructions, acts of God (i.e., extreme weather conditions:
Additional information: See part D PART D - OTHER Briel Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the Incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, bustructions, acts of God (i.e., extreme weather conditions:
Additional information: See part D PART D - OTHER Brief Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the Incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, bustructions, acts of God (i.e., extreme weather conditions:
Additional information: See part D PART D - OTHER Briel Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, but instructions, acts of God (i.e., extreme weather conditions:
Additional information: See part D PART D - OTHER Brief Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, bu
Additional information: See part D PART D - OTHER Briel Description: Various factors possibly contributed to the are not limited to, manufacturing or design	cause of the incident; the cause believe defect; deficiencies in manufacturers in	ed to be a riser failure. These possible factors include, but instructions, acts of God (i.e., extreme weather conditions:

