



Bricker & Eckler
ATTORNEYS AT LAW

COLUMBUS • CLEVELAND

BRICKER & ECKLER LLP
100 South Third Street
Columbus, Ohio 43215-4291
MAIN: 614.227.2300
FAX: 614.227.2390

www.bricker.com
info@bricker.com

Sally W. Bloomfield
614.227.2368
sbloomfield@bricker.com

FILE

April 19, 2010

RECEIVED-PUBLIC UTILITIES DIV

2010 APR 19 PM 3:23

Via Hand Delivery

PUCO

Ms. Renee Jenkins
Public Utilities Commission of Ohio
Administration/Docketing
180 East Broad Street, 13th Floor
Columbus, OH 43215-3793

Re: Case No. 08-1233-WS-UNC
Ohio American Water Company
Stipulation Page No. 9, ¶13 E 4

Dear Ms. Jenkins:

Pursuant to the Commission's November 12, 2008 Opinion and Order in Case No. 07-1112-WS-AIR, Ohio American Water Company submits for filing its compliance with the Stipulation and Recommendation, page 9 paragraph 13 E 4 pertaining to the submission of leak logs for the first quarter of 2010.

If you have any questions, please call me at the number listed above.

Sincerely,

Sally W. Bloomfield

Enclosure

cc: Parties of Record (w/Enclosure)

This is to certify that the images appearing are an accurate and complete reproduction of a case file document delivered in the regular course of business.
Technician SM Date Processed APR 19 2010

Ashtabula District

2010 Water Leak Log

CSL = Company Service Leak; CWM = Company Water Main; HYD = Hydrant; VLV = Valve; CO = Company Other; PSL = Private Service Leak; PWM = Private Water Main; PO = Private Other DR= Door Tag DTD= Door to Door																
	Location	Service Area	Township	Leak Type	Size	Boil Order (Y or N)	Number of Services Affected	Method of Notification	Data Boil Order Listed	Report Date	Repair Date	Elapsed Days	Size of Restoration	Type of Restoration	Restoration Completed	Comments
1	1807 E. PROSPECT		ASHTABULA	CWM	6"	N	0			1/17/2010	1/17/2010	0	5 X 8	STREET	TBD	
2	2015 E. 42nd ST.		ASHTABULA	CWM	6"	N	23	DTD	1/8/2010	1/23/2009	1/7/2010	6	5 X 10	STREET	TBD	
3	2002 E. 41st ST.		ASHTABULA	CWM	2"	Y	0			1/8/2010	1/7/2010	2	4 X 5	TREELAWN	TBD	
4	LUCAS AVE.		SAYBROOK	CWM	2.5"	N	0			1/7/2010	1/7/2010	0	3 X 15	STREET	TBD	
5	2718 RT. 20		ASHTABULA	CWM	6"	N	0			1/8/2010	1/8/2010	0	15 X 15	STREET	TBD	
6	1308 W. 40th ST.	CENTRAL	ASHTABULA	CWM	6"	N	0			1/10/2010	1/11/2010	1	5 X 8	TREELAWN	TBD	
7	705 NORMAN AVE.	HARBOR	ASHTABULA	CWM	2"	N	0			1/10/2010	1/11/2010	0	5 X 6 (3 X 6)	STREET/TREELAWN	TBD	
8	2133 LAKE RD.		ASHTABULA	CWM	12"	N	3	DTD	1/14/2010	1/12/2010	1/12/2010	0	13 X 7	TREELAWN	TBD	
9	COLUMBUS AVE. # HARMON E. 48th ST.	CENTRAL		CWM	6"	N	0			1/14/2010	1/19/2010	5	4 X 6	STREET	TBD	
10	WOODMAN BL BROADWAY		SAYBROOK	VLV	10"	N	0			1/14/2010	1/20/2010	6	4 X 6	STREET	TBD	
11	3308 SUPERIOR	CENTRAL	SAYBROOK	CWM	6"	N	0			1/20/2010	1/20/2010	0	4 X 1	STREET	TBD	
12	E. 21st ST. & COLUMBUS	CENTRAL		CSL	3/4"	N	1			1/21/2010	1/22/2010	1	2 X 3	STONE DRIVEWAY	01/10	
13	15653 SHEPPARD		SAYBROOK	CWM	6"	N	0			1/27/2010	1/27/2010	0	5 X 8	STREET	TBD	
14	W 9th ST.	HARBOR		CWM	12"	Y	1	DTD	2/1/2010	1/29/2010	1/30/2010	0	2 X 5 - 3 X 5	STREET/TREELAWN	TBD	
15	5008 OGDEN		ASH. TWP.	CWM	6"	N	0			1/30/2010	1/30/2010	0	6 X 10	STREET	TBD	
16	6208 AUSTIN		ASH. TWP.	CWM	6"	N	0			1/30/2010	1/30/2010	0	12 X 8	TREELAWN	TBD	
17	S. SANBORN RD.		ASH. TWP.	CWM	6"	N	0			1/27/2010	1/22/2010	5	10 X 8	TREELAWN	TBD	
18	1844 E. PROSPECT	CENTRAL	SAYBROOK	CWM	8"	N	0			1/28/2010	2/2/2010	5	5 X 8	TREELAWN	TBD	
19	1421 MICHIGAN	HARBOR		CWM	6"	N	0			2/1/2010	2/1/2010	0	15 X 8	STREET	TBD	
20	742 W. 52nd ST.	S. CENTRAL		CWM	2"	N	0			2/1/2010	2/3/2010	2	5 X 15	STREET	TBD	
21	3027 BLAIR	HARBOR	ASH. TWP.	CWM	6"	N	0			2/1/2010	2/3/2010	2	4 X 4	STREET	TBD	
22	1138 HARMON RD.	CENTRAL		CWM	2"	N	0			2/1/2010	2/4/2010	3	3 X 8	SIDEWALK	TBD	
23	120 W. 42nd ST.			CWM	6"	N	0			2/4/2010	2/5/2010	1	5 X 8	TREELAWN	TBD	
24	6303 JEFFERSON RD.	S. CENTRAL		CWM	6"	N	0			2/10/2010	2/10/2010	0	4 X 7	STREET	TBD	
25	6519 SANBORN		SAYBROOK	CSL	3/4"	N	1			2/10/2010	2/11/2010	1	3 X 4 - 4 X 5	TREELAWN	TBD	
26	3200 NRE		ASH. TWP.	CSL	3/4"	N	1			2/17/2010	2/18/2010	1	6 X 8	TREELAWN	TBD	
27	3312 NRE		ASH. TWP.	CWM	6"	N	0			2/20/2010	2/20/2010	0	5 X 8	STREET	TBD	
28	2308 EUREKA		ASH. TWP.	CWM	3/4"	N	1			2/25/2010	2/25/2010	0	20 X 4	TREELAWN	TBD	
29	6047 SHELTON		KINGSVILLE	CWM	2"	N	0			3/1/2010	3/2/2010	1	4 X 6	TREELAWN	TBD	
30	3333 SUBURBAN		ASH. TWP.	CWM/CSL	1 1/4" 3/4"	Y	4	DTD	3/4/2010	3/1/2010	3/2/2010	1	6 X 6 - 4 X 6	STREET	TBD	
31	4203 LAKE RD.		ASH. TWP.	CSL	6"	N	0			3/2/2010	3/2/2010	0	4 X 6	TREELAWN	TBD	
32	4025 LAKE AVE.	HARBOR		CSL	6"	N	0			3/4/2010	3/4/2010	0	2 X 3 - 4 X 6	DRIVEWAY - TREELAWN	TBD	
33	742 W. 41st	CENTRAL		CSL	3/4"	N	1			3/8/2010	3/10/2010	2	5 X 8	DRIVEWAY	TBD	
34	913 E. 16th	HARBOR		CSL	3/4"	N	1			3/5/2010	3/10/2010	5	15 X 20	TREELAWN	TBD	
35	4603 DWIGHT	CENTRAL		HYD	6"	Y	33	DTD	3/13/2010	3/5/2010	3/11/2010	6	6 X 8	TREELAWN	TBD	
36	ROGER'S PLACE (ACMC)	HARBOR		CWM	6"	N	0			3/12/2010	3/11/2010	5	7 X 11	STREET	TBD	
37	6234 EDWARDS AVE.	S. CENTRAL		CSL	3/4"	N	1			3/19/2010	3/19/2010	0	9 X 5	STREET	TBD	
38	4708 FERN AVE.	S. CENTRAL		CWM	6"	N	0			3/19/2010	3/24/2010	5	5 X 10	TREELAWN	TBD	
39	AUSTINBURG RD. OAW TANK		ASH. TWP.	CWM	2.5"	Y	8	DTD	3/22/2010	3/22/2010	3/25/2010	3	6 X 20	STREET	TBD	
40	E. 2nd ST. & WILBUR	HARBOR		CWM	6"	N	0			3/28/2010	4/1/2010	4	4 X 6	TREELAWN	TBD	
41	2507 W. 8th ST.			CWM	2"	Y	2	DTD	4/9/2010	4/5/2010	4/7/2010	2	3 X 5	STREET	TBD	
42	6122-8123 MCNUIT		SAYBROOK	CWM	2"	N	0			4/5/2010	4/7/2010	2	5 X 6	STREET	TBD	
43	6841 SANBORN RD.		ASH. TWP.	CSL	3/4"	N	1			4/7/2001	4/8/2010	2	4 X 6	TREELAWN	TBD	
44	5220 BENEFIT RD.	S. CENTRAL													TBD	
45	4014 RT. 20														TBD	
46	907 W. 5th ST.	HARBOR		CWM	20"					4/13/2010	4/14/10	1	8 X 6	TREELAWN	TBD	
47															TBD	
48															TBD	
49															TBD	
50															TBD	
51															TBD	

Ohio American Water Company
Franklin County District

Leak Log - 2010

Updated: 4/16/2010

Location	Service Area	Township	Leak Type	Size	Boil Order (Y or N)	Number of Customers Affected	Method of Notification	Date Boil Order Lifted	Report Date	Repair Date	Elapsed Days	Size of Restoration	Type of Restoration	Date Restoration Completed	Comments
3610 Rodell Road	BL	Madison	CSL	3/4"	N	0	N/A	N/A	10/23/09	11/13/09	21	3X5	Soil	Pending	Company non-surfacing service leak repaired-- Restoration pending
5075 Sunaton	BL	Madison	CSL	3/4"	N	0	N/A	N/A	11/5/09	11/19/09	15	3X5	Soil	Pending	Company curb valve leak repaired--additional days were required to remove large diameter tree on top of service. Restoration pending
3383 Graystone on Madison School Drive	BL	Madison	CSL	3"	N	0	N/A	N/A	11/17/09	11/18/09	2	5X5	Pavement	Pending	Company service valve leak repaired--Restoration pending
3393 Sundale Road	BL	Madison	CSL	3/4"	N	0	N/A	N/A	12/7/09	12/15/09	3	10X10	Pavement	Pending	Company service leak repaired--Restoration pending
5050 Bentler Drive	BL	Madison	CSL	3/4"	N	0	N/A	N/A	12/7/09	12/9/09	3	5X5	Soil	Pending	Company service leak repaired--Restoration pending
3721 Aurelia	BL	Madison	N/A	N/A	N/A	N/A	N/A	N/A	12/10/09	Pending		1X2	Pavement	Pending	Main valve located under pavement--Restoration pending
3384 Latonia	BL	Madison	N/A	N/A	N/A	N/A	N/A	N/A	12/14/09	Pending		1X2	Pavement	Pending	Main valve located under pavement--Restoration pending
3353 Claretta	BL	Madison	N/A	N/A	N/A	N/A	N/A	N/A	12/14/09	Pending		1X2	Pavement	Pending	Main valve located under pavement--Restoration pending
3427 Brandenbury Way	BL	Madison	N/A	N/A	N/A	N/A	N/A	N/A	12/16/09	Pending		1X2	Pavement	Pending	Main valve located under pavement--Restoration pending
3023 Evanston	BL	Madison	N/A	N/A	N/A	N/A	N/A	N/A	12/16/09	Pending		2X2	Soil	Pending	Main valve located under pavement--Restoration pending
3734 Mexico	HR	Blendon	CWM	8	N	N/A	N/A	N/A	10/15/09	10/15/09	1	6X6	Pmt/Soil	Pending	Main valve located under pavement--Restoration pending
4211 Camellia Ct	HR	Blendon	CSL	3/4"	N	N/A	N/A	N/A	10/29/09	11/5/09	8	6X6	Soil	Pending	Curb box located under soil and raised-- Restoration pending
6521 Cherokee Rose	HR	Blendon	N/A	N/A	N	N/A	N/A	N/A	N/A	N/A	N/A	6X6	Soil	Pending	Point restored 11/24/09; soil pending
3646 Harbin Dr	HR	Blendon	VUV	2	N	N/A	N/A	N/A	11/23/09	11/24/09	2	4X4	Point	Pending	Due to service line replacement for above leak at 4211 Camellia Ct
5580 Stockholm (on Madrid)	HR	Blendon	CWM	8	N	N/A	N/A	N/A	1/9/10	1/11/10	3	6X6	Soil	Pending	
3527 Dempsey	HR	Blendon	VUV	6	Y	23	Door Hangers	1/19/2010	1/18/10	1/18/10	1	6X12	Soil	Pending	
6009 Sunlawn	HR	Blendon	PSL	3/4"	N	N/A	N/A	N/A	2/22/10	3/2/10	9	N/A	N/A	N/A	
6095 Dalar W	HR	Blendon	CSL	3/4"	N	N/A	N/A	N/A	2/25/10	2/26/10	2	6X6	Soil	Pending	
3500 Caracas Ct	HR	Blendon	PSL	3/4"	N	N/A	N/A	N/A	2/26/10	3/4/10	7	N/A	N/A	N/A	
6001 Sunrayvalve	TB	Norwich	CWM	6"	N	0	N/A	N/A	10/27/09	10/28/09	2	5X10	Soil	Pending	Company water main repaired--Restoration pending
6001 Sunrayvalve	TB	Norwich	CVIV	6"	N	0	N/A	N/A	11/6/09	11/12/09	7	5X5	Soil	Pending	Company main valve repaired--Restoration pending
6051 Sunrayvalve	TB	Norwich	CWM	6"	N	0	N/A	N/A	11/6/09	11/16/09	11	5X10	Soil	Pending	Company water main repaired--leak was observed a couple of days longer to pinpoint the source.
9011 Glendev N	WH	Perry	CWM	6	N	N/A	N/A	N/A	10/24/09	10/24/09	1	6X6	Soil	Pending	Restoration pending
804 Lookout Pt	WH	Sharon	CSL	3/4"	N	N/A	N/A	N/A	12/17/09	1/24/10	29	12X6	Soil	Pending	Minor Leak, No visible flow
970 Clubview S	WH	Perry	CWM	8	Y	28	Door Hangers	1/21/2010	1/20/10	1/20/10	1	10X20	Point	Pending	

CSL = Company Service Leak; CWM = Company Water Main; HYD = Hydrant; VLV = Valve; CO = Company Other; PSL = Private Service Leak; PWN = Private Water Main; PQ = Private Other DRe Door Tag; DTD = Door to Door

[illegible]

Ohio American Water Company
Lawrence County District
2010 Water Leak Log

CSL = Company Service Leak; CWM = Company Water Main; HTD = Hydrant; VLV = Valve; CO = Company Other; PSL = Private Service Leak; PWM = Private Water Main; PO = Private Other DR; Door Tag; DTD = Door to Door

	Location	Service Area	Township	Leak Type	Size	Bolt Order (Y or N)	Number of Services Affected	Method of Notification	Date Bolt Order Lifted	Report Date	Repair Date	Elapsed Days	Size of Restoration	Type of Restoration	Date Restoration Completed	Comment
1	Township Road 1042-Booth BL		Union	CWM	2	N	0	N/A	N/A	01/04/10	01/04/10	0	4X8	Blacktop	1/10/10	
2	Buffalo Creek Road		Union	CWM	4	N	0	N/A	N/A	01/04/10	01/04/10	0	3X8	Berm	N/A	
3	Old Pullys Nursing Home		Fayette	PO	8	N	0	N/A	N/A	01/04/10	01/04/10	1	N/A	N/A	N/A	Private Fire Service-SC-Nelly Fire Dept.
4	Robertson Road		Chas-Village	CWM	2	N	0	N/A	N/A	01/04/10	01/04/10	1	8X8	Blacktop	N/A	
5	Overlook Drive		Chas-Village	CWM	2	N	6	N/A	N/A	01/04/10	01/04/10	0	6X8	Berm	3/25/10	
6	Madison Street		Fayette	CSL	3/4	N	1	N/A	N/A	01/08/10	01/08/10	5	4X4 & 4X4	Yard	3/25/10	Replace Service
7	Township 1022		Fayette	CWM	2	N	0	N/A	N/A	01/08/10	01/08/10	1	4X8 & 2X6	Berm & Street	3/25/10	
8	Township Rd. 1000		Fayette	CWM	2	N	10	N/A	N/A	02/17/10	02/17/10	0	4X8	Concrete	3/25/10	
9	East Drive		Fayette	CWM	6	N	0	N/A	N/A	03/08/10	03/11/10	3	4X8	Grass	3/25/10	Bel Leak Saddle
10	North Huntington Heights		Chas-Village	CWM	2	N	0	N/A	N/A	03/18/10	03/18/10	0	8X8	Grass	3/25/10	
11	11255 County Rd. 1		Union	CSL	1	N	1	N/A	N/A	3/19/10	3/24/10	5	6X6 & 8X8	Blacktop		Replace Service

12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76

CSL = Company Service Leak; CWH = Company Water Main; HYD = Hydrant; VLV = Valve; CO = Company Other; PSL = Private Service Leak; PVM = Private Water Main; PO = Private Other

Location	Service Area	Township	Leak Type	Size	Boil Order (Y or N)	Number of		Method of Notification	Data Boil Order Ltrd	Report Date	Repair Date	Elapsed Days	Size of Restoration	Type of Restoration	Date Restoration Completed	Comment	VERIFIED
						Affected	Customers										
714 Bygonne Drive	Imperial Estates	Millin	CSL	3/4"	N	1	0	N/A	4/23/2010	4/23/2010	1	8' x 12'	Yard	spring 10	service line leak from main to curb box replaced service line		
966 Benedict	Madison	Madison	CWM	6"	N	0	0	N/A	1/8/2010	1/8/2010	1	4'x4'	Yard	spring 10	isolating location of leak		
976 Benedict	Madison	Madison	CWM	6"	N	0	0	N/A	1/8/2010	1/8/2010	1	4'x4'	Yard	spring 10	isolating location of leak		
986 Benedict	Madison	Madison	CWM	6"	N	0	0	N/A	1/8/2010	1/8/2010	1	4'x4'	Yard	spring 10	repaired leak on main at service tap		

Ohio American Water Company

Marion District

2010 Water Leak Log

[illegible]

Ohio American Water Company
Portage County District
2010 Water Leak Log

CSL = Company Service Leak; CWM = Company Water Main; HYD = Hydrant; VLV = Valve; CO = Company Other; PSL = Private Service Leak; PWH = Private Water Main; PO = Private Other DR= Door Tag; DTD = Door to Door

Location	Service Area	Township	Leak Type	Size	Boil Order (Y or N)	Number of Services Affected	Method of Notification	Date Boil Order Lifted	Report Date	Repair Date	Elapsed Days	Size of Restoration	Type of Restoration	Date Restoration Completed	Comment
3560 Duffield	Beechcrest	Brimfield	CWM	6" C.I.	Y	28	Street Signs	2/24/2010	2/22/2010	2/22/2010	0	0	Crushed Line	2/22/10	
2764 Elton	Aurora East	Shalersville	CSL	3/4" cu	N	14	Door hangers	N/A	3/30/2010	4/2/2010	0	5 X 10	In the grass at road's edge		
3472 Keswick	Aurora East	Shalersville	CSL	3/4" cu	N	12	Door hangers	N/A	4/6/2010	4/6/2010	0	5 X 10	In the grass at road's edge		

PSL = Company Service Leak; CWM = Company Water Main; HYD = Hydrant; VLV = Valve; CV = Company Other DR = Door Tag; DTD = Door to Door

[illegible]