










Legend

- Study Area
- Sampling Point
- Culvert Inlet/Outlet
- Culvert Pipe
- Stream
- Wetland
 - PEM
 - PFO
 - PSS
 - PUB
- Wetland Continuation
 - PEM
 - PFO
 - PSS
 - PUB

Sheet Identifier





FIGURE 4-24
AQUATIC RESOURCE LOCATION MAP
SENECA WIND PROJECT
 SENECA WIND LLC
 SENECA COUNTY, OHIO



Notes:
 1) Aerial photograph provided by ESRI's ArcGIS Online World Imagery map service (© 2015 ESRI and its data suppliers).



Legend

- Study Area
- Sampling Point
- Culvert Inlet/Outlet
- Culvert Pipe
- Stream
- Wetland
 - PEM
 - PFO
 - PSS
 - PUB
- Wetland Continuation
 - PEM
 - PFO
 - PSS
 - PUB

Sheet Identifier







FIGURE 4-25
AQUATIC RESOURCE LOCATION MAP
SENECA WIND PROJECT
SENECA WIND LLC
SENECA COUNTY, OHIO




Notes:
1) Aerial photograph provided by ESRI's ArcGIS Online World Imagery map service (© 2015 ESRI and its data suppliers).









This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

12/3/2018 2:27:12 PM

in

Case No(s). 18-0488-EL-BGN

Summary: Correspondence of Seneca Wind, LLC Submitting Aquatic Resource Report, Part 6 of 12 electronically filed by Teresa Orahod on behalf of Dylan F. Borchers