













Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
154				Farmstead – Equipment Storage Building: Shallow-pitch gable roof, clad in metal sheets, sliding, equipment-scale metal doors	ca. 1980	Good	X Location <input type="checkbox"/> Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Appears on aerial imagery between 1971 and 1995 (historicalia.com)	Recommended as a non-contributing feature to the historic property
154				Farmstead – Grain Bin: Poured concrete pad, circular footprint, clad in corrugated metal with standing-seam metal, conical roof	ca. 1980	Good	X Location <input type="checkbox"/> Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Appears on aerial imagery between 1971 and 1995 (historicalia.com)	Recommended as a non-contributing feature to the historic property
154				Farmstead – Quonset Hut: Open-ended, metal Quonset hut with deep corrugation used to store agricultural equipment	ca. 2000	Good	X Location <input type="checkbox"/> Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Appears on aerial imagery between 1995 and 2004 (historicalia.com)	Recommended as a non-contributing feature to the historic property
154				Farmstead – Machine Shed: 5 bays long with central, double-height projection, gable roof clad in standing-seam metal sheets, concrete footings or stem walls, gable-end walls clad in vertical boards, each bay has 1 or 2 hinged doors clad in corrugated metal, including the double-height bay	ca. 1930	Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting      X Association X Materials Adjacent newer farm buildings impact integrity of setting	Recommended as a contributing feature to the historic property





Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
154				Farmstead – Storage Building: storage building with gambrel roof clad in asphalt shingles, front projects over open work area	ca. 2020	Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials  Not shown on aerial photographs up to 2017 (historicaerials.com) – likely recently moved to site	Recommended as a non-contributing feature to the historic property
155	NA		2715 Old Kropp Road	House: 1 story, ranch style, cross-gable roof clad in asphalt shingles, brick veneer and aluminum siding, windows are a combination of aluminum sliders and vinyl sash units, all with SDLs, applied shutters, inset entry porch set on decorative metal post	1972	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Windows replaced	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G
156	NA		3000 Old Kropp Road	Farmstead – House: 1-story, minimal tradition, cross gable roof clad in asphalt shingles, exterior brick chimney, concrete block foundation, asbestos siding, aluminum slider, picture, and casement windows, metal awnings; domestic 2-car garage with hip roof clad in asphalt shingles, walls clad in horizontal tongue-and-groove siding, vehicular doors are mock panel with upper lights, pedestrian door is paneled with 9 lights	1951	Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials  Road reconfiguration between 1995 and 2004 affects setting (historicaerials.com) – likely recently moved to site	Recommended not eligible, due to a lack of significance and integrity
156				Farmstead – Agricultural Outbuildings: buildings include 1 gambrel-roof dairy barn on T-plan with concrete-block stem wall, standing-seam metal cladding to roof and sides, metal-clad sliding doors, and ground-level, 4-light casement windows, 1 concrete silo without roof, 1 frame granary with central drive, 1 English barn with gable roof, tongue-and-groove siding, hayloft casement windows and sliding, vehicular-scale door, and 2 grain bins	ca. 1920 and early 21 <sup>st</sup> century	Fair / Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Grain bins first appear between 1995 and 2004 but remaining buildings in place since 1953, some changes to individual buildings (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity







Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
157	NA		6500 Royalton Drive	House: split level, front gable with cross-wing for attached 2-car garage, asphalt shingle roofing, brick chimney, brick veneer to ground level, vinyl siding elsewhere, vinyl sash windows, inset door with mock-paneled side lights (unit not visible), garage doors are mock paneled roller units; outbuildings include concrete-block 2-car garage and metal, RV-scale garage	1966	Good	<div> X Location X Workmanship </div> <div> <input type="checkbox"/> Design X Feeling </div> <div> <input type="checkbox"/> Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Vinyl siding and windows, entrance configuration altered, detached 2-car garage built around same time as house, infill development on street since 1971 (historicaerials.com)</p>	Recommended not eligible, due to a lack of significance and integrity
158	NA		7310 Ruoff Drive	House: 1 story, ranch style, cross-hip roof clad in asphalt shingles, brick veneer and vinyl cladding, inset front entrance porch with mock-paneled door and fanlight and modern turned posts, vinyl sash windows with applied shutters	1973	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Vinyl siding, door and windows, porch posts replaced with incompatible units</p>	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G
159	NA		7333 Ruoff Drive	House: 2-story, ranch style house, cross-gable roof clad in asphalt shingles, brick veneer and vinyl siding, inset front porch with turned posts, paneled front door, metal sash windows, applied shutters, octagonal, louvered, gable-end vent	1972	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Vinyl siding, metal windows</p>	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G
160	NA		7315 Ruoff Drive	House: ranch style, hipped roof on V-plan, asphalt roof shingles, inset front porch with bracketed posts on concrete pad, brick veneer and vertical-board siding, 1-over-1 sash windows and 1 picture window, double, paneled front doors	1972	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> X Materials </div> <p>No alterations apparent</p>	<p>Recommended not eligible for failing to achieve the exceptional significance necessary to satisfy Criteria Consideration G.</p> <p>Should its high level of integrity be retained in 2022, it would be recommended potentially eligible under Criterion C</p>


Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
161	NA		7341 Ruoff Drive	House: 1 story, ranch style, gable roof clad in asphalt shingles, brick veneer and vinyl siding, metal casement windows, applied wood shutters, inset entry porch with mock-paneled door with fanlight, attached 2-car garage with mock-paneled door, mock hinges, and mock door handles	1971	Good	<div> X Location X Workmanship </div> <div> <input type="checkbox"/> Design <input type="checkbox"/> Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Applied shutters and replacement doors alter the mid-century design, windows replaced</p>	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G
162	NA		3908 Lukens Road	House: 1 story, ranch style, cross-hip roof clad in asphalt shingles, Roman brick veneer cladding, 3 doors on front façade, including inset main door with 3 cascading teardrop lights, side door with single upper light, and 3-light, paneled pedestrian garage door, wood-framed casement windows in a variety of styles, attached 2-car garage	1966	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Windows and some doors are likely to be replacements</p>	Recommended not eligible, due to a lack of significance and integrity
163	NA		3900 Lukens Road	House: split-level, cross-hip roof clad in asphalt shingles, brick chimney, brick veneer and stucco siding, vinyl sash windows with 1 picture window, applied shutters, mock-panel door with upper light, 3-car garage with mock-panel roller doors	1965	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Windows and doors replaced</p>	Recommended not eligible, due to a lack of significance and integrity
164	NA		3878 Lukens Road	House: 1 story, ranch style, cross-gable roof with asphalt shingles, brick veneer cladding, inset front porch with square posts, vinyl sash windows with 1 picture window, applied shutters, security front door	1974	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Windows replaced, front posts possibly replaced</p>	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
165	NA		3858 Lukens Road	House: 1 story, ranch style, cross-gable roof with standing-seam metal roofing, stuccoed chimney, shed-roof porch on square posts, attached 1-car garage with mock-panel roller door, brick veneer, board-and-batten, vertical T1-11, and fiber-cement cladding, vinyl and metal sash windows, mock-paneled front door	1966	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Porch addition, windows, doors, and siding replaced	Recommended not eligible, due to a lack of significance and integrity
166	NA		3842 Lukens Road	House: 1 story, ranch style, side gable, roof clad in asphalt shingles, attached 2-car garage with mock-panel roller door, stone veneer siding, metal-framed windows in picture-window, bay, and sliding-sash styles, inset entry patio has mock-paneled front door with mock leaded light	1966	Good	X Location    X Workmanship X Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and doors replaced	Recommended not eligible, due to a lack of significance and integrity
167	NA		3826 Lukens Road	House: 2-story ranch style house with extended cross-gable-on-hip roof, asphalt roof shingles, brick veneer and vinyl siding, vinyl casement windows and large bay window, front door consists of 1 full-length light with full-length side lights, attached 2-car garage has mock-paneled unit with mock hinges and handles	1966	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Porch addition, windows, doors, and siding replaced	Recommended not eligible, due to a lack of significance and integrity
168	NA		3734 Lukens Road	House: 2 stories, Classical revival, side gable roof, multicolored brick veneer and aluminum siding, 1-over-1 metal-framed windows and 1 picture window, mock-paneled front door set under continuous garage roofline has porch with Classical column, side lights have mock leadwork.	1972	Good	X Location    X Workmanship X Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Vinyl siding, windows and doors may have been replaced	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G

Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
169	FRA1095427		Pleasant View Middle School / 7255 Kropp Road	School: Modernist school complex composed of multiple, interconnected 1- and 2- story wings, roof is mostly flat with parapet with one depressed gable, cladding is brick veneer with decorative tilework as accents to curtain walls, curtain-wall framing system appears to be vinyl with vinyl 1-over-1 sash units, 1 2-story, windowless wing has brick buttresses, dedicated 1959 as “Pleasant View High School” per entrance plaque	1958	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Original curtain-wall system and associated windows replaced	Recommended not eligible, due to a lack of integrity
170	NA		7300 Kropp Road	House: 1 story ranch-style house with contemporary, detached, 2-car garage, asphalt roof shingles to both, house is clad in brick veneer with exterior brick chimney and vinyl casement windows, front door not visible, garage has concrete-block construction and mock-paneled, roller door	1963	Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and door replaced, outbuildings constructed 1995-2004 and in 2020 (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
171	NA		7280 Kropp Road	House: 1 story, ranch style, side gable, standing-seam metal roof, aluminum siding, vinyl sash windows, applied shutters, front door has mock-paneled unit and 1 mock-paneled side light; detached, concrete-block, 2-car garage with hipped roof clad in standing-seam metal, mock paneled roller door	1963	Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Doors, windows, and roofing replaced, arage added 1971-1988 (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
172	NA		7220 Kropp Road	House: 1 story, ranch style, side gable, asphalt-shingle roof, decorative fascia board, brick chimney, brick-veneer siding, vinyl sliding-sash windows, applied shutters, front door has mock-paneled unit with 4 upper lights, aluminum storm door, front stoop has metal railing, attached 2-car garage, mock-paneled roller door	1961	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and doors replaced	Recommended not eligible, due to a lack of significance and integrity






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
173	NA		7254 Kropp Road	House: 1 story, ranch, hip-on-hip roof with asphalt shingles, stone chimney, stone-veneer and stucco siding, metal sliding-sash windows, applied shutters, modern access ramp with prefabricated baluster, mock-paneled door unit, attached 2-car garage, mock-paneled roller door	1960	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Windows and doors replaced, front access ramp alters design of main façade	Recommended not eligible, due to a lack of significance and integrity
174	NA		7208 Kropp Road	House: split level, cross-gable roof clad in asphalt shingles, brick chimney, attached 2-car garage with mock-panel door, siding is brick veneer and vinyl, 1-over-1 vinyl windows with mock muntins (internal grill), inset front patio with decorative metal posts, front door has mock-paneled unit.	1971	Good	X Location    X Workmanship X Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Windows and doors replaced	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G
175	NA		7101 Kropp Road	Former Farmstead: ruins include 1 1-story building with evidence of lath-and-plaster exterior walls and window/door openings, 1 smoke house/coal shed with vertical boards and overhanging metal roof, and a possible English barn; 2 functioning metal-clad storage sheds with sliding, machinery-scale doors	1961	Ruined	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Analysis of farmstead integrity; barns collapsed and new standing buildings constructed west of the original site 1971-1994 (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
176	NA		6933 Kropp Road	House: split level, gable-on-gable roof clad in asphalt shingles, attached 2-car garage with paneled door, siding is brick veneer and clapboard, 1-over-1 wood sash windows, applied shutters, front door has broken-pedimented entablature with flush unit; additional metal-clad, machinery-storage building in rear yard	1972	Good	X Location    X Workmanship X Design    X Feeling X Setting <input type="checkbox"/> Association  X Materials  Only setting has been altered – metal-clad, machinery-storage building added 1994-2004 (historicaerials.com)	Recommended not eligible, due to a lack of significance; does not possess exceptional significance necessary to satisfy Criteria Consideration G




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
177	NA		6919 Kropp Road	Farmstead: front-gable-with-wing house, corrugated metal roof, brick chimney, vinyl siding, hipped entry porch with turned posts, 1-over-1 vinyl sash windows, extended gable addition to rear of house; outbuildings include 1 domestic garage with 1 roller door and 1 sliding door clad in vinyl, 1 chicken house, 1 large, metal-clad equipment shed with sliding door, 1 small garage clad in horizontal boards with sliding door and metal roof, 1 rusted metal grain bin, and 2 metal-clad barns	1900 - 1940	Ruined / Fair / Good	X Location    X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Setting affected by some nearby residential development, material integrity affected by condition of outbuildings, layout of farmstead has not changed since earliest available aerial image (1953) (historicaerials.com)	Recommended not eligible, due to a lack of integrity
178	NA		6901 Kropp Road	House: 1-story, ranch-style house with cross-gable roof clad in asphalt shingles, 2 attached garages, 1 for 2 cars with metal roller door and 1 for 1 cars with mock-paneled door, brick veneer, stucco, and vinyl siding, 1-over-1 vinyl windows and 1 picture window, 2 pedestrian doors have mock-paneled units; detached, metal-clad garage	1967	Good	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Metal-framed garage added 1994-2004, garage addition at east end of house built after 2017 (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
179	NA		6717 Kropp Road	Farmstead – House: 2-story, 2-door house, depressed hip roof clad in standing-seam metal with metal-boxed eaves, 2-story addition to rear, 1 story garage addition to side, 1-story, ¾-length front porch with flat roof, metal-boxed eaves, and metal fascia, common-bond brick to original core of house, vinyl siding to the additions, 3 visible doors are wood-paneled with upper lights, windows on the original core have stone lintels and sills, 1-over-1 vinyl windows throughout	ca. 1850	Good	X Location    X Workmanship <input type="checkbox"/> Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Dominant rear addition in incompatible materials, windows and roofs replaced, footprint of additions appear on earliest-available aerial photograph (1953) (historicaerials.com)	Property recommended not eligible, due to a lack of integrity






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
179				Farmstead – Outbuildings: gable-front domestic garage with metal roof and tongue-and-groove siding, sliding and hinged doors, 6-over-6 vinyl window; English barn with side sheds, corrugated metal and vertical board cladding (some missing), asbestos roof shingles, multiple sliding doors, evidence of 6-light casement windows to lofts; perforated metal grain bin; chicken house with variety of cladding		Poor / Fair	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Material integrity affected by condition, some outbuildings lost 1971-1994 and others 1994-2004 (historicaerials.com)	Property recommended not eligible, due to a lack of integrity
180	NA		6716 Kropp Road	House: 2 ½-story, American Foursquare house, pyramidal roof with corner flares, hipped dormers, asphalt-shingle roof, full-length porch with boxed roof set on fluted columns, vinyl siding, front wood-paneled door with upper light, 1-over-1 sash windows, wood and vinyl units; detached, front-gable, 2-car garage with asphalt shingle roof, vinyl siding, mock-paneled roller door	1900	Good	X Location <input type="checkbox"/> Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Vinyl siding and windows, some porch alterations, garage built 1971-1994, nearby infill development (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
181	NA		6908 Kropp Road	Farmstead – House: 2-story, 2-door I-house house, side gable with asphalt-shingle roof, 2-story addition to rear, full-length, hipped porch with turned posts on concrete foundation, aluminum siding, front door units are wood-paneled with single upper lights, 1-over-1 vinyl windows, applied shutters	1900	Good	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Rear additions, aluminum siding, windows replaced,	Recommended not eligible, due to a lack of significance and integrity
181				Farmstead – Outbuildings: 1 concrete silo with metal roof, 2 corrugated-metal grain bins with moderately-pitched, conical roofs, 1 wood-framed chicken house with shed roof, vertical-board cladding, and mostly missing fenestration, 1 4-bay, wood-framed, open equipment storage building, multiple modern, metal-framed storage buildings with sliding doors	ca. 1930-1994	Poor / Fair / Good	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Few existing outbuildings shown on 1953 aerial image, some date to 1965-1971, remaining to 1971-1994 (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
182	NA		7022 Kropp Road	House: 1 story, ranch style, side gable, asphalt-shingle roof, brick chimney, brick veneer and vinyl siding, vinyl 1-over-1 sash windows and 1 picture window, applied shutters, inset front entrance with original flush door with wood trim and original side lights, dimensional lumber access ramp, attached 2-car garage with mock-paneled door	1973	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Vinyl siding and applied shutters, windows and garage door replaced, access ramp to front</p>	Recommended not eligible, due to a lack of significance and integrity; does not possess exceptional significance necessary to satisfy Criteria Consideration G
183	NA		7102 Kropp Road	Farmstead: 2 ½-story, American Foursquare house, pyramidal roof, hipped dormers, asphalt-shingle roof, stone foundation, full-length hipped porch set on square posts with prefabricated baluster, clapboard siding, window and openings on ground floor reduced to accommodate new units, windows 1-over-1 vinyl units, door is mock-paneled with upper lights; outbuildings include frame meat house clad in vertical board with corrugated metal roof, wood-framed barn with vertical board siding in poor condition, and new metal clad storage building with 1-over-1 sash window and front deck	1900	Poor / Good	<div> X Location <input type="checkbox"/> Workmanship </div> <div> <input type="checkbox"/> Design <input type="checkbox"/> Feeling </div> <div> <input type="checkbox"/> Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Altered openings, windows and doors replaced, and altered front porch on house; significant loss of large outbuildings after 2013, addition of metal-clad building after 2017 (historicaerials.com)</p>	Recommended not eligible, due to a lack of significance and integrity
184	FRA0175827		Charles Kropp Farm / 7190 Kropp Road	Farmstead – House: 2-story, gable-with-wing (T-plan) house, brick chimney, roof clad in standing-seam metal, brick foundation, modern wraparound porch set on concrete pad with fluted, fiberglass columns, vinyl siding, vinyl sash windows, applied shutters, mock-paneled door unit	1900	Good	<div> X Location <input type="checkbox"/> Workmanship </div> <div> <input type="checkbox"/> Design <input type="checkbox"/> Feeling </div> <div> <input type="checkbox"/> Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> <p>Porch, siding, windows, and door altered, wraparound porch added 2011-2013, significantly altered setting through outbuilding losses and new construction (historicaerials.com)</p>	Previously surveyed; recommended not eligible, due to a lack of significance and integrity






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
184				Farmstead – Outbuildings: 1 5-bay, wood-framed, equipment shed with modern standing-seam, metal roof, 3 sliding doors, 1 mock-panel, roller, garage door, and 1 bay partly clad in horizontal siding and tarp; 1 concrete silo without roof; 1 English barn with side sheds with older standing-seam metal roof, decaying, vertical-board siding, sliding, and hinged doors, further gable extension for newer, metal-clad shed; 1 granary with pyramidal roof, asphalt roof shingles, clapboard siding, and vertical-boarded windows; 1 poured concrete ice house with metal door; 2 large, metal-clad storage buildings; domestic garage for RV and 2 cars clad in modern standing-seam metal with mock-paneled roller doors	1900-2015	Ruined / Fair / Good	<div> X Location <input type="checkbox"/> Workmanship </div> <div> <input type="checkbox"/> Design <input type="checkbox"/> Feeling </div> <div> <input type="checkbox"/> Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Outbuilding losses since 1971; modern outbuildings: 2 large, metal-clad storage buildings (1994-2015), new garage (2013-2015) (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
185	NA		7810 Haenzel Road	House: 1 story, ranch style, hip-on-hip roof with attached 2-car garage and enclosed breezeway, exterior brick chimney, brick veneer siding, vinyl windows in different styles, inset front entrance (unit not visible) and side entrance to breezeway with mock-paneled door and central oval light with mock leadwork, attached 2-car garage with mock-paneled door low brick retention wall with stairs from driveway	1962	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Doors and windows replaced	Recommended not eligible, due to a lack of significance and integrity
186	NA		7813 Haenzel Road	Farmstead – House: 2 ½-story, American Foursquare house, pyramidal roof, hipped dormer, asphalt-shingle roof, full-length hipped porch set on square posts with capitals, vinyl siding, vinyl 1-over-1 windows, front door unit not visible, side door to driveway is wood-paneled with upper light	1900	Good	<div> X Location <input type="checkbox"/> Workmanship </div> <div> X Design X Feeling </div> <div> <input type="checkbox"/> Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Windows replaced, vinyl siding; condition of outbuildings affects integrity of setting	Recommended not eligible, due to a lack of significance and integrity




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
186				Farmstead – Outbuildings: askew frame garage/workshop with asbestos-shingled hip roof, tongue-and-groove siding, and 4-light casement; metal-framed electrical shed; meat house with metal roof; multiple framed buildings in varying states of disrepair obscured by vegetation	ca. 1900 – 2010	Ruined / Poor / Good	X Location <input type="checkbox"/> Workmanship X Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Electrical shed appears new, all others in states of ruin; layout of farmstead appears to be intact (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
187	NA		7996 Haenzel Road	Farmstead – House: 2 stories, gable with wing (T-plan), asphalt shingle roof, front porch with square posts and modern log-style baluster, vinyl windows, mock-paneled door with oval light with mock leadwork	1870	Good	X Location <input type="checkbox"/> Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Windows replaced, vinyl siding; condition of outbuildings affects integrity of setting	Recommended not eligible, due to a lack of significance and integrity
187				Farmstead – Outbuildings: askew wood-frame back house/root cellar with clapboard siding and asbestos roof shingles; domestic 1-car garage with side shed, asbestos roof tiles and clapboard siding, remnants of 1-over-1 windows; wood-frame workshop with 2 hinged doors clad in vertical tongue-and-groove; English barn with gable roof and side shed, remnants of sliding door, louvered ventilation openings to lofts, vertical tongue-and-groove siding, asbestos roof shingles to core, corrugated metal and wood shakes to side shed; 2 frame chicken houses with vertical board siding	ca. 1850-2010	Ruined / Poor / Good	X Location <input type="checkbox"/> Workmanship X Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Grain bins appear new, all others in varying states of ruin; layout of farmstead appears to be intact (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity







Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
188	NA		7665 Haenzel Road	House: Minimal Traditional, 1 ½ stories, side gable roof clad in asphalt shingles, exterior brick chimney, enclosed front entrance with front gable and Classical door casing with fluted pilasters, vinyl siding and windows, applied shutters, dimensional lumber front deck with prefabricated baluster; outbuildings include extended-gable 1-car garage with side unit, clad in vinyl with metal roller door, and metal-clad chicken house	1948	Good	X Location <input type="checkbox"/> Workmanship X Design        X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Vinyl siding and windows, incompatible front deck	Recommended not eligible, due to a lack of significance and integrity
189	NA		3019 Kropp Road	House: 1 story, ranch style, side gable, asphalt-shingle roof, brick veneer and gable-end clapboard siding, shed-roof front porch on brick and concrete pad with turned posts, mock-paneled front door, 1-over-1 wood sash windows with decorative wood bulkheads, applied shutters, 2 1-car garages (door units not visible)	1972	Good	X Location      X Workmanship X Design        X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Front door replaced, otherwise intact	Recommended not eligible, due to a lack of significance; does not possess exceptional significance necessary to satisfy Criteria Consideration G
191	FRA1095527		3326 Kropp Road	Farmstead – House: 2 ½ stories, American Foursquare with hip and gable dormers, standing-seam metal roof, stone foundation, full-length, hip-roof porch set on square posts, vinyl siding, mostly 1-over-1 vinyl windows with wood-framed, double-hung sash windows on porch, paneled front door with central, beveled, oval light	1911	Good	X Location <input type="checkbox"/> Workmanship X Design        X Feeling x <input type="checkbox"/> Setting      x <input type="checkbox"/> Association <input type="checkbox"/> Materials Siding, roofing, and window units altered, significant infill development since 1971 impacts agricultural setting (historicaerials.com)	Property as a whole recommended eligible under Criterion A  The house is recommended as contributing to the historic property





Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
191				Farmstead – Domestic Garage: rusticated concrete block construction, hip roof clad in standing-seam metal, 4 wood garage doors, 2 of which are original hinged, paneled doors with 12 upper lights, 1 of which is plywood-panel roller door with 4 upper rights	ca. 1920	Very Good	X Location    X Workmanship X Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Roof replaced, central garage door replaced during the historic period, significant infill development since 1971 impacts agricultural setting (historicaerials.com)	Recommended as contributing to the historic property
191				Farmstead – Windmill and Workshop: intact metal windmill with wind rotor blades and wind vane; rusticated concrete block shop with hip roof clad in standing-seam metal, brick chimney, plywood-panel roller door with 4 upper lights, paneled pedestrian door, 6-light metal casement windows	ca. 1911 and ca. 1920	Fair	X Location    X Workmanship X Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Roof replaced, central garage door replaced during the historic period, significant infill development since 1971 impacts agricultural setting (historicaerials.com)	Recommended as contributing to the historic property
191				Farmstead – English Barn: 3 bays with gable roof, attached feed shed, roof clad in standing-seam metal sheets, missing in some areas, vertical tongue-and-groove siding, central-bay threshing openings infilled to create a pedestrian door on one side, additional wood pedestrian doors, passive ventilation through louvered openings to ground, mid-level, and loft levels on all elevations, wood-frame feed shed set on concrete stem wall with bracketed posts set on concrete pads	ca. 1900	Fair	X Location    X Workmanship X Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Threshing-door opening infill occurred during historic period, ondition impacts material integrity somewhat, significant infill development since 1971 impacts agricultural setting (historicaerials.com)	Recommended as contributing to the historic property







Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
191				Farmstead – Other Outbuildings: include 1 aisled, wood-framed, storage barn set on poured concrete stem wall with extended gable roof, sliding machinery doors and 3 openings on the aisle side; 1 gable-front, wood-frame, equipment storage garage clad in vertical boards and set on concrete stem wall, both ends contain plywood paneled roller doors; other outbuildings appear modern	ca. 1935	Fair / Good	X Location    X Workmanship X Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Condition impacts material integrity somewhat, significant infill development since 1971 impacts agricultural setting (historicaerials.com)	ca. 1935 outbuildings recommended as contributing to the historic property, modern buildings non-contributing
192	NA		3101 Kropp Road	Farmstead – House: 1 story, shallow-pitched hipped roof clad in asphalt shingles, exterior brick chimney, brick-veneer cladding, concrete front stoop, front door is mock-paneled unit with fanlight, windows are vinyl casements, window and door openings partly infilled to accommodate new units	1960	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Altered fenestration openings, window and door units replaced; house built south of the original farmstead, multiple new outbuildings since house constructed (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity
192				Farmstead – Outbuildings: 1 wood-frame back house clad in horizontal boards, 1 shed clad in tongue-and-groove siding with metal roofing; 1 concrete silo without roof; 7 metal grain bins; 2 multi-bay, wood-framed open equipment storage buildings, one with corrugated metal siding, the other with standing-seam metal siding; 1 barn complex adjacent to the silo with multiple wings and framing systems, including concrete block and wood framing clad in corrugated metal	ca. 1930 – 2011	Poor / Good	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Only silo and 2 barns (now connected as 1) close to the road are visible on 1954 aerial image (with the old farmhouse and small outbuildings shown north of the existing farmstead), continuous development thereafter, with final 2 large metal storage buildings added 2009-2011 (historicaerials.com)	Recommended not eligible, due to a lack of significance and integrity




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
193, 194, 195, 196	NA		7570 Kuhlwein Road 7580 Kuhlwein Road 7590 Kuhlwein Road 7600 Kuhlwein Road (Parcel ID 240-000107 – Same as Resource Number 198)	4 Workers' Houses: 4 cottages and 2 garages associated with Darby Dan Farm, 1 story, minimal traditional style, side gable roofs with asphalt shingles, 7580 has original asbestos siding (clapboard style), others have vinyl siding, fenestration configurations are the same for all 4 houses, all have mock-paneled front doors, windows are 1-over-1 vinyl units in singles and pairs; 2 2-car garages with individual doors	1953	Good	X Location <input type="checkbox"/> Workmanship X Design <input type="checkbox"/> Feeling X Setting        X Association <input type="checkbox"/> Materials  Windows and doors replaced, some vinyl siding; garages constructed 1965-1971 (historicaerials.com)	Recommended not eligible, due to lack of integrity
198	NA		7600 Kuhlwein Road (Parcel ID 240-000107 – Same as Resource Numbers 193-196)	Horse Barn: isolated location, associated with Darby Dan Farm, 13 bays, wood-frame construction, gable roof with gable dormers and 3 ridge-top, louvered, ventilation cupolas, 1 visible brick chimney stack, asbestos roof cladding, horizontal board siding, window openings have no visible complete units but show evidence of horizontal sliding shutters	ca. 1935	Poor / Fair	X Location      X Workmanship X Design        X Feeling X Setting        X Association <input type="checkbox"/> Materials  Material integrity impacted by condition	Recommended not eligible, due to a lack of integrity
199	NA		7400 Kuhlwein Road	House: 1 story, ranch style, cross-hip roof clad in asphalt shingles, brick chimney, brick-veneer cladding, inset front porch has mock-paneled front door, metal casement window and metal bay window	1966	Good	X Location      X Workmanship X Design        X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Windows and door replaced	Recommended not eligible, due to a lack of significance and integrity
200	NA		7401 Kuhlwein Road	House: 1 story, ranch style, cross-gable roof clad in asphalt shingles, brick chimney, brick-veneer cladding, poured concrete front stoop (door unit not visible), 1-over-1 vinyl windows with applied shutters, attached 2-car garage	1978	Good	X Location      X Workmanship X Design        X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Windows replaced	Recommended not eligible, due to a lack of significance and integrity; fails to achieve exceptional significance necessary to satisfy Criteria Consideration G






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
201	NA		7383 Kuhlwein Road	House: 2 stories, ranch style with hip-on-gable roof, including gable extension for porch, exterior stone chimney, asphalt shingles, brick-veneer and stucco siding, porch set on square posts, vinyl slider and 1-over-1 sash windows with 1 picture window, mock-paneled front door, attached 2-car garage has original plywood-panel roller door	1964	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and front door replaced	Recommended not eligible, due to a lack of significance and integrity
202	NA		7350 Kuhlwein Road	House: split level with hip-on-gable roof, brick chimneys, asphalt roof shingles, brick-veneer and clapboard siding, inset front porch set on decorative metal posts, vinyl casement windows, mock-paneled front door, attached 2-car garage mock-paneled roller door; wishing well in front yard	1964	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and front door replaced	Recommended not eligible, due to a lack of significance and integrity
203	NA		7345 Kuhlwein Road	House: split level with gable-on-gable roof, brick chimney, asphalt roof shingles, brick-veneer and T1-11 siding, inset front porch set on square posts, mock-paneled front door, 1-over-1 vinyl windows with applied shutters, attached 2-car garage has Craftsman-style, up-and-over door	1978	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Vinyl windows, doors replaced with incompatible units	Recommended not eligible, due to a lack of significance and integrity; fails to achieve exceptional significance necessary to satisfy Criteria Consideration G
204, 205	NA		849 Darby Creek Drive 855 Darby Creek Drive (Parcel ID 240-000007-00)	2 Workers' Houses: 2 cottages and 1 garage associated with Darby Dan Farm, 1 story, minimal traditional style, side gable roofs with asphalt shingles, vinyl siding, fenestration configurations are the same for both houses, front door units not visible, windows are 1-over-1 vinyl units, front stoops and side porches are made from dimensional lumber, 1 with a prefabricated balustrade; 1 2-car garages with individual doors, mock-paneled roller units	1948	Good	X Location    X Workmanship <input type="checkbox"/> Design      X Feeling X Setting      X Association <input type="checkbox"/> Materials Vinyl siding and windows, incompatible porches, former outbuildings replaced by garage 1965-1971 (historicaerials.com)	Recommended not eligible, due to a lack of integrity





Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
206	NA		911 Darby Creek Drive (Parcel ID 240-003098-00 – Same as Resource Number 207)	House: 1 story, minimal traditional style, gable-on-gable roof clad in asphalt shingles, 1 brick chimney and 5 satellite dishes, clapboard and vertical tongue-and-groove siding, attached 1-car garage with mock-panelled roller door, 1-over-1 vinyl windows, mock-panelled front door, front deck built from dimensional lumber with irregular ballustrade	1948	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling X Setting    X Association <input type="checkbox"/> Materials Replaced doors and windows, incompatible front deck, satellite dishes dominate roof (historicaerials.com)	Recommended not eligible, due to a lack of integrity
207	NA		917 Darby Creek Drive (Parcel ID 240-003098-00 – Same as Resource Number 206)	House: 1 ½ stories, gable front, brick chimney, asphalt roof shingles, stone foundation, ¾-length front porch with boxed eaves set on columns, vinyl siding, front window openings have been altered to accommodate vinyl units, front door is mock-paneled, side windows are 2-over-2 double-hung sash units on 1 side and 8-light metal casements on the other; detached 4-car garage with mock-paneled doors and an asphalt-shingle roof	1900	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling X Setting    X Association <input type="checkbox"/> Materials Altered fenestration openings, window and door units replaced, vinyl siding; garage constructed 1953-1954 (historicaerials.com)	Recommended not eligible, due to a lack of integrity
208	FRA0175928		Walter Cook House / 6241 Alkire Road	House: 2 stories, Italianate, hipped roof with 2-story bay window projection, dentiled, bracketed cornice, 1 porch with dentiled cornice, 1 porch without dentilation is probably a newer addition or replacement, all ground floor doors and windows are boarded over, second-floor windows have 1-over-1 vinyl units, stone lintels and sills	1885	Fair	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Current condition affects material and design integrity,	Previously surveyed; concur with previous determination of eligibility
209	FRA1095128		Darby Dan Farm / 801 Darby Creek Drive	House: 2 stories, side gable with wing, asphalt shingles, brick chimney, side addition has flat roof, vinyl siding, front porch with boxed eaves set on square columns, modern stone front entrance piers, 1-over-1 vinyl windows, front door unit not visible	1900	Good	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design    X Feeling X Setting    X Association <input type="checkbox"/> Materials Additions, vinyl siding, vinyl windows, addition of stone piers to porch	Property recommended eligible under Criterion A  House is recommended contributing to the historic property




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
209				Horse Barn: 18 stalls, gambrel roof with gable wing, asphalt roof shingles, brick chimney, clapboard siding, pair of wood cross-brace, sliding doors with 2 6-light windows each, 6-light, wood awning windows	ca. 1910	Good	X Location    X Workmanship X Design      X Feeling X Setting      X Association X Materials No visible alterations, setting unchanged since 1953 (historicaerials.com)	Recommended contributing to the historic property
209				Gate House: stone wall and piers with strap pointing, modern metal gates; stone gatehouse with strap pointing, pyramidal roof clad in clay tiles, wood casement windows, glazed metal door	ca. 1954 (wall) & ca. 1965 (gatehouse)	Good	X Location    X Workmanship X Design      X Feeling X Setting      X Association X Materials Modern metal gates, strap pointing may be a later alteration; dating estimated with aerial imagery (historicaerials.com)	Recommended contributing to the historic property
209				Horse Barn: 9 bays, wood-frame construction, gable roof with gable dormers and 2 ridge-top, louvered, ventilation cupolas, 1 brick chimney stack, asphalt roof cladding, horizontal shiplap siding, 8-light windows with evidence of horizontal sliding shutters, pair of sliding, batten doors to driveway with upper divided lights inserted, hayloft door with board-and-batten cladding	ca. 1935	Fair / Good	X Location    X Workmanship X Design      X Feeling X Setting      X Association <input type="checkbox"/> Materials Some windows units and muntins missing, peeling paint	Recommended contributing to the historic property





Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
209				Additional Outbuildings: include 1 horse barn with cross-gable roof clad in asphalt shingles, board-and-batten siding, some 6-light and 4-light windows, other openings lack units, pair of sliding doors with 4-light windows inserted; 1 horse barn with second-floor office, corrugated gable roof, asbestos shingles clad pent-roof front porch set on battered posts, tongue-and-groove siding, 4 wood batten exterior doors to stalls, 1 paneled pedestrian door with upper lights; fuel shed with gas pumps; additional equipment storage barns dating to 1950s and 1960s	ca. 1935, ca. 1955 & ca. 1965	Poor / Fair	<div> X Location X Workmanship X Design X Feeling <input type="checkbox"/> Setting X Association <input type="checkbox"/> Materials </div> <p>Some windows units and muntins missing, peeling paint, missing roofing, larger storage buildings at southern end of cluster constructed in 1950s and 1960s, smaller storage buildings at southern end of cluster demolished 2011-2013 (historicaerials.com)</p>	Recommended contributing to the historic property
209				Tenant House: 3 bays, 2 stories, central gable clad in asphalt shingles, brick chimney, rusticated concrete-block foundation, ¾-length porch with hip roof set on square piers with capitals, clapboard siding, windows are 1-over-1 vinyl units with 2 picture windows to porch and a single multi-light, round window within central gable, front door not visible	ca. 1880	Good	<div> X Location X Workmanship X Design X Feeling X Setting X Association <input type="checkbox"/> Materials </div> <p>Most window units replaced, massing of porch suggests it may have been added or replaced (unconfirmed)</p>	Recommended contributing to the historic property
209				Breeding Shed: gable roof clad in asphalt shingles, deep overhangs set on square posts, braced batten doors to stalls at one end with central void accessed by by pair of batten sliding doors at the other, clapboard and tongue-and-groove siding	ca. 1935	Good	<div> X Location X Workmanship <input type="checkbox"/> Design X Feeling <input type="checkbox"/> Setting X Association X Materials </div> <p>1 post missing, pent-roof extension of gable to 1 side, adjacent outbuilding lost 1954-1957 (historicaerials.com)</p>	Recommended contributing to the historic property






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
209				Dairy Barn and Milk House: 7-bay barn has flared gambrel roof clad in asphalt shingles, shed dormers and cupola, shiplap siding, paired sliding batten doors at ground and loft levels, most with 4-light windows inserted, paired wood-framed, 4-light windows along ground floor; concrete block milk house with gable roof clad in asphalt shingles and stuccoed chimney, door not visible, 1-over-1 windows (material not inspected)	ca. 1935	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling X Setting    X Association X Materials  Windows set within doors appear to be later additions, historical aerials show fenced paddocks to the west of the cluster developed in the 1950s, now planted (historicaerials.com)	Recommended contributing to the historic property
209				House: complex, 1-story ranch-style residence, multiple cross gables clad in asphalt shingles, exterior stone fireplace, stone veneer and board-and-batten siding, 1-over-1 metal windows, glazed front entrance, set within manicured grounds that contain a tennis court and swimming pool adjacent to Darby Creek	1954	Good	X Location    X Workmanship X Design    X Feeling X Setting    X Association X Materials  No visible alterations	Recommended non-contributing to the historic property
210	NA		55 Darby Creek Drive	House: 1 story, ranch style, hip with crosswing roof clad in asphalt shingles, stone chimney, stone veneer, stucco, and clapboard siding, inset entrance porch with flush door and security door, most windows are multi-light metal casements, attached 2-car garage with paneled roller door	1956	Good	X Location    X Workmanship X Design    X Feeling X Setting <input type="checkbox"/> Association X Materials  1 window replaced with vinyl unit	Recommended not eligible, due to a lack of significance
211	NA		81 Darby Creek Drive	House: 1 story, ranch style, parallel-hip roof clad in asphalt shingles, stone chimney, brick veneer, stucco, and clapboard siding, inset entrance porch (door not visible), most visible windows are vinyl sliding or casement units with 1 multi-light metal casement to the attached 2-car garage with paneled roller door, rear patio has a decorative metal post supporting the extended hip roof	1956	Good	X Location    X Workmanship X Design    X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials  Most windows replaced, otherwise appears intact	Recommended not eligible, due to a lack of significance




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
212	NA		101 Darby Creek Drive	House: 1 story, ranch style, hip roof with rear wing clad in asphalt shingles, stone chimney, stone veneer, vertical T1-11, and vinyl siding, inset entrance porch supported by fluted columns (door not visible behind storm door), visible windows are vinyl casement and bay units, attached 2-car garage with mock-paneled roller door	1956	Good	<div> X Location <input type="checkbox"/> Workmanship </div> <div> <input type="checkbox"/> Design <input type="checkbox"/> Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Siding, windows, and garage door replaced, incompatible Classical columns added	Recommended not eligible, due to a lack of significance and integrity
213	NA		123 Darby Creek Drive	House: 1 story, ranch style, parallel-hip roof clad in asphalt shingles, vinyl-clad stove chimney, stone veneer and vinyl siding, entrance patio, mock-paneled front door and side lights, windows are vinyl sliding or casement units, driveway leads to the rear of the house	1956	Good	<div> X Location X Workmanship </div> <div> X Design X Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Vinyl siding, windows and door replaced, chimney replaced	Recommended not eligible, due to a lack of significance and integrity
214	NA		143 Darby Creek Drive	House: 1 story, ranch style, hip roof with cross-wing clad in asphalt shingles, stone chimney, stone veneer and vinyl siding, poured concrete entrance patio (door not visible behind storm door), windows are vinyl sliding units with heavy frames, attached 2-car garage with mock-paneled roller door; modern detached garage with gambrel roof, vertical T1-11 cladding, and a single, mock-paneled roller door	1956	Good	<div> X Location X Workmanship </div> <div> X Design <input type="checkbox"/> Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Windows, garage door, and siding replaced; new front patio; new detached garage	Recommended not eligible, due to a lack of significance and integrity
215	NA		163 Darby Creek Drive	House: 1 story, ranch style, hip roof with garage cross-wing and projection clad in asphalt shingles, stone chimney, stone veneer, vertical board, and vinyl siding, poured concrete entrance patio converted to porch with shed roof set on square posts with turned balluster, mock-paneled front door with fanlight, windows are vinyl sliding units with heavy frames, attached 2-car garage with paneled roller door	1956	Good	<div> X Location X Workmanship </div> <div> <input type="checkbox"/> Design <input type="checkbox"/> Feeling </div> <div> X Setting <input type="checkbox"/> Association </div> <div> <input type="checkbox"/> Materials </div> Prominent, modern front porch addition, windows and front door replaced, vinyl siding	Recommended not eligible, due to a lack of significance and integrity






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
216	NA		187 Darby Creek Drive	House: 1 story, ranch style, hip-on-hip roof clad in standing-seam metal, stone chimney, stone veneer, stucco, and clapboard siding, mock-paneled front door with security door, windows are metal sliding units, 1 with applied shutters, attached 2-car garage with paneled roller door	1956	Good	X Location    X Workmanship X Design <input type="checkbox"/> Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Roof, windows, and front door replaced, applied shutters	Recommended not eligible, due to a lack of significance and integrity
217	NA		207 Darby Creek Drive	House: 1 story, ranch style, hipped roof with cross-wing, asphalt roof shingles, stone chimney, stone veneer, vinyl, and vertical-board siding, front door is mock-paneled with mock-lead lights, windows are vinyl units in different styles, including an octagon, applied shutters, attached 2-car garage has a mock-paneled unit	1956	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and doors replaced, mock shutters added	Recommended not eligible, due to a lack of significance and integrity
218	NA		223 Darby Creek Drive	House: 1 story, ranch style, hip roof with front projection and inset entrance (front door not visible), asphalt roof shingles, stone chimney, stone veneer, stucco, and vinyl siding, windows are metal units in different styles, applied shutters, attached 2-car garage has a mock-paneled unit	1956	Good	X Location    X Workmanship X Design <input type="checkbox"/> Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and garage door replaced, mock shutters added	Recommended not eligible, due to a lack of significance and integrity
219	NA		245 Darby Creek Drive	House: 1 story, ranch style, hip roof with rear wing, standing-seam, metal roof, stone chimney, stone veneer, vinyl, and vertical-board siding, front porch with flat roof, turned posts, and turned balluster added, door is mock-paneled with central oval light, windows are metal and vinyl units in different styles, attached 2-car garage has a paneled roller door	1956	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Prominent modern front porch addition, metal roof, windows and front door replaced	Recommended not eligible, due to a lack of significance and integrity




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
220	NA		267 Darby Creek Drive	House: 1 story, ranch style, parallel-hip roof clad in asphalt shingles, stone chimney, stone veneer and vinyl siding, entrance patio, flush front door with 3 cascading lihts, side light, windows are 1-over-1 vinyl units and 1 picture window, driveway leads to the rear of the house	1956	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows replaced, side light may be modern	Recommended not eligible, due to a lack of significance
221	NA		287 Darby Creek Drive	House: 1 story, ranch style, hip roof clad in asphalt shingles, stone chimney, stone veneer, stucco, and clapboard siding, front door not visible, most windows are multi-light metal casements and 1 picture window, attached 2-car garage with paneled roller door	1956	Good	X Location    X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association X Materials No visible alterations	Recommended not eligible, due to a lack of significance
222	NA		448 Darby Creek Drive	House: 2 stories, front gable with cross, asbestos roof shingles, brick chimney, rooster-comb finials, 2 porches set on square posts, 1 with balluster, the other with dimensional-lumber handrail, drop siding, visible windows are 1-over-1 vinyl sash units, visible door is mock-paneled with fanlight; modern rear shed with gambrel roof and T1-11 siding	1900	Fair / Good	X Location    X Workmanship <input type="checkbox"/> Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Windows and door replaced, alterations to porches; former farmstead, lost smaller outbuildings in 1960s and barn between 1971 and 1995 (historicaerials.com)	Recommended not eligible, due to a lack of integrity
223	FRA0968428		Metro Parks House / 341 Darby Creek Drive	Barn: isolated location, wood frame construction, 3-bay English barn with gable roof clad in standing-seam metal, central pair of sliding, braced, batten equipment doors, and remnants of sliding pedestrian door, vertical tongue-and-groove siding, passive, louvered ventilation openings to attic story, other openings boarded over	ca. 1920	Poor	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Formerly part of small farmstead, associated buildings, including farmhouse, demolished 2004-2009 (historicaerials.com)	Previously surveyed; recommended not eligible, due to a lack of integrity






Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
225	MAD0023607		Former US 40 Cottage Court / 9420 West Broad Street	Tourist Court: cluster of approximately 16 tourist cabins with central office building and caretaker's residence, minimal traditional style, gable roofs with asphalt shingles, binyl siding, pent-roof hoods over cottage entrances (door units not visible), visible windows are vinyl in 1-over-1 and horizontal sliding styles, office building and caretaker's residence have metal awnings; additional ranch-style single- or multi-family residence with extended gable roof and brick veneer cladding has multi-light metal casement windows facing the highway	1950, ca. 1970, & ca. 2000	Good	X Location      X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials 1953 aerial image shows 13 cabins with office and caretaker's residence, ranch-style building added 1965-1971, multiple cottages lost 1971-1980, new cottages added 1995-2004 (historicaerials.com)	Previously surveyed; recommended not eligible, due to a lack of significance and integrity
226	FRA0176028		John West House / 1982 Galloway Road	House: 2 stories, Italianate, hipped roof with central flat roof, cornice brackets with pendants, stretcher-bond brick construction, 1-over-1 vinyl windows, stone lintels and sills, front paneled door with upper light and transom, front walk and stairs are modern poured concrete, 2-story, rear porch	1876	Good	X Location      X Workmanship X Design      X Feeling X Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Roof may have lost widow's walk (parapet), vinyl windows	Previously surveyed; concur with previous determination of eligibility
227	FRA0176128		Fulton Brothers' Store / 1954 Galloway Road	Restaurant / Store: commercial use ground floor, apartments second floor, 2 stories, flat roof with parapet and front, bracketed cornice, common-bond brick, 1-over-1 metal winodws, stone lintels and sills, front elevation dominated by pent-roof, open dining area with modern wood fencing and dimensional wood posts, picture windows just visible within	ca. 1880	Good	X Location      X Workmanship <input type="checkbox"/> Design      x <input type="checkbox"/> Feeling X Setting      x <input type="checkbox"/> Association <input type="checkbox"/> Materials Incompatible front addition, windows replaced	Previously surveyed; concur with previous determination of eligibility




Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
228	FRA0176228		Ernest Tyler House / 1915 Galloway Road	House: 2 ½ stories, eclectic Queen Anne style, hipped roof with cross gables, asphalt roof shingles, brick chimneys, stretcher-bond brick construction, windows have stone lintels and 1-over-1 metal units, applied shingles, front door has paneled unit with 2 upper lights, 2 porches with shed-roof hoods set on square posts, shed-roof additions	1869	Good	X Location      X Workmanship <input type="checkbox"/> Design      x <input type="checkbox"/> Feeling x <input type="checkbox"/> Setting      x <input type="checkbox"/> Association <input type="checkbox"/> Materials Shed-roof additions out of keeping with style, porches have bulky massing and appear to be replacements (historicaerials.com)	Previously surveyed; concur with previous determination of eligibility
229	FRA0176828		Everett Hensley House / 6342 O'Harra Street	House: 1 story, vernacular Victorian style, extended hip roof with front porch and gable-roof rear additions, dentil cornice, roof clad in asphalt shingles, central brick chimney, stone foundation rusticated wood-block siding, front porch with turned posts, brackets, and ballusters, paneled front door with upper light and transom, wood-framed, double-hung sash windows in 2-over-2 and 4-over-4 configuration, wood surrounds with depressed Gothic arch lintel; wood-framed shed clad in flush board siding with 4-panel door (1930); modern garage (2019)  Winter home for postman Jess Byrum (per OHI form)	1900	Very Good	X Location      X Workmanship X Design      X Feeling X Setting      X Association X Materials Asphalt shingles appear to be the only modern alteration	Previously surveyed; concur with previous determination of eligibility
231	FRA0176928		Clay House / 6439 O'Harra Street	House: 1 ½ stories, Second Empire style, mansard roof clad in asphalt shingles, rear, shed-roof addition, brick foundation, rusticated wood-block siding, corner pilaster detail, 1-over-1, double-hung sash windows, with notched surrounds, paneled front door with single upper light; wood-frame shed and privy with shed roof, vertical board cladding	1900	Good	X Location      X Workmanship x <input type="checkbox"/> Design      X Feeling <input type="checkbox"/> Setting      x <input type="checkbox"/> Association X Materials Loss of front porch, loss of former agricultural buildings (1994-2004),	Previously surveyed; concur with previous determination of eligibility







Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
233	FRA0174128		Dr. J. M. Phillips Estate / 6011 W Broad Street	Former Farmstead: site of former farmstead, most structurally sound building appears to be a storage barn with evidence of former sliding doors and battened hayloft doors, gable roof, vertical tongue-and-groove siding	1879	Ruin	<input type="checkbox"/> Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Only remaining standing structure in the process of collapse	Previously surveyed; recommended not eligible, due to a lack of significance and integrity
234	FRA1066428		US 40 over Scioto Big Run	Culvert: stone arch culvert under highway set behind poured-concrete box culvert	ca. 1833, ca. 1930-1950	Fair / Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling <input type="checkbox"/> Setting    X Association X Materials	Previously surveyed; recommended not eligible, due to intergity
235	NA		Galloway Cemetery, Alkire Road (Parcel ID: 240-000238-00 & 240-000202)	Cemetery: municipal cemetery located on the east side of Alkire Road south of the town of Galloway, 8.5 acres marked out on a grid pattern, carved wooden entrance sign, chain-link fencing, markers range in date from the late nineteenth century until today, vegetation is lawn with yew, cedar, and deciduous trees, hand pump set on poured concrete pad	1879	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Chain-link fencing, 4-square grid layout expanded to 5 1971-1994 and to 7 2007-2009, rural setting impacted by residential infill since the 1950s (historicaerials.com)	Recommended not eligible, due to a lack of exceptional significance required for Criteria Consideration D

Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
236	NA		Ebenezer M.E. Cemetery, Grove City (Parcel ID: 230-001054-00)	Cemetery: previously associated with former Ebenezer Methodist Church at 2870 Kunz Road, located near the intersection of Kunz and Johnson Roads on south side of Johnson Road, .56 acres, modern, pierced metal entrance sign and historic wrought-iron fence along sidewalk, chainlink fence to interior boundaries, marked burials date from the mid nineteenth century through the late twentieth century, vegetation consists of lawn and oak, cedar, and yew trees	ca. 1845	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Modern chain-link fencing, modern entrance sign and hardscaping, infill development (historicaerials.com)	Recommended not eligible, due to a lack of exceptional significance required for Criteria Consideration D
237	NA		2870 Kunz Road	Methodist Church/House: front gable roof with shed-roof front addition, common-bond brick with stucco on addition, corrugated metal roofing, brick chimney, central clock within gable, sanctuary windows have stone arches and sills, 2-over-2 wood-framed sash windows on front addition, 1 multi-light, metal casement window visible on screened-in front porch	1870	Good	X Location    X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Dominant front addition with change of use to residence, residential infill impacts historical setting	Recommended not eligible, due to a lack of integrity
238	NA		Alton Cemetery, Alton Darby Creek Road (Parcel ID: 240-001223)	Cemetery: municipal cemetery located on the west side of Alton Darby Creek Road north of US-40 (West Broad Street), 14.2 acres marked out on a grid pattern, surrounded by chain-link fence, markers range in date from the mid nineteenth century until today, veterans memorial flagpole, vegetation is lawn with yew, cedar, and deciduous trees, hand pump located outside concrete block maintenance shed	ca. 1850s	Good	X Location    X Workmanship <input type="checkbox"/> Design    X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Plan of 4 rectangles expanded, to 5 1957-1965, to 6 1971-1980, and to current assymetrical configuration 1994-2004, infill development (historicaerials.com)	Recommended not eligible, due to a lack of exceptional significance required for Criteria Consideration D



Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
239	FRA0875528		Clover Cemetery, Alton Darby Creek Road (Parcel ID: 241-001341-00)	Cemetery: located on the west side of Alton Darby Creek Road south of Thorn Apple Golf Course, approximately .5 acres, carved wood entrance sign, chain link fence surrounding perimeter with interior plot demarkated by wrought-iron fence, lacks interior paths, marked burials date from the early nineteenth century through the 1870s, vegetation consists of lawn with deciduous and cedar trees	ca. 1820	Fair	X Location      X Workmanship X Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting      X Association X Materials Modern chain-link fence, substantial surrounding development 1994-2004 includes addition of detention ponds adjacent to cemetery, impacting integrity of setting and feeling (historicaerials.com)	Recommended eligible under Criterion A for achieving exceptional significance under Criteria Consideration D
240	NA		Gundy Cemetery, Norton Road (No Parcel ID)	Cemetery: located on the east side of Norton Road between Johnson and Grove City Roads, .96 acres surrounded by chain-link fence, lacks formal paths markers range in date from the early nineteenth century through the late-twentieth century vegetation is lawn with a few evergreen and deciduous trees, survey control monument within grounds	ca. 1820s	Good	X Location      X Workmanship X Design      X Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Modern chain-link fence, substantial surrounding development 1957-1994 impacts integrity of setting and feeling (historicaerials.com)	Recommended not eligible, due to a lack of exceptional significance required for Criteria Consideration D
241	NA		Oak Grove Cemetery, Alkire Road (Parcel ID: 230-000363)	Cemetery: located on the north side of Alkire Road west of Darby Creek Drive, metal entrance sign with scrollwork, 5.7 acres, post-and-wire fencing along street, chain-link fencing around rest of perimeter, organic circulation system with central circular burial area surrounding a grave monument to the Biggert family, markers range in date from the early nineteenth century a number of military burials, vegetation is lawn with ro present day, a variety of evergreen and deciduous trees, survey control monument within grounds	ca. 1830s	Good	X Location      X Workmanship X Design      X Feeling <input type="checkbox"/> Setting      X Association X Materials Circulation plan in place since earliest available aerial photo (1953), rural setting eroded by development since 1954 (historicaerials.com)	Recommended not eligible due to a lack of exceptional significance required for Criteria Consideration D

Appendix B. Properties Identified During the Historic Property Investigation								
Resource Description							Resource Evaluation	
Resource Number	OHI Number	Photo	Property Name / Address	Architectural Style/ Type	Built Date	Current Condition	Integrity	NRHP Individual Eligibility
242	FRA0175527		Toland House / Alkire Road, West of Georgesville	Ruined House: brick chimney and chimney breast, stone and clay-pipe remains of well or cistern	ca. 1860	Ruin	<input type="checkbox"/> Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Ruins	Previously surveyed; recommended not eligible, due to a lack of significance and integrity
243	FRA0175427		Boyd House / 5500 Harrisburg Georgeville Road	House: 1 ½ stories, complex plan, original core of building has side gable roof, chinked, adzed log construction, exterior brick chimney, 6-over-6, double-hung wood-framed windows, Victorian addition adds gable crosswings with returns, clapboard siding, vinyl windows with SDLs, doors not visible, whole building has prominent, modern, continuous wraparound porch with prefabricated post-and-baluster system clad in a standing-seam metal roof, asphalt shingles to the roof	ca. 1830-1890	Good	X Location           X Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association X Materials Log-structure original section retains material integrity, dominant, incompatible porch negatively impacts integrity of design and feeling	Previously surveyed; recommended not eligible due to lack of integrity
243				Outbuildings: 2 small frame storage buildings set on stone piers/walls, with corrugated metal roofs and vertical board siding; modern buildings include 1 large, metal-clad pole barn (ca. 2016)	ca. 1900, ca. 2016	Poor / Very Good	X Location <input type="checkbox"/> Workmanship <input type="checkbox"/> Design <input type="checkbox"/> Feeling <input type="checkbox"/> Setting <input type="checkbox"/> Association <input type="checkbox"/> Materials Outbuildings lost/moved and new barn constructed since 2015 (historicaerials.com)	Previously surveyed; recommended not eligible due to lack of integrity
244	FRA0968528		Metro Parks Barn / 583 Darby Creek Road	Horse Barn: 2 rectangular barns connected by semicircular wings create an overall oval plan, central entrance cross-wings have gable roof with central, louvered cupolas, asphalt-shingle roof, pairs of sliding doors on each gable end, board-and-batten siding, windows are 4 x 4 wood-framed sliding sash units	ca. 1960	Good	X Location           Workmanship X Design           X Feeling <input type="checkbox"/> Setting           X Association Materials Constructed 1957-1965, nearby paddocks and outbuildings demolished 1995-2009 (historicaerials.com)	Previously surveyed; recommended not eligible due to lack of integrity



# Phase I History Architecture Reconnaissance Survey

Pleasant Prairie Solar Energy Center Project

Prairie and Pleasant Townships

Franklin County, Ohio

## APPENDIX

# C

## OHIO HISTORIC INVENTORY FORMS



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0175928 REV		4. Present Name(s): <b>Courtright House</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 6241 Alkire Road		19a. Design Sources: Unknown	35. Plan Shape: Other
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-001730-00		21. Building Type or Plan: Other House Type	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 39.7 x 51.6 feet
Zone: 17 Easting: 315200 Northing: 4420362		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Irma Zamora 1982 Galloway Road Galloway, Ohio, 43119	40. Chimney Placement: No chimney observed
11. On National Register? NO		26. Property Acreage: 0.24257	41. Distance from & Frontage on Road: 51.1 x 90 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Deteriorated
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: AGRICULTURE		29. Basement? No	Date(s):
		30. Foundation Material: Stone bearing	Associated Activity:
17. Date(s) or Period: 1885	17b. Alteration Date(s):	31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Transitional High Victorian Gothic		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
Transitional Italianate			
18a. Style of Addition or Elements(s): Transitional		33. No. of Bays: 3 Side Bays: 3	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Brick	


2. County: **Franklin**4. Present or Historic Name(s): **Courtright House**

8. Site Plan (location map) with North Arrow

6. Specific Address or Location: **6241 Alkire Road**



1. No. FRA0175928	4. Present Name(s): Courtright House
2. County Franklin	5. Historic or Other Name(s):



Door Selection: Two doors symmetrical  
Door Position: Altered  
Orientation: Other  
Symmetry: Bilateral symmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slagle		1975	Ohio Historic Inventory: Walter S. Cook Residence (Courtright House and Farm)

42. Further Description of Important Interior and Exterior Features

This two-story common bond brick house was constructed circa 1885 in the Italianate style. The house was previously recorded in the Ohio Historic Inventory in 1975. The dwelling features a two-story projecting bay window on the façade. The building's hipped roof is covered in asphalt shingles and it rests on a stone foundation wall. The roof's eaves slightly overhang and are defined by Italianate style brackets and a dentiled cornice. The façade features two one-story entry porches, situated on either side of the projecting bay window. The windows and doors on the first floor are covered in plywood board. The windows on the second floor are 1-over-1 double hung vinyl sash. All windows have bracketed and incised stone lintels and sills.

43. History and Significance

This property was determined eligible in 2006 by the Ohio SHPO under Criterion C, presumably as an intact example of the Italianate style in Galloway. The building retains integrity of location, setting, design, feeling and association to its beginnings in this late nineteenth century railroad town.

44. Description of Environment and Outbuildings (See #52)

There are no remaining outbuildings present on this property.

45. Sources of Information

Frank Slagle, "Walter S.Cook Residence or Courtright House and Farm," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0175928.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:


1. No. FRA0176028 REV		4. Present Name(s): <b>Adams House</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s): <b>John West House</b>	
6. Specific Address or Location: 1982 Galloway Road		19a. Design Sources: Unknown	35. Plan Shape: Square
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-000123-00		21. Building Type or Plan: Other House Type	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 42 x 61 feet
Zone: 17 Easting: 315203 Northing: 4420173		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Richard Queen 7788 Alkire Road Galloway, Ohio. 43119	40. Chimney Placement: No chimney observed
11. On National Register? NO		26. Property Acreage: 0.70535	41. Distance from & Frontage on Road: 25 x 50 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Excellent
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations:		29. Basement? No	Date(s):
		30. Foundation Material: Brick bearing	Associated Activity:
17. Date(s) or Period: 1875	17b. Alteration Date(s):	31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Transitional Italianate		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
None		33. No. of Bays: 3 Side Bays: 3	
18a. Style of Addition or Elements(s):		34. Exterior Wall Material(s): Brick	
19. Architect or Engineer: Unknown			

2. County: **Franklin**4. Present or Historic Name(s): **Adams House**6. Specific Address or Location: **1982 Galloway Road**

8. Site Plan (location map) with North Arrow



1. No. FRA0176028	4. Present Name(s): Adams House
2. County Franklin	5. Historic or Other Name(s): John West House



Door Selection: Single centered  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral symmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slagle		1975	Ohio Historic Inventory: John West House (Adams House)

42. Further Description of Important Interior and Exterior Features

This two-story common bond brick house was constructed circa 1875. The house was previously recorded in the Ohio Historic Inventory in 1975. The dwelling was constructed in the Italianate style and features a symmetrical three-bay façade with a Window-Door-Window fenestration pattern. The simple hipped roof, which is covered in asphalt shingles, overhangs the eaves, and features decorative Italianate style brackets at the cornice. Windows are 1/1 vinyl replacement sash, set into the original opening, with stone lintels and sills. The foundation wall appears to be parged. The front entry door is recessed behind an Italianate style simple stone surround. A transom window remains in situ over what appears to be a modern clad single-leaf entry door.

43. History and Significance

This two-story common bond brick house was constructed circa 1875. The house was previously recorded in the Ohio Historic Inventory in 1975.

44. Description of Environment and Outbuildings (See #52)

There are no outbuildings but the property has a well maintained lawn and exterior.

45. Sources of Information

Frank Slagle, "John West House or Adams," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176028.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0176128 REV	4. Present Name(s): <b>Fulton Brothers' Store</b>		
2. County: <b>Franklin</b>	5. Historic or Other Name(s):		
6. Specific Address or Location: 1954 Galloway Road		19a. Design Sources: Unknown	35. Plan Shape: Other
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-001727-00		21. Building Type or Plan: Restaurant/Bar	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: COMMERCIAL	37. Window Type(s): 1 over 1 Storefront
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Restaurant/bar	38. Building Dimensions: 44 x 99 feet
Zone: 17 Easting: 315134 Northing: 4420424		24. Ownership: Public	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Galloway Martin LLC. 711 Alton Road Galloway, Ohio, 43119	40. Chimney Placement: No chimney observed
11. On National Register? NO		26. Property Acreage: 0.24368	41. Distance from & Frontage on Road: 10 x 30 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: COMMERCE		29. Basement? No	Date(s):
17. Date(s) or Period: 1880		30. Foundation Material: Stone bearing	Associated Activity:
17b. Alteration Date(s):		31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Element Commercial/Chicago Style		32. Roof Type: Flat Roof Material: Unknown	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 4 Side Bays: 5	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Brick	

2. County: **Franklin**4. Present or Historic Name(s): **Fulton Brothers' Store**6. Specific Address or Location: **1954 Galloway Road**

8. Site Plan (location map) with North Arrow






1. No. FRA0176128

4. Present Name(s): Fulton Brothers' Store

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Single off center  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slale		1975	Ohio Historic Inventory: Fulton Brother's Store

42. Further Description of Important Interior and Exterior Features

This two-story, common-bond brick commercial building was constructed circa 1880. It is four-bays wide and five-bays deep. The building is currently used for commercial purposes on the first floor and residential purposes on the second floor. This building was previously recorded in the Ohio Historic Inventory in 1975. The building was constructed in the Commercial Italianate style and features replacement 1-over-1 metal windows with stone lintels and sills. It is covered by a flat roof with parapet and a front-bracketed cornice. The building rests on a stone foundation wall. The façade has a pent-roof, outdoor dining area addition with modern wood fencing, dimensional wood posts.

43. History and Significance

This is the last remaining store building in Galloway, if only one every exsisting. Town has frame 2-story post office building which may have been a commercial building at one point. This building was previously recorded in the Ohio Historic Inventory in 1975.

44. Description of Environment and Outbuildings (See #52)

There are no outbuildings.

45. Sources of Information

Frank Slalge, "Big Tony' Pizza Carry Out or Fulton Brothers' Store," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176128.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO


Section 106/RPR Review:

RPR Number:

1. No. FRA0176228 <b>REV</b>		4. Present Name(s): <b>Peters House</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 1915 Galloway Road		19a. Design Sources: Unknown	35. Plan Shape: Irregular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 220-001707-00		21. Building Type or Plan: Other House Type	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 45 x 63 feet
Zone: 17      Easting: 315103      Northing: 4420527		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Patricia A. Gow and Gerald W. Swain 1915 Galloway Road Galloway, Ohio, 43119	40. Chimney Placement: Three or more chimneys
11. On National Register? NO		26. Property Acreage: 0.2535	41. Distance from & Frontage on Road: 30.5 x 89.7 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two and a half story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: AGRICULTURE		29. Basement? Yes	Date(s):
		30. Foundation Material: Stone bearing	Associated Activity:
17. Date(s) or Period: 1869		31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
17b. Alteration Date(s):		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18. Style Class and Design: Dominant      Queen Anne		33. No. of Bays: 3      Side Bays: 5	
18a. Style of Addition or Elements(s):		34. Exterior Wall Material(s): Brick	
19. Architect or Engineer: Unknown			
8. Site Plan (location map) with North Arrow		6. Specific Address or Location: <b>1915 Galloway Road</b>	
46. Prepared By: <b>Lillian Hutzell</b>		47. Organization: <b>Cardno</b>	
49. PIR Reviewer:		48. Date Recorded: <b>12/02/2020</b>	
		50. PIR Review Date:	



1. No. FRA0176228	4. Present Name(s): Peters House
2. County Franklin	5. Historic or Other Name(s):



Door Selection: Altered  
Door Position: Altered  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slagle		1975	Ohio Historic Inventory: Peters House

42. Further Description of Important Interior and Exterior Features

This two-and-a-half-story stretcher-bond brick house was constructed circa 1869. The dwelling was constructed in the Queen Anne Style and features a steep-pitched hipped roof with cross gables, covered in asphalt shingles. The dwelling's roof is pierced by two patterned brick chimneys. The building rests on a dressed stone foundation wall. The windows are 1-over-1 metal replacement sash, flanked y faux shutters, with stone lintels and sills. The façade contains two porches with shed-roof, supported by square posts.

43. History and Significance

The house was previously recorded in the Ohio Historic Inventory in 1975. Peter's, the original builder and owner, owned the elevator across the street.

44. Description of Environment and Outbuildings (See #52)

There are only modern outbuildings on this property.

45. Sources of Information

Frank Slagle, "Ernest Tyler House or Peter's Place," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176228.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0176528 REV		4. Present Name(s): Thompson/Wilcox Farmstead	
2. County: Franklin		5. Historic or Other Name(s): Thompson Place	
6. Specific Address or Location: 1040 Alton Road		19a. Design Sources: Unknown	35. Plan Shape: Irregular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-006431-00		21. Building Type or Plan: Upright and Wing	17b.
7. City or Village: Galloway		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1 4 over 4
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 36.1 x 41.2 feet
Zone: 17 Easting: 313833 Northing: 4422066		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Kenneth S. and Arlene A. Chappellear 1040 Alton Road Galloway, Ohio 43119	40. Chimney Placement: Gable end, exterior
11. On National Register? NO		26. Property Acreage: 1.37243	41. Distance from & Frontage on Road: 75.7 x 245.4 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s): Carriage House
16. Thematic Associations: AGRICULTURE		29. Basement? No	Date(s): 1880
17. Date(s) or Period: 1880		30. Foundation Material: Stone bearing	Associated Activity: Original/Most significant construction
17b. Alteration Date(s):		31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Transitional High Victorian Gothic		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
Transitional Italian Villa		33. No. of Bays: 5 Side Bays: 3	
18a. Style of Addition or Elements(s): Transitional		34. Exterior Wall Material(s): Brick Board and batten	
19. Architect or Engineer: Unknown			

2. County: Franklin

4. Present or Historic Name(s): Thompson/Wilcox Farmstead

6. Specific Address or Location: 1040 Alton Road

8. Site Plan (location map) with North Arrow






1. No. FRA0176528

4. Present Name(s): Thompson/Wilcox Farmstead

2. County Franklin

5. Historic or Other Name(s): Thompson Place



Door Selection: Single off center  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Slagle		1975	

42. Further Description of Important Interior and Exterior Features

The Thompson farmhouse is a two-story common bond brick Italianate dwelling. The house's cross-hipped roof is covered in asphalt shingles. The building rests on a dressed stone foundation wall. The house's facade has 1/1 wood sash and 4/4 wood sash with incised stone hoods and bracketed stone sills. Side elevations have plain stone lintels and sills. A few of the side elevation windows retain original wooden shutters. Entry into the house is sheltered by a two-bay shed-roofed porch, supported on wood posts. The dwelling's entry door features a wood bracketed entry surround with sidelights. The door is an original glazed wood panel door.

43. History and Significance

This 1.37-acre parcel contains the remnants of the Thompson/Wilcox Farmstead. The house is an excellent, highly intact Italianate farmhouse with a number of important outbuildings. The property retains an original carriage house, corn crib, and privy - all of which were important the workings of a late nineteenth century farmstead. Integrity of setting within the property is fairly intact; however, the parcel is surrounded by modern suburban developments and does not maintain its original farmland or wood lots.

44. Description of Environment and Outbuildings (See #52)

The property retains a number of interesting older domestic and agricultural outbuildings. A circa 1880 frame barn is located directly on Alton Road west of the house on the opposite side of the farm drive. This barn was likely intended as a carriage house, given its prominent location and decorative detailing. The barn is clad in board and batten, and features a prominent rooftop cupola. The façade features original arched barn doors with hinged straps, and arched louvered windows for controlled ventilation and light. The roof is clad in standing seam metal. The farm also contains a frame one-seat privy, clad in vertical board and sheet metal, and a frame corn crib. The corn crib is clad in vertical board and has an enclosed side drive for loading corn through a hinged hatch.

45. Sources of Information

Frank Slagle, "Wilcox Frank L. Farm or Thomspson Place," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176528.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0176628 REV		4. Present Name(s): O'Harra/Wilcox Farmstead	
2. County: Franklin		5. Historic or Other Name(s): Joseph O'Harra Home	
6. Specific Address or Location: 1200 Alton Road		19a. Design Sources: Unknown	35. Plan Shape: L-shaped
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-006463-00		21. Building Type or Plan: 1 House	17b.
7. City or Village: Port Columbus Int. Airport		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 51.8 x 61.1 feet
Zone: 17 Easting: 313500 Northing: 4421746		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Natalie J. Jennings 1200 Alton Road Galloway, Ohio 43119	40. Chimney Placement: Double gable end, flush
11. On National Register? NO		26. Property Acreage: 5	41. Distance from & Frontage on Road: 305.3x 227.3 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s): Wisconsin Dairy Barn Summer Kitchen Date(s):
16. Thematic Associations: AGRICULTURE		29. Basement? Yes	Associated Activity:
17. Date(s) or Period: 1860		30. Foundation Material: Stone bearing	Original/Most significant construction
17b. Alteration Date(s):		31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Transitional Greek Revival		32. Roof Type: Gable Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 5 Side Bays: 1	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Asbestos/asphalt siding	

2. County: Franklin


4. Present or Historic Name(s): O'Harra/Wilcox Farmstead

6. Specific Address or Location: 1200 Alton Road

8. Site Plan (location map) with North Arrow







Door Selection: Single centered  
Door Position: Recessed  
Orientation: Other  
Symmetry: Bilateral symmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slagle		1975	Ohio Historic Inventory: Wilcox Home (since 1926)

42. Further Description of Important Interior and Exterior Features

The O'Harra/Wilcox farmhouse is a circa 1860 central-passage Greek Revival style dwelling. The property was surveyed and included in the Ohio Historic Inventory in 1975. This form observes that the Wilcox family had owned the property since 1926. The farmhouse is a five-bay frame building with a Window-Window-Door-Window fenestration pattern. The frame dwelling is clad in asbestos shingle, and rests on a stone foundation wall. The side gable roof is covered in asphalt shingle. Two symmetrically-placed interior brick chimneys pierce the roofline on the north and south sides of the façade. The dwelling's roofline is characterized by a wood entablature with cornice returns. Greek Revival style pilasters frame the façade but are covered by the asbestos shingle treatment. A one-story front entry portico, supported on decorative square supports, shelters entry into the Greek Revival style entry. The original wood frame door, which is covered by a modern aluminum storm door, is flanked by incised pilasters and sidelights. The door is topped by a single-pane transom.

43. History and Significance

The Greek Revival style, five-bay central-passage house is the only example of this type surveyed in the project area and represents an excellent mid-nineteenth century example of this style and type in Prairie Township. The farmstead itself is a good example of an early-to-mid nineteenth century farm that transitioned from other crops to dairying in the early twentieth century. The entire 14-acre property is eligible agricultural significance, as expressed through the extant buildings. The property as a whole has an excellent integrity of location, setting, design, materials/workmanship, feeling and association.

44. Description of Environment and Outbuildings (See #52)

There are several outbuildings of interest on this 14-acre parcel. A log meat house is situated behind the main house. This outbuilding was likely constructed prior to the Greek Revival house. The building has a (modern) wood shake roof and was constructed with half-dovetail notches. The building rests on a stone foundation wall. The property also contains a circa 1900 dairy barn, complete with original basement milking parlor for approximately twenty cows. The building is clad in vertical board and rests on a concrete block ground floor. The side gable roof is covered in diamond-shaped slate tile. Directly north, across the farm drive, is a small circa 1920 concrete block milk house. The side gable building features an original glazed wood panel door. A circa 1920 one-story concrete block and frame granary abuts the dairy barn.

45. Sources of Information

Frank Slagle, "Wilcox Home (since 1926) or Joseph O'Harra," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176628.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0176828 REV		4. Present Name(s): <b>Bryum House</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 6342 O'Harra Road		19a. Design Sources: Unknown	35. Plan Shape: Rectangular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-001715-00		21. Building Type or Plan: Other House Type	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 2 over 2 4 over 4
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 32.2 x 51.4 feet
Zone: 17 Easting: 315024 Northing: 4420485		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Donna L. Martin 5680 Greendale Drive Galloway, Ohio, 43119	40. Chimney Placement: Off center within ridgeline
11. On National Register? NO		26. Property Acreage: 0.1396	41. Distance from & Frontage on Road: 10.9 x 51.5 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: One story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: POLITICAL/SOCIAL WELFARE		29. Basement? Yes	Date(s):
17. Date(s) or Period: 1900		30. Foundation Material: Stone bearing	Associated Activity:
17b. Alteration Date(s):		31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Element No academic style - Vernacular		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 3 Side Bays: 5	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Wood	


2. County: **Franklin**4. Present or Historic Name(s): **Bryum House**6. Specific Address or Location: **6342 O'Harra Road**

8. Site Plan (location map) with North Arrow





1. No. FRA0176828	4. Present Name(s): Bryum House
2. County Franklin	5. Historic or Other Name(s):



Door Selection: Single centered  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral symmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slagle		1975	Ohio Historic Inventory: Hensley Everett House (Jess Byrum Home)

42. Further Description of Important Interior and Exterior Features

This one-story Folk Victorian style house was constructed circa 1900. The dwelling contains a single rear central brick chimney, and its front gable roof is covered in asphalt shingles. It rests on a rough-cut limestone foundation and is clad in rusticated wood-block siding. Windows are wood 2-over-2 and 4-over-4 double hung sash, surrounded by gothic-arched lintels. The dwelling features a hipped roof that extends to cover a front porch area. The porch is supported on turned wood columns and features decorative Victorian millwork. Entry is sheltered under the porch through a glazed wood panel door with a single-pane transom. There are two small additions at the rear of the house.

43. History and Significance

The house was previously recorded in the Ohio Historic Inventory in 1975. House was used by postman, Jess Byrum, as a winter home. Byrum lived at 1856 Alton Road in the summer.

44. Description of Environment and Outbuildings (See #52)

There are only modern outbuildings on this property.

45. Sources of Information

Frank Slagle, "Hensley Evertt House or Jess Byrum Home," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176828.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0176928 REV	4. Present Name(s): Clay House	
2. County: Franklin	5. Historic or Other Name(s):	
6. Specific Address or Location: 6439 O'Harra Road	19a. Design Sources: Unknown	35. Plan Shape: Irregular
	20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-001718-00	21. Building Type or Plan: Upright and Wing	17b.
7. City or Village: Prairie (Township of)	22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway	23. Present Use: Single Dwelling	38. Building Dimensions: 35.1 x 43.5 feet
Zone: 17 Easting: 314802 Northing: 4420472	24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building	25. Owner's Name & Address, if known: Georgia Lynn Hensley 6496 O'Harra Road Galloway, Ohio, 43119	40. Chimney Placement: Two chimneys asymmetrical
11. On National Register? NO	26. Property Acreage: 0.24948	41. Distance from & Frontage on Road: 16.1 x 75.7 feet
13. Part of Established Hist. Dist? NO	27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)	28. No. of Stories: One and a half story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations:	29. Basement? Yes	Date(s):
	30. Foundation Material: Brick bearing	Associated Activity:
17. Date(s) or Period: 1880	31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Dominant Second Empire/Mansard	32. Roof Type: Mansard Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):	33. No. of Bays: 3 Side Bays: 4	
19. Architect or Engineer: Unknown	34. Exterior Wall Material(s): Wood	

2. County: Franklin

4. Present or Historic Name(s): Clay House

6. Specific Address or Location: 6439 O'Harra Road

8. Site Plan (location map) with North Arrow






1. No. FRA0176928

4. Present Name(s): Clay House

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Single off center  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
Frank Slagle		1975	Ohio Historic Inventory: Mrs. Hensley House (Clay House)

42. Further Description of Important Interior and Exterior Features

This one-and-a-half-story wood-frame house was constructed circa 1880 in the Second Empire style. The dwelling is clad in rusticated wood-block siding and rests on a brick foundation wall. The house has 1/1 wood sash windows with decorative wood surrounds, and the second half-story is lit by inset gable dormers. The mansard roof is covered in asphalt shingles. It features corner pilaster detailing. The front entrance has a glazed wood panel door with a single-pane transom window.

43. History and Significance

The house was previously recorded in the Ohio Historic Inventory in 1975, where it is noted as among very few Second Empire houses in Southwest Franklin County. It is, as well, among the smallest Second Empire dwellings in the region. The front porch appears to have been removed since the 1975 survey work.

44. Description of Environment and Outbuildings (See #52)

There are no outbuildings.

45. Sources of Information

Frank Slagle, "Mrs. Hensley House or Clay House," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 1975), FRA0176928.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0194238 NEW		4. Present Name(s): <b>Inglass Farmhouse</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 589 Amity Road		19a. Design Sources: Unknown	35. Plan Shape: Irregular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 241-000576-00		21. Building Type or Plan: HOUSE TYPES	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 148 x 110 feet
Zone: 17 Easting: 311577 Northing: 4425759		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Linda L. and Dacid L. Staten 589 Amity Road Galloway, Ohio, 43119	40. Chimney Placement: Three or more chimneys
11. On National Register? NO		26. Property Acreage: 25.22	41. Distance from & Frontage on Road: 45 x 1198.5 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two and a half story	52. Historic Outbuildings & Dependencies Structure Type(s): English or Three Bay Barn
16. Thematic Associations:		29. Basement? Unknown	Date(s):
		30. Foundation Material: Brick bearing	Associated Activity:
17. Date(s) or Period: 1890	17b. Alteration Date(s):	31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Transitional Queen Anne		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 3 Side Bays: 3	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Brick	

2. County: **Franklin**4. Present or Historic Name(s): **Inglass Farmhouse**6. Specific Address or Location: **589 Amity Road**

8. Site Plan (location map) with North Arrow







Door Selection: Single off center

Door Position: Flush

Orientation: Other

Symmetry: Bilateral asymmetry

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

*42. Further Description of Important Interior and Exterior Features*

The house is a good example of the transitional Queen Anne style in the project area. No other examples of this type were present as of this survey. The house is a solid brick masonry dwelling, laid in a common bond. The dwelling's multi-hipped roof is covered in diamond-patterned asphalt shingles. Front-gable dormer windows, with decorative wood shingles, light the second half-story. As well, multiple patterned brick chimneys protrude from the asymmetrical roofline. Windows are primarily replacement 1/1 vinyl sash with stone lintels and sills. The cornice line appears to be clad in metal. The porch is a defining characteristic on this dwelling. The one-story porch wraps the full façade and extends approximately half-way down the with elevation. The porch is supported on slender paired Colonial Revival style wooden supports, which rest on brick piers.

*43. History and Significance*

This two-story brick house as constructed circa 1890 as a Free Classic Queen Anne style house. According to the OHI form for this property, it was owned by the Ingalls family for at least four generations, as of 1975. It is unclear if the property remains in family ownership, as it was transferred by the Erwin family (the fourth generation) to the David and Linda Staten in 1983.

The Ingalls house is a good example of a Free Classic/Transitional Queen Anne style house, constructed circa 1890 in Prairie Township. It retains an excellent integrity of location, setting, design, feeling, and association. Its setting has changed over the years, as it does not retain many original outbuildings with integrity but it remains on a 25-acre parcel in rural Franklin County. The house has a moderate level of integrity of materials and workmanship due to the replacement of its original wood sash; however, there is sufficient integrity of materials and workmanship to convey this significance.

*44. Description of Environment and Outbuildings (See #52)*

This property contains an English stick barn with vertical metal cladding and sliding vehicular doors on the ground level. It also has a hayloft on the upper levels and ground floor 4-light casement windows.

*45. Sources of Information*

Franklin County Property Assessor, accessed online in January 2021 at:  
<http://apps.franklincountyauditor.com/ParcelSheet/241-000576-00>



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA0875528 <b>REV</b>		4. Present Name(s): <b>Clover Clemetery</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: Alton Darby Creek Road in Clover Park		19a. Design Sources: Unknown	35. Plan Shape: Unknown
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 241-001341-00		21. Building Type or Plan: Other Building Type	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Cemetery	37. Window Type(s): Unknown
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Cemetery	38. Building Dimensions: 164 x 139 feet
Zone: 17      Easting: 314766      Northing: 4425848		24. Ownership: Public	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Prairie Township Trustees 23 Maple Drive Columbus, Ohio, 43228	40. Chimney Placement: Unknown
11. On National Register? NO		26. Property Acreage: 0.506	41. Distance from & Frontage on Road: 394 x 0 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Unknown	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations:		29. Basement? No	Date(s):
		30. Foundation Material: Unknown	Associated Activity:
17. Date(s) or Period: 1824	17b. Alteration Date(s):	31. Wall Construction: Unknown Unknown	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: None      Other		32. Roof Type: Unknown Roof Material: Unknown	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 0      Side Bays: 0	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Unknown	

2. County: **Franklin**4. Present or Historic Name(s): **Clover Clemetery**6. Specific Address or Location: **Alton Darby Creek Road in Clover Park**

8. Site Plan (location map) with North Arrow





1. No. FRA0875528

4. Present Name(s): Clover Cemetery

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Unknown

Door Position: Unknown

Orientation: Unknown

Symmetry: Unknown

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
Keith Workman		2007	Ohio Historic Inventory: Clover Cemetery

*42. Further Description of Important Interior and Exterior Features*

The cemetery contains approximately 75-100 marked grave stones, and likely many more unmarked burials, mostly dating from the 1840s through the 1880s. Typical monument types include the headstone, die base and cap stones, and tab in socket stones. Footstones are prevalent as well. The grounds do not contain foot paths or scenic elements. Few trees are present on the site. The cemetery is bounded by a modern chain link fence. A small cast iron fence is located therein and may have been intended for a particular family's plot. Common family surnames include Clover, Anderson, Ballenger, Dougherty, Gatton, Keller, Martin, McCooy, Postle, and Wright. There are several Civil War-era veterans interred in this cemetery.

*43. History and Significance*

The Clover Cemetery is an approximately one-acre family burial ground associated with the Clover family, who were among the first settlers of Prairie township. The cemetery is located in what used to be known as Clover Settlement, but is now a park, maintained by the township. As far as can be determined, this is the only remaining property associated with Clover Settlement. The cemetery is named after the Clover family who arrived in 1813 from Ross County. They were originally from Virginia. They formed what was called the "Clover Settlement".

*44. Description of Environment and Outbuildings (See #52)*

This cemetery is in good shape and is maintained by the Prairie Township. It contains numerous headstones and a few footstones dating as far back as 1824. It contains the graves of many of the early settlers of Prairie Township. And many individuals that served in the War of 1812 and Civil War.

*45. Sources of Information*

Central Ohio Grave Search, "Clover Cemetery: Galloway, Franklin County, Ohio," Accessed online in January 2021 at: <http://www.centralohiogravesearch.com/uploads/cem-clover.htm>

Keith Workman, "Clover Cemetery," Ohio Historic Inventory Survey Form (Columbus, OH: Historic Preservation Office, Ohio Historical Society, 2007), FRA0175528.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1094528 NEW		4. Present Name(s): <b>Thorn Apple Country Club and Golf Course</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 1051 Alton Darby Creek		19a. Design Sources: Unknown	35. Plan Shape: Rectangular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 241-000046-00/241-000915-00		21. Building Type or Plan: Other Building Type	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Golf/Tennis	37. Window Type(s): Storefront
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Golf/Tennis	38. Building Dimensions: 148 x 110 feet
Zone: 17 Easting: 313869 Northing: 4426924		24. Ownership: Public	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Thorn Apple Country Club Inc. 1051 Alton Darby Creek Road Galloway, Ohio, 43119	40. Chimney Placement: Off center within roof surface
11. On National Register? NO		26. Property Acreage: 39.641	41. Distance from & Frontage on Road: 180.9 x 1341.5 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: One story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: Golf		29. Basement? No	Date(s):
17. Date(s) or Period: 1966-1967		30. Foundation Material: Poured concrete	Associated Activity:
17b. Alteration Date(s):		31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: None No academic style - Vernacular		32. Roof Type: Gable Roof Material: Metal	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 3 Side Bays: 5	
19. Architect or Engineer: Jack Kidwell		34. Exterior Wall Material(s): Brick Metal	

2. County: **Franklin**4. Present or Historic Name(s): **Thorn Apple Country Club and Golf Course**6. Specific Address or Location: **1051 Alton Darby Creek**

8. Site Plan (location map) with North Arrow







Door Selection: Single off center

Door Position: Flush

Orientation: Unknown

Symmetry: Bilateral asymmetry

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

*42. Further Description of Important Interior and Exterior Features*

The building has a low horizontal profile, a broad rooftop pylon chimney, and a series of glazed metal curtain wall windows with concrete sills that look out onto the course. The front gable roof is covered in metal and the rear of this building is clad in ribbed metal, rather than brick veneer. Inspection of historic aerials from 1967 to 2017 indicates that this course has been altered very little since its inception. The course is covered in turf grass and features strategically-placed deciduous and evergreen trees and small ponds. Paved paths lead through the course and have also been little altered. According to reviews of the course, the holes are considered long, which may have led to its preservation, as advances in club and ball technology have made this feature desirable.

*43. History and Significance*

This eighteen-hole golf course was designed by Jack Kidwell and constructed in 1966. Kidwell was a self-trained golf course architect who made a name for himself in the Ohio golfing community by assisting avid golfers with developing timeless courses on a reasonable budget. The American Society of Golf Course Architects notes that, "many of the golf courses he is credited with were for farmers who wanted to get into the golf business, who had little or no money, knew nothing about turfgrasses or the golf business, but relied on Jack to properly guide them." His biography goes on to state that, "Jack's golf courses are virtually unchanged since his first one in 1957 until his last one in the late 1990s, simply because they were so fundamentally sound, fun to play, easy to maintain, and profitable." According to this website, he assisted with design of over 100 courses across Ohio. Kidwell was most active in the 1970s, and this course may be where he was testing ideas that later became his trademark. Kidwell's most celebrated course is Hickory Hills Country Club in Grove City, Ohio which he designed and opened in 1979. Kidwell managed this course, for which he received an Award of Merit in 1984 from the Ohio Golf Course Association. The Thorn Apple Country Club is among his earlier works and remains intact.

*44. Description of Environment and Outbuildings (See #52)*

The property contains a club house with integral cart garage, designed in the contemporary style and a course which includes a 245-yard par three with back tees over 7,000 yards.

*45. Sources of Information*

Thorn Apple Country Club, Home page," Accessed online in January 2021 at: <http://www.thornapplegolf.com/>

American Society of Golf Course Architects, "Jack Kidwell," Accessed online in January 2021 at: <https://asgca.org/architect/jkidwell/>

Ohio Golf Association, "Jack Kidwell," Accessed in January 2021 online at:  
[https://www.ohiogolf.org/hall\\_of\\_fame/inductees/jack-kidwell](https://www.ohiogolf.org/hall_of_fame/inductees/jack-kidwell)





# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1094628 NEW		4. Present Name(s): Queen Anne House	
2. County: Franklin		5. Historic or Other Name(s):	
6. Specific Address or Location: 6552 West Broad Street		19a. Design Sources: Unknown	35. Plan Shape: Square
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-001639-00		21. Building Type or Plan: OTHER BUILDING TYPES	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 38.5 x 57 feet
Zone: 17 Easting: 314131 Northing: 4424529		24. Ownership: Public	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: HSH Enterprise LLC. 5781 Cumhurst Court Galloway, Ohio, 43119	40. Chimney Placement: Two chimneys asymmetrical
11. On National Register? NO		26. Property Acreage: 0.22386	41. Distance from & Frontage on Road: 87.5 x 58.9 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two and a half story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations:		29. Basement? No	Date(s):
		30. Foundation Material: Stone bearing	Associated Activity:
17. Date(s) or Period: 1894	17b. Alteration Date(s):	31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Element High Victorian Gothic		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s): None		33. No. of Bays: 4 Side Bays: 3	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Brick	

2. County: Franklin

4. Present or Historic Name(s): Queen Anne House

6. Specific Address or Location: 6552 West Broad Street

8. Site Plan (location map) with North Arrow





Door Selection: Single off center

Door Position: Flush

Orientation: Other

Symmetry: Bilateral asymmetry

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

*42. Further Description of Important Interior and Exterior Features*

The building is constructed of frame and has a cross-hipped roof, covered in asphalt shingles. It rests on stone piers, infilled later with a full molded concrete block foundation wall and is clad in vinyl siding. Windows are primarily 1/1 vinyl replacement sash. The small first floor storefront is located on a projecting hip portion of the building, situated strategically at the corner of Center Street and West Broad Street. The three-bay storefront is remarkably intact and includes two wood windows on either side of a set of glazed wood panel doors. The double doors are topped with a two-light transom window. Entry is sheltered under a full-length porch, supported on wood posts. Entry into a first floor living space is recessed from the street and sheltered under a one-bay shed-roofed entry porch, supported on wood posts.

*43. History and Significance*

This two-story commercial/residential building was constructed circa 1900 in the village of Alton. This building was likely intended as a commercial business with living space on the second floor. Alton grew rapidly upon the construction of the National Road through the area in 1836 but slowed considerably after the development of the railroad as a primary mode of transportation in the 1860s. An 1872 map of Prairie Township shows a growth around Alton Station, north of the Alton proper along the Little Miami Railroad, demonstrating the town-building capacity being on such a line could bring. It wasn't until the revival of overland travel in the early twentieth century that Alton began to grow again, albeit in a limited capacity – serving a portion of southwest Franklin County.

Original ownership of this building is unclear, but Franklin County property assessor records indicate it was owned by the Seaman family in 1920. Further research into the Seaman family indicates that they owned a dry good store on National Turnpike in 1920. The 1910 US census documents Susan Seaman as a merchant on Main Street in Alton as well. It seems likely that the Seaman family constructed this store and residence, but more research will need to be accomplished in order to prove this assertion. The Seaman family owned this building until 1960, according to the Franklin County Property Assessor.

*44. Description of Environment and Outbuildings (See #52)*

Surrounded by hard surfacing and RV park to sides and rear affect integrity of setting and feeling, fenestration replaced, applied shutters added.

*45. Sources of Information*

Franklin County Property Assessor, "6515 West Board Street," Accessed in January 2021 online at: <http://apps.franklincountyauditor.com/ParcelSheet/240-001636-00>

Ancestry.com. 1920 United States Federal Census [database on-line]. Provo, UT, USA: Ancestry.com Operations, Inc.,



2010. Images reproduced by FamilySearch.

Ancestry.com. 1910 United States Federal Census [database on-line]. Lehi, UT, USA: Ancestry.com Operations Inc, 2006.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1094728 NEW		4. Present Name(s): Seaman Dry Good Store	
2. County: Franklin		5. Historic or Other Name(s):	
6. Specific Address or Location: 6515 West Broad Street		19a. Design Sources: Unknown	35. Plan Shape: L-shaped
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-001636-00		21. Building Type or Plan: Department/General Store	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: COMMERCIAL	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: COMMERCIAL	38. Building Dimensions: 42.9 x 59.3 feet
Zone: 17 Easting: 314256 Northing: 4424456		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Barry Raymond 717 Center Street RM 937 Beverly, Ohio, 45715	40. Chimney Placement: Off center within ridgeline
11. On National Register? NO		26. Property Acreage: 0.1752	41. Distance from & Frontage on Road: 50.5 x 50.9 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: COMMERCE		29. Basement? Yes	Date(s):
17. Date(s) or Period: 1900		30. Foundation Material: Stone bearing	Associated Activity:
17b. Alteration Date(s):		31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Element Commercial/Chicago Style		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 3 Side Bays: 2	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Aluminum or vinyl siding	

2. County: Franklin

4. Present or Historic Name(s): Seaman Dry Good Store

6. Specific Address or Location: 6515 West Broad Street

8. Site Plan (location map) with North Arrow







Door Selection: Single centered

Door Position: Flush

Orientation: Other

Symmetry: Bilateral asymmetry

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

*42. Further Description of Important Interior and Exterior Features*

The building is constructed of frame and has a cross-hipped roof, covered in asphalt shingles. It rests on stone piers, infilled later with a full molded concrete block foundation wall and is clad in vinyl siding. Windows are primarily 1/1 vinyl replacement sash. The small first floor storefront is located on a projecting hip portion of the building, situated strategically at the corner of Center Street and West Broad Street. The three-bay storefront is remarkably intact and includes two wood windows on either side of a set of glazed wood panel doors. The double doors are topped with a two-light transom window. Entry is sheltered under a full-length porch, supported on wood posts. Entry into a first floor living space is recessed from the street and sheltered under a one-bay shed-roofed entry porch, supported on wood posts.

*43. History and Significance*

Original ownership of this building is unclear, but Franklin County property assessor records indicate it was owned by the Seaman family in 1920. Further research into the Seaman family indicates that they owned a dry good store on National Turnpike in 1920. The 1910 US census documents Susan Seaman as a merchant on Main Street in Alton as well. It seems likely that the Seaman family constructed this store and residence, but more research will need to be accomplished in order to prove this assertion. The Seaman family owned this building until 1960, according to the Franklin County Property Assessor.

This two-story commercial/residential building was constructed circa 1900 in the village of Alton. This building was likely intended as a commercial business with living space on the second floor. Alton grew rapidly upon the construction of the National Road through the area in 1836 but slowed considerably after the development of the railroad as a primary mode of transportation in the 1860s. An 1872 map of Prairie Township shows a growth around Alton Station, north of the Alton proper along the Little Miami Railroad, demonstrating the town-building capacity being on such a line could bring. It wasn't until the revival of overland travel in the early twentieth century that Alton began to grow again, albeit in a limited capacity – serving a portion of southwest Franklin County.

*44. Description of Environment and Outbuildings (See #52)*

There are no outbuildings.

*45. Sources of Information*

Franklin County Property Assessor, "6515 West Board Street," Accessed in January 2021 online at:  
<http://apps.franklincountyauditor.com/ParcelSheet/240-001636-00>

Ancestry.com. 1920 United States Federal Census [database on-line]. Provo, UT, USA: Ancestry.com Operations, Inc., 2010. Images reproduced by FamilySearch.

Ancestry.com. 1910 United States Federal Census [database on-line]. Lehi, UT, USA: Ancestry.com Operations Inc, 2006.







# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1094828 <b>NEW</b>		4. Present Name(s): <b>School House</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 1223 Alton Road		19a. Design Sources: Unknown	35. Plan Shape: Square
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-000263-00		21. Building Type or Plan: One-room Schoolhouse	17b. Some alteration
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: One-room Schoolhouse	37. Window Type(s): Casement
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 72.1 x 77 feet
Zone: 17      Easting: 313357      Northing: 4421676		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Raymond and Kathy M. Miller 1223 Alton Road Galloway, Ohio, 43119	40. Chimney Placement: Center
11. On National Register? NO		26. Property Acreage: 1.00489	41. Distance from & Frontage on Road: 56.7 x 134.6 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: One and a half story	52. Historic Outbuildings & Dependencies Structure Type(s): Garage
16. Thematic Associations: Public Education		29. Basement? No	Date(s):
		30. Foundation Material: Unknown	Associated Activity:
17. Date(s) or Period: 1890	17b. Alteration Date(s): 1940	31. Wall Construction: Brick bearing	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Dominant      Italianate		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 3      Side Bays: 4	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Brick	

2. County: **Franklin**4. Present or Historic Name(s): **School House**6. Specific Address or Location: **1223 Alton Road**

8. Site Plan (location map) with North Arrow




1. No. FRA1094828

4. Present Name(s): School House

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Single off center  
Door Position: Recessed  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

42. Further Description of Important Interior and Exterior Features

This house is a former one-room school house in the Italianate style. The building has been much altered. It is covered in a hipped roof with asphalt shingles and hipped side dormers. There is a shed-roof front projection over what may have been the original entrance. The front porch is covered in a hipped roof supported by square posts. The front entrance had a flush door with 3 cascading lights. There is painted brick within the corbeled cornice. The windows are 12-light steel casement windows and 1-over-1 vinyl windows. There is a large rear addition that is clad in board and batten with an attached 2-car garage.

43. History and Significance

44. Description of Environment and Outbuildings (See #52)

The property contains a concrete block 2-car garage with an exterior brick chimney, hipped roof, and steel-frame casement windows.

45. Sources of Information

Netronline, "Historic Aerials," 1953.





## OHIO HISTORIC INVENTORY

Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1094928 <b>NEW</b>		4. Present Name(s): <b>Kuntz Farmstead</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 6821 Alkire Road		19a. Design Sources: Unknown	35. Plan Shape: Square
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-000067-00		21. Building Type or Plan: American foursquare	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 37.6 x 61.8 feet
Zone: 17      Easting: 313995      Northing: 4419539		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Object		25. Owner's Name & Address, if known: Paul R. and Victor P. Phillippi 6665 Big Plan Circleville Road London, Ohio, 43140	40. Chimney Placement: Two chimneys asymmetrical
11. On National Register? NO		26. Property Acreage: 80.371	41. Distance from & Frontage on Road: 64.5 x 942.6 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two and a half story	52. Historic Outbuildings & Dependencies Structure Type(s): Transverse Frame Barn English or Three Bay Barn Date(s):
16. Thematic Associations: AGRICULTURE		29. Basement? Yes	Associated Activity:
		30. Foundation Material: Concrete block	
17. Date(s) or Period: 1921		31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: None      No academic style - Vernacular		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 2      Side Bays: 3	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Aluminum or vinyl siding	

2. County: **Franklin**4. Present or Historic Name(s): **Kuntz Farmstead**6. Specific Address or Location: **6821 Alkire Road**

8. Site Plan (location map) with North Arrow





Door Selection: Single off center

Door Position: Flush

Orientation: Other

Symmetry: Bilateral asymmetry

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

*42. Further Description of Important Interior and Exterior Features*

This property contains a two-and-a-half story American Foursquare house with Craftsman stylistic details. The dwelling is clad in vinyl siding, and rests on a molded concrete block foundation wall. The building's hipped roof is covered in asphalt shingles, and two hipped dormers are light the second half-story. Windows are 1/1 vinyl sash. The façade is characterized by a full-length front porch, supported on battered wood columns that rest on concrete piers. A low decorative concrete knee wall provides a sense of enclosure from the nearby rural road. Although there is no evidence as such, this house appears to be a catalog purchase from one of the popular prefabricated housing manufacturers of the time, such as Sears or Aladdin.

*43. History and Significance*

This eighty-acre farmstead was developed by Edward and Anna Dellinger Kuntz circa 1921. In 1912, Edward and Anna were married, and in 1920, they purchased the property on which this farm was built. They were enumerated in the 1920 US Census with their four-year old son, Frederick living in a rented property on Georgesville Road. By 1930, the US Census recorded the Kuntz family residing in their farmhouse on Alkire Road. In that year, their home value was \$20,000, and the farm was producing grain and livestock. The Kuntz family owned this farm for at least three generations. It was sold in 2013 to Paul and Victor Phillippi. The Kuntz farmstead is an important example of an early twentieth century farm, owned and operated by three generations of the same family until the 2010s. The property retains a circa 1921 farmhouse, English Barn, garage, and windmill- all with sufficient integrity---that combine to associate this property with early-to-mid twentieth century farmsteads. The farm has a good integrity of location, design, setting, feeling, and association.

*44. Description of Environment and Outbuildings (See #52)*

The property contains multiple agricultural outbuildings, dating from the Kuntz family's farming operation. Among the more interesting ones is a circa 1925 frame English barn, clad in vertical board and sheet metal. There are also several equipment storage barns and metal grain bins on the property as well. A metal windmill is present in the domestic yard.

*45. Sources of Information*

Franklin County Property Assessor, "Historical Parcel Sheet, 6821 Alkire Road," Accessed online in January 2021 at: <http://apps.franklincountyauditor.com/ParcelSheet/240-000067-00>; Ancestry.com. 1920 United States Federal Census [database on-line]. Provo, UT, USA: Ancestry.com Operations, Inc., 2010. Images reproduced by FamilySearch.

Ancestry.com. Ohio, U.S., County Marriage Records, 1774-1993 [database on-line]. Lehi, UT, USA: Ancestry.com Operations, Inc., 2016.

Ancestry.com. 1930 United States Federal Census [database on-line]. Provo, UT, USA: Ancestry.com Operations Inc, 2002.







# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1095028 NEW		4. Present Name(s): Split-Level Ranch House	
2. County: Franklin		5. Historic or Other Name(s):	
6. Specific Address or Location: 6800 Alkire Road		19a. Design Sources: Unknown	35. Plan Shape: Rectangular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-002553-00		21. Building Type or Plan: Split-Level	17b.
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): Horizontal Slider
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 57.2 x 36.1 feet
Zone: 17 Easting: 314007 Northing: 4419627		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Thomas and Charlee J. Sullivan 6800 Alkire Road Galloway, Ohio, 43119	40. Chimney Placement: Other
11. On National Register? NO		26. Property Acreage: 4.094	41. Distance from & Frontage on Road: 118.4 x 503.2 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations:		29. Basement? Yes	Date(s):
		30. Foundation Material: Poured concrete	Associated Activity:
17. Date(s) or Period: 1965	17b. Alteration Date(s):	31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: None No academic style - Vernacular		32. Roof Type: Gable Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s): Element		33. No. of Bays: 5 Side Bays: 2	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Brick Clapboard or weatherboard	

2. County: Franklin

4. Present or Historic Name(s): Split-Level Ranch House

6. Specific Address or Location: 6800 Alkire Road

8. Site Plan (location map) with North Arrow





1. No. FRA1095028	4. Present Name(s): Split-Level Ranch House
2. County Franklin	5. Historic or Other Name(s):



Door Selection: Single centered  
Door Position: Recessed  
Orientation: Unknown  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

42. Further Description of Important Interior and Exterior Features

This split-level ranch style house is covered in a side gable roof with asphalt shingles. It is clad in a brick veneer on the first level and clapboard siding on the second level. There is a prominent exterior brick chimney to the left of the front entrance on the facade. There is an upper story porch with iron railings. The front entrance has a full-height, multi-light entrance with heavy wood transoms and mullions. The windows are metal slider windows.

43. History and Significance

44. Description of Environment and Outbuildings (See #52)

There are no outbuildings.

45. Sources of Information

Netronline, "Historic Aerials," 1953-1971.



## OHIO HISTORIC INVENTORY

Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1095128 <b>NEW</b>		4. Present Name(s): <b>Darby Dan Farm</b>	
2. County: <b>Franklin</b>		5. Historic or Other Name(s):	
6. Specific Address or Location: 925 Darby Creek Drive		19a. Design Sources: Unknown	35. Plan Shape: L-shaped
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 240-000250-00/240-000124-00/240-003107-00		21. Building Type or Plan: 1 House	17b. Substantial alteration/addition
7. City or Village: Prairie (Township of)		22. Original Use, if apparent: Multiple Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Multiple Dwelling	38. Building Dimensions: 43.8 x 56.9 feet
Zone: 17      Easting: 310757      Northing: 4422299		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Lizanne G. Megrue 925 Darby Creek Drive Galloway, Ohio, 43119	40. Chimney Placement: Gable end, flush
11. On National Register? NO		26. Property Acreage: 69.5	41. Distance from & Frontage on Road: 201.8 x 1282.6 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two and a half story	52. Historic Outbuildings & Dependencies Structure Type(s): Transverse Frame Barn Other Outbuilding/Structure/Feature
16. Thematic Associations: AGRICULTURE		29. Basement? No	Date(s): 1945 1935
17. Date(s) or Period: 1880		30. Foundation Material: Stone bearing	Associated Activity:
17b. Alteration Date(s): 1935		31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: None      No academic style - Vernacular		32. Roof Type: Gable Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s): Transitional		33. No. of Bays: 3      Side Bays: 1	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Aluminum or vinyl siding	

2. County: **Franklin**4. Present or Historic Name(s): **Darby Dan Farm**6. Specific Address or Location: **925 Darby Creek Drive**

8. Site Plan (location map) with North Arrow





Door Selection: Single centered

Door Position: Flush

Orientation: Other

Symmetry: Bilateral symmetry

**Report Associated With Project:**

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

*42. Further Description of Important Interior and Exterior Features*

An earlier, circa 1880, frame tenant house (preexisting) is part of this building cluster. This house, like its counterpart at the entry gate, was likely intended for a farm manager or trainer's family, rather than for a farmhand.

*43. History and Significance*

This property contains a large remnant of the celebrated Darby Dan Horse Farm, which is approximately 1,700 acres. The farm's counterpart is in the center of horse country in Lexington, Kentucky on Old Frankfort Pike. In conjunction with the Lexington farm, Darby Dan has produced two Kentucky Derby winners, Chateaugay in 1963 and Proud Truth in 1967. As well, the farm's horses won the Preakness Stakes once and the Belmont twice. According the owner, Squire Galbraith, the family donated 2,500 acres for the adjacent Battelle-Darby Creek Park. While the farm once produced thoroughbred horses, it now produces sod and has an event venue at the Darby House, which was constructed for John W. Galbreath in 1954.

*44. Description of Environment and Outbuildings (See #52)*

The Darby Dan farm was established in 1935 and contains a number of horse barns, a breeding shed, a gas house, numerous tenant houses, and the Darby House. The main gate house features a stone entry fence and stone gate house, constructed circa 1935. A circa 1900 frame three-bay tenant house (preexisting) and circa 1945 18-stall frame horse barn are located directly west of the main entry. The gambrel-roofed barn is clad in horizontal siding and has original sliding wood doors. The oldest horse barns appear to date from the mid-1930s and are located near Darby Creek Road, south of the main entry. These barns include a frame breeding shed, a 16-stall board and batten horse barn, and several large equipment storage sheds. A frame circa 1935 gas house is also located nearby. The stone and frame Darby House is located at the end of the farm road near Darby Creek. It is likely not eligible for the NRHP due to a number of modern interventions, but should be thoroughly surveyed on the interior to determine its status.

*45. Sources of Information*

Darby Dan Farm, "Our History," Accessed online in January 2021 at <https://darbydanohio.com/our-history/>

Darby House, "Our History," Accessed online in January 2021 at: <https://www.darbyhouse.com/our-history>





# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1095227 NEW		4. Present Name(s): Myer House	
2. County: Franklin		5. Historic or Other Name(s):	
6. Specific Address or Location: 2341 Darby Creek Drive		19a. Design Sources: Unknown	35. Plan Shape: Rectangular
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 230-001916-00		21. Building Type or Plan: Other House Type	17b.
7. City or Village: Pleasant (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): Casement
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 60.2 x 60 feet
Zone: 17 Easting: 311342 Northing: 4418965		24. Ownership: Public	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Darby Creek Horse Farm LLC. 2375 Darby Creek Drive Galloway, Ohio, 43119	40. Chimney Placement: Lateral Exterior
11. On National Register? NO		26. Property Acreage: 10.64729	41. Distance from & Frontage on Road: 167.5 x 586.2 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Excellent
15. Other Designation (NR or Local)		28. No. of Stories: One and a half story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations:		29. Basement? Unknown	Date(s):
		30. Foundation Material: Concrete block	Associated Activity:
17. Date(s) or Period: 1941	17b. Alteration Date(s):	31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Dominant Tudor/English Revival		32. Roof Type: Gable Roof Material: Clay tile	Archaeological (OAI):
None		33. No. of Bays: 3 Side Bays: 3	
18a. Style of Addition or Elements(s):		34. Exterior Wall Material(s): Stone	
19. Architect or Engineer: Unknown			

2. County: Franklin


4. Present or Historic Name(s): Myer House

6. Specific Address or Location: 2341 Darby Creek Drive

8. Site Plan (location map) with North Arrow



1. No. FRA1095227	4. Present Name(s): Myer House
2. County Franklin	5. Historic or Other Name(s):



Door Selection: Single centered  
Door Position: Recessed  
Orientation: Unknown  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

42. Further Description of Important Interior and Exterior Features

This one-and-a-half-story Tudor Revival house was constructed circa 1941 by the Myers family. According to the local informants, Donald Myers owned an autobody shop in Columbus and built this house in the early 1940s. The dwelling is clad in stone veneer and has a steeply pitched side-gable roof covered in terra cotta clay tiles. The façade features a prominent exterior stone chimney on the front patio with an exterior fireplace. Directly south of the fireplace is a projecting gable bay with a sloping gable wall. This wall features a small rounded decorative window opening. The north and south elevations have low stone walls with ball finials. The windows are multi-light steel casement in a wide variety of configurations. The front entrance has a wood front door with metal strap hinges and a small window. There are no older outbuildings on this property. The half-story is lit by a shed-roof dormer with 10-pane steel casement windows. There is a small one-story rear addition, covered in a flat roof and clad in vinyl siding with sash window.

43. History and Significance

The Myers house is an important example of the Tudor Revival style in Franklin County, Ohio. The house retains its integrity of location, setting, design, materials, workmanship, feeling and association. Although it is missing all of its original agricultural outbuildings, the house remains tucked behind a dense vegetative border lining Darby Creek Drive. Inspection of historic aerials indicates that this vegetative screening has been in place at least since the early 1950s.

44. Description of Environment and Outbuildings (See #52)

There are no outbuildings.

45. Sources of Information

Netronline, “Historic Aerials,” 1953-1971.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1095327 NEW		4. Present Name(s): Emmelhainz Farmstead	
2. County: Franklin		5. Historic or Other Name(s):	
6. Specific Address or Location: 2341 Darby Creek		19a. Design Sources: Unknown	35. Plan Shape: Square
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 230-001171-00		21. Building Type or Plan: American foursquare	17b.
7. City or Village: Pleasant (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 33.2 x 61.9 feet
Zone: 17 Easting: 311383 Northing: 4419147		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Jeffrey E. and Patricia A. Emmelhainz 1932 Darby Creek Drive Galloway, Ohio, 43119	40. Chimney Placement: Lateral Exterior
11. On National Register? NO		26. Property Acreage: 108.92	41. Distance from & Frontage on Road: 186.8 x 960.2
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s): Other Outbuilding/Structure/Feature Poultry House/Chicken Coop Date(s):
16. Thematic Associations: AGRICULTURE		29. Basement?	Associated Activity:
17. Date(s) or Period: 1900		30. Foundation Material: Stone bearing	53. Affiliated Inventory Number(s): Historic (OHI):
17b. Alteration Date(s):		31. Wall Construction: Mortise and tenon/braced frame	Archaeological (OAI):
18. Style Class and Design: None No academic style - Vernacular		32. Roof Type: Hip Roof Material: Asphalt shingle	
18a. Style of Addition or Elements(s): Transitional		33. No. of Bays: 3 Side Bays: 3	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Aluminum or vinyl siding	

2. County: Franklin

4. Present or Historic Name(s): Emmelhainz Farmstead

6. Specific Address or Location: 2341 Darby Creek

8. Site Plan (location map) with North Arrow






1. No. FRA1095327

4. Present Name(s): Emmelhainz Farmstead

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Single off center  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

42. Further Description of Important Interior and Exterior Features

The farmhouse was constructed circa 1880 and is a three-bay frame dwelling with a hipped roof. The house is clad in vinyl siding and has 1/1 vinyl sash. The building rests on a stone foundation wall and the roof is covered in asphalt shingles.

43. History and Significance

This farmstead was developed by the Emmelhainz family circa 1880. The fourth generation of Emmelhainz, Jeffrey and Patricia, reside on this property and produce eggs and vegetables for the local market. According to the owners, the 110-acre farmstead was purchased in 1888 from the Bighart family by Joseph and Charlotta Emmelhainz. Among the first buildings constructed on the property that remains extant is the English Barn in 1880. This barn was constructed by the second generation, Edward and Ruth Emmelhainz. According to the owners, the barn was built from red ash on the property and sawn at a local mill. The first farming operations on the property were for dairying, but this quickly shifted in the early twentieth century to production of beef cattle and hay. With reductions in beef cattle prices in the mid-twentieth century, the family began producing hay, row crops, and grains. The farm shifted operations in the last twenty years to produce vegetables and eggs.

44. Description of Environment and Outbuildings (See #52)

There are two important domestic outbuildings remaining behind the house. A frame meat house, used as a coal shed in the mid-twentieth century, is situated directly at the rear of the dwelling for access. The building is clad in vertical board and features a characteristic overhanging front gable roof, supported on brackets. The farmstead contains a fine complement of domestic and agricultural outbuildings that demonstrate farming operations from the late nineteenth through the late twentieth centuries. A circa 1930 frame chicken house, clad in vertical board, is also located in the domestic yard. The English barn is situated south of the main house, abutting a farm road. This frame barn is constructed of large timbers which are joined together by pegging. The building is clad in metal siding and has a corrugated metal roof. The cupola was removed circa 1950 by the owner's grandfather. Other farm buildings of interest include a livestock scale, circa 1945; a gas house, circa 1930; and a machine storage barn circa 1930.

45. Sources of Information

History is according to the current owners.



# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1095427 NEW	4. Present Name(s): Pleasant View Middle School	
2. County: Franklin	5. Historic or Other Name(s):	
6. Specific Address or Location: 7255 Kropp Road	19a. Design Sources: Unknown	35. Plan Shape: Other
	20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 230-001534-00	21. Building Type or Plan: Other Building Type	17b.
7. City or Village: Pleasant (Township of)	22. Original Use, if apparent: School	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway	23. Present Use: School	38. Building Dimensions: 536.6 x 550.7 feet
Zone: 17 Easting: 313125 Northing: 4416134	24. Ownership: Public	39. Endangered? YES By What? Demolition
10. Classification: Building	25. Owner's Name & Address, if known: Southwestern Local Board 3805 Marlane Drive Grove City, Ohio, 43123	40. Chimney Placement: Unknown
11. On National Register? NO	26. Property Acreage: 39.94	41. Distance from & Frontage on Road: 115.6 x 1182.3 feet
13. Part of Established Hist. Dist? NO	27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)	28. No. of Stories: Two story	52. Historic Outbuildings & Dependencies Structure Type(s):
16. Thematic Associations: Public Education	29. Basement? Yes	Date(s):
	30. Foundation Material: Poured concrete	Associated Activity:
17. Date(s) or Period: 1958	31. Wall Construction: Curtain Wall	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: None Modern Movements	32. Roof Type: Flat Roof Material: Unknown	Archaeological (OAI):
18a. Style of Addition or Elements(s):	33. No. of Bays: 0 Side Bays: 0	
19. Architect or Engineer: Unknown	34. Exterior Wall Material(s): Brick Tile block	

2. County: Franklin

4. Present or Historic Name(s): Pleasant View Middle School

6. Specific Address or Location: 7255 Kropp Road

8. Site Plan (location map) with North Arrow




1. No. FRA1095427

4. Present Name(s): Pleasant View Middle School

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Three or more  
Door Position: Recessed  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

42. Further Description of Important Interior and Exterior Features

The Pleasant View Middle School is a modernist school complex, composed of multiple, interconnected 1- and 2- story wings. The roof is mostly flat with parapet and one depressed gable. The building is clad in a brick veneer with decorative tilework as accents to the curtain walls. The curtain-wall framing system appears to be vinyl with vinyl 1-over-1 sash units. There is one 2-story windowless wing with brick buttresses.

43. History and Significance

According to the entrance plaque the school was dedicated the "Pleasant View High School" is 1959.

44. Description of Environment and Outbuildings (See #52)

The Pleasant View Middle School is a modernist school complex, composed of multiple, interconnected 1- and 2- story wings.

45. Sources of Information

Entrance plaque on the Pleasant View Middle School.





# OHIO HISTORIC INVENTORY

## Draft Form - Not Reviewed by OHPO

Section 106/RPR Review:

RPR Number:

1. No. FRA1095527 NEW		4. Present Name(s): Reibel Farmstead	
2. County: Franklin		5. Historic or Other Name(s):	
6. Specific Address or Location: 3326 Kropp Road		19a. Design Sources: Unknown	35. Plan Shape: Square
		20. Contractor or Builder: Unknown	36. Changes associated with 17/17b Dates: 17. Original/Most significant construction
6a. Lot, Section or VMD Number: 230-001182-00		21. Building Type or Plan: American foursquare	17b.
7. City or Village: Pleasant (Township of)		22. Original Use, if apparent: Single Dwelling	37. Window Type(s): 1 over 1
9. U.T.M. Reference Quadrangle Name: Galloway		23. Present Use: Single Dwelling	38. Building Dimensions: 46.5 x 43.7 feet
Zone: 17 Easting: 312306 Northing: 4417228		24. Ownership: Private	39. Endangered? NO By What?
10. Classification: Building		25. Owner's Name & Address, if known: Thomas A. and Sandra K. Kreb 3101 Kropp Road Grove City, Ohio, 43123	40. Chimney Placement: No chimney observed
11. On National Register? NO		26. Property Acreage: 79.117	41. Distance from & Frontage on Road: 61 x 897.1 feet
13. Part of Established Hist. Dist? NO		27. Other Surveys:	51. Condition of Property: Good/Fair
15. Other Designation (NR or Local)		28. No. of Stories: Two and a half story	52. Historic Outbuildings & Dependencies Structure Type(s): English or Three Bay Barn Garage
16. Thematic Associations:		29. Basement? Unknown	Date(s): 1900 1910
		30. Foundation Material: Stone bearing	Associated Activity:
17. Date(s) or Period: 1910	17b. Alteration Date(s):	31. Wall Construction: Mortise and tenon/braced frame	53. Affiliated Inventory Number(s): Historic (OHI):
18. Style Class and Design: Element Colonial Revival		32. Roof Type: Hip Roof Material: Asphalt shingle	Archaeological (OAI):
18a. Style of Addition or Elements(s):		33. No. of Bays: 2 Side Bays: 2	
19. Architect or Engineer: Unknown		34. Exterior Wall Material(s): Aluminum or vinyl siding	

2. County: Franklin

4. Present or Historic Name(s): Reibel Farmstead

6. Specific Address or Location: 3326 Kropp Road




8. Site Plan (location map) with North Arrow

1. No. FRA1095527

4. Present Name(s): Reibel Farmstead

2. County Franklin

5. Historic or Other Name(s):



Door Selection: Single off center  
Door Position: Flush  
Orientation: Other  
Symmetry: Bilateral asymmetry

Report Associated With Project:

Primary Author	Secondary Author(s)	Year	Title
No Records	..	..	..

42. Further Description of Important Interior and Exterior Features

The farmhouse was constructed circa 1910 and features Colonial Revival style elements, such as Palladian windows in the dormers. The building is clad in vinyl siding and rests on a molded concrete block foundation wall. Windows are 1/1 vinyl sash, set into original openings. He façade is characterized by a full-length porch, supported on incised wood supports. The hipped roof is covered in metal panel roofing.

43. History and Significance

This farmstead was originally developed by the Reibel family in the early twentieth century, according to the current owners.

44. Description of Environment and Outbuildings (See #52)

The farm contains a circa 1910 American Foursquare house with Colonial Revival style details, a circa 1900 English Barn, a circa 1935 stock barn, and several garage/workshop buildings, circa 1910. There are two molded concrete block garage/workshop buildings in the domestic yard. The garage northeast of the house features original wood folding doors. An original metal windmill is located behind the house as well. A circa 1900 frame English Barn is located in the farmyard, east of the main house. This barn is clad in vertical board and retains its original louvered windows. The timber frame and pegged barn has a circa 1945 run-in feeding shed appended to its north elevation. A circa 1935 two-aisle stock barn with hay hood is located south of the English barn. It is clad in vertical board. A circa 1935 machine shop, clad in vertical board, is situated near the stock barn.

45. Sources of Information

Netronline, “Historic Aerials,” 1971.

# Phase I History Architecture Reconnaissance Survey



Pleasant Prairie Solar Energy Center Project  
Prairie and Pleasant Townships  
Franklin County, Ohio

## APPENDIX

# D

## FIELD SURVEY MAPS





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area
- Index



7.5' Quadrangle:  
GALLOWAY

Project No.  
e320301701

This map and all data contained within are supplied as is with no warranty. Cardno, Inc. expressly disclaims responsibility for damages or liability from any claims that may arise out of the use or misuse of this map. It is the sole responsibility of the user to determine if the data on this map meets the user's needs. This map was not created as survey data, nor should it be used as such. It is the user's responsibility to obtain proper survey data, prepared by a licensed surveyor, where required by law.


## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
www.cardno.com





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project


### Prairie and Pleasant Townships

### Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area




## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Pleasant and Pleasant Townships Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area




## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Pleasant and Pleasant Townships Franklin County, Ohio



3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)




- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area

N  
W E  
S

**7.5' Quadrangle:  
GALLOWAY**

**Project No.  
e320301701**




## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area





## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area




## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report


### Pleasant Prairie Solar Energy Center Project

### Prairie and Pleasant Townships


### Franklin County, Ohio



3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)



- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project



### Prairie and Pleasant Townships

### Franklin County, Ohio


**Cardno**

3901 Industrial Blvd., Indianapolis, IN 46254  
 Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area



# Field Sites Survey Overview


## Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project


### Prairie and Pleasant Townships

### Franklin County, Ohio

**Cardno**  
 3901 Industrial Blvd., Indianapolis, IN 46254  
 Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)



- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area





## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio



3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)






- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area

7.5' Quadrangle:  
GALLOWAY

Project No.  
e320301701



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project

### Prairie and Pleasant Townships


### Franklin County, Ohio



3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
www.cardno.com



- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area





# Field Sites Survey Overview Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio


**Cardno**

3901 Industrial Blvd., Indianapolis, IN 46254  
 Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report


### Pleasant Prairie Solar Energy Center Project

### Prairie and Pleasant Townships


### Franklin County, Ohio



3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
www.cardno.com



- Field Survey Sites
- APE
- 2-Mile Study Area
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project



### Prairie and Pleasant Townships

### Franklin County, Ohio


**Cardno**

3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
www.cardno.com





- Field Survey Sites
- APE
- 2-Mile Study Area
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project



### Prairie and Pleasant Townships

### Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area




## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report Pleasant Prairie Solar Energy Center Project Prairie and Pleasant Townships Franklin County, Ohio




3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)





- Field Survey Sites
- 2-Mile Study Area
- APE
- Direct Project Area



## Field Sites Survey Overview

### Historic Architecture Reconnaissance Survey Report

### Pleasant Prairie Solar Energy Center Project


### Prairie and Pleasant Townships

### Franklin County, Ohio





3901 Industrial Blvd., Indianapolis, IN 46254  
Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
www.cardno.com





- Field Survey Sites
- 2-Mile Study Area
- Direct Project Area
- APE

  
 7.5' Quadrangle:  
 GALLOWAY  
 Project No.  
 e320301701



**Field Sites Survey Overview**  
 Historic Architecture Reconnaissance Survey Report  
 Pleasant Prairie Solar Energy Center Project  
 Prairie and Pleasant Townships  
 Franklin County, Ohio

  
 3901 Industrial Blvd., Indianapolis, IN 46254  
 Phone (+1) 317-388-1982 Fax (+1) 317-388-1986  
[www.cardno.com](http://www.cardno.com)



**This foregoing document was electronically filed with the Public Utilities**

**Commission of Ohio Docketing Information System on**

**2/19/2021 12:36:46 PM**

**in**

**Case No(s). 20-1679-EL-BGN**

Summary: Application - 11 of 25 (Exhibit H – Part 2 of 2 - Historic Cultural Resources Records Reports) electronically filed by Christine M.T. Pirik on behalf of Pleasant Prairie Solar Energy LLC