

NA-1142- GA-BIN

RECEIVED-DOCKETING DIV

t No

oertif

rnis is accurate document

June 23, 2009

Ms. Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426 Re: Rockies Express Pipeline LLC Docket No. CP07-208 Weekly Report #52, Period Ending June 17, 2009

Dear Ms. Bose:

Pursuant to Environmental Mitigation Measure 7 in the Appendix to the Federal Energy Regulatory Commission's May 30, 2008 Order in Docket No. CP07-208, Rockies Express Pipeline LLC hereby submits its weekly construction progress report for activities for the week ending June 17, 2009.

If you have any questions regarding this report, please contact Crystal Heter at (303) 914-7795.

Respectfully submitted,

/s/ Shippen Howe

Shippen Howe Van Ness Feldman 1050 Thomas Jefferson Street, NW Washington, DC 20007

Attorneys for Rockies Express Pipeline LLC

cc: Laura Turner April Magrane, Tetra Tech



Rockies Express Pipeline LLC

REX EAST Project

FERC Weekly Report

Weekly Report #:

Start: 6/11/2009 End: 6/17/2009

Environmental Training (this week / to date):

422 man hours /17174 man hours

484 people /12372 people

Spread/Facility A1

Name Anderson, Bob

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread A1 corridor: Typical station construction at the Mexico CS, rough clean up, the last HDD was authorized to return to work by the COE, flood/levee protection efforts, and installation and maintenance of ECD's and signage.

Environmental training is ongoing as necessary for returning employees. The waterbody crossing schedule has been updated in that table. Two dedicated environmental crews are working. See variance request table attached to this report for additional information on variances. Cultural monitor was onsite this period where applicable.

There were no NCR's recorded this period.

Next Week

Environmental Inspection team will continue inspection of contractor activities. Daily morning briefings will continue to be conducted between Contractor, Rockies inspection management, and Compliance Monitor, when available.

Spread/Facility A2

Name Anderson, Bob

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread A2 corridor: Contractor has demobilized from spread. Topsoil replacement, tile repair, and final restoration will begin with dry weather and allowable access. Two contractor response crews returned and are available for any ECD maintenance needs. REX EI staff continue to inspect ROW.

There were no NCR's recorded this period.

Next Week

Environmental Inspection staff will continue inspection of ROW. Restoration work is scheduled to resume on 06/15/09, weather permitting.

Spread/Facility B

Name Anderson, Bob

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread B corridor: Compressor and Meter Station construction is ongoing and nearing completion. Tile repairs continue. Contractor foreman has returned to set up re-mobilization to the spread for restoration.

The contractor continues repairs with an environmental crew. Final ROW restoration is proposed to recommence as 500n as weather and soil conditions are permitting. Cultural monitoring was not required onsite this period.

There were no NCR's recorded this period.

Next Week

Environmental Inspection will continue as needed per plan. Mobilization will occur when deemed dry enough.

Spread/Facility C

Name Anderson, Bob

Summary

Mainline has been mechanically completed. ROW is being inspected for re-growth and for SWPPP measures/requirements. Hand work on ECD's is occurring where access is available. Rough clean up is occurring. Environmental training is ongoing as needed for returning employees.

Construction of the two meter stations is listed by the LEI as complete.

Cultural monitoring was not required onsite this period.

There were no NCR's recorded this period.

Next Week

The required inspections will occur per SWPPP and the Rockies Compliance and Winterization plan. Activities are to increase as conditions improve with expansion of crew and equipment as needed.

Spread/Facility

Name Edlin, Mike

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread D corridor: rough clean-up and restoration (now delayed with heavy rains), drain tile repairs, hydrotesting, installation, inspection, and maintenance of ECD's is occurring. Environmental inspectors have been placing appropriate signage.

Saturated conditions have severely limited work.

D

Contractor has two environmental crews working. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been completed for the last time as all crossings are complete. Environmental training is ongoing as needed. Cultural monitoring is no longer required on Spread D, as all areas for monitoring are completed. Biological monitor was not required.

An NCR was recorded on 06/12/09 at MP 266.5; please see compliance details for more information.

Next Week

Environmental Inspection team will continue inspection of contractor activities. Daily morning briefings will continue to be conducted between Contractor, Rockies inspection management, and Compliance Monitor, when available.

Spread/Facility E

Name Edlin, Mike

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread E corridor: Rough clean-up and final restoration (limited by weather), mainline hydrotesting, installation, inspection, and maintenance of ECD's is occurring. Environmental inspectors have been placing appropriate signage.

Contractor has four environmental crews working. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been completed for the final time as all crossings are now complete. Environmental training is ongoing as needed. Cultural monitor was not required this period. Eagle monitor was not required this period.

NCR's were recorded this period on 06/12/09 at MP 335.9, and on 06/13/09 at MP 358.8; please see compliance tables for more information.

Next Week

Environmental Inspection team will continue inspection of contractor activities. Rough clean up and final restoration will continue as weather permits. Daily morning briefings will continue to be conducted between Contractor, Rockies inspection management, and Compliance Monitor, when available.

Spread/Facility F1

Name McMahon, Shannon

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread F1 corridor: Activities included El's maintaining appropriate signage, installation, maintenance, and inspection of appropriate ECD's, hydrotesting, anomaly cut-outs were completed, and rough & final clean up. Cultural monitoring on the spread was required this period where necessary (Hoosier Hills).

Contractor has one environmental crew working. See variance request table attached to this report for additional information on variances. Environmental training is ongoing as needed. Clean up was hampered due to weather conditions again this period.

There were no NCR's recorded this period.

Next Week

Environmental Inspection team will continue inspection of contractor activities. Daily morning briefings will continue to be conducted between Contractor, Rockies inspection management, and Compliance Monitor, when available.

Spread/Facility F2

Name McMahon, Shannon

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread F2 corridor: Installation, maintenance, and inspection of appropriate ECD's, tie-ins completed this period, and restoration, seeding, and clean up.

Contractor has two environmental crews working. See variance request table attached to this report for additional information on variances. Environmental training is ongoing as needed.

There were no NCR's were recorded this period.

Next Week

Environmental team will continue inspection of contractor activities. Daily morning briefings will continue to be conducted between Contractor, Rockies inspection management, and Compliance Monitor, when available.

Spread/Facility G

Name Harker, Margie

Summary

Clean-up of the Little Miami HDD site is continuing. E.I.s with survey continue to verify and stake setbacks from waterbodies, place signs, and pre-construction photos. Contractor also been tree clearing, brush-hogging, fence removing, measurement of topsoil, topsoiling, grading, stringing, trenching, road bores, welding, and inspection of equipment. Contractor has an environmental crew working.

Contractor has two environmental crews working on ECD's. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been updated and attached. Environmental training is ongoing as needed. Pre-construction well testing has been completed.

There were no NCR's recorded this period.

Next Week

Environmental training and inspections of contractor activities will continue and expand. Daily meetings with contractor will continue.

Spread/Facility H

Name Schwarz, Wes

Summary

Big Darby HDD cleanup continues. E.I.s and survey are verifying setbacks from waterbodies and wetlands, as well as preconstruction photography. Fencing crew and road approach crews continued as did clearing, grading, stringing, road bores, welding and coating, lower-in, backfill, and tie-ins. EI team continued inspection of the installation and maintenance of ECD's and equipment prior to entering the ROW. Cultural monitor was required this period near Old Hwy 207. A FRAC-out response continued this period at Walnut Creek and is being reviewed by Ohio EPA. Frac-out contingency plan was successfully implemented.

Contractor has four environmental crews working. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been updated and attached. Environmental training is ongoing as needed.

There were no NCR's recorded this period.

Next Week

Above activities continue and expand. El team will continue inspection of the activities. Environmental training is ongoing.

Spread/Facility I

Name Janik, Kevin

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread "I" corridor: Standard station construction activities at Chandlersville Station; EI's placing appropriate signage; installation, maintenance, and inspection of appropriate ECD's, equipment inspection, road approaches, clearing, grading, topsoiling, ditching, stringing, welding, road bores, blasting, and tie-ins.

Contractor has three environmental crews working. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been updated and attached. Environmental training is ongoing as needed.

There were no NCR's recorded this period.

Next Week

Above activities will continue and expand.

Spread/Facility J

Name Campbell, Bernard

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread J corridor: The installation, maintenance, and inspection of appropriate ECD's, meter station construction, clearing activities, equipment inspection, grading, road bores, ditching, stringing, bending, and hydrotesting.

Contractor has three environmental crews working. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been updated and attached. Environmental training is ongoing as needed.

An NCR was recorded on 06/16/09 at MP 582.5; please see compliance tables for more information.

Next Week

Above activities will continue and expand. Expanded mobilization to continue. Environmental training is ongoing as necessary. El team will continue inspection of all activities.

Spread/Facility K

Name Padgett, Jackie

Summary

The following construction activities were observed by the environmental inspection team throughout the Spread K corridor: The installation, maintenance, and inspection of appropriate ECD's, pre-construction photos, clearing and grading activities, and equipment inspection, topsoiling, trenching, stringing, blasting, drain tile work. Cultural monitoring was not required this period; bio monitoring occurred as required for pre-blasting.

Contractor has two environmental crews working. See variance request table attached to this report for additional information on variances. The waterbody crossing schedule has been updated and attached to this report. Environmental training is ongoing as needed.

An NCR was recorded by LEI at the Phillips Road contractor yard on 06/04/09; and on 06/08/09 at MP 609.9; please see compliance details for more information.

Next Week

Setback verification and above activity continues with expanded mobilization. EI team will continue appropriate inspections.

Spread/Facility	Arlington CS	Name	Kinney, Mike
ahiagati génità	1 Himpon 00	THEFY	

Summary

The Arlington Station in-service request was granted on June 1, 2009.

Next Week

Spread/Facility Bertrand

Bertrand CS

Name Vanya, Kevin

Summary

The Bertrand Compressor Station in-service request was granted on June 1, 2009.

Next Week

Spread/Facility Blue Mound CS

Name Suggs, Garvin

Summary

Activities this week included typical station construction continuing towards completion, maintenance of appropriate ECD's, and environmental training if needed. Housekeeping efforts occur daily. There were no compliance issues.

Final tie-ins at station have been completed.

Next Week

The above typical station construction activities will continue towards completion as warranted.

Spread/Facility Chandlersville

Name Connelly, Mike

Summary

Activities this week included typical station construction, delivery and receipt of ancillary items and equipment, maintenance of appropriate ECD's, and environmental training if needed. Housekeeping efforts occur daily.

Office building erection is complete. Welders are continuing to fabricate large and small diameter piping. E&I are pulling and terminating wires.

Next Week

The above typical station construction activities will continue towards completion as warranted.

Spread/Facility Hamilton CS Name Rhea, Richard

Summary

Typical start up compressor station construction is occurring and will expand as weather permits. Fencing, miscellaneous excavations, anchor bolts, various electrical, various PVC piping, welding/fab, backfilling around building, concrete work, various electrical, install forms, remove all trash, compressor building and overhead crane erection, pipe epoxy coating, delivery and receipt of ancillary tools and equipment, and environmental training as needed.

Next Week

Above listed typical station activities will continue and expand.

Spread/Facility Mexico CS Name Larson, Ray

Summary

Work this period included typical station construction activity that continues toward completion, installation and maintenance of appropriate ECD's, and environmental training if needed. Spread A1 EI's routinely make compliance checks at the station, with no compliance issues noted. All hydrotesting has been completed.

E&I crews continue installing instruments and pulling and terminating cable.

Next Week

Above typical station activities will continue towards completion.



Rockies Express LLC REX East Project FERC Weekly Report

Weekly Report No: 52

Start: 6/11/2009 End: 6/17/2009

Construction Progress Tracking

Attached

Compliance Tracking

Attached

Variance Tracking

Attached

Landowner Complaint Resolution Tracking

Attached

Other Agency Correspondence

None

Waterbody Crossing Schedule Attached

Construction Emissions Tracking:

None

REX EAST 6/19/200911:46 AM

Rockies Express Pipetine LLC Spreads A1 thru F

> REX EAST - WEST OF LEBANON CONSTRUCTION PROGRESS TRACKING Progress as of 06/17/09

View Completion 95,08%

	2	A1 - WELDED	A2 - WELDED	B - PRICE	C - PRICE NTP	D - ASSOCIATED	; ;		•	
		NTP 07/22/08	NTP 07/18/08	GREGORY NTP 07/09/08	4/08		E - Sheehan	F1 - Price	F2 - Gragory	TOTAL
		Beg Station 0+00	Beg Station 3760+76	Beg Station 7604+76	Beg Station 10066+52	Beg Station 12576+93	Beg Station 16146+45	Seg Station 19779+16	Beg Station 21354+53	
Contract Description	Craits			Ericing station FU066+32	Ending station 123/0+83	Ending Station 16146+45	Ending Station 19778+16	Ending Station 21394+33	Ending station 23396442	Average % Sum
Mobilization To Contr Yard	LS	100%	100%	100%	100%	100%	100%	3 0 %	80%	96%
Demobilization	S 1	30%	%0	% 0	960	2%	%0	9%0	9 % 0	0.N
के अन्द्रियां कि रहा कि को हो सिंह अने कि कि सिंह सिंह सहरक	A Second Second							and the second states and the second seco		
								all and the second second second		
Clear and Grade	ΓĿ	100:00%	100.00%			100.00%	100.00%	99.82%	100.00%	%86766
Ditch	ĽΕ	100.00%	100.00%			100.00%	98.94%	90.82%	100.00%	30.97%
String	LF	100.00%	100.00%	ACCERT TO A DESCRIPTION		100.00%	100.00%	90 .82%	100.00%	96.96%
Berid	۲F	100.00%	100.00%			100.00%	100.00%	99.82%	%00'001	%95788
Weld	ĽF	100.00%	100.00%	】 · · · · · · · · · · · · · · · · · · ·		100.00%	99.92%	99.82%	100.00%	99.97%
NOE	ĻF	100.00%	100.00%	到時實情家在1942年一時一時	· 如果是一些的。 · · · · · · · · · · · · · · · · · · ·	100.00%	%Z6'66	39.82%	\$00:001	36.97%
Coat	LF	100.00%	100.00%			100.00%	%Z6:66	99.82%	%00'001	89.97%
Lower in - Backfill	LF	100.00%	100.00%			100.00%	%#6'66	99.82%	100.00%	%2H-96
Hydrotest	ΤĿF	89.44%	100.00%		素はいたいない言語の意	100.73%	102.24%	99.82%	2.02%	38.03%
Clean and Dry	Ξ	99.23%	100.00%			\$3.60%	%00.0	99.82%	%.00'0	72.83%
Celiper Pig	LF	98.15%	100.00%	生生 法公约公式 建制度器		100.83%	44.12%	83.82%	%00'0	80.36%
Tie In	LF	100.00%	100.00%			100.00%	99.94%	89.82%	\$00.001	\$26.68
Environmental Front and	5	100.00%	100.00%			72.47%	36.88%	75.82%	55.05%	80.04%
Clean up - Rough	5	100.00%	100,00%	時間時間になっていまた目に表		72.47%	30.88%	75.92%	65.05%	80.04%
Reclamation/Seeding	5	51.99%	36.27%			23.63%	3.36%	37.54%	%00'0	44.10%
blechanically Complete	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	1. 10. 11. 10. 10. 10. 10. 10. 10. 10. 1	11 12 10 100 100 West 10 100	100.00% (100.00%)	1020200 100:00000000 01 25	308,76%	1 1 1 1 2 87.18% at 0.7 1 1	50.82% Contraction	1.7.1 (301. %21.3.2 032)34.7.14	
Plage and Pack	8					-				
	The second se		くたいこう たいちょう たいかい ちょうちょう ちょう たいしょう しょう たました 御							THE PARTY OF THE P

<u>G</u>	
N (A	
ANO	
LEB	
Ъ.	i
≜ST	Ì
ji E	
EAS	
REX	į

CONSTRUCTION PROGRESS TRACKING

REX EAST 6/19/200911:48 AM

Rocides Express Provine LLC

Overall Completion

TOTAL

Spread K - Cambridge, OH Price Gregory Spread J - Zanesville, OH Rockford Spread I - Zanesville, OH Henkles McCoy Spread G • Wilmington, Spread H • Circleville, OH OH Price Gregory Michels

		Beg Station 23396-42	Beg Station 26191+22	Beg Station 28884+83	Ending Station 30452+22	Bed Station 32114+20	
	_	Ending Station 26191+22	Ending Station 28884+83	Ending Station 30452+22	Ending Station 32114+20	Ending Station 33720+25	
Contract Description	Units	αTY	ary	ατν	οτγ	ary	Average % Sum
Mobilization To Contr Yard	51	100%	100%	100%	%001	100%	A CONTRACTOR OF
Demobilization	รา	760	%0	540	- 3	0%	0%
NTP to ROW Date		02/04/03	05/04/09	05/06/09	05/06/09	64/30/03	
	er ogen Linkston					的复数建制编成化的设施器或制度加强的	
Clear and Grade	5	12.70%	%86.94			25,83%	
Ditch	LF	9.39%	8.38%	。 一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一一		18.92%	See Street St
String	15	0.00 %	64.75%			10.52%	24,6226
Bend	Ŀ	0.00%	50.44%			5.16%	10 10 E
Weld	IJ	0.00%	15.87%			9,00%	
NDE	ĽΕ	0.00%	14.72%			9400.0	2860 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
Cost	LF	1.85%	13.90%			0.00%	
Lower in - Beckfill	LF	0.07%	5.24%	「「「「「「」」」のである。「「」」」」		0:00%	
Hydrofest	LF _	0:00%	0.93%			0.00%	6.05
Clean and Dry	LF	0.00%	0.00%			0.00%	A DESCRIPTION OF A DESCRIPTION
Caliper Pig	LF	0.00%	0.00%	and a start of the		0.00%	all
Tie In	LF	0.00%	0.00%		States and the second	9600.0	THE REPORT OF THE PARTY OF THE
Reclamation/Seeding	ĽF	0.00%	0.00%	· · · · · · · · · · · · · · · · · · ·		%00.0	1
Mexterrecally Complete		1	20.63%			1	14 TA BE 27828 C TA STOL
Purge and Pack	*						
A COMPANY OF THE OWNER O	BURNER OF STREET					A REAL PROPERTY AND A REAL	

Created by Misci Johnson

REX EAST ECL Weekly Construction Progress Report.xls

Spread/ Facility	Date	Report ID	Reported By	ΜΡ	1	Type	Summary	Corrective Action	Cost
Noncompliance	ance								
Resolved									
	6/12/2009	6/12/2009 Jblackwell- 061209-2	Jason Blackwell CM 335.9	CM 33.		Failure to Adhere to Plan/Procedures	In sufficient secondary containment at one pump; no containment for another at same location.	Once notified, crews immediately made repairs and placed the second pump in containment. Resolved.	
	6/13/2009	6/13/2009 Jblackwell- 061309-2	Jason Blackweil CM 358.8	CM 32		Off ROW Travel	Monitor observed four contractor pick ups parked off-ROW in a private entrance.	LEI had contractor remove the pickups. Retraining of the individuals occurred on ROW access, use, and limits. During conference call, contractor agreed to develop a plan to prevent such further NCR's, or pursue a parking variance. No darnage was done to the rocked entrance where parking occurred. Resolved.	

Page 1 of 6

Spread/ Date Facility	Date	Report ID F	Reported By	-	MP	Type	Summary	Corrective Action	Cost
К	6/4/2009	6/4/2009 K01-39968-1 Jack Padgett	Jack Padgett	EI	578	Off ROW Other	(MP reference is a spread reference only. Yard was off-line and off-ROW.) Moinfus contractor borrow warra of the	Approval through the variance process is to be sought for use of this yard.	
							Philips Road, Ohio contractor yard prior to FERC approval.	Updated report: FERC authorization letter for use of the Phillips Contractor yard was	

Updated report: FERC authorization letter for use of the Phillips Contractor yard was received 06/17/09.

9
ē.
3
сч.
. •
ς.
, in the second
•
8
=
-
~
. •
· ` ` `
- at
-
· Z
·Ξ.
r.,

Corrective Action		ECD's not installed after initial Repairs were implemented where applicable. disturbance and fail to maintain equipment However, LEI wishes to protest this NCR in
Summary		ECD's not installed after mitial disturbance and fail to maintain equipm
MP Type		Failure to Adhere to
₩₽		CM 266.5 Failure to Adhere to
Reported By		David Langlois
Report ID		5/12/2009 Dianglois- 061209-3
Date	Protest	6/12/2009
Spread/ Facility	Resolved - Protest	A

ECD's not installed after initial Repairs were implemented where applicable. disturbance and fail to maintain equipment However, LEI wishes to protest this NCR in	that, report does not contain any photos of off-	ROW sediment or discharges into waterbodies;	the attached photos of silt fence reflect a	sediment load of 1/3 to 1/2 while the monitor's	report reflects "80% build up of sediment";
ECD's not installed after initial disturbance and fail to maintain equipm	bridge.				
5 Failure to Adhere to	Plan/Procedures				
5					

Additionally, monitor's photo reflects a slope breaker requiring maintenance (only) with no evidence of discharge or impact to sensitive resources (problem area).

bridge corners shown in photos do not reflect

undermining as the monitor reports.

statement is not a requirement cited in Rockies plan and procedures IV.F, the section cited for weather patterns, over the last 8 weeks". This report does not address any locations that did not have temporary erosion controls installed soil. The cited section for the violation does The report also relates that "ECDs were not violation. Likewise, from section IV F, the immediately after initial disturbance of the installed adequately to withstand seasonal not apply to this NCR.

A side skirt on a bridge came loose and was have only been recorded as a problem area. impact. Rockies believes this NCR should hanging into the waterbody, creating no Resolved onsite; admin pending protest.

Spread/ Date Facility	Date	Report ID	Reported By	MP	Type	Summary	Corrective Action	Cost
_	6/16/2009	6/16/2009 Gmiller-06.1609- Greg Miller 1	- Greg Miller	CM 582.5	Failure to Adhere to Plan/Procedures	FERC CM recorded an NCR for "spoil from the trench that had not been placed 10 feet back from the top of banks" at six waterbodies. Also cited was lack of sediment barriers around spoil piles.	FERC CM recorded an NCR for "spoil IEI notified contractor and they sent a long- from the trench that had not been placed neck too the area to reach what soils could 10 feet back from the top of banks." at six be pulled back. Sediment barriers were then waterbodies. Also cited was lack of be reached due to the side cut configuration but was secured with sediment barriers. Tailgate Training of all crews involved and utility inspectors was held 06/18/09 on soil storage requirements. Resolved.	

•

Note, for protest however: Procedures Section V.B.4 cited for this violation refers to soil placement 10 feet from water's edge, not top of banks, as cited in this NCR. The waterbodies were all dry and the monitor confirms no flow present. There was no water's edge to judge this an NCR and there was no noted indication that any spoil entered any waterbodies. Resolved under protest. Problem Area category is more applicable.

Spread/ Facility	Date	Report ID	Reported By		MP Type	be	Summary	Corrective Action	Cost
Problem Area	\rea								
Resolved		-							
Ħ	6/15/2009	6/15/2009 H10-39979-2	Jory Goetting	E	515.13 Spill		Frac out occurred at Little Walnut Creek HDD.	Spill of fluid was contained as much as practical and drilling stopped until further notice. Pending.	
н	6/9/2009	6/9/2009 [01-39973-2	Kevin Jarik	Ξ	558.21 Fail Pla	Failure to Adhere to Plau/Procedures	Mulching with wood chips spread on the ROW has over-exceeded one-ton per acre limits.	LEI met with contractor and advised of problem. Contractor agreed to remove and dispose of the chips. Pending action. A closure report will be filed when complete. Update: Report I01-39976-2 reflects all excess wood chips have been removed from the ROW. Resolved.	
ч	6/10/2009	6/10/2009 102-39974-2	Curt Landrum	ᇳ	547.08 Spill	E .	Hoe hose burst open and created a spill to soils.	Crews stopped the leak, repaired the hose, and cleaned up approximately 4 gallons of hydraulic oil that spilled to the ground. Diapers and shovels were used to clean up. Resolved.	

Spread/ Facility	Date	Report ID	Reported By	46	MP Type	Summary	Corrective Action	Cost
н	6/13/2009	6/13/2009 I03-39977-2	David J. Hammons	EI	558.07 Spill	One half gallon of hydraulic oil spilled while a dozer blade was being unloaded, and ripped a line.	Contractor immediately stopped the leak, contained and cleaned up the soils. Soils were placed in plastic bags and removed from the ROW. Resolved.	
Unresolved	R							
Ξ	6/15/2009	6/15/2009 H10-39979-2	Joey Goetting	E 2	515.10 Spil	Frac-out occurred at Little Walnut Creek and the Rockies Frac-out contingency plan was implemented. Work has been halted until management plans for recovering the mud and regaining circulation are in place. All drilling fluids spilled were contained. Work has been halted.	Pending complete resolution plan by management. Work is on hold.	
Ħ	6007/1/1/9	6/17/2009 H04-39981-1	Ryan McLeod	E	496.05 Spill	Frac-out of drilling fluid occurred at Deer Creek HDD. The spill was immediately contained by crews implementing the Rockies HDD Frac-out contingency plan. The spill was upland of the creek and there were no discharges into the creek. Work is on hold.	Resolution is currently pending management review. Pending.	

Page 6 of 6

Spread Variance ID MPI Lavei Data Data Description Status Statu						Rockies Express Pipeline L REX EAST Project FERC Weekly Report Variance Tracking	Properties of the sector of th		
WSB-054 Level 1 6/12/2009 Gregory & Cook Construction is requesting authorization to caread aria nile line south of the location where a drain lile, located with the approved ROW, is working the approved ROW, is working properly. In order to verify that the drain lile problems are occurring of ROW, it is increased to the increased to the approved ROW.	Spread	I Variance ID MP/ Loc	ation	I Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
	ph.	WS-B-054	Level	_	6/12/2009	Gregory & Cook Construction is requesting authorization to excavate a drain tile line south of the approved ROW on Tract No. IL-MU-016.000.	Water is ponding across the ROW in the location where a drain tile is located. It appears from all checks that the new drain tile, located with the approved ROW, is working properly. In order to verify that the drain tile problems are occurring off ROW, it is necessary to excavate the original drain tile line located outside the approved ROW.		Like use.

Page 1 of 13

spreau	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
σ	MM-G-006	458.5	Level 2	6/5/2009	6/13/2009	6/13/2009 Price Gregory is requesting a variance to dispose of cuttings and drill fluid from the Caesars Creek HDD on 221.6 acres of actively cultivated farmland in Warren County, Ohio.	The disposal of the cuttings and drill fluids at this location will allow for a beneficial use of the material versus the disposal in a landfill. The cuttings and drill fluid will be spread over the field, and later incorporated into the existing agricultural field by the landowner. The site being requested was previously approved as Variance No. MM-G-I on 1/19/2009 for the Little Miami River HDD.	Аррлохед	
ى ب	MM-G-008		Level 1		6/15/2009	6/15/2009 Price Gregory requests authorization to construct a flume structure in the dry waterbody channel that will be aligned in a manner to prevent both bank erosion and stream bank scour. This flume will maintain an unrestricted flow and prevent soil from entering the waterbody. The flume will be designed to withstand and pass the highest expected flow while the flume is in place. During cleanup operations the channel will be restored to it's pre-construction location and condition.	The center lines of WB-OH-451- LL and WB-OH-451-HH are 90' apart. ATWS is available on the west side of WB-OH-451-LL, and on the east side of WB-OH-451- HH. However, there is no ATWS available between the waterbodies for placement of dirt when constructing the grade through this area. The fluming of WB-OH-451- LL will allow the grade dirt to be carried across and place in the ATWS located on the west side of this waterbody.	Approved	Sandbag inlet and outlet of flume. Place geotech in bottom of channel to facilitate restoration efforts. Maintain flow.

Page 2 of 13

Spread	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
с	WS-G-005		Level 2	6/9/2009		 6/13/2009 Price Gregory is requesting an additional 1.4 acres of ATWS located on the going-away-side of U.S. HWY 71 between Station No. 24945+40 and 24952+48. 	The majority of the ATWS for the bore of U.S. HWY 71 is located over the existing TETCO pipelines. Based on the agreements with TETCO, this workspace is not usable for the storage of spoil from the U.S. HWY 71 bore pit. Therefore, additional workspace is being requested on the north side of the approved ROW that parallels U.S. HWY 71. In addition, the agreement with TETCO requires that their pipelines be bored. Therefore, additional workspace is be requested along the south side of the approved ROW for the storage of spoil associated with the bore of the TETCO pipelines.	Approved	All activity must remain within boundaries of tract - 081
U	WS-G-007		Level 2	6/14/2009	· · · · · · · · · · · · · · · · · · ·	Price Gregory is requesting an additional 35' of ATWS along the north side of the approved ROW for the purpose of storing topsoil.	The topsoil storage for Tract No. OH-CT-037.N01 is located on the south side of Hurley Road. In order maintain separation between the topsoil and subsoil on this tract, the topsoil would have to be transported across the road and placed on different property owners tract. The additional ATWS will allow the topsoil from Tract No. OH-CT-037.N01 to be maintained within this tract.	Pending FERC	

Page 3 of 13

Friday, June 19, 2009

Spread	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Danied	Description	Justification	Status	Stipulations
Ö	WS-G-008		Level 1		6/16/2009	6/16/2009 Price Gregory is requesting authorization to use the existing gravel parking lot of the Chester Township Fire Department for employee parking. The parking lot is located at the intersection of State Road 380 and County Road 61 (Mound Road) immediately adjacent to the pipeline crossing.	The parking lot is adjacent to the pipeline crossing. The use of this parking area will eliminate congestion within the ROW while crews are working in this area. The parking lot will be utilized for like use vehicles only.	Approved	Approved Like use parking only. Not to be used for storage of construction related materials.
υ	WS-G-009		Level 1		6/16/2009	6/16/2009 Price Gregory is requesting authorization to use the existing gravel area located north of the approved ROW on Tract No. OH- WA-109.000 for parking employee vehicles. The proposed area has previously been disturbed and graveled by the loggers when the timber was removed from this tract.	The proposed parking area is adjacent to the pipeline ROW. The use of this parking area will eliminate congestion within the ROW while crews are working in this area. The parking area will be utilized for like use vehicles only.	Approved	Like use parking only. Not to be used for storage of construction related materials.
н	AR-H-002	1	Level 2	6/16/2009		Michels is requesting permission to use an access road off Rainbow road on tract OH-FF- 076.000. The landowner has given permission.	The access road will give the contractor an easement to and from the right-of-way during the pond installation and other construction activities. Access road will be used for heavy equipment. Will be restored to original conditional. Landowner does not want improvements.	Pending FERC	
Friday, J	Friday, June 19, 2009								Page 4 of 13

Spread	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations	
±	RA-H-001	504.5	Level 2	6/9/2009	6/13/2009	6/13/2009 Michels is requesting permission to relocate the pipeline's centerline up to a distance of 80 feet to the south of the original proposed centerline, staying well within the original workspace. Currently the centerline is located numing parallel with the tributary to Buskirk Creek (WB-OH-501- CC). The pipeline lies within the creeks banks the entire length of the creek's bottom. The proposed re- route removes the pipeline from the perimeters of the tributary and its steep banks. Total length of re-route 1144 feet.	ROW realignment will preserve the existing waterbody bed while minimizing the potential for minimizing the potential for the creek bottom and slopes, as a result of construction activity. The proposed re-alignment will raise proposed re-alignment will raise the pipe out of the water table, minimize the possibility of future pipe exposure, and allow for future minimenace in an area better suited for the staging of construction equipment.	Pevoudde		
щ	WS-H-007 Rev 1	539.6	Level 2		6/13/2009	6/13/2009 Price Gregory International, Inc requests approximately 1.2 Acres of additional temporary work space (ATWS) on the west, north, and east side of the Columbia Gas Meter Station per the attached drawings. Erosion Control Device's (ECD) will be installed in accordance with the REX Enviromental Plan and Procedure.	The use of this extra temporary work space will allow for equipment and material storage while the meter station is constructed and provide a safe work area for project personnel. The ATWS will also provide a travel lane for the mainline contractor.	Approved		
Friday,	Friday, June 19, 2009								Page	Page 5 of 13

WS-H-012 516.77 Level 2 66/2009 6(132009 Middet request permission to deposal site. The land owner has being result of the active site in a contain rocks Approved No tree removal approval. R R R R R R R Approval. Approvad No tree removal approval. R	ad	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
504.5 Level 2 6/12/2009 Michels request the use of additional temporary workspace The steep slopes associated with additional spoil storage areas to & OH-PW-025.000 along the proposed re-route will require (arws) on tracts OH-PW-022.000 & OH-PW-025.000 along the poult edge of the ROW, 20hx75fi & 20hx265fi. The steep slopes associated with the proposed re-route will require additional spoil storage areas to additional storage areas to additi		WS-H-012	516.77	Level 2	6/6/2009	6/13/2009	Michels request permission to utilize this location for a rock disposal site. The land owner has given permission to haul rock aquired from the right-of-way to this site.	The Ohio AJMA requires the uppermost 42 inches from pipeline trench,bore pits, or other excavations shall not contain rocks of any greater concentration or size than existed prior to pipeline construction. Final restoration will also generate rock greater than 3 inches that will have to be hauled off site.	Approved	No tree removal approved.
Level 26/12/2009Michels is requesting permissionThe Ohio AMIA requires the to utilize this location for a rockuppermost 42inches from the oppermost 42inches from the oppermost 42uppermost 42inches from the pipeline trench, bore pits, or other excavations shall not contain rocks acquired from the right-of-way to this location.fne Ohio AMIA requires the to rother excavations shall not contain rocks of any greater concentration or size than existed prior to pipeline construction. Final restoration will also generate rock greater than 3 inches that will have to be hauled off site.		E10-H-SW	504.5	Level 2			Michels request the use of additional temporary workspace (atws) on tracts OH-PW-022.000 & OH-PW-025.000 along the south edge of the ROW, 20ftx75ft & 20ftx265ft.	The steep slopes associated with the proposed re-route will require additional spoil storage areas to enable the ability to achieve a safe work environment for workers and equipment.	Pending FERC	
		WS-H-014		Level 2			Michels is requesting permission to utilize this location for a rock disposal site. The owner has given permission to haul rock acquired from the right-of-way to this location.	The Ohio AMIA requires the uppermost 42 inches from the pipeline trench, bore pits, or other excavations shall not contain rocks of any greater concentration or size than existed prior to pipeline construction. Final restoration will also generate rock greater than 3 inches that will have to be hauled off site.	Pending FERC	

Page 6 of 13

Spread	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations	
щ	510-H-SW		Level 2	6/12/2009		Michels request permission to utilize this location as a mud disposal site. Landowner has given permission for the use of 3.572 acres to dump & stack drill mud and cuttings, he does not want it spread.	This drill mud disposal location will be used only in the event one of our primary locations is discontinued or over whelmed. This safety net will allow the HDD's a contingency plan.	Pending FERC		
Ŧ	910-H-SM	514.9	Level 2	6/12/2009		Michels is requesting permission to perform excavation work west of the approved workspace of the entry side of the Scioto River HDD. The variance is for an area 50 feet on the north side of the centerline, and 25 feet on the south side of the centerline, and from the western edge of the HDD drill pad extending to the west for a distance of 100 feet.	The pipe does not have adequate cover at the HDD entry point, therefore it is necessary to intercept the 42" pipe west of the existing entry point to install bends. The area where the excavation will be performed within a saturated wetland and will require additional pipe depth to accommodate weights, also the consistency of the spoil is unlikely to stack and will require additional space to store.	Pending FERC		

Page 7 of 13

Spread Variance ID) MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
7 10-H-SW	<i>,</i>	Level 2	6/16/2009		Michels is requesting permission to perform excavation work cast of the approved workspace of the exit point for the Scioto River HDD. The request is for an area 120 feet on the south side of the centerline of the 42" proposed pipeline. This area includes the 35 feet designated for topsoil storage, also requesting 40 feet on the north side of the centerline. Beginning at the eastern edge of the existing approved workspace and extending to the east 100 feet.	The Ohio AMIA requires a minimum of 5 fect of top cover where it crosses agricultural/crop land. The pipe does not have adequate cover at the exit point to install bends and meet the AIMA requirements. Therefore, it is necessary to intercept the 42 ^m pipe east of the exit point to achieve the 5 feet of cover. The area where the exervation will be performed is an actively cultivated agricultural field. The additional workspace out side the approved permanent workspace is being requested so the trench walls can be adequately sloped to provide a safe work environment for the tie-in welders and to properly store topsoil.	FERC Ferding	
Friday, June 19, 2009								Page 8 of 13

Stipulations	
Status	Pending FERC
Justification	The Ohio AMIA requires a minimum of 5 feet of top cover where it crosses agriculture/crop land. The pipe does not have adequate cover at the exit point to install bends and meet the AIMA requirements. Therefore, it is necessary to intercept the 42" pipe west of the exit point to achieve the 5 feet of cover. The area where the excavation will be performed is an additional workspace out side the approved permanent workspace is being requested so the tranch walls can be adequately sloped to provide a safe work environment for the tie-in welders and to properly store topsoil.
Description	Michels is requesting permission to perform excavation work west of the approved workspace of the exit point for the Walnut Creck HIDD. The request is for an area 120 feet on the south side of the centerline of the 42" proposed pipeline. This area includes the 35 feet designated for topsoil storage, also requesting 40 feet on the north side of the centerline of the proposed 42" pipeline. Beginning at the western edge of the existing approved workspace and extending west 100 feet.
Date Approved / Denied	
Date Submitted	6/12/2009
Levei	Level 2
spread Variance ID MP/ Location	WS-H-018
opread v	₽ ₩

Page 9 of 13

Spread	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
Ŧ	WS-H-020	533.9	Level 2	6/11/2009	6/13/2009	6/13/2009 Michels is requesting permission to perform excavation work cast of the approved workspace of the emtry point for the HWY 33 HDD, landowner has given consent. The request is for an area 120 feet on the south side of the centerline of the 42° proposed pipeline. This area includes the 35 feet designated for topsoil storage, also requesting 40 feet on the north side of the centerline of the proposed 42° pipeline. Beginning at the eastern edge of the existing approved workspace and extending east 100 feet.	The Ohio AMIA requires a minimum of 5 feet of top cover where the pipeline crosses agriculture/cropland. The pipe does not have adequate cover at the exit point to install bends and meet the AMIA requirements. Therefore, it is necessary to intercept the 42" pipe east of the entry point to achieve the 5 feet of cover. The preformed is a pasture field. The preformed is a pasture field. The additional workspace out side the approved permanent workspace out side the approved estared so the trench walls being requested so the trench walls for the tie-in welders and to properly segregate topsoil.	Approved	Boundary of wetland WL- OH-532-AAA1 is to be clearly marked in the field, and ATWS is to remain 50 feet from the wetland boundary. All Project nequirements apply to work within 200 of the spring well.
-	600-1-M4		Level 2	6/8/2019	6/13/2009	6/13/2009 Reugest a variance for an offisite mud disposal site for drilling fluids generated by the Muskingum River HDD. Materials would be delivered to the Shelly and Sands industrial site. The disposal site is within the Shelly and Sands industrial complex. The site is located directly off of HWY 60 just north of Duncan Falls.	This site is located at the Shelly and Sands sand and gravel mines. The location is a large 16.15 acre bowl shaped depression that was created by previous sand and gravel mineing. The owners of the mine want the material to fill in and rehabilitate the area.	Аррточед	

,

Page 10 of 13

Friday, June 19, 2009

(2009 Rockford Corp. is requesting a variance to place a flurne in water body WB-OH-585-CCCC and use spoil from grade work to build a travel lane will be approximately 16' to 18' wide and will be sandbagged on either side to ensure proper flow should any occur.	spread Variance ID MP/ Loca) MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
	CM-J-049	584.6	Level 1		6/16/2009	Rockford Corp. is requesting a variance to place a flurne in water body WB-OH-585-CCCC and use spoil from grade work to build a travel lane instend of using rock. This travel lane will be approximately 16' to 18' wide and will be sandbagged on either side to ensure proper flow should any occur.	This variance is needed to ensure an adequate travel lane exist through this water body once grade has been established. This water body is not listed in Table 4.6.2-1, it has a <i>HHE</i> //QHEI of 12, and was considered dry at the time grade work commenced. The crossing method proposed was open cut and there was no requirement to mainten flow	Approved	

Page 11 of 13

	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denied	Description	Justification	Status	Stipulations
Rev 1	MM-J-039 Rev 1	583.6	Level 2	6/16/2009		Rockford Corp. is requesting a wariance to utilize Salt Creek, WB-OH-583-4B, as a water source for hydrostatic testing of a portion of Spread J. This water body is located at Sta. # 30773+62 and is between Okey Road and Pine Lake Road. Its surveyed bank to bank width is 55 feet and its QHEI score is 62.	Rockford Corporation's two approved water sources for hydrostatic testing are the Muskingum River located at the hickoff and Wills Creek located 22.4 miles from there. Due to an ervironmental issue, Rockford was required to start their crews almost a mile from the kickoff. This has required the Muskingum River unusable until nearly the end of the project due to the rotation of crews back to and through the kickoff, Rockford will be unable to test any pipe until it has reached Wills Creek. This will delay Rockford's testing schedule by nearly one month if a water source closer to the kickoff isn't approved. Salt Creek used in conjunction with the Muskingum River once it becomes available will allow Rockford to test the first 2/3rds of the project on schedule. Rockford estimates it will need to remove approximately 3.7 million gallons from this water source which will hydro-test from Salt Creek to the test break at Salt Creek to the test break at source utilized will hydro-test from Salt Creek to the test break at source utilized will hydro-test from source utilized will hydro-test from source utilized will hydro-test from source utilized will have no implet on the aquatic life, and that withdrawal will be done in	FERC	

Sprea	Spread Variance ID	MP/ Location	Level	Date Submitted	Date Approved / Denled	Description	Justification	Status	Stipulations
							accordance with the Wetland and Water Body Construction and Mitigation Procedures.		
*	MM-K-016		Level 1	· · · · · · · · · · · · · · · · · · ·	6/14/2009	6/14/2009 Price Gregory Construction, Inc. request permission to construct a flume structure in the dry waterbody channel that will be aligned in a manner to prevent both bank erosion and streambank scour. This flume will maintain an unrestricted flow and prevent soil from entering the waterbody. The flume will be designed to withstand and pass the highest expected flow while the flume is in place. During cleanup operations the channel will be restored to it's pre- construction location and condition.	This request is needed to minimize the overall distrubance during construction of the right of way across these dry waterbodies while allowing any flow of water to continue through the flume using the Best Management Practices.	Approved	
×	MM-K-402		Level 3	6/11/2009		Request a variance from the Ohio AIMA Construction Standards and Polices requiring for a pipeline depth of a minimum of 5 fect of top cover where it crosses pasture land or agricultural land to a maximum cover of 3 feet between MP 621.0 to MP 630.0 due to coal mining subsidence.	The pipeline in the mining subsidence area will be 42" O.D., .740 wall thickness, X-70 cathon steel pipe and for overburden control which will allow for movement of pipe at the time of coal mining subsidence a maximum cover of 3 feet is required. Five (5) feet of cover over the pipe will restrict the movement of the pipe at the time of coal mining subsidence.	Pending FERC	
Friday,	Friday, June 19, 2009								Page 13 of 13

Date Mile Post	st Tract	Description	Resolution	Status
6/8/3009	IL-PK-132.S03	Landowner complianed that they wanted topsoil returned/replaced.	Heavy saturation and weather conditions have delayed construction restoration; already documented across the pipeline. Pending.	Pending
6/5/2009	li-SA-055.000 and 056.000	Landowner filed complaint that he is unhappy with topsoil replacement and the conidtion of his field.	Agent advised LO that he would pass the complaint on to ROW supervisor. Pending.	Pending
2/2/2009	IN-SB-221.000	LO has several complaints regarding mixing of topsoil and restricted access to property due to pipe stringing.	ROW has attempted to resolve issues with LO. Topsoil has been moved further away from the pipeline. The topsoil was separated from the subsoil and the pipe is in the ground. Landowner has been provided access to his cut off property.	Resolved
5/14/2009	IN-FR-129.001	LO is concerned about water coming down hill and flooding his field due to disturbances.	REX has contracted with Mundell and Assoc. and will analyze and recommend a solution. A drain tile system was installed correcting the flooding issue.	Resolved

Tuesday, June 23, 2009

Page 1 of 3

Date	Mile Post	Tract	Description	Resolution	Status
6/5/2009	6	IN-FR-129.001	LO wants contractor to stop working due to water and mud issues and is going to contact an attorney.	Land agent has informed the LO that the property will be restored when construction is completed. Agent continues to discuss with LO.	Pending
5/5/200	<i>5/5/2009</i> 431.7	Off-Line	Complaint of dust needing abatement. Dust in house.	Met with land owner and assured her REX would provide house cleaning service. Cleaning performed on 5/18/09	Resolved
6/3/200	6/3/2009 459.9	OH-CT-006.000	Concerns over entry for HDD and access.	Pending issues working through legal department.	Pending
6/11/200	6/11/2009 515.4	000.780-W4-HO	LO complained of pea gravel being dumped instead of drilling mud as agreed to.	Land agent to meet with LO. Pending.	Pending
5/19/200	5/19/2009 578.5	OH-MK-168.SO1	LO culvert plugged by contractor.	Agent notified landowner that Chief Inspector was notified culvert was cleaned out.	Resolved
6/9/200	6/9/2009 551.8	011-PY-015.009	Disruption of water supply.	Water well running dry. Cloudy material in water. LO alleges stringing truck damaged line, causing leak. Pending.	Pending

Page 2 of 3

Date Mile	Mile Post Tract	Description	Resolution	Status
6/11/2009 580.0	0.0 OH-MK-186.000	Driveway damaged.	Gravel was delivered and placed. Resolved.	Resolved
6007/11/9	Off-line	Citizen called hotine requesting information.	ROW agent referred person to Rockies website and public relations for follow-up. Resolved.	Resolved
5/26/2009 609	OH-GN-124.000	LO complained that survey stakes had been changed. Bat clearing crew cleared trees off ROW and left others.	Field reviewed with EI the FERC Alignment and casement Exhibits no issues were discovered.	Resolved
5/13/2009 609.5	1.5 OH-GN-128.000	Spring Mitigation, Temporary fence, cross over plugs, construction debris issues all conveyed in letter.	REX submitted answer to LO letter to FERC and resolve issues. FERC Monitor met with landowner reviewed ROW for compliance.	Resolved
6/11/2009 627.3	13 OH-BL-039.000	Damage to fence from falling of bat trees.	ROW agent compensated LO for fence and tree removal. Resolved.	Resolved
S/11/2009 635.5	.5 OH-ME-126.001	LO was day-sleeping when awakened by Rockies crews in her yard with stakes and signs.	Agent met with landowner and informed of survey crew and El posting requirements.	Resolved

Tuesday, June 23, 2009

Page 3 of 3

I

ROCKICS EXPRESS PIDOLING

REX East Waterbody Crossing Schedule

Spread: A1				:				
County	ЧW	Waterbody ID	Feature Name	Type	Width (ft)	Width (ft) Crossing Method Crossing Date Date Complete	Crossing Date	Date Complete
Audrain	001.0	WB-MO-00-A	Littleby Creek	ፈ	40	Dam & Pump	09/20/08	09/22/08
Audrain	004.5	WB-MO-04-A	Tributary to West Lick Creek	I	12	Open Cut	06/10/08	06/10/08
Audrain	007.2	WB-MO-07-A	Middle Lick Creek	đ,	20	Dam & Pump	10/02/08	10/03/08
Rails	016.4	WB-MO-16-A	Tributary to Spencer Creek	۵.	12	Dam & Pump	10/05/08	10/05/08
Pike	022.4	WB-MO-22-A	Tributary to Lake Vandalia	6 .	21	Dam & Pump	10/22/08	10/29/08
Pike	023.5	WB-MO-23-A	Tributary to South Spencer Creek	1	12	Open Cut	10/29/08	10/31/08
Pike	025.8	WB-MO-25-B	South Spencer Creek	I	20	Open Cut	11/05/08	11/07/08
Pike	028.8	WB-MO-28-B	Tributary to Peno Creek	I	15	Open Cut	11/12/08	80/71/11
Pike	029.7	WB-MO-29-AAA	Peno Creek	ፈ	50	Open Cut	11/12/08	80/11/11
Pike	036.7	WB-MO-36-A	Tributary to Grassy Creek	I	30	Open Cut	11/28/08	11/28/08
Pike	040.9	WB-MO-40-A	Grassy Creek	ዲ	30	Open Cut	60/20/10	60/90/10
Pike	041.7	WB-MO-41-A	Tanyard Branch	Ţ	10	Open Cut	12/01/08	12/03/08
Pike	042.5	WB-MO-42-A	Salt River	۵.	320	QCH	10/15/08	01/26/09
Pike/Pike	042.7	WB-MO-43-A	Tributary to Salt River	ب	50	U DH	10/15/08	01/26/09
Pike	043.4	WB-IL-43-AAAA	Mississippi River	£	1500	QCIH	10/15/08	01/28/09

Friday, June 19, 2009

Rockies Express Pipeline

REX East Waterbody Crossing Schedule

Pike	043.8	WB-IL-43-DDDD	Irrigation Ditch	П	10	Open Cut	Not Crossed	Not Crossed
Pike	043.8	WB-IL-43-CCCC	Ditchway	П	15	Open Cut	02/16/09	07/1/00
Pike	043.9	WB-IL-44-AAAA	Plum Point Slough	£	40	Open Cut	07/20/09	02/22/09
Pike	046.3	WB-IL-45-A	Sand Slough	Ł	30	Open Cut	60/EZ/Z0	02/24/09
Pike	047.3	WB-IL-47-AAA	The Sny Canal	<u>م</u>	50	QCH	07/22/08	09/27/08
Pike	049.8	WB-IL-49-A	Tributary to Towhead Lake	4	35	Open Cut	02/06/09	02/06/09
Pike	052.6	WB-IL-51-B	Sixmile Creek	ρ.,	30	Open Cut	02/04/09	02/06/09
Pike	056.9	WB-IL-56-B	Cold Run	4	12	Open Cut	60/01/10	01/14/09
Pike	058.7	WB-IL-58-AAA	Buckeye Creek	Ą	15	Open Cut	01/12/09	01/06/09
Pike	061	WB-IL-60-A	Honey Creek	Ê.	30	Open Cut	12/08/08	12/12/08
Pike	063.9	WB-IL-63-A	Bay Creek	ρ.,	25	Open Cut	60/61/10	02/04/09
Pike/Scott	071.2	WB-IL-69-B	Illinois River	<u>6-</u>	500	DOH	12/15/08	In progress
Spread: G								
County	dW	Waterbody ID	Feature Name	Type	Width (ft)	Crossing Metho	d Crossing Date	Width (ft) Crossing Method Crossing Date Date Complete
Warren	446.58	WB-OH-432-A1	Tributary to Clear Creek P	c P	12	Open Cut	60/90/20	
Warren	446.58	WB-OH-432-A2	Tributary to Clear Creek	ć P	12	Open Cut	60/80/20	
Warren	447.3	WB-OH-447-BBBB	Clear Creek	4	10	Open Cut	0/110/08	
Warren	448.44	WB-OH-434-A	Tributary to Clear Creek	1 -11	15	Open Cut	07/14/09	

Friday, June 19, 2009

Rockies Express Pipeline

REX East Waterbody Crossing Schedule

Warren	451.3	WB-OH-436-A	Little Miami River	£.	99	QCH	01/31/09	04/27/09
Warren	452.53	WB-OH-438-B	Tributary to Little Miami Riv er	I	13	Dam & Pump/ Flume	07/20/09	
Warren	454.54	WB-OH-451-HH	Tributary to Little Miami River	¢,	10	Dam & Punp/ Flume	07/27/09	
Warren	454.99	WB-OH-451-EE	Tributary to Little Miami River	£	14	Dam & Punp/ Flume	08/03/09	
Warren	455.17	WB-OH-451-DD	Tributary to Little Miami River	Ł	10	Dam & Pump/ Flume	60/1/09	
Warren	455.41	WB-OH-451-AA	Shaffers Run	đ	53	Dam & Pump/ Flume	08/12/09	
Warren	457.45	WB-0H-457-4A	Tributary to Sandy Run	ч	10	Dam & Pump/ Flume	08/17/09	
Clinton	459.56	WB-OH-458-AAA	Caesar Creek	ę.	134	QQH	60/10/60	
Clinton	466.7	WB-OH-466-AAAA	Tributary to Anderson Fork	Ł	15	Open Cut	08/24/09	
Clinton	469.82	WB-OH-468-AAA	Anderson Run	ę	30	Open Cut	60/11/90	
Fayette	479.05	WB-OH-464-A	Grassy Branch	Ą	15	Open Cut	60/20/60	
Fayette	480.39	WB-OH-465-A	Rattlesnake Creek	Å	40	Open Cut	60/L0/60	
Fayette	483.67	WB-OH-468-A	Missouri Ditch	Ą	10	Dam & Pump/ Flume	09/12/09	
Fayette	484.30	WB-OH-469-A	Sugar Creek	Ą	30	Open Cut	60/81/60	
Fayette	486.37	WB-OH-484-AAA	Paint Creek	Ъ	24	Open Cut	09/25/09	
Fayette	487.8	WB-OH-487-4D			10	Open Cut	60/08/60	

Friday, June 19, 2009

•

Rockies Express Pineline

REX East Waterbody Crossing Schedule

						Canadi U
	Flume					
10/26/09	Dam & Pump/	30	North Fork Paint Creek P	WB-OH-481-A	496.56	Fayette
60/61/01	Open Cut	01	Compton Creek P	WB-OH-493-5A	494.09	Fayette
10/12/09	Open Cut	12	Dews Run	WB-0H-478-A	492.97	Fayette
60/51/01	Open Cut	32	East Fork Paint Creek P	WB-OH-490-AAAA	490.9	Fayette

Spread: H								
County	МР	Waterbody ID	Feature Name	Type	Width (ft)	Width (ft) Crossing Method Crossing Date Date Complete	Crossing Date	Date Complete
Fayette	499.44	WB-OH-497-BBB	Tributary to Deer Creek	ш	01	OCH	06/25/09	
Fayette	499.56	WB-OH-498-AAA	Deer Creek	ď	100	QCH	06/25/09	
Pickaway	500.80	WB-OH-499-BBB	Clark Run	a .	15	Open Cut	07/20/09	
Pickaway	504.60	WB-OH-501-EE	Buskirk Creek	۵.	20	Dam & Pump/ Flume	08/03/09	
Pickaway	507.07	WB-OH-491-B	Dry Run	۹.	25	Dam & Pump/ Flume	08/17/09	
Pickaway	509.2	WB-OH-493-A	Big Darby Creek	Ъ	170	DOH	02/04/09	03/10/06
Pickaway	510.14	WB-OH-508-BBB	Tributary to Big Darby Creek	I	20	Dam & Pump/ Flume	09/24/09	
Pickaway	511.18	WB-OH-511-4A	Tributary to Big Darby Creek	4	12	Dam & Pump/ Flume	60/60/60	
Pickaway	514.62	WB-OH-499-A	Scioto River	Ч	200	DOH	05/28/09	In Progress
Pickaway	515.45	WB-OH-500-A	Mud Run	Ł	10	Open Cut	02/15/09	In Progress
Pickaway	515.91	WB-OH-500-B	Walnut Creek	۵.	06	DDD	05/15/09	In Progress

Friday, June 19, 2009

	-
	· · ·
	- · · ·
	me f *
	····
	· · · ·
	· · · · · ·
X	SIN
A	
< E	
X	N .3
)	
- <i>&</i> ``	
N	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
•	

REX East Waterbody Crossing Schedule

Pickaway	516	O&E CANAL	Ohio & Eric Canal	I	20	QQH	05/15/09 In Progress
Pickaway	518.97	WB-OH-503-A	Bull Run	۵.	10	Dam & Pump/ Flume	07/06/09
Pickaway	520.15	WB-OH-504-A	Turkey Run	6 .	20	Dam & Pump/ Flume	07/13/09
Pickaway	520.51	WB-OH-505-A	Little Walnut Creek	۵.	15	Dam & Pump/ Flume	07/13/09
Pickaway	523	WB-OH-523-4A	Tributary to Little Walnut Creek	đ	30	Open Cut	07/16/09
Fairfield	525.64	WB-OH-510-D	Tributary to Little Walnut Creek	<u>م</u>	50	Open Cut	60/02/20
Fairfield	526.64	WB-OH-511-A	Little Walnut Creek	4	30	Dam & Pump/ Flume	08/03/09
Fairfield	534.06	WB-OH-532-AAA	Ohio Canal	е.	12	QQH	06/25/09
Fairfield	534.56	WB-OH-519-A	Tributary to Hocking Ríver	-	10	Open Cut	60/17/60
Fairfield	537.95	WB-OH-522-B	Fetters Run	-	21	Open Cut	10/01/06
Spread: I							
County	MP	Waterbody ID	Feature Name	Type	Width (ft)	Crossing Methor	Width (ft) Crossing Method Crossing Date Date Complete
Репу	551.48	WB-OH-549-BBB	Tributary to Center Branch Rush Creek	ы	10	Open Cut	06/12/09
Petty	551.49	WB-OH-549-AAA	Tributary to Center Branch Rush Creek	I	0	Open Cut	06/14/09
Репу	553.17	WB-OH-549-EE	Somerset Creek	<u>م</u>	16	Dam & Pump/ Flume	06/16/09

Friday, June 19, 2009

	06/26/09 06/26/09	Dam & Pump/ Flume Dam & Pump/ Flume	40 12	<u>е</u> е	Manns Run Tributary to Salt Creek	WB-OH-578-BBB WB-OH-580-4B	579.85 580.93	Muskingum Muskingum
Date Date Complete	od Crossing	Width (ft) Crossing Method Crossing Date	Width (ft	Type	Feature Name	Waterbody ID	MP	County
								Spread: J
	06/26/09	Open Cut	20	Ш	Tributary to Muskingum River	WB-OH-578-DDDD	578.5	Muskingum
·	06/15/09	DCH	420	щ	Muskingum River	WB-OH-575-AAA	577.39	Muskingum
	01/06/09	Open Cut	10	L E	Tributary to Duncan Run E	WB-OH-573-AAA	575.48	Muskingum
	60/03/06	Open Cut	81	4	Brush Creek	WB-OH-571-4A	571.16	Muskingum
	60/10/20	Open Cut	150	Open Water	Open Water Area	WB-OH-568-EEE	570.47	Muskingum
	06/29/09	Open Cut	271	Open Water	Open Water Area	WB-0H-552-D	566.77	Muskingum
	06/26/09	Open Cut	30	<u>6</u> .	Moxahala Creek	WB-0H-548-C	566.09	Репту
	06/24/09	Open Cut	12	Π.	Tributary to Moxahala Creek	WB-OH-563-CCC	565.10	Репу
	06/22/09	Open Cut	150	Open Water	Open Water Area	WB-OH-559-AAA	561.47	Рспу
	60/61/90	Open Cut	109	Open Water	Open Water Area	WB-OH-544-E	560.80	Репу
	60/11/90	Open Cut	421	Open Water	Open Water Area	WB-OH-544-F	560.75	Репу
	60/11/90	Open Cut	9	1	Tributary to Center Branch Rush Creek	WB-OH-540-D	556.63	Репту

REX East Waterbody Crossing Schedule

Rockies Express Pipeline

REX East Waterbody Crossing Schedule Rockies Express Pipeline

Muskingum	582.17	WB-OH-580-000	Tributary to Williams Fork	I	15	Open Cut	06/27/09
Muskingum	582.94	WB-OH-581-DDD	Tributary to Buffalo Creek	ፈ	40	Dam & Pump/ Flume	06/27/09
Muskingum	583.52	WB-OH-583-4A	Buffalo Fork Salt Creek	£.	40	Dam & Pump/ Flume	06/28/09
Muskingum	583.62	WB-OH-583-4B	Buffalo Fork Salt Creek	<u>م</u>	. 35	Dam & Pump/ Flume	06/28/09
Guernsey	592.98	WB-0H-591-AAA	Tributary to Mannon Run	П	13	Open Cut	06/29/09
Guemsey	594.26	WB-OH-592-II	Tributary to Crane Run	I	12	Open Cut	06/29/09
Guernsey	600	WB-OH-598-CCC	Wills Creek	6- 1	4	Open Cut	60/62/90
Spread: K							
County	MP	Waterbody ID	Feature Name	Type	Width (ft)	Crossing Method	Width (ft) Crossing Method Crossing Date Date Complete
Noble	611.90	WB-OH-610-AAA	Tributary to Leatherwood Creek	ρ.	10	Open Cut	07/11/09
Belmont	623.1	WB-OH-BRR-3-A	Slope Creek	6	10	Open Cut	08/04/09
Belmont	625.3	WB-OH-BRR-5-A	Tributary to South Fork Captina Creek	<u>م</u>	15	Dam & Pump/ Flume	08/08/09
Belmont	626.46	WB-OH-626-4A	Impounded Tributary to Brushy Creek	Open water	30	Open Cut	08/11/00
Belmont	627.27	WB-OH-611-C	Tributary to South Fork Captina Creek	1	10	Open Cut	08/13/09
Belmont	628.46	WB-OH-612-D	Tributary to Piney Creek P	L	15	Dam & Pump/ Flume	08/15/06

Friday, June 19, 2009

Rockies Express Pipeline

REX East Waterbody Crossing Schedule

08/19/09	08/22/09	08/25/09	08/28/09	60/1£/80
Dam & Pump/ Flume	Open Cut	Dam & Pump/ Flume	Open Cut	Open Cut
30	15	13	10	10
ፈ		4 4	ы	I
Piney Creek	Tributary to Crabapple Creek	Crabapple Cr ce k	Tributary to Peavine Creek	Tributary to Peavine Creek
WB-OH-628-BBB	WB-OH-615-E	WB-OH-616-A	WB-OH-633-BBBB	WB-OH-633-AAAA
629.78	631.3	631.94	633.7	633.8
Belmont	Belmont	Befmont	Behront	Belmont

Friday, June 19, 2009