PUCO



December 23, 2009

D10-1142-GA-BIN

Ms. Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426

Re: Rockies Express Pipeline LLC

Docket No. CP07-208

Weekly Report #79, Period Ending December 23, 2009

Dear Ms. Bose:

Pursuant to Environmental Mitigation Measure 7 in the Appendix to the Federal Energy Regulatory Commission's May 30, 2008 Order in Docket No. CP07-208, Rockies Express Pipeline LLC hereby submits its weekly construction progress report for activities for the week ending December 23, 2009.

If you have any questions regarding this report, please contact Crystal Heter at (303) 914-7795.

Respectfully submitted,

/s/ Shippen Howe

Shippen Howe Van Ness Feldman 1050 Thomas Jefferson Street, NW Washington, DC 20007

Attorneys for Rockies Express Pipeline LLC

Laura Turner

This is to certify that the images concaring are an accurate and complete reproduction of a case file document delivered in the regular course of Technician Date Processed



#### **Rockies Express Pipeline LLC REX EAST Project**

**FERC Weekly Report** 

End:

Weekly Report #:

Start: 12/17/2009

12/23/2009

Environmental Training (this week / to date): 0 man hours /19757.5 man hours 0 people /14483 people

Spread/Facility

ΑI

Name Elshoff, Paul

**Summary** 

The Spread A-1 In-service Request was granted by the FERC on 06/25/09.

Sub Contractor is available to address eminent environmental or safety issues that arise.

There were no NCR's recorded this period.

**Next Week** 

Sub Contractor is available to address eminent environmental or safety issues that arise.

Spread/Facility

A2

Name Elshoff, Paul

Summary

The Spread A-2 In-service Request was granted by the FERC on 06/25/09.

Sub Contractor is available to address eminent environmental or safety issues that arise.

There were no NCR's recorded this period.

**Next Week** 

Sub Contractor is available to address eminent environmental or safety issues that arise.

Spread/Facility

В

Name Elshoff, Paul

Summary

The Spread B In-service Request was granted by the FERC on 06/25/09.

Sub Contractor is available to address eminent environmental or safety issues that arise.

There were no NCR's recorded this period.

**Next Week** 

Sub Contractor is available to address eminent environmental or safety issues that arise.

C Spread/Facility Name Elshoff, Paul Summary The Spread C In-service Request was granted by the FERC on 06/25/09. Sub Contractor is available to address eminent environmental or safety issues that arise. There were no NCR's recorded this period. **Next Week** Sub Contractor is available to address eminent environmental or safety issues that arise. D Name Schwarz, Wes Spread/Facility Summary The Spread D In-service Request was granted by the FERC on 06/25/09. Sub Contractor is available to address eminent environmental or safety issues that arise. There were no NCR's recorded this period. **Next Week** Sub Contractor is available to address eminent environmental or safety issues that arise. Spread/Facility E Name Schwarz, Wes Summary The Spread E In-service Request was granted by the FERC on 06/25/09. Sub Contractor is available to address eminent environmental or safety issues that arise. There were no NCR's recorded this period. **Next Week** Sub Contractor is available to address eminent environmental or safety issues that arise. Name Schwarz, Wes Spread/Facility Fl Summary The Spread F-1 In-service Request was granted by the FERC on 06/25/09. Sub Contractor is available to address eminent environmental or safety issues that arise. There were no NCR's recorded this period. **Next Week** Sub Contractor is available to address eminent environmental or safety issues that arise.

#### Spread/Facility F2 Name Schwarz, Wes

#### Summary

The Spread F-2 In-service Request was granted by the FERC on 06/25/09.

Sub Contractor is available to address eminent environmental or safety issues that arise.

There were no NCR's recorded this period.

#### **Next Week**

Sub Contractor is available to address eminent environmental or safety issues that arise.

Spread/Facility G	Name	Schwarz, Wes
Summary		
The Spread G In-service Request was granted by the FERC on 11/09/09.		
Fencing crew working. Sub Contractor is available to address eminent environment environment.	onmental o	or safety issues that arise.
There were no NCR's recorded this period.		
Next Week		
Final efforts to continue.		
Spread/Facility H	Name	Goetting, Joey
Summary		
The Spread H In-service Request was granted by the FERC on 11/09/09.		
One crew completing fencing.		•
There were no NCR's recorded this period.		
Next Week		
Fencing being completed.		
Spread/Facility <sup>I</sup>	Name	Landrum, Curt
Summary		•
The Spread I In-service Request was granted by the FERC on 11/09/09.		
Fencing crew is working.		
There were no NCR's recorded this period.		
Next Week		
Fencing crew working.		
Spread/Facility <sup>J</sup>	Name	Ezell, Rick
Summary		
The Spread J In-service Request was granted by the FERC on 11/09/09.		
All work and In-Service Punchlist items are complete.		
There were no NCR's recorded this period.		
Next Week		
Work is complete. Drain tile repair contractor is to start.		
Spread/Facility K	Name	Davis, Pat
Summary		
The Spread K In-service Request was granted by the FERC on 11/09/09.		
Work is completed. In-Service Punchlist items are complete. Monitoring con	tinues.	
There were no NCR's recorded this period.		•
Next Week		
Work is complete. Monitoring continues.		

Spread/Facility Arlington CS Name Kinney, Mike Summary The Arlington Station in-service request was granted on June 1, 2009. **Next Week** Construction for initial work complete. Spread/Facility Bainbridge CS Name Franzene, Eric Summary The Spread D In-service Request was granted by the FERC on 06/25/09, including Bainbridge CS. Construction is deemed 100% complete. **Next Week** Work is completed. Spread/Facility Bertrand CS Name Vanya, Kevin Summary The Bertrand Compressor Station In-service Request was granted on June 1, 2009. Construction is complete. **Next Week** Construction is complete. Spread/Facility Blue Mound CS Name Suggs, Garvin Summary The Spread A-2 In-service Request was granted by the FERC on 06/25/09, including Blue Mound CS. Construction is complete. **Next Week** Work is complete.

Spread/Facility Chandlersville Name Connelly, Mike

#### Summary

The REX-East In-service Request was granted by the FERC on 11/09/09, including the Chandlersville CS.

Construction is complete.

#### **Next Week**

Work complete.

Spread/Facility Hamilton CS Name Rhea, Richard '

Summary

The REX-East In-service Request was granted by the FERC on 11/09/09, including the Hamilton CS.

Work is complete.

**Next Week** 

Work completed.

Spread/Facility Mexico CS Name Larson, Ray

Summary

The Spread A-1 In-service Request was granted by the FERC on 06/25/09, including the Mexico CS.

Construction is complete.

**Next Week** 

Construction is complete.



#### **Rockies Express LLC** REX East Project FERC Weekly Report Weekly Report No: 79

Start: 12/17/2009 End: 12/23/2009

Construction Progress Tracking	
None	
Compliance Tracking	
None	
Variance Tracking	
None	
Landowner Complaint Resolution Tracking	
Attached	
Other Agency Correspondence	*
None	
Waterbody Crossing Schedule	
None	
Construction Emissions Tracking	
None	
West of Lebanon - RestorationList	
Attached	
East of Lebanon - RestorationList	
Attached	



**FERC Weekly Report** Compliance Tracking

Summary	
Type	
Æ	
Reported	Ву
Report ID	
Date	
Spread/	Facility

Cost

**Corrective Action** 

There were no compliance issues reported this week.



Rockies Express Pipeline LLC REX EAST Project FERC Weekly Report

Variance Tracking
Level Date Description Ju
Submitted Approved /
Denied

Spread Variance ID MP/ Location

Status Stipulations

Justification

There were no variance request reported this week.



# Rockies Express Pipeline LLC REX East Project FERC Weekly Report Landowner Complaint Resolution

Date	Mile Post Tract	Tract	Description	Resolution	Status
10/20/2009 35		MO-PI-069.000	Topsoil, erosion, and berm issues.	12-14-09 Inspected by KM Field Agent. Ag inspector is going to inspect the area to verify the amount of top soil loss. L/O paid for fence repair, berm removal and crop loss.	Pending
		; ;		Field Inspection by EI - Apparent blasting through crossing Steep hill covering much of ROW. Stony outcrop @ station 1845+0. ROW level and smooth to edges of ROW. Much of area covered with erosion control fabric, some ECF applied over story material; few larger rocks noted @ ROW edge. Several large water bars functioning properly; area stable with no continuing erosion. Claim of lost soil is likely misplaced; soil was found in water bars and along slopes. Any extra rock picking would require partial removal of ECF, exposing the area to possible crosion. Note: The ROW appears to have been mostly forested; therefore top-soil segregation was not required_ReVeg < 70% in some areas. Minor issues pending appropriate conditions and may have to wait until spring. Pending.	,7
10/30/2009 33.5		MO-PI-063.000 & 064.000	Ground erosion and incomplete reclamation in general.	ROW met with landowners and obtained a bid for the restoration by a local contractor, ROW told landowners that they would pass this information on to KM. We also agreed on a price for the prove up dig. Pending.	Pending

Date	Mile Post	Tract	Description	Resolution	Status
11/23/2009 63.5		IL-PK-120.S02	Sewer system leaking; gas line cut, now experiencing very high utility bills.	Report from Field Agent 12/3/09 - The reason LO called back today was because ROW had left a message on her phone that ROW was in the area so give ROW a call. She couldn't find ROW number so that was the reason she called Ohio again.  Corrective Actions (1)Needs all sewer laterals replaced septic tank waste is on top of the ground and running into road. (est. rec'd. by local plumber). (2)Needs gas shutoff replaced going into house. (3) Gravel on driveway gone because buried under mud from equipment and trucks entering & exiting. (4) needs 250° of fence replaced. (5) Needs yard reseeded along pipeline going into house after pipeline was replaced. (6) needs 3 acres of alfalfa reseeded. (UNHAPPY)  Field Agent told them he would be back to settle within a week.	Pending
10/29/2009	4	MO-PI-091.000 & 092.000	The ground on the ROW is not level. There are depressed areas that cause water to pool and flood adjacent lands.  A minimum 32" ripping is required by the Easement. This has not been done.  Rocks great than 2" are required to be picked up. This has not been done.  Complete soil testing compared to adj. land is required. This has not been done.  Has not been done.  Has not received 2009 crop loss payment.  Drainage areas have not been cleaned out due to pumping from construction.	Getting 2009 crop price for payment. Other issues added to punch list to be addressed next spring. Meeting with landowner to pay 09 crop damages. Pending.	Pending
11/27/2009 36.5	9 36.5	MO-PI-076.000	LO left message on voice mail. Agent returned call. LO stated that the restoration was awful. Lime was not put down, no fertilizer and did not plant with the grass that was agreed upon.	Landowner to provide an estimate to do the work himself and will get back in touch with the field agent. Pending.	Pending
11/9/2009	9 58.5	IL-PK-093.000 & 94	LO farms the ground and he wants contact to discuss a crop damage payment for his 2nd year loss. Pending.	Pending second year estimates for payment.	Pending

Date Mile Post		Description	Resolution	Status
	MO-PI-052.N01	REX has not put fence back up. Nothing is growing in several areas on property. Part of driveway needs to be graveled.	additions. She was pleasant just wanted to know what was going on. Told her nothing would be done until spring due to the weather and upcoming winter.  Talked to landowner told her REX would talk to KM and see about getting someone from construction and El out to her property. Pending.	Pending
	IL-PK-012.000	Wants contact to discuss settling damage claims.	12/22/09: Field agent made contact and will meet with LO immediately after the first of the new year. Pending.	Pending
	MO-P1-025.000	Tile, dirt and terrace problems.	ROW had previously written a check for total compensation for reimbursement for tile and terrace work performed by a 3rd party contractor, crop damages for 2009 along with damages as a result of a prove up dig performed in October. Prior to the prove up dig, L/O demanded payment for the use of a temporary access lane to reach the dig location. This amount was approved by KM Operations who was supervising the prove up digs and payment was issued by ROW to L/O. The check was voided by ROW because L/O would not sign a Release form for damages to date.  ROW, Land Agent now working A-1 in Missouri called L/O on 11-16-09 and is planning on meeting with him later this week.  11/18/09 ROW - L/O is extremely upset that REX has done nothing regarding restoration. His terraces are not draining, one has held water all summer, drain tile from the terraces were downsized and not draining. He's not been able to plant because of the flooded terraces. He has not been compensated for his crop loss, dozer and land leveling and he continues to lose top soil Line marker has been placed in his field. Recent dig site has not been cleaned up. Issues added to Punchlist for completion when weather permits.	Pending

Update: 12-02-09 - Paid L/O for dozzer work claim. Offered 2009 crop darnages and prove-up dig payment. LO brother refused and confirmed tile repair and other dirt work was listed on REX punch list to complete. Pending.

Date	Mile Post	Tract	Description	Resolution	Status
11/5/2009	14 6	MO-PI 091.000, 092, 093	Has not had a response from REX regarding the letter he received about the Environmental Complaint Resolution Program.	Getting 2009 crop price for payment. Other issues added to punch list to be addressed next spring. Meeting with landowner to pay 09 crop damages. Pending.	Pending .
11/20/2009		Offline	During construction, LO reports his gas was shut off and never turned back on. He wants damages to frozen pipes and toilet addressed.	Week 78 update: Field Agent contacted L/O. L/O is getting an estimate for repairs and will contact Field Agent with information. L/O advised Field Agent that the gas company is ATMOS and he thought they were the ones that locked the service because they could not get in to light the pilots. Pending.	Pending
11/16/2009 103	\$ 103	IL-MO-079.002 & 093.000	15' hole dug under Hwy 104 filled up with water, not crossable.	Pending appointment and follow up investigation.	Pending
10/20/2009 141.2	141.2	IL-CS-048.000 various	Mud hole on pipeline tracks.	Called Ag Inspector asked him to look at the tract and add it to the punch list, that it sounded like a field tile problem. Field Agent advised LO that the issues have been added to the Punch list. L/O was fine with us fixing it in early spring. Pending.	Pending
10/30/2009	9 93.5	IL-MO-028.N01	There is a gully that he can not get across without a bridge.  The bridge he has was damaged and has not been repaired.  There are rows of dirt that need to be moved. Someone needs to come out and look at it.	Called LO and told him that the Ag inspector had look at his issues and added the gully to his punch list, but didn't see anything wrong with the bridge, He said he had been back and looked at it himself and that we had not hurt his bridge, and if we took care of the gully he would be fine. Pending.	Pending

Date	Mile Post	Tract	Description	Resolution	Status
10/26/2009 131.5	131.5	IL-SA-266.000	Waterway was taken out now causing gully erosion; spoke to agent last April; has not been fixed.	Added to punch list. Ag Inspection: Erosion and subsequent top-soil loss are apparent east and west of WB-IL-131-AAAA @ 6942+22 along the south limits of the Row. Unable to ascertain whether a water way existed in this area without some other form of documentation (pictures) but, there is a definite swale running the length of the Row where the erosion has occurred however, a grassy water way does exist west and south of the above water body which may have been part of the water way that was said to have been removed.  Issues added to punchlist to be completed when weather permits. Pending.	Pending
10/27/2009 106	106	IL-MO-100.S03	Fence is loose; corner posts needs reset.	Sent it to the Ag inspector to get it added to the punch list.	Pending
11/26/2009	179.5	IL-MU-020.000	Crop damage and access road damage claims that have not been addressed. She was led to believe she would have had more contact with REX than she had.	Bid requested to repair drive - Added to Punch List. Pending.	Pending
12/7/2009		170.5 & 1 IL-MC-115.000 & 116.000	LO states he has drainage issues. He would like to talk about them and he also wants a map of the tile lines on his property as promised.	Field Agent contacted L/O and has scheduled an appointment/inspection with L/O for next week -12/14/09. pending.	Pending
11/17/2009 216	216	IL-ED-006.000	Water along the pipeline where it was dug up - probably a broken tile line.	ROW and EI have pending appointment to investigate issues. Pending.	Pending

Date	Mile Post Tract	Tract	Description	Resolution	Status
11/2/2009 233.3		П-ЕD-072.000	Call placed by LO husband - timber needs to be planted. There are mud holes on property. He wants to be compensated for work he did (picked up trash etc). Crew got off ROW.	11/11/09: ROW made appointment to meet with LO next week to review concerns and pay settlement for work performed.  Trees have been planted. Other issues pending.	Pending
12/20/2009 206		IL-DG-110.000	Crop loss and tile damage causing flooding.	12/21/09 - REX Rep. spoke with L/O. REX will coordinate an investigation with EI and field agent to review the status of tiles. Field Agent to pay crop loss after 1st of the year. Pending.	Pending
12/3/2009 259.5		IN-PE-069.000, 70, & 71	Field contours need to be restored to pre-construction condition.  Also, there is significant erosion in the pipeline ROW. LO has attempted to resolve the matter with the REX. REX has not provided a timeframe for resolution of his concerns.	After receipt of LO estimate 11/21/09 Kinder Morgan and REX agreed that an El should review this tract and see what was required to restore the ROW per FERC requirements (This issue was added to the Punch List). The estimate was high, and it would require El concurrence as to work required to be done. Before the estimate could be agreed upon REX would also require assurance if it was paid to the landowner that the work	Pending

	1					
Date	Mile Post	Tract	Description	Resolution	Status	
11/16/2009 269		IN-PU-013.N01	Not able to find property lines. Fence needs to be installed but can not be installed until property lines are surveyed.	Spoke to this LO today, just prior to him calling the hot line: Told LO that REX survey did NOT have fence shots coming across his property. They ended at his west property line.— Also said that a Certif. Survey had been ordered and it was my hope that this would be done sometime this week.— He complained that he was leaving town and how could we place fence if he wasn't here to approved the location. Asked if his son would be available. He asked, was REX going to pay him to work with me. REX said NO. We would go with the Certif. Survey and agent would be on site with them the day of the survey.—— Also said because there were no prior shots REX would be looking specially for evidence of old fence on entry and exit points of the easement.— He said there would not be any, because REX removed it all.— ROW advised not off ROW and that is where REX would be looking for evidence of existing fencing.—— He was not happy when we ended conversation. Pending.	Pending	
11/13/2009 243.5		IN-VE-016.000 & TAR	Unfinished restoration work.	Received Written Bid from Lubovich Excavating to correct all items listed above as an estimate only. Field Agent submitted this to REX management as also delivered copy to John Davern on 10-31-09 LO informed Field Agent that he has 2 additional washouts that are NOT on the Lubovich bid. Field	Pending	

Status	Pending	\$	Pending
Resolution	LO wants compensated for a sign off. It was Explained REX position was that the West waterway would be placed on the construction punch list and would be re-shaped, re-seeded and mulched. However it is felt after review that the rock on the access road is adequate and that the East waterway was adequate; and that there is no evidence of silt in the pond due to the construction. Landowner told Field Agent this was NOT acceptable Appointment set for Tue 11-10 for on site meeting with LO and REX management. 11/10/09 10am Kinder Morgan and REX management. 11/10/09 10am Kinder Morgan and REX met with LO to review his concerns. LO's demand has been payment for a full release. Kinder Morgan discussed that work for both waterways might be warranted and asked if LO would check with his excavator (because LO does not want REX to continue with work on punch list) to present a written bid for the work LO wants.—Asked if he would try to have it come in below his prior verbal demand.——Awaiting the written bid.	Update: 12/11/09 - Hand Delivered REX Tile Maps to L/O. L/O stated that he is still trying to get an outside tile bid and would advise Field Agent as soon as it is received. Pending.	El and ROW met with Landowner. Issues were added to Punchlist to be completed weather permitting. 12-08-09 Conveyed to FERC Enforcement Officer that final grade and reseeding will need to be conducted in the spring 2010 along with the elimination of slope breakers. No evidence of silting had been observed by REX El and all crops have been harvested. Pending.
Description	Silt in pond, two waterways not restored, one needs constructed, dirt removed that was not put back; roadway needs white rock base put back; drive to "old house" needs more rock.		Insufficient silt containment on easement boundaries. Sedimentation remaining in a pond on property. Temporary fencing and posts not cleaned up/properly disposed of. Unsatisfactory final grading/restoration.
Tract	IN-PE-039.000	* - 4* *	IN-JO-228.000 & 228.501
Mile Post	253.5		323.0
Date N	10/26/2009 253.5		12/1/2009

it Tract	Description	Resolution	Status
IN-SB-221.000	Owner called today which was a follow up call from the previous day. His complaints were: 1. The top soil is being mixed with the other soils and piled together. 2. The construction crews are walking and parking on the pile of topsoil and the water is causing the soils to run together. 3. Owners property is split by the right of way and he wants to cross it and REX are welding pipe. 4. We have worked as much as 30 feet off the right of way.	Our Field agent, ROW Manager and the inspectors have worked together to resolve issues as they arise and will continue to do so. The owner does not want our lead agent nor our field agent to resolve issues but we hope that will become acceptable as we have sent a number of people to that site. 1/23/09 our field agent called today to say they had moved the top soil pile further away from other contaminates and opened the line of pipe so the Owner could access his field across our right of way.	Pending
		10/14/09 update: All dirt work, seeding, and mulching of the property is now completed.	
		Update: 12/11/09 - When weather allows and a restoration contractor is in place, and an exact scheduled better known, REX is committed to:  Check on replacement fencing and correct any problems, adding possible H braces and possibly installing additional gates to allow the LO to access cultivation field with farm equipment and avoid LO making special arrangements to reach cropland and pasture this coming season.  Check on Berms, Erosion control devices, and remove straw bales, stakes, and black plastic fencing prior to planting season. It is preferred to allow these to	
·		remain until spring to minimize any further erosion.  Check on all areas that have been reseeded for germination and reseed or pay to have reseed the area of the pasture where LO has concerns that possibly the wrong type of seed has either drifted or was incorrectly planted in an area disturbed by REX. Also review to determine if any further grading will be required. Will have land agent, check directly with the LO prior to conducting any work and also to advise as to REX restoration schedule. Pending.	

Mile Post

Date

12/22/2009 343

Date	Mile Post	Tract	Description	Resolution	Status
11/17/2009	382	IN-FR-019.S02	Topsoil and erosion issues at WB bank.	Update: EI - NO Top soil was taken from LO's field. The bare area in his field is the area where the subcontractor regraded the ROW to take care of ponding issues.  12/11/09 Although the Lead EI considered the effort made by REX contractors in Nov. as successful, FERC monitor viewed the mitigation measures as not acceptable on the west side of the river. REX will discuss with Chief Environmental Inspector and LEI to determine and re-evaluate what has worked and what still is required and schedule a meeting if necessary with FERC, REX, EI's, Field Agent and LO. Before any entry onto the property, REX will notify the LO family. Pending.	Pending
12/16/2009 390.5	9 390.5	IN-FR-085.N01	LO called the KM Hotline but left no reason for the call.	Pending additional calls/contact. Pending.	Pending
11/17/2009	399	IN-FR-153.S01	Problem with a leach line. Black water coming out of it.	ROW closed this easement and worked with him during construction. The septic lateral lines were in the travel lane and Top soil dirt storage area.—He states they are laying wet, where the lines were always dry before construction.— He has noticed this in the last few months.——ROW inquired about a local professional that could give an opinion and estimate if needed.—He said he would call one from Brockville, IN. Also said that REX would ask a local REX rep (EI) to also drop by and investigate. Reminded him of cell number and he said he would call back when he had someone look at it from Brockville. Pending.	Pending
11/6/2009	99 422.5	OH-BU-140.000	Gravel pile left on property and gravel spread all over property. 3 sink holes in woods. Took more trees out and has not been paid.	Items are still on punch list waiting to be completed as weather allows. Pending.	Pending
11/5/2009	99 452	OH-WA-066.N03	LO wants someone to contact him to arrange for a joint site visit to review final restoration status.	11/11/09: Reviewed area with LO and told him we would look at photo's of area before we went through. He stated that we may not want to try and regrade and he would work with us on this. Told him REX would get back with him. Pending.	Pending

Date N	Mile Post	Tract	Description	Resolution	Status
10/30/2009	600	OH-CT-006.000	When Pipeline was put in it went through a valley. The valley drains to the Corp. of Engineer property. REX moved the LO dirt to Corp. of Engineer property to create a bern. The area is now about 12" lower than before. Standing water is collecting in the valley. A fence was put up between the property and Corp. of Engineers. The crew drove across the property to put up the fence and the area it is full of ruts.	ROW: This was discussed in our contractor morning meeting and added to the contractor punch list. In our meeting with LO, it was explained that as soon as it was dry enough we would get in and fix the transition and rut's. Called LO 10/29/09 @ 4;40 p.m. and discussed matter with her and she understands that we needed to wait until it dries a little. Pending.	Pending
_	11/21/2009 536.5	OH-FF-077.000	LO showed a tile problem to REX reps two weeks ago and LO has not had problems addressed.	Pending appointment/investigation.	Pending
11/27/2009	538.5	OH-FF-083.000	LO reports a bridge was washed out and he requested it to be replaced before deer season. The repair has not been made.	Appointment ROW & EI to address issues with L/O set.	Pending
11/10/2009	233	OH-FF-050.000	Dike or dam was built on each side of the creek (berm). This has created wet lands on field that is farmed.	ROW Agent notified the Lead Environmental Inspector of the complaint. Pending.	Pending
11/27/2009	509	OH-PW-050.00 & TAR	Driveway problems. Wants ROW agent to call him.	Field Agent spoke with LO and addressed his concerns, and assured him that we have added his issues to the construction punch list and the areas will be repaired. He agreed. Pending.	Pending
10/23/2009	518	OH-PW-093 and 095	Pile of dirt in field needs removed.	Added to punchlist. Pending.	Pending

Mile Post	Tract	Description	Resolution	Status
ОН-РО	OH-PW-013.000	Issues with restoration have not been resolved.	Michaels will reseed areas in the week of 10/26, weather permitting, spread clean-up will be completed within 2-3 weeks and at that point, Michaels will come back to landowner's property and repair grade work along with removing excess rock. This information was discussed with landowner and he is satisfied with this plan of action. Pending.	Pending
OH-FI	OH-FF-095.000	No seeding has been placed; afraid it will erode.	Plan to reseed location pending weather and season or correct any erosion by spring time to have the land ready for farming.	Pending
OH-FF-0006.000	OH-FF-076.000 & 076.000	Erosion problems that have not been fixed.	EI, Utility Insp., FERC Monitor, LO, and Field Agent met onsite concerning his tract. LO agreed to keep the trench breakers in place until April 15 which is when he expects full & final restoration. LO was satisfied with the Environmental Group for placing silt fence around his pond and reinforcing it with staked straw bales which was the basis of his calls to the Hotline. LO also noted the outstanding issues with his tracts which are:  1. Completion of his concrete driveway 2. Sunken spot in driveway 3. Fence replaced 4. Rough grading and uneven 5. Reseeding pasture / pond area 6. Possible tile not repaired 7. Low grade on TAR near boundary fence line LO understood the work is still in progress and not near final completion. Pending.	Pending
он-ь	OH-PY-041.000	LO wants someone other than current ROW agent to call him regarding "quite a few problems on his farm.	Appointment to review issues with ROW, EJ and L/O 12/9/09. Pending.	Pending
OH-N	OH-MK-124.000 & 125.000	Complained that three ponds have been destroyed. Two are completely filled with mud. The pump for well that feeds from one pond had to be replaced. Has spoken to field agent but issue is not resolved. LO has thoroughbred horses and is dependent upon the ponds.	Update: 12/08/09 - Field Agent and Lead EI conducted site visit @ 10:00 am. Ponds were clear in appearance and seem to have settled out. The third pond's water level is down about 4' in appearance.	Pending

Status	Pending	Resolved	Pending	Pending	Pending
Resolution	12/16/09- Field Agent and El Inspection - Ruts in pasture added to punch list. Agent to mail pictures back to L/O. Flood gate - no action required, Fence Missing - added to punch list, Gate smaller - no action required. Debris on Creek Bank - added to punch list for cleanup. Settling of Drive - added to punch list. Payment for grain and hay made in prior damage up front payment. Potential Slippage and Erosion of knoll - no action required. Sediment in creek - no action necessary. Potential problems with well - no action recessary no visible problems. Access to field - no action required was given access throughout construction. Gravel for remainder of driveway off ROW - no action required. List added to spread punchlist on 12/23/09. Pending.	12/16/09 - ROW settled claims and obtained a DCV to resolve these issues. Resolved.	LEI said waterbar in an area can be removed. Area will be backbladed to knock down ruts. Currently too wet for work. Pending.	12/16/09 - Field Agent met with L/O for inspection. Advised L/O that rocks over 3" will be removed in spring 2010 will also inspect the yield in seeding in Spring. If it is necessary it will be reseeded in the spring. Advised L/O that he would have gotten the mulch from the chipped limbs and stumps if it had been in the agreement and reminded the L/O that trees and rocks were set off the side of the ROW for his use. Pending.	From Field Agent 12/03/09 - L/O states that 2 p/l corners have been removed as well as a p/l fence. Surveyors marked the only corner they found missing, ROW has made arrangements with the contractor and survey team to meet with Mr. Jenkins who is an absentee I/o when the contractor returns after 12/08/09. LO is satisfied with arrangements. Pending.
Description	Ruts and rocks. Pictures of property not returned. Flood Gate not stable. Part of fence is missing and lacks stability. Gate along the driveway is not the same as the original. It is smaller. Debris left from trees cut down. Settling in driveway.  12/11/09 - Have not received payment for hay and grain for the additional 3 months of construction. Potential slippage and run off problems due to the contour of the knoll. Sediment and silt in the creek. Potential problems with well. Currently having it tested and will re-test it in the spring. Ruts are filled with water affecting seeding. Not able to access field (due to REX activities on ROW) to cut and seed it. Vehicles not able to navigate driveway.	Complaint of dust and mud slide damage at off-line property.	Has issues to discuss with land agent.	Rocks exceeding 3" in diameter remain on property. Seeding process was not in executed according to agreement. Stumps, limbs and trees were burned instead of being chipped as per agreement. Watering of seeding was not executed in accordance with agreement.	Comer survey stakes are not there and fencing is gone.
t Tract	OH-MK-003.000	Offline	OH-GN-057.N01 & 058.000	OH-GN-103.000	OH-GN-130.000 & 137.000
Mile Post	566.5			- 605	019
Date	11/16/2009	6/17/2009	11/25/2009	12/14/2009	12/3/2009

Date	Mile Post	Tract	Description	Resolution	Status
10/16/2009	632.7	OH-BI068.000	Construction disruption of a spring and pond.	We have ripped LO's ROW per our mitigation agreement and one additional time. We had a crew picking up rock for 2 days. LO has not responded to an offer presented to him as to him building a pond. Have had several bids from contractor's, and LO insists on building it himself or providing labor and equipment if another contractor builds pond. In addition Lead El has spoken to LO and explained our process of restoring his property as to mitigation agreement. LO has demanded we use a shaker process to filter his soil before topsoiling, Informed him that was not required per our agreement. Further assured him if there was rock present in the spring we were required to remove them. He remains unsatisfied.	Pending
				12-03-09 - LO refused the offer by REX to settle this issue and has requested payment to rebuild the pond.	
11/6/2009	632.5	00-81-068.000	LO crop ground is full of rocks. Top soil is thin. Subsoil was replaced with rock. Spring was cut and there is no water in his pond for livestock. Spring box is broken.	We have ripped LO's ROW per our mitigation agreement and one additional time. We had a crew picking up rock for 2 days. LO has not responded to an offer presented to him as to him building a pond. Have had several bids from contractor's, and LO insists on building it himself or providing labor and equipment if another contractor builds pond. In addition, Lead El has spoken to LO and explained our process of restoring his property as to mitigation agreement. LO has demanded we use a shaker process to filter his soil before topsoiling, Informed LO that was not required per our agreement. Further assured LO if there was rock present in the spring we were required to remove them. He remains unsatisfied.	Pending
				12-03-09 - LO refused the offer by REX to settle this issue and has requested payment to rebuild the pond. Pending.	
10/23/2009 627.7		OH-BL-042.000	Sowed wrong seed; rocks pushed into meadow off-ROW; water draining onto adjacent property now; rocks needed at culvert.	ROW has made several calls. LO wife took message. Will continue to contact to make an appointment. Pending.	Pending
10/26/2009	618.5	ОН-ВК-004.000	Fence not repaired right; Crews removed a section that should not have been touched.	Fence has been repaired to edge of ROW. Original fence not on P/L. L/O not satisfied however survey is correct. P/L discrepancy; making arrangements with surveyors to meet with property owner.	Pending

Application	Spread A-1  II-PK-124.502  MO-AU-134.000  MO-AU-136.000  MO-AU-136.000		ľ	CONSCI	Date Complete
Rebait offich in fan  Pick rock Check lenraces for Check lenraces for Check terraces for Repair existing roces Repair existing necess Repair existing rocess Repair existing rocess Repair existing rocess Check terraces for Check for rockin and che Pick rock and che Pick	IL-PK-124.502 MO-AU-134.000 MO-AU-136.000 MO-AU-138.000		1.14 元 · · · · · · · · · · · · · · · · · ·		
Check terraces to Check terraces to Check terraces to Check terraces to Repair existing roc Repair existing roc Repair ditch Check terraces fo Check terraces for and the Repair ericsion; re	MO-AU-134,000 MO-AU-136,000 MO-AU-138,000		ď	ch in fan	
Check terraces for  Check terraces for  Pick rock  Pick rock  Repair existing rocess  Repair ercsion and repert ferrace for  Check terraces for  Repair ercsion; re  Repair ercsion; re  Repair ercsion; and Repair ercsion; re  Repai	MO-AU-136.000		2	ck rock	
Check terraces for  Repair existing rock Pick rock Pick rock Repair existing rock Repair existing rock Repair existing recess to Repair ditch Check terraces for Repair erosion; re Pick rock and che Pick rock and c	MO-AU-138.000		5	races for	
Pick rock Remove detrifs Repair existing for Repair existing for Repair ditch Check terraces for Check terrace for Check			Ö	-	
Remove debris Repair existing rog Check terraces for Repair erosion; all Re	MO-AU-140.000		ř.	ckrock	
Repair existing rocess Repair existing rocess Repair existing rocess Repair existing rocess Repair ditch Check terraces fo Check for took Pkk rock and che Check terrace for Check terrace and che Pkk rock and che	MO-AU-141.000		<u>a.</u>	CK POCK	
Repair existing ros Repair existing ros Repair ditch Check terraces for Repair erosion; re Repair erosion; re Repair erosion; and Check tock and che Pick rock and che Check terrace for Check terrace and che Pick rock and	MO-AU-156.000		Ř	этоуе дерлів	
Repair existing rose  Researching necess Researching necess Researching necess Repair dritch Check terraces for Repair erosion; and che Pick rock and che Check ferrace for Check ferrace and che Pick rock and che Pic	MO-PI-007 N01		až i	epair existing road	
Repair of the Repair erosion of Prock terraces for Check for row sport repair erosion; at Active Check for rock and che Pick rock and che Pic	MO-PI-009.000		Ž.	spair existing road	
Repair ditch Check terraces for Check for box snd dree Pick rock and dree Check terrace for Check for cock and che	MO-PI-010.000		ď	seeding necessary	
Check terraces to Repair erosion; re Check for rock Pick rock and che Pick rock and che Pick rock and che Check terrace for check for	000.110-14-0M		2 0		
Check terraces for Check for low spot in the Check for low spot in the Check for low spot in the Check for mock and other check for mock in the Check for mock and other c	MO-FI-021.000		Ö		
Check terraces to Check tond for profit of pro	MO-PI-023.000		O	neck terraces for possible recontour	
Check tond for px  Repair drain tile Check terraces for Check tor tow spot in a page in erosion; selection in the control of the control	MO-PI-025.000		Ō	neck terraces for possible recontour	
repair drain tile Check terraces for Check for tow spot repair erosion; repair erosion; repair erosion; repair erosion; repair erosion; repair erosion; repair force Check for tow spot repair force Check for took and check for took, repair erosion repair existing road prick rock and check for took, repair erosion for Check for rock, repair erosion for Check for rock, repair erosion for Check for rock and check for took and check for force and check for force and check for force and check for rock and ch	MO-PI-026.000		Ö	의	
Check terraces to Check terraces to Check terraces to Repair erosion an Repair erosion; re Repair erosion; r	MO-PI-027.000		2		
Check terraces to Repair erosion; all Repair erosion; all Repair erosion; te Pick rock and che Pick rock and che Pick rock, repair te Pick rock and che Check terrace for Pick rock and che	MO-PI-028.000		O	heck terraces for possible recontour, repair drain tile	
Repair erosion; all Repair erosion; all Repair erosion; all Repair erosion; to a sepair erosi	MO-PI-029.000		0	heck terraces for possible recontour, repair drain tile	
Repair erosion; si Repair erosio	MO-PI-032.000		Y.	epair erosion area	
Repair erosion; re Repair erosion; re Repair erosion; re Repair fence Check for low spo Repair erosion Repair fence Check for low spo Repair erosion Repair fence Check for cock Pick rock and che Pick rock and che Pick rock, repair et Pick rock, repair et Check ferrace for Check for rock and che Pick rock and che	MO-PI-034.000		2	ppair erosion; silt fence removed	
Repair erosion; re Repair erosion; re Repair erosion; re Repair erosion; re Repair erosion Repai	MO-PI-034.N04		<u> </u>	apair grosion; reseed; silt fence removed	
	MO-PI-036.000		<u>«</u>	apair erosion; reseed, landowner wants water bars and silt fence removed	
	MO-PI-037.000		ά.	opair erosion; reseed, landowner wants water bars and sit fence removed	
	MO-PI-038.000		ď	epair erosion	
	MO-PI-041.000		92	pair fence	
nepair existing no Additional grave I Pick rock Pick rock and che Pick rock and che Pick rock and che Pick rock in and che Pick rock, repair a Pick rock, repair a Pick rock, repair a Pick rock, repair a Pick rock ferrace for Check forck and che Pick rock and che	MO-PI-042.000		S	heck for kow spots and possible re-grading and re-seeding; repair fence	
Additional gravel r Pick rock Pick rock Pick rock and che Pick rock and che Pick rock and che Pick rock and che Pick rock, repair a Pick rock, repair a Pick rock, repair a Pick rock ferrace for Check forck and che Pick rock and che	MO-PI-052:N01		2	pair existing road	
Pick rock Pick rock and che Pick rock and che Pick rock and che Pick rock and che Pick rock, repair e Pick rock and che	MO-PI-055.000		¥	ditional gravel needed on existing road	
Pick rock and che Pick rock and che Pick rock and che Pick rock and che Pick rock, repair o Pick rock and che	MO-PI-063.000			CK TOCK	
Pick rock and drie Pick rock and drie Pick rock, and drie Pick rock, repair o Pick rock and drie	MO-PI-064.000			CK TOCK	
Pick rock and dhe Pick rock and dhe Pick rock, repair e Check ferrace for Check ferrace and check for rock and check ferrace for Check for for ferrace for Check for for ferrace for Check for for for ferrace for Check for for for ferrace for ferrace for ferrace for for for for for for for for ferrace for	Onn Sept - OM			ck rock and check for re-seeding	
Pick rock and che Pick rock, repair e Pick rock and che	MC-PI-U65.NUT			ck rock and check for re-seeding	
Pick rock, repair of Pick rock and of Pick rock an	MO-FI-U00 U00			ck rock and check for re-seeding	
Pick rock, repair a Pick rock, repair a Pick rock for reck is pair a Check ferrace for Check for for and check ferrace ferrace ferrace for Check ferrace for Check ferrace for Check for for ferrace fer	000 000 IG CM		<u> </u>	ok rock and check for re-seeding	
Pick rock, repair to Check for rock, repair to Check ferrace for Check ferrace ferrace for Check ferrace	140 PIO DE OCO			Co Loca, legal at oscil, attest for a second at the second	
Check for possible Check terrace for Check terrace and che Pick rock and che	000.000.000			ok lock, lebal blostor, dreck til te-sebuing	
Check terrace for Repair driveway Pick rock and che	MO.PLO72.000		<u> </u>	ock Tock, pages 1998 to 1, care of Kir 19-seeing	
Check terrace for Check for and che Pick rock and che	MO-PI-074 000		3 (	TECN TO TOOSINE TESTED AND THE THIRD TO THE TESTED AND THE TESTED	
Check for the control of the control	MO-PI-075,000		0		
Repair driveway Pick rock and che	MO-PI-075.000TAR				
では、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、一般などのでは、	MO-PI-078,001		Ř		
では、一般では、一般では、一般では、一般では、一般では、一般では、一般では、一般	MO-PI-082.000		H.	ck rock and check for proper decompaction	
(1) (1) (2) (2) (2) (2) (3) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	MO-PI-091,000		<u>H</u>	ck rock and check for proper decompaction	
(1) (1) (2) (2) (2) (2) (3) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	MO-PI-091,000TAR		ä	ck rock and check for proper decompaction	
	MO-PI-091.000TAR2		<u>E</u>	ck rock and check for proper decompaction.	
	MO-PI-092.000		ä	ck rock and check for proper decompaction	
	MO-PI-092.000TAR		ď	ck rock and check for proper decompaction	
	MO-PI-094.000		ā.	ck rock and check for proper decompaction	
	MO-PI-094.000TAR		ä	ck rock and check for proper decompaction	
	MO-PI-096.000		P	ck rock and check for proper decompaction	
	MO-PI-098.000	27701	ď	ck rock and check for proper decompaction	
	Spread A-2		\$100 CO		The second secon

	6 9/2	Phank for toneral for-	
	74.3	Check for toosoal loss	
	74.4	Check for toosol loss	
	74.7	Check for toosoi lose	
	75.0	Repair erosion	
	76.0	Check drain tile out-flow	
	76.2	Repair erosion	
	76.2	Check erosion	
	76.4	Check slump west of road	
	76.8	Check ECD @ outflow of drain exiting ROW	
	6.92	Check ECD at outbow of drain exiting ROW	
	77.9	Repair erosion	
	80.5	Check ECD at drain tile outflow	
The state of the s	81.2	Check erosion	
	81.3	Check slump	
	82.9	Check slump	
	87.5	Check top-soil loss from Ag field; reseed if necessary	
	87.5	Check drain tile outlet @ outliow	
	87.7	Check for top-soil loss from adjacent Ag field; check ECD at drain tile outlet	
	94.0	The second of th	
	87.8 90.6	Chapter and Chapte	
	03.0	Charle water hars	
	V C00	Check water bare	
	0.00	Check EChe	
	07.0	Chark slimm	
	93.1	Charles Jumn Benair Water har faiture	
	0.00	Chack drain file arthat	
	033	Remove debris	
	92.5	Check ECD at drain tile mater	
	25/2	Check waterbar	
	3 7	Check ECD @ crain tile outles	
	979	Chack waterhar for house	
	2 170	Spring Transity Control of the Contr	
	7 76	Check drain the outer	
	7 76	Renair waterbar	
	7	Repair waterbar and emston	
	098	Repair erosion	
	92'6	Repair water bar	
	8.56	Repair Erosion	
, .	95.9	Check slopes for erosion	
	0.96	Repair water bar	
	96.2	Repair erosion	
	9.96	Repair water bars	
	9.96	Repair water bars	
	99.2	Repair erosion and water bars	
	99.2	Repair erosion and water bar	
	99.3	Remove silt deposition	
	99.3	Repair water bars	
	99,4	Repair water bars	
	99.4	Repair water bars	
	99.4	Kepair Erosion	
	9.66	Repair erosion	
	9.66	Kepair erosion and water bars	
	7.66	Oneck erosion	
	7.66	Check erosion	

	100.9	Repair erosion	
	101.0	Repair erosion	
	101.4	Repair erosion	
	101.5	Repair erosion	
	123.2	Check for low spots and possible regrading	
	123.5	Check for low spots and possible regrading	
	123.5	Check for tow spots and possible regrading	
	123.7	Check for low spots and possible regrading	
	141.2	Muchole on ROW. AG El advises looks like tile problem. LO ok with Spring repair.	
	142.2	Repair terraces	
	The said of the said	上,这个时间,他一天就就一个时间,这个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一	A COMMAND AND AND AND AND AND AND AND AND AND
GAS Rd 1	144.8		
GAS Rd 2	145.1	Put nock on field entrance	
GAS Rd 4	147.5	Check for possible additional re-seeding	
GAS Rd 6	149.2	Check for possible additional re-seeding	
CIS Rd 7	150	Check possible tile or grading problem 7920+87 and check for possible additional re-seeding	
CIS Rd 8	150.6		
GAS Rd 8	151.4	Check for possible re-seeding	
CIS Rd 9	151.8		
GAS Rd 9	151.9	Check for possible re-seeding	
GAS Rd 10	152.5		
CIS Rd 11	153	Rebuild barm on CIS Spring Creek and repair erosion	
GAS Rd 11	153.6	Check for possible re-seeding	
GAS Rd 14	155.8	Pick up rocks west of trees on ROW 8216+00	
GAS Rd 15	156.5	Shape, seed and mulch waterway, (several ditches) 8284+00	
GAS Rd 15	156.6	Seed and mulch 30' wide strip 8282+00	,
Rd 15 to Rd 16	156.4-157.6	Grass waterway needs to be seeded, mulched and crimped, station 8264+00.	
CIS Rd 17	157.8	Shape, seed and mulch dirch 126 wide 8321+78	
GAS Rd 17	158.2	Remove SF at riser 8352+00	
1945 Rd 17	158.2	Seed and mulch waterway 8353+20	
CIS RG 20	108.8	I KRE GOOD STORY OF HWYST 64-30-90	
CIS Rd 21		Law.c.vol. Argust ensoin	
200 M2	181.4	Charles and anealists on acciding	
GAS Rd 21	161.5	Chart make and nessible re-seading	
CIS Rd22	161.8	Retair slove breaker	
CIS Rd 22	161.6	Check grade and possible re-seeding	
CIS Rd 22	161.8	Check grade and possible re-seeding	
GAS Rd 22	162.1	Check grade and possible re-seeding	
GAS Rd 22	162.6	Repair erosion	
CIS Rd 23	162.9	0.55	
CIS Rd 24	163.9	Retrieve, silt off ROW. Check grade and possible re-seeding	
CIS Rd 25	164.3	Check for possible tile or grading problem	
GAS Rd 25	165	Check for possible re-seeding	
GAS Rd 25	164.99	Needs two short fences across ROW replaced, 8717+92 and 8708+06 (approx.)	
CIS Rd 27	166	Check for possible tile or grading problem 8789+00.	
CIS Rd 27	166.9	Check for low spots and possible regrading	
CIS Rd 28	167	Seed and mulch grass strip, MP 166.7, sta. 8799+35 to 8800+00.	
CIS Rd 29	168	Raise berm at property line, shape reseed and mulch waterway from property line to yard 8668+00	
CIS Bd 30	168.9	Requireflich in field and mad between tracks 8014-70	
Rd 33	1712		
	4 707	True actor to the second secon	

	GAS Rd 33	171.4		
	GAS Rd 35	172.2	Pick up skids and boards buried to 200' up ROW 9089+00	
	GAS Rd 36	174-174.3	Seed and mulch waterway	
	GAS Rd 37	174.4	Check grade	
	GAS Rd 37	174.5	Fix ditch beside drive and seed 9215+55	
	GAS Rd 37	174.8		
	CIS Rd 38	174.9		
	CIS Rd 39	175.5		
	GAS Rd 39	176	Repair erosion	
	GAS Rd 39	176.7	Check for possible tile or grading problem 9328+11	
	CIS Rd 40	177.2	Check for possible tile or grading problem 9358+00	
	GAS Rd 40	177.7	Check for possible tile or grading problem 9365+00	
	GAS Rd 40	177.8	Pick up rocks on ROW 9377+60	
	CIS Rd 41	178.7	Repair erosion	
	CIS Rd 41	178.9	Repair drain tile	
!	CIS Rd 41	178.9		
	[GAS Rd 41	179.4	Check for possible tile or grading problem 400' W of drive 9466+94	
	CIS Rd 42	180.1	Check for possible tile or grading problem 8512+69	
	CIS Rd 43	181	Check for possible lile or grading problem	
	GAS Rd 43	181.4	Check grade	
	GAS Rd 43	181.5	Check for possible tile or grading problem 9591+53	
	GAS Rd 43	182	Check grade	
	CIS Rd 44	182.6		
	GAS Rd 44	182.6		
	GAS Rd 44	182.9		
	GAS Kd 44	183	Check for low spots and possible re-grading	
	CIS Kd 46	183.9		
	CIS Rd 46	184.1	Possible ble or grading problem 9722+00	
	Cio no 40	7.407	Crieda or Spots and possible re-diagoning	
	CAS NO 40	U.404.U	Crossine we or grading problem by 1048 9/4424U	
		2	Chass faire freeds to de secues and muches (mr. 102), statuti 3/03/10). Fick up tash by market note.	
	GAS Rd 46	184.9	k for low	
	CIS Rd 47	185.5	Check for low spots and possible re-grading. Grassy waterway needs restoration (MU-041) 9780+00.	
	O A S D 4 47	0 00 7	Check grass lane at 9/09*10 for possible recomput, seed and mulch.	
	CIS Bd 50	187 0	Check of pussible tile of grading property of sortion	
	CIS Rd 50	187 0	Change stand and matter was 002/0+/0	
	GAS Rd 50	188.1	Check grade	
	GAS Rd 50	188.2	Check grade	
	CIS Rd 51	188.3	Check for low spots and possible re-grading	
	CIS/GAS RD 50	187.99-188.1	After topsoil decompaction, the cultural resource sits and landowner's garden needs to be seeded and mulched 9934+70 to 9938+60, and THEN remove the safety fence around the cultural resource site.	
	CIS Rd 51	188.9	Pick up sticks and rocks first 300' from road 9973+18	
	GAS Rd 51	189.2		
	CIS Rd 53	190	Check for low spots and possible re-grading	
Spread C				
	CIS WB-193-BBB	193.6	Repair tile	
	590Gas	193.7	Repair tile	
	Rd 590 Burbon GAS	193.9		
	Rd 800 CIS	195.8		
	Rd 800 GAS	196.3		
	900 Gas 10389+78	196.8		
	Hwy 57 Cis	198.8	Check for low spots and possible regrading	

1276 GAS   WB-199-A CIS   WW-199-A CIS   Hwy 130 CAS   1675 CIs   1965 Cas	201.2 203.6 203.6 203.6 203.6 204.7 204.7 204.7 208.4 210.8 211.8 213.2 213.2 213.3 219.9 222.6 222.6 222.6 222.6 222.6 223.3 228.3 228.3 228.3 228.3 228.3 228.3 228.3 228.3 228.3 228.3 228.3 228.3 230.4	Regalr subsidence area Check erosion Check for low spots and possible regrading	
WB-199-A CIS		Sheck for low spots and possible regrading	
Hwy 130 Cis Hwy 130 Cis 1675 Cis 1966 Cis 1966 Cis 2360 Cis 2360 Cis 2360 Cis 2360 Cis 2510 Cis 2510 Cis 2510 Cis 500 GAS 500 GAS 500 GAS 500 GAS 1725 Gas Hwy 150 Cis Private drive 11991+3 Hwy 150 Cis 775 Cis 775 Cis 775 Cis 775 Cis 775 Gas 1775 Gas 1775 Gas 1775 Gas WB-235-AAA W5005 E 5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W50005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W50005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 W50005		Theck for low spots and possible regrading	
HWY 130 GAS   1675 CIs   1965 CIs   1965 CIs   2360 C		Check for low spots and possible regrading Theck for low spots and possible regrading Theck for low spots and possible regrading Theck for low spots and possible regrading	
1675 CB		Areck for low spots and possible regrading  Aleck for low spots and possible regrading  Aleck for low spots and possible regrading	
1965 Cis 1965 Cis 2360 Cis 2360 Gas 2360 Gas 2360 Gas 2510 Cis 2510 Cis 2510 Cis 500 GAS 500 GAS 500 GAS 500 GAS 500 GAS 500 Cis 1725 Gas 1725 Gas 1775 Gas		Aleck for low spots and possible regrading	
1965 Gas 2065 Cis 2360 Cis 2360 Gas 2360 Gas 2360 Gas 2510 Gas 2510 Gas 2510 Gas 2510 Gas 170 Gas 1725 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve Access Road to valve E500 GAS WB-235-AAA WB-235-AAA WB-235-AAA Silles Rd. W5005 E5005 W5005 W5005 W5005 W5005 W5005 W5005 S250W		ATTACK TO TOWN STORE STORE THE THE THE TOWN THE	
250 GAS 2360 Cis 2360 Cis 2360 Cis 2360 Cis 2360 Cis 2510 Cis 275 C			
2000 Cis 2360 Gas 2360 Gas 2360 Gas 2510 Cis 2510 Gas 2510 Gas 500 Gas 500 Gas 500 Gas 175 Cis 1725 Gas 1775 Gas 1776 Gas 1777 Ga			
2560 Cas 2360 Cas 2360 Cas 2360 Cas 2360 Cas 2510 Cas 2510 Cas 2510 Cas 2510 Cas 2510 Cas 2510 Cas 575 Cas 700 Cas 850 Cis 700 Cas 1425 Cas 1425 Cas 1775 Cas 1775 Cas 1775 Cas 1775 Cas Access Road to valve Access Road Scool S			
2360 Gas 2360 Gas 2510 Cis 2510 Cis 2510 Gas 500 GAS 500 GAS 500 GAS 500 Cis 700 Gas 850 Cis 1425 Gas 1425 Gas 1725 Gas 1775 Gas			
2510 Gas 2510 Gas 2510 Gis 2510 Gas 500 GAS 500 GAS 500 GAS 500 GAS 1725 Gas 1725 Gas 1775 Gas 1775 Gas Access Road to valve Access Road Sas W500S W500S W500S W500S S250W			
2510 Cis 2510 Gas HW-49 Cis 500 Gas 500 Gas 576 Cis 700 Gas 850 Cis 850 Cis 1725 Gas 1725 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve Access Road to valve E500 GAS W500 GAS		Check for low spots and possible regrading	
2510 Gas Hwy 49 Cis 500 GaS 500 GaS 700 GaS 700 GaS 850 Cis 1725 Cas 1725 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve Access Road to Valve Builes Rd WB-235-AAA W5005			
HWY 49 Cis 500 GAS 575 Cis 700 Gas 850 Cis 1950 Cis 1425 Gas 1425 Gas 1725 Gas 1775 Gas 1775 Gas 1775 Gas 1775 Gas 1775 Gas 1775 Gas 1775 Gas Wecess Road to valve Access Road to valve Rocess Road to valve Webook E 500 GAS Webook Webook Webook Webook Sales Valve Webook Webook Sales Valve Sales Valve Sales Valve Sales Valve Sales Valve Sales Valve Sales Valve Webook Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Sales Valve Sales Valve Webook Sales Valve Sales Valve Webook Sales Valve Webook Sales Valve Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Webook Sales Valve Sales Valve Webook Sales Valve Sales Valve Webook Sales Valve Sales Valve Webook Sales Valve Sales Val		Check for low spots and possible regrading	
500 GAS 575 Cls 700 Gas 850 Cls 850 Cls 1350 Cls 1425 Gas 1725 Gas 1775 Gas 1775 Gas Access Road to valve Access Road Sas		Repair erosion	
700 Gas 850 Cils Private drive 11991+3 Hwy 1 Gas 1350 Cils 1425 Gas 1775 Gas 1775 Gas Access Road to valve Access Road Sacon Saco		Check for low spots and possible regrading	
700 Gas   850 CIS   Private drive 11991+3   Hwy 15 Gas   1425 Gas   1725 Gas   1775 Ga			
850 CIS Private drive 11991+3 Hwy 9 Gas 1350 Cis 1425 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve Access Road to valve Access Road to Valve E050 GAS W5005			
Hwy 9 Gas 1350 Cie 1425 Gas 1425 Gas 1725 Gas 1775 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve Access Road to valve RESS Road to valve Access Road to valve RESS ROAG WESS ROAG WHE-235-AAA WESS		Check for low spots and possible regrading	
1350 Cis 1425 Gas 1425 Gas 1725 Gas 1775 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve Access Road to valve 2050 GAS WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA W500S E 500S W550S W650S W650S W650S			
1350 Cie 1425 Gas 1425 Gas 1725 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve			
1425 Gas Hwy 150 Cis 1725 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve E050 GAS WB-235-AAA Stiles Rd. W5005 E5005 W5005 W5005 W5005 W5005 W5005 W5005 W5005 S250W			
1425 Gas Hwy 150 Cis 1725 Gas 1775 Gas 1775 Gas Access Road to valve E050 GAS WB-235-AAA N5005 E5005 W5005 W5005 W5005 W5005 W5005 S250W		Renair substances area	
Hwy 150 Cis 1725 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve 2050 GAS WB-235-AAA WB-235-AAA W500S E 500S W500S W50S W50S W50S W50S		Add sinne breaker British and research	
1775 Gas 1775 Gas 1775 Gas 1775 Gas Access Road to valve Access Road to valve 2050 GAS WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA WB-235-AAA		Ъ.	
1775 Gas 1775 Gas Access Road to valve 2050 GAS WB-235-AAA WB-235-AAA WB-235-AAA W5005 E 5008 W5508 W4005 S250W	T	Carbon IVI INV Spots and possible regularing	
1775 Gas			
Access Road to valve Access Road to valve 2050 GAS WB-235-AAA Silles Rd. W500S E 500S W500S W500S W500S W500S W500S S250W	Ī	Nepall Brosin	
Access Road to valve  Access Road to valve  2050 GAS  WB-235-AAA	Ī	repair drain the	
Access Road to valve 2050 GAS WB-235-AAA WB-235-AAA Silles Rd. W500S E 500S W500S W500S W500S W500S W500S S250W	233.8	JACK for low spots and possible regrading	
2050 GAS WB-235-AAA WB-235-AAA Silies Rd. W500S E 500S W560S W400S S250W	233.8	Repair erosion	
WB-235-AAA WB-235-AAA Siles Rd. W5005 E 5005 W4005 S250W	235.3	Chack for cosethle consoline	
Stiles Rd.   Stiles Rd.   W5005   E 5005   W4005   W4005   S250W			
Silles Rd. W5005 E 5005 W6005 W6005 W6005 W6005 S250W	2,252	VETOR HOSEUIT	
3	Ī	albumi permenent iner erutance and chean out hero unca	
	6		The second secon
W500S E 500S W560S W400S S250W	304 50	Rebair and continue waterhar on west side of McCracken Creek	El verified work not reeded.
E 500S W550S W400S S250W	T		Complete 11-13-09
W550S W400S S250W		ays, disk travel lane	Complete, LO sign off
W400S S250W			Complete 11-13-09
\$250W	295.50		Complete 11-13-09
	Γ	V side of road	Entrance needs moved,
S450W	Γ		Complete 11-13-09
8450W	Γ		Estimated completion 01/09/2010
800W	Γ		Estimated completion 01/09/2010
Mustang Access Rd	284.40		Estimated completion 01/09/2010
Pum Creek	Γ		El verified work not needed,
400W			El verified work not needed.
725W to Byrd Branch			Complete 11-05-09
WB-th-263-C	266.70	90	Complete 11-13-09
550 Rd. Little Raccoon		d repair erosion on hill, east side of Little Raccoon Creek.	Complete 11-12-09
	259.50		El and ROW Investigating prior to final resolution
	ľ		Complete 11-12-09
80E		83	ROW has sign off 9-29-09, no fence needed
Temporary Access Road	Ī	wilvoor	Complete 9-15-09 and 11-11-09

	West side 249-66	249.81	Checkfrepair erosion	Complete 10-13-03
	550W	249.50	Remove road access rock	Complete 10-15-09
		249.50	Prick rock	Complete 10-15-09
		249.50	Remove debris	Complete 11-09-09
	S360E	245.80	Remove debris	Complete 11-09-09
	Little raccoon	245.10	Repair E bank erosion	Estimated completion 01/09/2010
		244.70	drain tile ditch settling, N edge ROW	Complete 11-12-09
		241.96		Complete 11-12-09, LO sign off 10-28-09
		241.95	Rocks, stakes, silt fence at sink hole, settling from drain tile	Complete 9-15-09
	HWY 71	240.30	West side north corner repair ruts in ROW	Complete 10-01-09
		239.50		Complete 9-19-09
		238.30		Complete 11-12-09
	GAS E500S	243.20	Check grade of access pad and bar ditch to match flow	
			3000年代の東京の東京の東京の東京の東京の東京の東京の東京の東京の東京の東京の東京の東京の	
IN-MN-018 000			Check/repair erosion on hill side	
IN-MIN-018.000			Erosion on hill side	
IN-MN-027.001			Check erosion	
IN-MN-027.507			Check ergeion	
IN-MN-032.006			Check for low spots and possible re-grading	
IN-MN-053.S06			Check grade	
IN-MIN-061.S01			Check grade	
IN-JO-213.501			Remove temp fence	
IN-JO-227.000			Vinyl fencing replaced, driveway repair, seeding	
IN-JO-228.000 & 228.501		323.00	Silting issues, regrading issues, fenoe clean up issues.	
IN-JO-260.000			Check for low spots and possible re-grading	
IN-JO-261.000				
IN-JO-262.000			Fencing, seeding	
IN-JO-269.000			Repair water bar	
IN-10-303.000			ĺ.	
IN-JO-319.000			Repair erosion and check for low spots and possible re-grading	
IN-SB-085.000			1	
IN-SB-087.001			Remove dabris	
IN-SB-087.002			Remove debris	
IN-SB-146.000			Pick up rock	
IN-SB-147.000				
IN-SB-203.S01			Check erosion and check pond	
IN-SB-204.000			Gravel lang	
IN-SB-205.000			Grave lane, put back fence	
N-SB-206.000			Put back fence	
IN-SB-209.000			Gravel lane	
IN-58-213.000			C/3	
IN-SB-214.000			Check for low spots and possible re-grading	
IN-DC-0/3.000	800 - 600 - 000 -	TO CHARLES A SECTION OF THE PARTY OF THE PAR	Check grade	S. C. Constant of the Constant
Colego T-1	The state of the s		经营业的 1. 计通讯记录 1. 计通记录 1. 计通讯记录 1. 计通记录 1. 计通讯记录 1. 计通讯记录 1. 计通讯记录 1. 计通记录 1. 计记录 1. 计通记录 1. 计通记录 1. 计通记录记录 1. 计通记录 1. 计通记录 1. 计通记录记录 1. 计通记录记录 1. 计通记录 1. 计通记录记录 1. 计通记录 1.	A CONTRACT OF THE STATE OF THE
M ED 040 004 040 003		Spreadwide	Removal of remaining temporary ECU's spread wide.	Complete 11/8/2009
020.000			Check grade and emskin	Complete 11/2/2009
	Pipe Creek		Check for low spots and possible re-grading	Estimated completion 01/09/2010
	Salt Creek		Repair east and west banks	Complete 11/14/2009
		389 - 392	Repair erosion	Complete 11/12/2009
109.001, 110.000	Highland center Rd		Check for low spots and possible re-grading	Estimated completion 07/09/2010
129.001			Check for possible tile or grading problem	Estimated completion 01,09/2010
	Big Cedar Rd		Check for possible tile or grading problem.	Complets 11/12/2009
Section Spread Fr. 2 Inc. 1889	The second secon	のでは、中華にはいる。		
		Spread wide	Removal of remaining temporary ECD's spread wide.	Completed 44/16/00

	WB-OH-400-B to Reily Milhitle Rd.		Check grade and slope breaker	Completed 11/14/09
OH-BU-105.000			Restore grass waterway	Completed 11/17/09
OH-BIJ-140.000		. 1	Gravel pile left on property and gravel spread all over property. 3 sink holes in woods. Took more trees	
000		422.5	lout and has not been paid.	Awaiting drier conditions.
A-1-1-1-1000			CHARLE SI WAISHWAY DANKS	Completed 11/1/03
OH-WA-020.S01			Shope breaker removal on treot	Completed 11/17/09
OH-WA-024.004, 005, 001			Pick mick	Completed 11/17/09
Spread G	· · · · · · · · · · · · · · · · · · ·	N		CONTINUE TO THE PROPERTY OF TH
OH-WA-024.005		444	Pick rock (away side of Hwy 122)	Completed 12/16/2009
OH-WA-031.000		445.2	_	O109/2010 estimated zompledon
OH-WA-034.000		446.3		Complete 11-12-09
OH-WA-036.000		446.5		Forested area not required by easement or P&P
OH-WA-041.000		448		Completed 12/14/09
OH-WA-042,S01		448	Check for low area and possible re-grading	or (0) and the solutions of compatibles
OH-WA-044.000		448.3	Correct access across pipeline	Completed 11/18/09
OH-WA-063.000		451.6	Check for low spots at HDD & Bore location for possible re-grading.	C1/08/2010 estimated compation
OH-WA-066.N02		451.7	Pick rock and seed	Complete El signed off
OH-WA-073 000		452.3		LO compensated
OH-WA-075.N01		452.3	Repair erosion in back of property	Complete 11-12-09
OH-WA-084.000		454.2	Check for low spots and possible re-grading	01/05/2010 estimated completion
OH-WA-085.000		454.3	Repair erosion; correct fences; remove gravel in drive & pad; drag drive	Completed 11/24/09
OH-WA-087,000		455.2		01/04/2010 estimated completion
OH-CT-006.000		460	Re-grade ruts and trensition	Completed 11-08-09
OH-CT-007.000		460.1		LO compensated
OH-CT-027.000		463.1		Completed (2/15/09/10)
OH-CT-049.000		466.6	Gravel on drives (2) 1 part done; repair property pens	Completed (2/11/09)
OH-CT-050.000		466.7	Check for low spots and possible re-grading	Completed to 1 (d) 1 (b) to the contract to th
OH-CT-058:000		99	Add base and gravel on lane crossing R.O.W (ONE NEEDED)	(Self place of the place of th
000.100-10-10		- F04	replain property seeming	Completed 12/03/03
OH-C1-002.000		402	Repair property peris, second	Completed 12/05/08
OH-EV-005 000		477 E	Dieways dehile	Compared 11-52-08
OH-EV-013 000		480 1	Chark for low and and possible re-grading or deshall the renair	CHIPTING ALBERTA ATTICIONES
OH-FY-021 D00		484	Renace contrast market	No market needed on this tract
OH-F7-021 S02		484	Add prave in lane, replace cancrele marker	Commissed 12/03/09
OH-FY-028.S01		485.5		01/09/2010 estimated completion
Speanth				The state of the s
OH-FY-069.000	GA Knight	497		WILImonitor unitksjoring 表面包含:这是是完全是
OH-PW-002,000	GA Waterloo	500.1	Check low spot for possible re-grading; area needs smoothed where slit fence was removed at creek.	Completed 11/17/09
OH-PW-003.000	GA Waters Rd	500.4		Wall month of the Control Span Control By Co
OH-PW-026	CI 5 pts.	504.8	Waterbars on slope need reshaped, waterbars holding water, silt fence needs removed.	Completed 11/20/09
OH-PW-030.000	GA 5 pts.	505.3	Grass strips need seeded.	Completed 10/29/2009
OH-PW-35/36	GA Justus Rd.	506.2	Check low spot for possible re-grading	Will monitor until spring
OH-PW-048	GA London Rd.	508.9	ఠ	Completed 11/23/09
0H-PW-050		508	40	Will monitor and spring the second spring the second spring the second spring the second seco
OH-PW-057	Off of Darby Rd.	510	Tile repair needed, sides of access rd need seeded.	Completed 10/29/2009
0H-PW-060	Off of Darby Rd.	510.2	Area near creek needs recontoured.	Completed 11/14/2009
OH-PW-067	Cl Turney Caldwell	511.1	Gravel drive that crosses the ROW is washing, re-apply gravel and check drainage.	Completed 10/29/2009
	GA HWY Z3	515.3	Access No needs upped leading to drill pad.	Completed 11/20/09
ORD-M-HO	Ci Locabourie	47/LC	Several Sink noies, waterbar needs moved, sit tence needs removed and the work dossidie.	Completed 11/15/09

OH-PW-092 OH-PW-093 OH-PW-111			Inpeds rocked	
OH-PW-093 OH-PW-111	GA Lockbourne Rd.	517.8	Surmos need removed.	Completed 11/23/09
OH-PW-111	GA Lockbourne Rd.	518	Rocks and wood debris in field need removed; check ditch line for subsidence and re-grading	Completed 11/14/09
	CI Bloomfield Rd.	220	Sink hole Cliside of access rd, low spot at creek big rocks in field.	Will month to the spring large and a spring large a
	GA Bloomfied Rd.	520.5		
OH-PW-113			Winchester HG.	Completed 11/24/09
\$L!-W-HO	Cleti Nocher.	176	Check low spois in ag heid for regrading; access rd edges need seeded.	Completed 11/20/09
01-W+00	CI EII NOCHEI.	977.0		COMPIGNO 11/24/US
000 100 H	GA 674 HWY	524.4	Check differ for Settling/low spots and regrading	
000,100-17-10	CI Royalton Rd.	324.0	Approach rock needs removed.	Completed 11/23/08
001-11-00	GA ROYAIION FG.	9 3C3	EXISTING SECRESS TO DECRET SIND DUIL SECOSS THE TOW.	Completed 11/23/09
OH 56,12	C. Newscard Monthon	0.020	Wallsroaf repaired.	Compression 11/2 1/08
21-11-10	C. Amanda Northern	2.002	The department of DNR for desired file or coefficients	
07-11-TO	Of Pickeringer	0.520	Deneck well spot on KOW for a rain use of setting	Completed 400900000
OH-FF-30	CA Lithocolle	K21 1	Trock needs mished uhan mihat mad Troc needs mished uhan mihat mad	Completed 11/5/2009
OH-EE-74	Ci Delmbour Bd	5'36 2E	The grade and standing union.	
OH-FF-84	Cl Hwy 37	538.5	Februarissues and dravel drave needs mocked.	Completed 12/4/09
OH-FF-089.1RD	CI Old Milersport	539.5	Bardich needs fixed.	Completed 12/3/09
OH-FF-090.000	GA Old Millersport	539.6	Drain tile exposed	Completed 12/3/09
OH-FF-090.000	GA Old Millersport	536.8	WB-OH-536-FF banks need re-seeding.	Completed 11/12/2009
OH-FF-091.000	GA Old Millersport	540	Check low spot for re-grading.	WY
OH-FF-092.000	GA Old Millersport	540.3	വ	Will manke sufficient of the second of the s
OH-FF-092.000	GA Old Millersport	540.4	Erosion in upland area that needs seeded	Completed 11/12/2009
	GA Old Millersport	539.8-540.5		Completed 11/12/2009
OH-FF-094,00	GA 188	540.7		Completed 12/3/09
00.50.02	GA 188	. <u>*</u>	Check multiple low spots for re-grading; correct stope breaker holding water, recover sediment off persons.	
OH-FF-103	Cl Fider Rd	543.5	Debuts needs removal from field and bar ditch needs regraded	Completed 11/10/2009
OH-EE-104	GA Fider Bd	543.6	Area on both either of western nearly reconfinited and conduct	Completed 14/10/2009
OH-FE-105	GA Elder Rd	544		Completed 11/9/2009
OH-FF-107	CI Fairfield Union	544.5	Needs seeded and fenced.	Completed 11/20/09
OH-FF-124.S01	GA Richland Rd.	545.5		Completed 11/9/2009
OH-FF-127	CI Gun Barrel Rd.	546.4	Remove Dewatering Structure. Work topsoil when area becomes dry enough.	Completed 11/16/09
Spread	2011年1月1日日本学月1日日日日	多河 医三角 的复	Principle of the second control	<u> </u>
:		548.8 28935+00		Complete 11/7/2009
		549.5 28966+62	Remove rock and c	Complete 11/7/2009
		549.8 28982+00	Rebuild water bars	
		to 28988+00		Complete 11/8/2009
OH-DY-D15 DOM		551.1 29057+00	Smooth up grade in residential area.	accomplete of between me O
		553 2 29163+00	Repair drain files	LO Compensated for dameges
		553.9 29199+00		
OH-PY-029.002		to 29201+00		LO Compensated for damages
		554.9 29252+25	Repair grade where water is standing in field.	Complete 11/9/2009
		558.1 29325+80	Repair grade and trench subsidence where water is standing in field.	Can not access this tocation, ag. field is too wet
		556.2 29328+13	Repair grade of bar	Complete 11/10/2009
	WB-OH-548-C	566.1 29850+23	Restone east bank to original elevation. Fix area adjacent to east bank where water is ponding.	Complete 11/11/2009
		562.5 29864+64	Repair ruts in road.	Complete 11/10/2009
HAM I GOO EUG-MITEHO		2989	Ruis in pastius, Farce Missing, Debris on Crack Bank, Satilling of Drive - added to punch list 12/23/09.	
	10.2000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.000 10.00			The state of the s
		582.1	Return hill to natural contours. Repeir Water Bar	Complete 11/3/2009

		582.7	Remove sediment from hay bales running adjacent to water body on the north side of ROW	Completed 11/6/2009
		585.2 30872+00		Completed 10/29/2009
	WB-OH-585-AAAA	585.2 30873+00	Repair erosion to hill side on the sestem side of waterbody	Completed 10/29/2009
		586.9 30950+13	586.9 30950+13   Repair overloaded water bar and eroston	Completed 10/29/2009
		587.9	Repair blown out water bar and erosion	Completed 11/10/2009
i	WB-OH-573-A	588.1 31014+10	Repair water bars on western and eastern banks and on hills leading up to banks. Repair fence. Mulch enosing the present on hank Check for possible recognized	
	WB-575-C	290		Completed 11/8/2009
	GAS HWY 60		Correct subsidence over ditch line (@ come out hale of road bore	Completed 11/6/2009
		GN 026, 028 &	Water bars in pasture area too big for LO's equip, to travel over, additional gradework may be	
		026	Necessary	Too Wet at this time will monitor
	Okey & Pine Lake Road		Remove road approach rock both sides	Completed 11/7/2009
	WB-OH-577-B	591.9	Banks of waterbody need seeding.	Completed 11/8/2009
		584	Remove timber debris in ag field	Completed11/7/2009
	WB-581-B	596.1	Checkromect subsidence in waterbody and re-grade in ag fleid	Too Wet at this time will monitor
		577.5 - 581.5	Flagging, stakes and signage need to be removed	Completed 11/11/2009
		577.5	Seed & stabilize CIS HWY 60 (bar dilch)	Completed 11/6/2009
		577.5	Remove flagging on power poles	Completed 11/11/2009
		577.6		Completed 11/6/2009
		577.8	Repair erosion in swale	Completed 11/11/2009
		577.8 - 577.9	Re-seeding needed	Completed 11/9/2009
		577.9	Checkkorrect deep gracks appearing in steep slope	Completed 11/11/2009
		Spread Wide	Water bars have erosion channels in throats, need HB checks installed and reseeded	Completed 11/14/2009
		Spread Wide	Survey Laths need picked up after the installation of the line marker posts	Completed 11/14/2009
Shread K				
		613.8 -613.9	Repair erosion and re-seed	Completed 11/6/2009
		613.5	Install ECDs at ends of two permanent slope breakers	Completed 11/6/2009
		614.2-614.3	Re-seeding needed	Completed 11/6/2009
		612.6-613.3	Repair erosion and re-seed	Completed 11/6/2009
	WB-OH-615-EEE	616.6	Re-seeding needed	Completed 11/6/2009
		615.6-615.5	Re-seeding needed	Completed 11/6/2009
		614.6-614.7	Re-seeding needed	Completed 11/6/2009
		614.07	Replace straw bales on the NE side of WB	Completed 11/6/2009
		614.38	Replace straw bales on Side of ROW	Completed11/8/2009
		614.07-614.38	Re-seeding needed	Completed 11/8/2009
		610.19-611.99	Re-seeding needed	Completed 11/8/2009
	WB-OH-610-8BB	611.41	Remove/repair loose curiex in waterbody	Completed 11/10/2009
		611.63-611.97	Install ECD's at the end of permanent stope breakers	Completed 11/11/2009
		611.58	Seed/seed-aid needed in area of Dominion Valve	Completed 11/11/2009
	WB-OH-633-CCCC	633.18	Correct curlex installation on east bank of waterbody	Completed 11/11/2009
	WL-OH-618-A	633.68	Correct curlex installation on both banks of waterbody	Completed 11/11/2009
	WB-OH-618-C	633.71	Correct curiex installation on both banks of waterbody	Completed 11/11/2009
		638.64	Clarington Hub station. Re-contour landsiide area on the north east side	Completed 11/11/2009