

FILE

2



06-1142-GA-BIN

January 25, 2010

Kimberly D. Bose, Secretary  
Federal Energy Regulatory Commission  
888 First Street, N.E., Room 1A  
Washington, DC 20426

RE: Docket No. CP07-208-000  
Rockies Express Pipeline LLC, REX-East Project  
Report for Environmental Condition No. 60

Ms. Bose:

Rockies Express Pipeline LLC ("Rockies Express"), in accordance with Environmental Condition No. 60 of the Commission's May 30, 2008, certificate order for the REX-East Project,<sup>1</sup> hereby files the water supply well report following the pipeline being placed in service. For the three wells that appear on the attached table as still needing attention, Rockies Express has been in touch with the landowners and intends to address the wells when the weather permits it to do so.

Please direct any questions with respect to this matter to Paul Gayer at (303) 914-7804.

Respectfully submitted,

/s/ Shippen Howe

Shippen Howe  
Van Ness Feldman, P.C.  
1050 Thomas Jefferson Street, NW  
Washington, DC 20007  
202-298-1800

Attorney for  
Rockies Express Pipeline LLC

Attachment

cc: John Peconom, FERC  
All Parties

<sup>1</sup> The REX-East project was granted a certificate of public convenience and necessity pursuant to Section 7(c) of the Natural Gas Act by the Federal Energy Regulatory Commission on May 30, 2008, in this docket. Rockies Express Pipeline LLC, 123 FERC ¶ 61,234 (2008). On June 2, 2008, Rockies Express, pursuant to Section 157.20(a) of the Commission's Regulations, 18 C.F.R. § 157.20(a), notified the Commission that it accepted the Commission's Order.

This is to certify that the images appearing are an accurate and complete reproduction of a case file document delivered in the regular course of business

Technician Dmm Date Processed 01-27-10

370 Van Gordon Street

P.O. Box 281304

Lakewood, CO 80228-8304

303/989-1740

RECEIVED-DOCKETING DIV  
2010 JAN 27 AM 10:45  
PUCO

ROCKIES EXPRESS FERC CONDITION 60 TABLE

File #	Trans Number	Description	Resolution	Status
401	IN-FR-193.000	LO concerned about water source being jeopardized.	Construction completed in area without incident.	Resolved
551.8	OH-PY-015.008	Construction caused well to dry up. Disruption of water supply.	REX Contractor Paid to Drill replacement water well July 2009. Water well running dry. Cloudy material in water. LO alleges stringing truck damaged line, causing leak. Pending.	Resolved
505.9	OH-PW-035.501	Loss of water from well due to dewatering.	07/22/09-Landowner changed his own water supply and resolved. ROW had a water supply tank installed for use until dewatering is complete and well recovers.	Resolved
621	Offline near OH-BL-016.000	Loss of spring.	Well has recovered. REX paid all plumbing bills. Resolved. ROW compensated LO to repair a holding tank he had, and utilized temporary supply until spring recovers. Resolved but will continue to monitor. REX drilled a replacement well 8/4/09.	Resolved
596.3	OH-GN-035.000	Water well flow disruption after blasting.	09/02/09: Meetings were held with LO. Determined there was no impact from REX operations. Resolved	Resolved
597.3	OH-GN-042.00	LO complaint of water well disruption after REX blasting.	EI made area assessment. Well is located over 800 feet from blast location with wells closer not having been impacted. REX did not believe it contributed to disruption. Nothing could be done unless there was more direct proof. Landowner was appreciative for the area assessment and results. Resolved.	Resolved
593	Off line landowner	Silt off ROW in Spring.	REX compensated landowner to repair overflow line from spring.	Resolved
593.8	OH-GN-072.000	Potential disturbed spring; no water.	10/07/09: REX installed new well for LO. Resolved.	Resolved
597	OH-GN-040.000	Landowner complained to hotline of damage to well.	ROW agent met with LO and advised that construction was 1000 feet away from the well and that REX could not have caused any damage to it. Resolved.	Resolved
588.2	OH-MK-013.000	Water line damage.	10/07/09: REX ROW is drilled new well for LO. Resolved.	Resolved
586.7	OH-GN-035.000	Well flow seems affected by blasting.	Well was not disturbed by construction. Resolved.	Resolved
333.5	IN-JO-297.000	REX was supposed to replace a water line after construction last spring but it wasn't done. He wants to talk to someone about it.	11/11/09 update: ROW compensated LO for waterline. Resolved	Resolved
26	MO-PT-027.000 28 29	Deep well has problems.		Resolved
596.8	OH-GN-039.000	Spring was hit and well has not recovered.	Water well problem was not due to REX. Well was over 1000 feet from construction. Spring that landowner had was disturbed during construction. LO stated that he has city water now, but would like to use the spring as a backup. ROW considers the immediate complaint resolved, but LO will monitor the flow. REX will pay water replacement until spring resumes. Resolved.	Resolved
555.6	OH-PY-038.504	LO complaint over water well testing.	LO will not allow a flow test of the original sample site in the house. ROW will not compensate LO due to this. ROW considers this resolved.	Resolved
586.5	OH-MK-003.000	Potential problems with well.	REX met with LO and there was no visible problem with well. No action was necessary. Further investigation not necessary.	Resolved
620.4	OH-BL-014.001	Spring water flow damaged due to construction	Replacement water delivered until replacement well was drilled. Drilled replacement well 11/09.	Resolved
622.2	OH-BL-018.001	Spring water flow damaged due to construction	Replacement water delivered until replacement well was drilled. Drilled replacement well 11/14/09.	Resolved
627.6	OH-BL-041.000	Spring water flow damaged due to construction	Replacement water delivered until replacement well was drilled.	Resolved
638	OH-ME-137.003	Spring water flow damaged due to construction	Replacement water delivered until spring recovered. Spring has recovered 11/24/09	Resolved
349.3	IN-SB-055.000	Orange water flow	Test revealed high iron content-purchased filter and softening systems.	Resolved
348	IN-SB-249.000	Orange water flow	Test revealed high iron content-purchased filter and softening systems.	Resolved
596	OH-GN-033.000	Spring damaged due to blasting	ROW to monitor to see if flow resumes after backfill. Spring will be monitored over winter and then be repaired if appropriate. Spring is for Cattle only.	Pending
596.5	OH-GN-037.000	Spring damaged due to blasting	ROW to monitor to see if flow resumes after backfill. Spring will be monitored over winter and then be repaired if appropriate. Pending.	Pending
429.6	OH-BL-170.000	Water well damaged due to well point dewater damage	Contractor replaced water well May 2009	Resolved
451.7	OH-WA-003.001	sediment in water well flow, disruption due to dewatering.	REX installed filters and replaced pump damaged by silt.	Resolved
516.4	OH-PW-086.000	Loss of water supply	REX supplied water during construction and replaced well.	Resolved
517.5	OH-PW-091.000	Well Damaged during construction and no longer producing	Well is secondary and supplies shop; not residence. 12/23/09 update: LO has yet to submit his bid estimate for repair.	Pending
520.8	OH-PW-114.000	off line owner lost water supply due to dewatering	REX supplied water during construction and replaced well.	Resolved
520.8	OH-PW-114.000	off line owner lost water supply due to dewatering	REX supplied water during construction and replaced well.	Resolved