

COLUMBUS I CLEVELAND CINCINNATI-DAYTON

BRICKER & ECKLER LLP 100 South Third Street Columbus, OH 43215-4291 MAIN: 614.227.2300 FAX: 614.227.2390

www.bricker.com info@bricker.com

Sally W. Bloomfield 614.227.2368 sbloomfield@bricker.com February 15, 2013

Via Electronic Filing

Ms. Barcy McNeal Administration/Docketing Public Utilities Commission of Ohio 180 East Broad Street, 11th Floor Columbus, Ohio 43215-3793

Re: Oregon Clean Energy, LLC Case No. 12-2959-EL-BGN

Dear Ms. McNeal:

In response to the Ohio Power Siting Board ("OPSB") staff's inquiry, Oregon Clean Energy, LLC, submits for the public record (which was submitted electronically to the OPSB staff) its response to the Ohio Historic Preservation Office request for additional information addressing the potential impact on historic structures within the project area.

Please do not hesitate to contact me if you have any questions.

Sincerely,

Sally W Broomfile

Sally W. Bloomfield

Enclosures

Cc: Chris Cunningham (w/Enclosures)



Mr. Dave M. Snyder Ohio Historic Preservation Office 800 E. 17th Avenue Columbus, OH 43211

Subject: Additional History/Architecture Survey Information Oregon Clean Energy Project, Oregon, OH – 2012-LUC-21879

Dear Mr. Snyder:

Thank you for your letter dated 12/26/12 requesting some additional information and clarifications with regard to the Phase I Cultural Resource Management Investigations Report previously submitted for the Oregon Clean Energy Project. Based upon conversations with you, Weller & Associates, Inc. has undertaken additional efforts to clarify issues with regard to potential resource impact. As you know, elements related to on-site archaeological and historic structure resource potential was forwarded to you on 1/30/13.

Enclosed please find a revised Appendix A provided by Vintage Resource Studies LLC that provides a more in-depth survey of historic structures within the project's surroundings. The report concludes that impacts on surrounding properties would be negligible and does not recommend the need for additional surveys.

We look forward to your review to confirm that we have provided you with the information requested. If you have any questions or require additional information, please do not hesitate to contact me. Thank you in advance for your assistance.

Sincerely,

ARCADIS U.S., Inc.

Lynn gresock

Lynn Gresock Environmental Consultant

cc: Chris Cunningham, OPSB (via e-mail) Ryan Weller, Weller & Associates (via e-mail) Tom Barrett, Vintage Resource Studies LLC Bill Martin, Bill Siderewicz, Oregon Clean Energy, LLC (via e-mail) Sally Bloomfield, Bricker & Eckler (via e-mail) ARCADIS U.S., Inc. 1 Executive Drive Suite 303 Chelmsford Massachusetts 01824 Tel 978 937 9999 Fax 978 937 7555 www.arcadis-us.com

Date: February 15, 2013

Contact: Lynn Gresock

Phone: 978-322-4520

Email: lynn.gresock@ arcadis-us.com

Vintage Resource Studies LLC

Worthington Ohio

Revised Appendix A History/Architecture Survey for Properties Outside of the 30 Acre Parcel for the Oregon Clean Energy, Gas-to-Electricity Project, in the City of Oregon, Oregon Township, Lucas County, Ohio



Addendum to the Phase I Cultural Resource Management Investigations for Areas Surrounding Approximate 12.1 ha (30 ac) Lallendorf Road Development in Oregon Township, Lucas County, Ohio.

> Thomas P. Barrett, Historian February 12, 2013

Table of Contents

Abstract	2
Literature Review	3
Survey Design and Research Questions	4
Environmental Setting	5
Historic Context and Themes	5-9
History/Architecture Survey of Refined APE	9-19
Conclusion and Recommendations	19-20
References	21-22

Figures.....Attachment A

- Figure 1 1965 Oregon 7.5" USGS Quadrangle Map with Project Site
- Figure 2 5-Mile Study Area and Previously Recorded Sites
- Figure 3 Arial Map of OPSB 5-mile Study Radius and 1 Mile Buffer
- Figure 4 Portion of the Illustrated Historical Atlas of Lucas and Part of Wood Counties, Ohio (Andreas & Baskin 1875) showing the approximate location of the project area
- Figure 5 Portion of the 1900 Maumee Bay, Ohio Quadrangle 15 Minute Series (Topographic) map showing the approximate location of the project area
- Figure 6 Diagram based on Ohio SHPO's Online Mapping System. The area highlighted in Zone 1, was determined to have a greater potential for impacts from the proposed gas-toelectric power plant. Properties within Zone 1 over fifty years old were photographed and documented in SHPO's Section 106 Survey Table

SHPO Section 106 Survey Tables for Zone 1 and Photo Log.....Attachment B

Ohio Historic Inventory Forms......Attachment C

Abstract

Vintage Resource Studies LLC conducted a Phase I history/architecture survey for the area of potential effect surrounding the proposed approximately 12.1 ha (30 ac) Oregon Clean Energy Center (the Project) site located on North Lallendorf Road in the City of Oregon, Lucas County, Ohio. This study is an addendum to the Phase I Cultural Resource Management Investigations for the Approximate 12.1 ha (30 ac) Lallendorf Road Development in Oregon Township, Lucas County, Ohio (Weller, November 12, 2012).

The lead agency for this undertaking is the Ohio Power Siting Board (OPSB). The proposed gas-to-electric power facility, proposed by Oregon Clean Energy LLC (OCE), will be a 799 megawatt natural-gas fired combined cycle power generating facility, similar to one located in the City of Fremont, in Sandusky County. The Project's tallest structures will be two 240-foot exhaust stacks. The next tallest structure will be the heat recovery steam generator, long and narrow features approximately 100 feet tall. The turbine building will be on the order of 70 feet, at its tallest, with all other Project buildings, structures and tanks significantly shorter. The objective of this history/architecture survey was to identify any sites or properties and evaluate them for the National Register of Historic Places (NRHP), within an area that is proportionate to the facility's impact on its surroundings, given its likely visibility.

The intent of this survey is to meet the requirements of the OPSB for siting power generating facilities, established in Chapter 4906-13-07 *Social and Ecological Data* of the Ohio Administrative Code, *Applications for Certificates for Electric Generation Facilities* § D. If the project becomes a federal undertaking or requires a federal permit in the future, more studies may be considered necessary in order to fulfill federal regulations under *36 CFR 800, Subpart B* - *The section 106 Process.* The OPSB *Application Requirements for Cultural Resource Surveys* is outlined as follows:

- (D) Cultural impact.
 - (1) The applicant shall indicate, on the 1:24,000 map referenced in paragraph (C)(1)(a) of this rule, any registered landmarks of historic, religious, archaeological, scenic, natural or other cultural significance within five miles of the proposed site.
 - (2) The applicant shall estimate the impact of the proposed facility on the preservation and continued meaningfulness of these landmarks and describe plans to mitigate any adverse impact.
 - (3) Landmarks to be considered for purposes of paragraphs (D)(1) and (D)(2) of this rule are those districts, sites, buildings, structures and objects which are recognized by, registered with, or identified as eligible for registration by the national registry of natural landmarks, the Ohio historical society, or the Ohio department of natural resources.

- (4) The applicant shall indicate, on the 1:24,000 map referenced in paragraph (C)(1)(a) of this rule, existing and formally adopted land and water recreation areas within five miles of the proposed site.
- (5) The applicant shall describe the identified recreational areas within one mile of the proposed site in terms of their proximity to population centers, uniqueness, topography, vegetation, hydrology, and wildlife. Estimate the impact of the proposed facility on identified recreational areas within one mile of the proposed site and describe plans to mitigate any adverse impact.
- (6) The applicant shall describe measures that will be taken to minimize any adverse visual impacts created by the facility

In accordance with OPSB guidelines, an 8 km (5 mi) study radius was studied for the area of potential effect (APE). The literature review was completed for the 5-mile study radius and field investigations supplemented the information from the literature review to evaluate potential effects of the Project on previously recorded Ohio Historic Inventory forms (OHI); National Register-listed sites, and State Historic Preservation Office (SHPO) determinations of eligibility (DOE) in the study radius.

Literature Review

There are nearly 2,100 identified OHI-recorded sites within the OPSB study radius. The vast majority of these resources is located to the west of the Project Area within Toledo and its adjoining suburbs and considered outside the reasonable area of potential effect by the proposed undertaking. Resources located within the customized APE aka Zone 1 (Figure 6) will be discussed further in this survey.

A review of the NRHP files and Ohio Historic Preservation Office (OHPO) consensus DOE files was conducted. There are 34 NRHP properties/districts and 36 DOE resources within the OPSB study radius. As for the OHI resources, the vast majority of these properties/districts are located to the west of the project within Toledo, essentially considered to be outside of the established potential impact area (Zone 1).

A review of the Cultural Resource Management (CRM) surveys was conducted for this Project. There were 26 previously conducted CRM surveys within the OPSB study radius. When the study radius is reduced to 1.5 to 2 miles, there were three studies that were considered pertinent to our history/architecture survey: Maumee River Crossing multiple corridor survey by Dobson-Brown et al. in 1994; the railroad grade separation study at Seaman Street and Norfolk and Southern Railroad intersection by Gibbs and O'Donnell in 1996; the widening of Route 2 (Navarre Road) Ohio Department of Transportation (ODOT) Interoffice Communication by Gasbarro in 1997 (previous studies by Toohey and Murphy et al 1987). It should also be noted that the Northwest Regional SHPO completed many OHI's in 1979 throughout Oregon Township, surveying much of the 50year-old built environment, throughout the study area. Cartographic/atlas resources were reviewed for the Project. An Illustrated Historical Atlas of Lucas and part of Wood Counties, Ohio (Andreas & Baskin 1875) indicates that there was one residence indicated within the central aspect of the Project Area. The United States Geological Survey (USGS) 1900 Maumee Bay, Ohio Quadrangle 15 Minute Series (Topographic) map indicates that there was already vast amount of oil wells and industrial activity immediately west of the project site.

Survey Design and Research Questions

The nature of the setting and scale of the power facility were important factors in identifying areas that might require more intensive survey, to identify any National Register-qualified, aboveground resources that might be affected by the proposed project. Field reconnaissance and consulting with the SHPO were both essential in establishing areas that could impacted by the power facility and therefore require more in-depth survey; and identifying those areas where the impacts of the Project will be minimal, but are still within the APE study radius.

Therefore, in consultation with SHPO, expectations based on the development of eastern Toledo, the environmental setting, and observations verified in the field; the 5-mile APE study area was separated into zones. It was determined that the eastern, less developed, and mostly rural "Zone 1" would be likely to have foreseeable impacts. The historically industrial and urbanized characterization of of "Zone 2" would have insignificant or no impact. See Figure 6 which shows the flat and rural quadrants of Zone 1, and the industrial/cityscape quadrants that define Zone 2.

Area of Potential Effect Zone	Characteristics and Themes	Level of Survey	Area Description
Zone 1 Potential for impacts from Project is greater in this area	Mixed use farms; crossroad communities; late -19 th century ditches (Black Swamp Drainage); Upright & Wing architecture; postwar suburban settlement; seasonal lake properties	Digital Photos documented pre-1964 structures on SHPO Section 106 Survey Table	Rural and suburban areas surrounding N. Lallendorf Rd. to Approx. 2.5 miles north, east and southeast of the Project site.
Zone 2 Impacts from Project unlikely or minimal	Industrial; Refineries; Urban Cityscapes; Interstate Highways; Maumee River Valley; Rail yards and beltline; shipping; Automotive manufacturing; Oil and gas exploration; glass manufacturing and research	Photolog completed in Phase I Survey. These areas were determined to have no potential for impact based on SHPO consultation and field reconnaissance	Areas south, west and northwest of the project site, mostly within the built up areas of City of Toledo proper

Table 1. Overview of the architectural field methods to identify potential impacts to history/architecture properties.

The objective of our Addendum fieldwork and literature research was to help answer two questions:

1. Will construction of the proposed Project adversely impact National Register-qualified, aboveground properties, beyond the North Lallendorf Road Project site?

2. What mitigation efforts can be incorporated into the Project to minimize or mitigate any foreseeable impacts to the continued meaningfulness and preservation of identified National Register-eligible or listed sites?

Environmental Setting

The surrounding terrain is, and has been, the subject of industrialization since the late nineteenth century. Oil, gas, radio, and electric facilities and constructs surround this Project with little for its preceding agricultural present or past.

The Project area is located in the upland, flat Lake Plains Region that is to the east of the Maumee River at Toledo and south of Lake Erie. The 5 mile study radius is centered on the Poject site which is located on the north side of an existing railroad easement and along the east side of North Lallendorf Road. There are two extant residences situated on lots that have frontage on this road and are within the Project area. The remainder of the parcel features two named ditches (Driftmeyer and Johlin) and agricultural fields. The terrain within the Project area and its surroundings is nearly flat. The surrounding landscape consists of large-scale industrial development, single-family residential homes, and occasionally farmsteads. Toledo and Oregon–associated developments are to the west about 2 miles.

Historic Context and Themes

Lucas County History

The history of Euroamerican settlement in Lucas County begins with the French. Sometime near 1680, the French are supposed to have built a fort, which acted as a trading post, at the falls of the Maumee River. This may be nothing more than tradition in order to bolster French claims to the region, but certainly the French were active along the Maumee River and used it extensively during the 1700s as a trade route. The first settlers in the county were Jean Baptiste Beaugrand and Gabriel Godfrey, who opened a trading house at the foot of the Maumee rapids in 1790. Other French traders, primarily from Detroit, traded along the Maumee, such as Peter Navarre who lived at the mouth of the river (Killits 1923; Knapp 1872; Scribner 1910; Waggoner 1888; Winter 1917).

The first American families arrived in 1807 and settled on the Maumee River. These early pioneers mainly traded with the Indians just like the French. American settlement of the region did not really grow until after the War of 1812. Increased settlement of the region led to concerns over the state boundaries of the Michigan Territory and the State of Ohio. The disputed boundary was Lucas County's northern border. As Michigan applied for statehood, they claimed land into what were Henry, Wood, and Sandusky Counties, Ohio. In retaliation, Ohio organized a new county named for the incumbent Governor of Ohio, Robert Lucas. This issue, which became a dispute between the two states, was called both "The Toledo War" and the Ohio-Michigan War and almost led to an armed conflict. The lands located in Lucas County that were disputed included Richfield, Sylvania, Washington, Oregon and Jerusalem townships and the northern parts of the townships of Spencer, Springfield and Adams. The disputed boundaries were peacefully resolved on June 20, 1835, on which day Lucas County was formed and Toledo was made the county seat (Scribner 1910; Waggoner 1888). President Andrew Jackson found in favor of the established state and in reparation, accepted Michigan's bid for admission to the Union (Andreas and Baskin 1875; Howe 1888; Killits 1923; Knapp 1872; Scribner 1910; Waggoner 1888; Way 1896; Winter 1917).

Settlement of Lucas County was hampered throughout the 1800s by the Black Swamp and epidemics of malaria and cholera. Transportation was limited to improved Indian trails and to the principal watercourses, the Maumee, Ottawa, and Swan Rivers. New road construction began in the 1820s. In 1839, work on the canal along the Maumee River began. By 1842, the canal was opened between Toledo and Grand Rapids. The Miami and Erie Canal link up with the Maumee River occurred the following year. Railroads became an increasingly important means of transportation and means of importing and exporting goods after the 1850s. Between 1835 and 1836, a rail line was built between Toledo and Adrian, Michigan. In 1853, the Cleveland and Toledo (Lake Shore) Railroad was completed. By 1910, Toledo was ranked fourth in the nation as a railroad center, having fourteen lines running through it (Scribner 1910).

Toledo is the economic center of the county. The city has grown dramatically in the nineteenth and twentieth centuries and much of this has been caused by its position as an important link between canal traffic, railroads, and lake shipping (Killits 1923; Scribner 1910; Waggoner 1888; Winter 1917).

Oregon Township

Oregon Township was created on June 11, 1837 from Port Lawrence and Manhattan Townships. In 1840, seven sections from the northwest portion of the township were annexed to the township of Manhattan. Then, both in 1856 and 1872, the township had its area further reduced, ceding land to the city of Toledo and the township of Port Lawrence. However, in 1874, a portion of Manhattan Township outside of Toledo was annexed back to Oregon Township increasing its size. Again in 1893, more land was taken to create Jerusalem Township (Scribner 1910; Waggoner 1888). In 1957, Oregon Township became the City of Oregon by way of popular vote. This action allowed the City of Oregon to own and operate its own wastewater treatment plant (City of Oregon 2012).

The City lies in the area once known as the "Black Swamp" and is located in the Maumee Lake Plains physiographic region. The topography is nearly level with a slight slope north toward Lake Erie (Waggoner 1888). The earliest documented occupation of present-day City of Oregon was an Ottawa village near the mouth of the Maumee River. The French had a trading post in the same vicinity as the Native American village with French settlers coming to the area around the year 1808. Among the French families to come to the area, the Navarre family still had descendants living in the county in 1910. The next Euro-Americans to settle the area were of English descent. This occurred during the 1820s and 1830s. Joseph Prentice came to the area and settled on the east side of the Maumee River in 1825. Luther Whitmore arrived next in 1829, then Robert Gardner in 1830 (Waggoner 1888).

Charles Jenison built the first steam powered saw mill in Oregon in the year 1836 on the Maumee River. The first road in the area ran from the Maumee River at Toledo to Woodville where it met up with the Maumee and Western Reserve Road. This road was known as the Woodville Road. At the road's intersection with the Maumee River, Herman Crane operated a flat-bottomed scow ferry. The first school in the City was built in 1834 on the Woodville Road. It was a log structure with classes taught by Elizur Stevens (Scribner 1910).

Early Euro-American inhabitants found valuable timber in the Black Swamp area. The land was cleared and was subsequently drained by the creation of ditches in order to make it suitable for agriculture (Scribner 1910).

Draining the Great Black Swamp

The Ohio General Assembly passed the 1859 Ditch law, which authorized the construction of open surface ditches by County Commissioners upon petition by one or more landowners to be affected. The following excerpt describes the ditching efforts that took place throughout this region between 1859 and the 1920's, a major catalyst for the area's development in the late 19th century:

Peter Wilhelm, whose great-great-great grandfather Jacob Wilhelm settled in southern Henry County in 1839, wrote of what had to take place to get a functioning ditch. "After a surveyor and engineer marked the course of a ditch (usually along section lines), a timber crew moved in and cleared the area of forest and underbrush," Wilhelm wrote. "Some timber was saved for building bridges, but the rest was stacked to the side and burned. Once crews had removed the stumps, workhorses and farm plows were used to clear the ground along the course of the ditch. After one pass with a plow, a second crew removed the loosened ground with horses and slip scrapers.

More than 15,000 miles of open ditches were dug throughout northwestern Ohio in this backbreaking manner, opening up 5 million acres of new land to settlement, he said. Most Wood County drainage ditches are wider and deeper than ditches elsewhere, and their size and numbers are impressive sights to newcomers. Wilhelm wrote that the construction of open drainage ditches is "best exemplified by the Jackson Cut-Off" which was dug in 1878-79.

North of Portage Road the Cut-Off takes a left turn, meandering about two more miles before it runs into Beaver Creek, just east of Grand Rapids, and ultimately into the Maumee River. It has been called "the largest waterway for purely drainage purposes in the state." It drains about 30,000 acres (47 square miles) of Wood County, and it cost \$110,000; a \$60,000 upgrading was done in 1948. Beginning in 1860, drainage ditches were painstakingly dug by man wielding a shovel. Writer Wilhelm wrote, "By the 1860s, literature in farmers" journals was pleading for machines drawn by animal power to replace hand labor." By 1890, the increasing expense of labor spurred the invention of a mechanical ditching wheel and in 1892 (after most of the still-existing ditches had already been dug by hand) James B. Hill, a machine shop worker in Bowling Green, built and patented a steam-driven mechanical ditching wheel, Wilhelm said. "Hill borrowed the idea from a Professor Sites of Tiffin who abandoned the idea in 1888 after several failures. Hill perfected Sites" idea and began manufacturing what he labeled the "Buckeye Ditcher." His first model was completed 1893." After moving his business several times because of financial problems, Hill sold out his business in 1902, and it settled in Findlay as the Buckeye Traction Ditcher Company. According to Wood County engineer Tony Allion, virtually no ditches have been dug since 1920. Until 1960, ditch maintenance was done primarily as a result of a landowner petition, Allion said. Now, however, the county maintains some 500 to 600 miles of ditches, while the remainder about 2,400 miles, is handled by property owners whose lands drain into them.

A direct consequence, and benefit, of the ditch-digging program, Wilhelm wrote, was the construction of roads. The dirt from the ditches made a bed several inches above the surrounding fields and made for well-drained roads when properly graded. Another consequence was that the land made tillable by the drainage of surface water was revealed to be some of the richest and most productive farmland in the world. An even more lasting consequence was the Black Swamp was gradually being eliminated. With the soil, with every drainage ditch dug, the resulting acres added to tillable farmlands were subtracted from the swamp, killing it acre by acre, farm by farm.

Is there anything left of the Black Swamp? Almost nothing. One 50-acre tract of wooded land near Rudolph is said by some to remain swamp-like. However, Greg Genzman of Perrysburg, chief ranger for the Wood County Park District, which owns the property, said the acreage is "a degraded remnant of the swamp, but there's very little left."

Others have said that the Goll Woods State Nature Preserve in Fulton County is the largest and most mature fragment of the Black Swamp remaining in Ohio," but geologist Jane Forsyth doubts that the swamp existed that far north of the Maumee River. In any case, the Black Swamp was defeated soundly, taking about 14,000 years to mature and not more than 60 years to eliminate, such was the determination of the settlers who defied it and who prospered from the rich land that came from it. <u>The most visible reminder of the Black Swamp is the vast</u> <u>network of drainage ditches which are still doing their job of keeping the swamp</u> <u>at bay</u> (from the article "Black Swamp Once Ruled the Land and People," published June 10,1999 in the Bowling Green Sentinel Tribune).

Large-scale drainage of the Black Swamp began after the reconstruction of the Maumee & Western Reserve Road, and the 1859 "Ditch Law" permitted the coordinated development of large-scale land drainage throughout the region. Most ditches were dug between1870-1920. By 1880 there was a ditch along every section of land within the Black Swamp. Earth excavated for the ditches provided raised roadbeds, and a system of paired ditches and roads developed in the Black Swamp (Wilhelm 1984:79-81). Among the gridded roads and ditches, the Maumee & Western Reserve Road still stands out as a dramatic arrow-straight diagonal running across the grid, unlike the few other roads that meander along streams or ridges.

Once open ditches were built, the land could be further "underdrained" by digging a trench and burying drain pipes. This practice was refined in western New York State and brought by migrants to the Black Swamp by 1860. The early under drains were made of wood planks split or sawn from the available timber. This contributed to clearing the land, timber sales, and the growing sawmill industry in the Black Swamp. The clay tile industry grew after 1880, and using local clay deposits, supplied durable hollow ceramic tiles for underdraining (Wilhelm 1984:83-84).

A few excerpts of local petition filings to the Oregon Trustees in 1885 (likely at the direction a regional "Ditch Supervisor") for the construction of new ditches in Oregon are documented on page 49 in *The History of Oregon and Jerusalem* written by Josephine Fassett, published in1961.

Charles Jenison built the first steam powered saw mill in Oregon in the year 1836 on the Maumee River. The first road in the area ran from the Maumee River at Toledo to Woodville where it met up with the Maumee and Western Reserve Road. This road was known as the Woodville Road. At the road's intersection with the Maumee River, Herman Crane operated a flat-bottomed scow ferry. The first school in the City was built in 1834 on the Woodville Road. It was a log structure with classes taught by Elizur Stevens (Scribner 1910).

In the late 19th Century and early 20th Century, the oil industry began to develop in the area. The area possesses oil resources as well as a broad range of transportation resources including the Maumee River, extensive railroads, canals, and highways. These circumstances lead to two large oil refineries being established in the city and becoming the two largest employers in the area in recent years (City of Oregon 2012).

The Project APE contains two local ditches: Johlin Ditch and Driftmeyer Ditch, both of which are visible on the 1875 Atlas and both appear to essentially follow the same route today.

Upright and Wing Houses

One of the most common house types in northwest Ohio is the upright-and-wing or gable-front-and-wing. This L-shaped house has its origins in the building traditions of New England and the Great Lakes region. This may account for its significant numbers in the northern tier of northwest Ohio counties, whose settlers often came from these areas.

The upright-and-wing house consists of a one-and-a-half to two story wing with a front gable roof and perpendicular orientation, and a side wing set at a right angle to it (sometimes known as the kitchen wing), one-half to one story tall, with a side gable and parallel orientation.

The upright element usually has three bays. Early examples contain a door to one side and can probably be traced to earlier gable-front Greek Revival houses. In later examples, particularly after 1850, the upright shrinks to two bays and the main entry shifts to the kitchen wing. This change may have been due to the growing recognition of the first floor of the upright as formal space and the kitchen wing as the informal, everyday center of family activity. Later examples also include a porch in the space provided by the recessed wing.

Because of their origin, these houses sometimes bear evidence of Greek Revival influence. However, northwest Ohio examples are usually simple Folk Victorian or Vernacular types with little or no stylistic influence. Folk Victorian upright-and-wings may include minor detailing in the porch or cornice line, including turned porch supports and bracketed eaves. Both masonry and frame construction were popular.

Upright-and-wing houses continued to be built well into the twentieth century. Even some contemporary house plans reveal the influence of this historic housetype. No systematic survey of upright-and-wing houses in northwest Ohio has been conducted (Harper, 1988).

Numerous upright-and-wing houses were identified during this survey and documented in the Section 106 Survey Table. However, none of the examples recorded in this survey were considered unaltered representations of the type to be considered for the NRHP.

History/Architecture Survey of Refined APE Demarcated "Zone 1"

Zone 1

Bay Shore Road

Starting at the northeast section of the survey area we designated Zone 1, following Otter Creek Road, north to Bay Shore Road, our team observed railroad facilities of the Port Authority to the west and industrial refineries and a water treatment center to the south, toward the Project. Following Bay Shore Road eastward, our team recorded and photographed 50-year-old properties for the SHPO Section 106 Survey Table. Immediately on the north side of the road, near the Lakefront Dock, is the Village of Harbor View, a small village of approximately 100, 1200 square foot, wood framed cottages dating to circa 1920. The village is surrounded by industrial activity and resides in the shadow of the existing coal-fired power plant. Our observations from this location indicate that the regional impacts of the new gas-to electric power plant, 2 miles south of this area, will not impose on the existing setting of Harbor View and its adjacent environment. The field survey continued eastward along Bay Shore Road and across Driftmeyer Ditch and Heckman Ditch, toward Stadium Road. Several previously inventoried properties were encountered along this section:

LUC-241-10 Located at 4328 Bay Shore Road is a circa 1870 gabled-ell, twostory, wood framed house. The "Louis Momany Residence" has no distinguishing architectural features and has been altered with modern materials. The house is situated in a mostly industrial area.

LUC-242-10 The Louis Dupont Residence at 4400 Bay Shore Road is a circa 1900 two-and-a-half-story, hipped roof with dormer, Craftsman foursquare home. The plain foursquare house is surrounded by industrial development and utility lines.

LUC-243-10 Located at 4454 Bay Shore Road is the Peter Momany Residence, a vernacular front-gabled, two story, framed house, with alterations. The common vernacular house is surrounded by trees, industrial development and utility lines. LUC-245-10 Located at 4526 Bay Shore Road is the Thomas E. Dunn Residence, a cross-gabled, vernacular house with Greek revival elements. The undistinguished house is surrounded by industrial development.

LUC-244-10 Located at 4516 Bay Shore Road, is the Edwin Case Residence. The house is a circa 1900, two-and-a-half-story, four-square, Craftsman, side gable house, with shallow dormer window at the roofline, was moved when the railroad expanded. The house is surrounded by industrial complexes and sits adjacent to the BP refinery complex to the south.

LUC-1285-10 Located at 4701 Bay Shore Road is the Bay Shore Generating Plant. The industrial energy-generating complex was established in 1955 and has been updated and expanded since that time. The Project will be located approximately 2 miles south of this plant.

LUC-271-10 (Demolished) formerly located at 4960 Bay Shore Road, was a circa 1860 story and vernacular residence. The building appears to be no longer extant or in ruin.

LUC-201-10 (Demolished) formerly located at 5451 Bay Shore Road, was the circa 1917 La Tabernilla Inn. The former Prairie-influenced inn, patterned after an establishment in Panama of the same name, with prohibition associations, is no longer extant. This segment of Bay Shore Road is now characterized by modern suburban-style homes and duplexes.

LUC-272-10 Located at 5224 Bay Shore Road is the Bay Shore Church, a circa 1880 Queen Anne-influenced, wood framed church that once featured an open belfry. The church has been converted into a dwelling with an attached garage at the rear elevation. The belfry has been removed but some of the architectural window elements and ornamentation at the gables remain. The modern Eagles Nest Golf Course is south of property.

LUC-322-10 (Demolished) located at 5520 Bay Shore Road, the Tompkins farm residence was a circa 1860 gabled ell farmhouse. The farmhouse appears to be no longer extant. This segment of Bay Shore Road is characterized by modern houses and golf course.

LUC-321-10 (Demolished) located at 5452 Bay Shore Road, was a circa 1870, vernacular, one-and-a-half-story house with Italianate features. The house is no longer extant and there is a modern duplex at this location, with modern homes and multiplexes in the surrounding vicinity.

LUC-320-10 (Demolished) formerly located at 5424 Bay Shore Road was a circa 1940 bungalow. The house is no longer extant as the area has been redeveloped with modern suburban homes and golf course.

Our field investigations along Bay Shore Road found none of the previously inventoried properties to meet minimum criteria for eligibility for National Register consideration based on alterations, demolition, and overall lack of integrity. Additional properties were documented in the history/architecture survey table that appeared to meet the 50-year threshold for National Register consideration. One of the documented properties in this area is the Wynn Elementary School, next to the Bay Shore Church, at 5224 Bay Shore Road. The mostly modern building features a small, circa 1930, core structure that follows a stone gothic revival style. The school has received major additions which obscure the original structure to the point of affecting the original meaningfulness of this example of Oregon's small regional schools and associated libraries that were built toward the late 1920's. No further National Register consideration is recommended for this property.

Three miles north of North of Harbor View is the Toledo Harbor Light National Register site. The lighthouse marks the entrance to the Toledo Shipping Channel where Lake Erie and Maumee Bay meet. Due to the site distance from this NRHP-listed lighthouse across the bay and the existing industrial features which can be viewable from the lighthouse (based on clear viewing sequences noted from online cameras installed at the site) site; no impacts to the continued meaningfulness of the 1904-built lighthouse and its Romanesque architectural features are anticipated by the project.

Cedar Point Road

One mile south of Bay Shore Road is Cedar Point Road. Our architectural survey of this road considered within the potential area of effect, starts in the industrial areas comprised of existing coal-fired power plant and refinery, at the Tintersection of North Lallendorf Road. Heading in an eastward direction, past agricultural farmland of the Project site, our team encountered brick gabled ell at 5252 Cedar Point Road, with multiple additions/alterations, a raised brick foundation and several outbuildings, which include an English three-bay barn, shed, and pole barn. This property and several more along this segment were recorded on the History Architecture Documentation Table.

The rural flavor of Cedar Point Road continues westward from the Project site. The survey encountered multiple 1920's bungalow houses, a few with agricultural outbuildings like the front-dormer 1½ story structure at 5415, which has two contemporaneous English barns with brick foundations and steel seam roofs.

At the intersection of Stadium Road and Cedar Point Road, is a circa 1950's concrete block, corner market, on the northeast quadrant. And across the street from the carryout, on the southeast corner, is the previously recorded, Mominee-McCullough Story (LUC-202-10). The former circa 1860 Italianate store and tavern was converted into a two-family dwelling at some point. The brick building appears to be an upright and wing in massing. None of the house's previous iterations as a focal point of the area can be discerned from the vinyl siding, which now covers its brick construction.

LUC-203-10 is another previously recorded property along Cedar Point Road. Noted in the field as Vail Farms aka the Jacob M. Berger Residence on the OHI form, the property is located at 6118 Cedar Point Road. It is a circa 1892, twostory, brick, gabled ell home, following the Upright and Wing tradition, common to this region. The house has been altered with an enclosed porch and modern materials, although the brick upright is in excellent condition. The outbuildings are mostly comprised of modern steel pole-buildings, as the farm appears to be an equestrian facility.

Crossing Tobias Ditch in Section 30, a concrete box culvert with parapet railings was noted. The structure was built in 1927, by the Lucas County Commissioners.

Approaching three miles east of North Lallendorf Road, near the intersection of Norden Road, at 6810 Cedar Point Road, is a circa 1890 farmstead. The farmstead features a small brick cross-gabled, 1 and ½ -story house with central chimney. The house is partially disguised by a first-story enclosed front porch at the façade. The outbuildings include: a massive steel silo; garage; pole barn; an elevated slightly tapered granary; and a large three-bay English barn which has "Myers Farm on the Bay Since 1890". The present use of the farm appears to be limited to corn or grain production.

Located at 7250 Cedar Point Road, is the Bay View Bed & Breakfast. The house appears to have been originally constructed in the late 19th century with an original brick, two-bay, upright which has been added onto with larger and dominant modern wing. Dormer windows have been added to the section that would have formerly been the original wing. The rear elevation of the house has a wall of double pane windows, giving the house a very contemporary appearance. There is an associated "potting shed" and "tea house". A timber-framed pole barn accompanies the house and is active with horse stables.

The agricultural landscape and view shed from this section of rural Oregon Township toward the Project site is generally obscured by the existing power grid to the southwest and an existing 400' tall radio tower to the northwest; along with multiple utility lines along Cedar Point Road. It is our assessment, that the overall rural setting will not be negatively impacted by the Project to the point of adversely affecting the sense of rural and agricultural meaningfulness of the area.

Corduroy Road

Standing near the intersection of Corduroy Road and North Curtice Road, at almost 3.5 miles from the Project site, and bordering western Jerusalem Township it was noted that effects of the Project would be limited at this point. Circling back toward the Project site our survey continued westward toward the Project area.

The circa-1960 Oregon Water Treatment Plant consumes much of the acreage on the west side of North Corduroy Road, with occasional modern suburban houses noted along the east side of the roadway, culminating into a grouping of modern residences (generally undistinguished Cape Cods and Ranches) at the intersection of Corduroy and North Curtice Roads.

Between North Curtice and Norden Road, a few agricultural outbuildings and barns were noted but accompanied by replaced modern homes. A circa 1900 barn was noted at 7025 Corduroy Road and another small English barn among ranch houses at 6706 Corduroy Road. A small altered gabled ell in poor condition was noted east of Norden road on the north side in the 7000 block of Corduroy, surrounded mostly by agricultural fields, power lines running east west, toward the Project site and many new-build homes in this area.

The intersection of Norden Road and Corduroy features an inconspicuous two story commercial building at the northeast corner ("Simpler Times" on small sign). An inspection northward along Norden Road failed to identify any 50 year old properties of note. The road is cuts through agricultural fields which are traversed by the aforementioned power lines that run east and west.

A small gambrel roof barn was recorded at 6450 Corduroy Road with two lean-to sheds. The associated house is modern brick single-story duplex. A few other houses along this segment included an altered bungalow on the north side (address unknown), and an undistinguished American Foursquare at 7010 Corduroy Road.

A small farmstead is located at 6450 Corduroy Road. The property consists of a circa-1880's, one-and-a-half-story, cross-gabled ell with modern finishes, all recent fenestration, and an attached garage. The house is accompanied by a three-bay English barn with gambrel roof and lean-to shed. The east gable end of the timber-framed barn has the foundation coursed in brick, approximately 8 feet high, what was likely a milk house, is now used as a dog kennel. The barn has asphalt shingles, partially clad in steel siding and board and batten.

Continuing westward along Corduroy Road there are numerous modern ranch homes and a few Craftsman bungalows, a Foursquare, and a modern interpretation of an Upright & Wing, in the 6000 block of Corduroy Road.

At 5734 Corduroy Road is LUC-251-10, is a small gable end house, recorded as a log-interior house and related to the Navarre family according to the OHI. The house is a one-and-a-half story, wood frame structure/residence, with a lean-to addition to the rear. The circa-1860's, side-gable house has been heavily altered in massing and new materials since it was first recorded for the OHI in 1979. The Navarre residence is buffered from the Project site by utility lines and trees. The Project will not have an effect on the qualities that qualify this property for NRHP for its associations with the settlement of Momeneetown and early development of Oregon's education system.

LUC-252-10 at 5764 Corduroy Road, no longer extant, was formerly situated at the southwest corner of Corduroy and Stadium Roads; the Momeneetown Store and Tavern is a circa 1860's, massive, rough course stone building. It was originally used as a general store, tavern and meeting hall. The building was later used as a nightclub. LUC-323-10 located at 5637 Corduroy Road; the circa-1860 vernacular wood frame Condon Residence is no longer extant. LUC-250-10, the Ai Fassett Sr. Residence; a circa 1860 brick Italianate farmhouse, situated on the south side of the road at 5502, had a setback of approximately 125 feet, is no longer extant. LUC-253-10, the Ecville School is located at 6601-6603 Corduroy Road is an 1879 one-room schoolhouse. The building is heavily altered in massing and materials.

At 5260 Corduroy Road, is a circa-1899 Queen Anne, gabled ell, with drop siding, fish scale siding and a small eyebrow window at each gable. Most of the visible foundation is concrete block, at the front corner porch with mansard roof. What appears to be an associated barn, directly across Corduroy Road is a three bay English barn with a shed lean-to, the brick foundation is visible at the shed. A concrete block garage is also present.

A circa-1910 Foursquare at 4701 features vinyl siding, asphalt shingle roof, concrete foundation, modern windows, and an enclosed porch. The house is associated with a deteriorated English barn, corncrib, and a large modern concrete block, commercial-size garage.

At this segment of Corduroy Road, on the north side, there is a large industrial park: Cedar Point Development Park, in the 4000 block. A gambrel-roofed barn was observed on the opposite side of the road, in fair condition, associated with a small brick bungalow, and 1960's commercial building. The commercial building looks like what could have been a lawn and tractor sales facility.

Past the previous farmstead, to the intersection of North Lallendorf Road there are a series of four ranch homes along the north side of Corduroy Road. At 4112 Corduroy Road is Ackerman Berry Farm, a small commercial operation with a small vineyard next to the driveway. The property features a modern cinderblock commercial building and a three-bay barn. The circa-1900 English barn has a modern single bay garage door, metal seam roof, and a few modern windows. There is a rear gabled addition on the rear elevation of the barn.

Along Corduroy from 4033 to 4005, is a series of post-WWII Cape Cod houses. Past the intersection of North Lallendorf Road, on the north side of the road, are the Johlin properties. LUC-249-10 at 3935 Corduroy is the Johlin Winery. The house is a gabled ell with Italianate features. There is a three bay brick garage behind the house, apparently used as a wine cellar and storage facility, another large brick building in ruin, and a large English-type barn that is completely clad in corrugated steel. A large wine barrel trailer parked in front of the barn says "Johlin Century Winery Est. 1870". Several abandoned automobiles were noted throughout the property. The house is in good condition. However, a porch at the front ell has been removed, all windows are modern, as is the steel roof and aluminum soffits. The rear wing appears to be of a later period, possibly from the 1930's although complimentary. The vineyards are no longer present and the most of the trees within the existing landscape, along the driveway, are young.

LUC-248-10, located at 3825 Corduroy Road, west of LUC-249-10, is a former farmstead once associated with Jacob Johnlin circa 1867. The Upright and Wing recorded in the OHI in 1979 that included a log structure, appears to have been replaced by a modern house circa 2007. The outbuildings which include: English barn, two silos, a garage, and a wagon barn, are in poor condition and the vineyard associated with this property is no longer extant. The proposed Project site is located one mile northeast of the property. A large landfill (Envirosafe, located on Otter Creek Road) is clearly visible and adjacent to both of the Johlin properties, along with the massive tanks that are part of the refinery located north

of the property. The original 1867 log home was donated by the Frederick Carl Johlin Sr. to Oregon Metroparks in 2006 and is now located at Pearson Park approximately 1.5 miles south of this site, surrounded by reestablished wetlands. The gated entrance to the park is on Seaman Street, west of Wynn Road.

Seaman Street; Stadium Road; North Curtice Road

Our investigation continued westward along the 3000 section of Seaman Street through the previously surveyed areas that surround the railroad grade separation at the Seaman Street and Norfolk Southern Railroad intersection.

On October 24, 1996, a Phase I Literature Review and Reconnaissance Survey was completed for the Seaman Street/Norfolk Southern Grade Separation in Oregon Township, Lucas County by ASC Group (*Phase I Literature Review and Reconnaissance Survey for the Proposed Improvement of the Seaman Street/Norfolk Southern Grade Separation in Oregon Township, Lucas County, Ohio*; ASC; 1996). The survey covered approximately 74 hectares around the intersection of Seaman Street and Lallendorf Road. Eleven 50-year-old structures were identified in the survey; none of the properties were recommended NRHP-eligible. Our field reconnaissance noticed that two of the previously inventoried properties were no longer extant: LUC-3386-10 and LUC-3387-10.

The Pearson Metropark is located on the south side of Seaman Street, at the southwest quadrant of Wynn Road. The relocated Johlin Cabin is visible approximately 400 feet south of the roadway amid wetlands and is surrounded by walking paths. The cabin retains its corner notch log construction, with horizontal plank siding at the gables. There are new 6 over 6 windows at all elevations but the front which just has a doorway and a single upper level 2 over 2 square light. The front porch is new with rough-hewn pillars and a wooden ADA ramp on the east side. A railroad passes diagonally through the park at the south side; the wooded section park is south of the railroad tracks features Works Progress Administration (WPA)-built elements such as culverts and picnic areas, according to the Metroparks website.

Across Seaman Street from Pearson Park to the north, and toward the Project site, a panoramic view of the industrial skyline dominates the landscape, which include: two 300 feet tall radio towers; water towers; smoke stacks; power lines; and oil tanks.

Oregon Fire Station #1 is located east of Pearson Park, at 5002 Seaman Street, at the southeast corner of Wynn and Seaman. The brick fire station was constructed in 1963. According to the City of Oregon's website, the Oregon Fire Department was organized in 1937 and has been growing ever since. The City of Oregon provides a part-time Fire Department with three modern fire stations equipped with the highest quality fire equipment. Number 1 Station is located at 5002 Seaman Rd., Number 2 Station is located at 1102 S. Wheeling, and Number 3 Station is located at 4421 Bayshore Road. The Fire Administration office is located behind Number 1 Station on Seaman Road.

A few 1940's-era cottages are located at 5022 and 5024 Seaman Street. A large gable end house with Greek revival elements is located at 5128 Seaman. The house sits on rusticated concrete blocks, has novelty siding and 6 over 1 pane windows on the second floor and 10 over 1 windows on the first floor. It has three-bay by two-bay fenestration. There is a modern stoop, centered front porch and enclosed side porch. 5136-5138 Seaman Street are circa 1940s cottages.

Modern and heavily altered houses are seen along the 5000 block of Seaman Street. There is a massive circa-1930's church with Art deco elements. The First Baptist Church building at 5157 Seaman Street has the profile of a large school from the era. The façade is recessed and stuccoed with a large crucifix. The sides are 8 panels of brick, separated by buttresses. The building has a flat roof and a falsefront, stepped roofline at the façade. All windows are multi-light industrial; 5 over 5 on the sides and the four windows at the front are 20 pane industrial, steel or aluminum-framed. The next segment of Seaman Street features a small cape cod, five or more undistinguished ranch homes, two common bungalows at 5248 and 5304. The City of Oregon Municipal Building is located at 5330 Seaman Road and is streamlined brick building that was constructed in 1964. The sprawling, single story building has a flat roof and rounded corners. The roofline edge is capped with limestone slabs and the scuppers drain into copper spouts.

A cross-gabled Queen Anne house on rusticated block is located at 5438. There is fish-scale wood siding at the gables and eyelid windows as well. The rest of the house is clad in asbestos shingles. There is a modern porch and modern windows throughout.

LUC-215-10 is an American Foursquare with an earthen-embanked summer kitchen on the right side. The circa-1900 Ai Ransom Fassett Jr. House. The house is an American Foursquare with hipped roof, dormer windows, and wraparound porch. The house and outbuildings are flanked by a wooded lot on the west side, and modern High School on the east side. The Mr. Fassett and daughter Josephine were instrumental figures in the City of Oregon's educational system and documenting local history (Fassett Middle School is located at 3025 Starr Avenue). The house has been altered with modern, updated, materials, and windows.

Two heavily altered Upright & Wing houses are located at 5501 and 5518. The house at 5518 has a Quonset hut, and 3-bay English Barn, all have been altered with modern materials.

Clay High School is essentially a new, standard school building. A few older structures were observed behind the new additions and main building, such as a circa1930's-era brick workshop. The school's power is supplemented by a large wind turbine, next to the building.

LUC-216-10, at 5749 Seaman Road is the 1893 Clay Chapel Methodist Protestant Church Parsonage. The small side-gable one and a half story cottage with Queen Anne elements is located behind the associated church on the corner of Seaman and Stadium Roads. The Parsonage, and what is now the National Gospel Tabernacle, are associated with the early settlement of Oregon Township, and approximately 1.5 miles east of the Project site.

259-10, at 212 North Stadium Road is the St. Ignatius Roman Catholic Church. The church was constructed in 1927, and is a brick Romanesque Revival building. The church is surrounded by modern development and features a massive rear addition.

At 229 Stadium Road, an altered and updated Upright & Wing was noted on the 106 Survey Table. Another Upright & Wing was noted at 334 Stadium Road with asbestos siding and a rear stucco-covered, later addition. Several ranches and standard bungalows were also observed throughout this segment. Several common American Foursquare homes are located in the 5000 block of Stadium Road, followed by a series of modern houses after 6500.

An American Foursquare constructed entirely of rusticated block was noted at 6660 Seaman Road. Near the 7000 block of Seaman Road is a gabled ell with 6/6 windows and two associated pole barns. At 7133 Seaman Road is the "Fleitz Farm": a Craftsman Foursquare with exposed rafters and brick foundation, established in 1906. There is a pole barn and small cinder block outbuildings at this property as well.

At 110 North Curtice is a bungalow with brick porch with brick and vinyl exterior walls. The Dwight D. Eisenhower School is located on the east side of N. Curtice and features 2 large wind turbines on its premises. The middle school was constructed circa 1960.

Navarre Road

The survey was conducted starting from east to west, toward the Project area. Located at 6827 Navarre Road is the "Goebbells's/Burkholder" Farm at the northwest quadrant of Curtice and Navarre Roads. The farmstead consists of an abandoned gabled ell with wraparound porch and updated materials throughout. The house and it's English barn with lean-to shed and steel gambrel roof, are abandoned and deteriorating to fair condition. A 19th century English barn with Mail Pouch on the side is located at 6459 Navarre Road, with an associated American Foursquare with dormer windows.

The Peach Farm is located at 6113 Navarre Road. The circa-1920's former dairy farm was evaluated in 1996 as eligible for the National Register under Criteria C as a representative farmstead with bank barn and brick American Foursquare house and associated outbuildings. The farmstead has been in the Peach family since its purchase in the first half of the 20th century. The property was included in a transportation study for the widening of LUC-2. The Project is approximately 3 miles northwest of this farmstead.

Another Foursquare house is located directly across from the Peach Farm at 6116 Navarre Road. Several other American Foursquare properties were noted within the 5000 block of Navarre Road and at 741 Stadium Road.

Post WW-II houses and massive contemporary homes were observed along North Stadium Road, heading north from Navarre Road. An Upright and Wing house with Queen Anne elements, vinyl siding, modern exterior materials and rear addition was noted near the intersection of Starr and Wynn. The house also features 19th century outbuildings including a gambrel-roofed, thee bay barn with shed addition, chicken coop, granary, shed, and steel silo.

A vinyl clad upright and wing was recorded at 4047 Star Ave. And another altered Upright and Wing was documented at 3748 Star Road. The area becomes heavily built up and commercialized closer to North Lallendorf Road.

At 3608 Navarre Road is a high-style brick Queen Anne, gabled ell house, with a turret at the corner of the ell. The house is currently used as a doctor's office. A two-bay, two-story, brick carriage house survives behind the house which is in good-to-fair condition.

The general characteristic of this section of Navarre Road is heavily commercialized with strip malls and a Walmart present. A small altered Queen Anne house with associated outbuildings was noted at 4728 Navarre Road. The house presently used as a realty office (Photo 232).

A small brick 1920's era Cape Cod with terra cotta detailing was observed at 5210 Navarre Road. This segment of Navarre Road is characterized by several nondescript, bungalow houses, and a gabled Foursquare. Immediately to the west side of the rail grade crossing is a large, and abandoned apartment or commercial building. Notable building features are its blue glazed tile exterior and a cantilevered concrete portico.

A survey of north Wynn Road at Cedar Point Road found an abandoned brick ellshaped garage/barn structure. The property is apparently owned by one of the power companies. The brick "barn" appears to date to circa 1900. No dwelling is extant at this site. The rest of Wynn Road in this area contains modern houses and two small bungalow/cottages.

Conclusion and Recommendations:

The objective of our Addendum fieldwork and literature research was to help answer two questions:

1. Will construction of the proposed Oregon Clean Energy Center adversely impact National Register-qualified, aboveground properties, beyond the North Lallendorf Road construction site?

The Johlin Farm and Winery (LUC-249-10) located 1.5 miles southwest of the Project on Corduroy Road, west of North Lallendorf Road, was indicated as eligible by the Northwest Regional SHPO in 1979 for its association with the early regional settlers and Italianate architecture (NRHP Criteria B and C). The setting has been compromised by adjacent landfill operations and there have been alterations to the house and loss of at least one of the outbuildings. It is our assessment that its continued meaningfulness as a century old winery and associations with Johlin family early settlement will not be affected by the Project.

The relocated Johlin Cabin to Pearson Park on Seaman Road was recorded in the attached SHPO Section 106 Survey Table.

The St. Ignatius Church (LUC-259-10) NRHP property located at 212 N. Stadium Road, over 1 mile east, was determined to be well outside of range of having any impacts by the Project. None of the elements which contribute to the continued meaningfulness of the 1927 Roman Catholic Church and its Romanesque Revival architecture, will be affected by the Project.

The Peach Farm (LUC-1541-10) located at 6113 Navarre Road (DOE LUC-2-21.15 PID: 9159) was considered outside of the essential range of impacts from the Project, based on our fieldwork. No impacts to the NRHP-qualified farmstead and American Foursquare house are anticipated.

It is our finding that the Project will not adversely impact National Registerqualified or listed aboveground properties that surround the 30-acre parcel. Overall, the power plant will not be an imposition to the existing setting of the area, which is characterized by the existing power facilities, landfill operations, oil refineries, shipping and railroad operations, and other industrial sites.

Our fieldwork and research efforts did not identify any unrecorded, NRHPqualified aboveground properties, to within a reasonable 1.5-to-2.5-mile range of the Project. It was determined that the likely range of impact from the Project on surrounding properties would be negligible based on the existing setting; and our field investigations of the non-industrial areas east of the Project site. Therefore, no further history/architecture impact investigations are recommended.

1. What mitigation efforts can be incorporated into the Project to minimize or mitigate any foreseeable impacts to the continued meaningfulness and preservation of identified National Register-eligible or listed sites?

Based on our research, no further history/architecture survey or mitigation is recommended for the Project. This report, in and of itself, provides a useful foundation for increasing the body of cultural resource knowledge. The documentation reflected in this report can be a base for others to add to in the future to gain a comprehensive architectural survey of upright and wing house in Ohio's northwest counties, as suggested by Glen Harper in his above-referenced 1988 article: Upright and Wing: The No-Nonsense House for documenting the vernacular's migration from the eastern Great Lakes region of New York and Pennsylvania to its common use in northwest Ohio.

References

Andreas and Baskin, pub.

1875 An Illustrated Historical Atlas of Lucas and Part of Wood Counties, Ohio. Andreas and Baskin, Chicago.

Dobson-Brown, D., K. Gibbs, L. Frye, and M. Nickerson 1994 A Cultural Resources Reconnaissance Survey Of The Maumee River Crossing In Lucas And Wood Counties, Ohio (Pid # 10718)

Fassett, Josephine

1961 *History of Oregon and Jerusalem The Story of Two Communities* The Hurley Company Inc., Camden, Arkansas

Gasbarro, Susan, ODOT Interoffice Communication, LUC-2-21.15 PID: 9159, Phase III History/Architecture Evaluation 1997, December 11

Gibbs, Kevin and Lori O'Donnell,

1996 Phase I Literature Review and Reconnaissance Survey for the Proposed Improvement of the Seaman Street/Norfolk Southern Grade Separation in Oregon Township, Lucas County, Ohio

Howe, H. 1888 *Historical Collections of Ohio, Vol. I*. H. Howe & Son, Columbus.

Killits, J., ed. 1923 *Toledo and Lucas County, Ohio 1623-1923*. The S.J. Clarke Publishing Co., Chicago and Toledo.

Knapp, H. S. 1872 *History of the Maumee Valley: commencing with the occupation by the French in 1680*. Slade Mammoth Printing and Publishing House, Toledo, Ohio.

Latham, M. 2010 Cultural Resources Survey of Proposed BP - Husky Toledo Refinery 138/69 kV Substation in Oregon Township, Lucas County, Ohio.

Scribner, H., ed. 1910 *Memoirs of Lucas County and the City of Toledo*. Western Historical Association, Madison, Wisconsin.

Weller, Ryan and Tom Barrett

2012 Phase I Cultural Resource Management Investigations for the Approximately 12.1 ha (30 ac) Lallendorf Road Development in Oregon Township, Lucas County Ohio

Winter, N. O.

1917 A History of Northwest Ohio: Narrative Account of Its Historical Progress and Development from the First European Exploration of the Maumee and Sandusky Valleys and the Adjacent Shores of Lake Erie, down to the Present Time. The Lewis Publishing Company, Chicago and New York.

Online Sources:

Bowling Green Sentinel Tribune, *Black Swamp Once Ruled the Land and People*, June 10,1999;

<u>http://www.nwoet.org/swamp/PDF/black_swamp_people.PDF</u> Accessed January 24, 2013

Harper, Glen A.

December 1988, *Upright and Wing: The No-Nonsense House*, *Archive Chronicle*, Volume 7, Number 3 Bowling Green State University; Center for Archival Collections

http://www.bgsu.edu/colleges/library/cac/ac/page47043.html (Accessed January 24, 2013)

Oregon, City of 2012 *History*. <u>http://www.oregonohio.org/Community/history.html</u> (Accessed October 4, 2012)

Wilhelm, Peter 1984:83-84 <u>http://www.horizonview.net/~ihs/Transportation/Transp-Story-M&WRrd.html</u> (Accessed January 28, 2013).

Primary Sources:

Oregon and Jerusalem Historical Society; email correspondence January 25, 2013

Peach, Gerald; personal correspondence in the field on January 14, 2013.

Attachment A

Figures

Figures Oregon Gas to Electric Power Plant APE Survey -Appendix A History/Architecture Vintage Resource Studies February 12, 2013




Figure 1. Project area on 1965 Oregon USGS 7.5 Minute Quadrangle Map




Figure 2. Previously recorded history/architecture sites within the 5-Mile APE.

Figures

Oregon Gas to Electric Power Plant APE Survey -Appendix A History/Architecture Vintage Resource Studies February 12, 2013




Figure 3. Arial Map of OPSB 5-mile Study Radius and APE with a 1 mile buffer around the Project site.

Figures

Oregon Gas to Electric Power Plant APE Survey -Appendix A History/Architecture Vintage Resource Studies February 12, 2013




Figure 4. Portion of the Illustrated Historical Atlas of Lucas and Part of Wood Counties, Ohio (Andreas & Baskin 1875) showing the approximate location of the project area.




Figure 5. Portion of the 1900 Maumee Bay, Ohio Quadrangle 15 Minute Series (Topographic) map showing the approximate location of the project area.

Figures Oregon Gas to Electric Power Plant APE Survey -Appendix A History/Architecture Vintage Resource Studies February 12, 2013




Figure 6. Diagram based on Ohio SHPO's Online Mapping System. The area highlighted in Zone 1, was determined to have a greater potential for impacts from the proposed gas-to-electric power plant. Properties within Zone 1 over fifty years old were photographed and documented in SHPO's Section 106 Survey Table.

Attachment B

SHPO Section 106 Survey Tables for Zone 1 and Photo Log

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM.	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
90-91		Ackerman Berry Farm	11		RESIDENTIAL/DOMESTIC	Unknown	unk / 1990ca	
	Lucas	4112 Corduroy Road	295948		Non-discernable House Type		Alteration	
	Oregon	Oregon	4614482		No academic style - Vernacular	Stucco	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				English Barn with modern overhead door.	n overhead door.		thomas	
							barrett	
							Vrs	
		Harbor View Village	17		RESIDENTIAL/DOMESTIC		/	
	Lucas	Bayshore Road			Cape Cod Cottage/Williamsburg			
	Oregon	Bay (corporate name Bay Village)				Wood		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				community of cottages mostly altered.	nostly altered.		thomas	
							barrett	
114			17		RESIDENTIAL/DOMESTIC	Brick bearing	1870ca. /	
	Lucas	4328 Bayshore Rd.	296465		Gabled Ell	Balloon/western/platform fram		
	Oregon	Oregon	4618333		No academic style - Vernacular	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number: LUC024110	Preparer Information	
							thomas	
							barrett vrs	
4 4 2		RBM Construction	17		Office		1900ca /	
	Lucas	4400 Bashore Road	296097					
	Oregon	Oregon	4618676					
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number: LUC024210	Preparer Information	
							thomas	
							barrett vrs	
112			17		RESIDENTIAL/DOMESTIC	Brick bearing	1880ca /	
	Lucas	4526 Bayshore Road	296648		American foursquare	Balloon/western/platform fram		
	Oregon	Oregon	4618327		Queen Anne	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number: LUC024510	Preparer Information	
							thomas	
							barrett	
							217	

Page 1 of 35

Section 106 Review Project Summary Form Documentation Table

×.	_
- 2	
. 0	D
- 2	5
-	2
	-
- 2	
- 24	-
-	
-	
_	
~	-
_	
-	
- 7	•
	,
	Ph.
	•
	-
• •	כ
- 2	-
	-
2	

Section 106 Review Project Summary Form Documentation Table

Projec	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	o County	Drowing Address	UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
⊇	Quad. Name	Property Address	Coora.	Information	Architectural Style	Exterior Wall	Current Condition	
107			17		RESIDENTIAL/DOMESTIC	Brick bearing	1900ca /	
	Lucas	4516 Bayshore rd.	296811		American foursquare	Balloon/western/platform fram		
	Oregon	Oregon	4618326		Queen Anne	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:	_	Further Description		OHI Number: LUC1900	Preparer Information	
							thomas barrett	
			17		RESIDENTIAL/DOMESTIC	Concrete block	1879ca. /	
	Lucas	4454 Bashore Road	296726		I House	Brick bearing		
	Oregon	Oregon	4618326		Italianate	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC024310	Preparer Information	
							thomas barrett vrs	
106		Enviro Safe	17					[
	Lucas	Otter Creek Road	294809					
	Oregon	Oregon	4615921					
Additi	Additional Sources of Information:	rmation:		Further Description landfill operation		OHI Number:	Preparer Information	
104-		Johlin's Blue Chip Farm	17		Agricultural Outbuildings		1870 ca /	
401	Lucas	3825 Corduroy Road	295456					
	Oregon	Oregon	4614926					
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				modern house associated with outbuildings.	d with outbuildings.		thomas	
							barrett vrs	
7					RESIDENTIAL/DOMESTIC	Brick bearing	ca. 187 /	
	Lucas	5252 Cedar Point Road			Gabled Ell	Brick bearing		
		Oregon (Township of)			Italianate	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field o	Field observation from roadway.	way.		Gambrel roof barn and e	Gambrel roof barn and english three bay barn associated with house.	d with house.	Thomas	
							barrett Vintage Resourse Studies	
							5]

2
6
0
È
2
*
+
2
C
2
7
2
2

ŝ
З
of
က
Ð
D
g
<u>Ω</u>

		Section 10	6 Reviev	v Project Summa	Section 106 Review Project Summary Form Documentation Table	ation Table
roject	Number:					
	Ref. Number	Present Name			Present use	Foundation Mater
hoto	County		UTM	Owner	Building Type	Wall Construction
~	•	Dronowty, Addroce	1000 C	Information		

Project	Project Number:		o Keviev		Section 100 Keview Project Summary Form Documentation Table			
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo		Property Address	MTU	Owner Information	Building Type	Wall Construction		Elig.
2	Quad. Name				Architectural Style	Exterior Wall	Current Condition	
89			17		RESIDENTIAL/DOMESTIC		/	
	Lucas	4033 4025 4015 4005 Corduroy Ro	295781		Cape Cod Cottage/Williamsburg			
	Oregon	Oregon	4614848		Craftsman/Arts and Crafts			
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
			17				1	
	Lucas	4960 Bay Shore Road	297717				Date demolished	
	Oregon	Oregon	4614811					
Additio	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC027110	Preparer Information	
				removed			thomas barrett vrs	
					RESIDENTIAL/DOMESTIC		1960ca /	
	Lucas	unknown addresses Corduroy Roa			Ranch			
		Oregon			No academic style - Vernacular			
Additio	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				4 consective ranches north to lollendorff Road	rth to lollendorff Road			
			17		RESIDENTIAL/DOMESTIC	Unknown	1940ca /	
	Lucas	4262 Corduroy Road	296268		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614836		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additio	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							thomas	
							barrett vrs	
87-88			17		RESIDENTIAL/DOMESTIC	Brick bearing	1920ca /	
	Lucas	340??? Corduroy Road			Bungalow	Brick bearing		
		Oregon			Craftsman/Arts and Crafts	Brick		
Additio	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				1960's block commercial	1960's block commercial building Gambrel roof three bay barn.	y barn.	thomas	
							barrett	
							VrS	

Documentation
Form
Summary
Project
Review
106
Section

35
of
4
ge
ğ

Project	Project Number:	Section 10)6 Revie v	v Project Summa	Section 106 Review Project Summary Form Documentation Table	ation Table	Page 4 of 35	
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		NTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
86			17		RESIDENTIAL/DOMESTIC	Brick bearing	1870 /	
	Lucas	4560 Corduroy Road	296386		Upright and Wing	Balloon/western/platform fram		
	Oregon	Oregon	4615192		No academic style - Vernacular	Aluminum or vinyl siding		
Additio	Additional Sources of Information:	ormation:	_	Further Description		OHI Number:	Preparer Information	
							thomas	
							barrett vrs	
82			17		RESIDENTIAL/DOMESTIC	Concrete block	1910 /	
	Lucas	4701 Corduroy Road	297374		American foursquare	Balloon/western/platform fram		
	Oregon	Oregon	4614836		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additio	Additional Sources of Information:	ormation:		Further Description	0	OHI Number:	Preparer Information	
				con crib. English Barn with steel roof.	th steel roof.		thomas	
							barrett rs	
81			17		RESIDENTIAL/DOMESTIC	Brick bearing	1920ca /	
	lucas	4811 Cordurov Road	297485		American foursquare	Balloon/western/blatform fram		
			001					
	Oregon	Oregon	4614875		Bungalow	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	ormation:		Further Description	0	OHI Number:	Preparer Information	
field							thomas	
							barrett	
							VrS	
80			17		RESIDENTIAL/DOMESTIC	Unknown	1890ca / 2000ca	
	Lucas	4920 Corduroy Road	297592		Upright and Wing	Balloon/western/platform fram	Alteration	
	Oregon	Oregon	4614557		Greek Revival	Aluminum or vinyl siding	Good/Fair	
Additio	Additional Sources of Information:	ormation:	-	Further Description		OHI Number:	Preparer Information	
							thomas	
							barrett	
							VrS	
79			17		RESIDENTIAL/DOMESTIC	Brick bearing	1940ca /	
	Lucas	4960 Corduroy Road	297717		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614811		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additio	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett	
							VRS	

Project	Project Number:	Section 10)6 Reviev	w Project Summ	Section 106 Review Project Summary Form Documentation Table	ation Table	
	Ref. Number	Drosont Namo			Present use	Foundation Material	<u>}</u>
Photo	County		UTM	Owner	Building Type	Wall Construction	٩
2	Quad. Name	Lioperty Audress	coora.	Information	Architectural Style	Exterior Wall	0
92-		Johlin Winery	17	johlin	RESIDENTIAL/DOMESTIC	Brick bearing	-
103	Lucas	3935 Corudroy Road	295628		Gabled Ell	Brick bearing	
	Oregon	Oregon	4615041		Italianate	Brick	ш
Additi	Additional Sources of Information:	ormation:		Further Description	0	OHI Number: LUC024910	10 1
				Winery in operation. Adj building in ruin also. Bric	Winery in operation. Adjacent landfill operation observed. Brick barn, and brick building in ruin also. Brick garage. Hocking Block paved driveway.	. Brick barn, and brick driveway.	<u>م</u> ط
							>
130		Edward Scheizer House	17	schweizer	RESIDENTIAL/DOMESTIC	Brick bearing	÷
	Lucas	3948 Seaman Road	295660		Upright and Wing	Brick bearing	
	Oregon	Oregon	4613800		Greek Revival	Brick	
Additi	Additional Sources of Information:	ormation:		Further Description	0	OHI Number: LUC21410	P
OHI 15	OHI 1979/ Field Review 2013	13		Brick Barn present.			- ·
							<u> </u>
			17		RESIDENTIAL/DOMESTIC		-
	Lucas	5024-5022 Seaman Street	297840		Cape Cod Cottage/Williamsburg		
	Oregon	Oregon	4613985			Stone	
Additi	Additional Sources of Information:	ormation:		Further Description	0	OHI Number:	a
Field							-
							<u> </u>
		Oregon Fire Station #1	17		Fire station	Concrete block	· ~
	Lucas	5020 Seaman Street	297825		Garage	Brick bearing	
	Oregon	Oregon	4614023		pom	Brick	
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	•

NRHP Elig.

Year Built/Altered

>

Current Condition

1870ca /

Alterations

Preparer Information

thomas

barrett

VLS

Excellent

1870ca. /

Preparer Information

Thomas

Barrett

VRS

1945ca. /

Preparer Information

Thomas

Barrett

VRS

1963ca. /

Preparer Information

Thomas

Barrett

VRS

1830ca. / 2006

Concrete block

Hewed log

Park Double Pen

Metroparks

17 297487

Johlin Cabin Pearson Metropark

139

Field

Pearson Metropark

Oregon

Lucas Oregon Metropark interpretive sign. Field observation.

Additional Sources of Information:

Date moved

Good/Fair

Preparer Information

OHI Number:

Further Description

4613755

Thomas

Barrett

The hand hewn log cabin was previously located 1.5 miles away on Corduroy Road, between Coy and Lallendorf. 20x26 foot. Frederick Carl Johlin Sr. donated the structure to Metroparks in 2006. Pearson Park is considered preserved area of Black Swamp

VRS

۳
- 2
5
Z
-
്
Ð
0
<u> </u>

Projec	Project Number:							
		Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo ID	County Quad. Name	Property Address	UTM Coord.	Owner Information	Building Type Architectural Style	Wall Construction Exterior Wall	Alterations Current Condition	
137- 138		Dale Richardson House	17	Dale Richardson	RESIDENTIAL/DOMESTIC		1945ca. /	
	Lucas Oregon	4651 Seaman Street Oregon	297070 4513830		Cape Cod Cottage/Williamsburg			
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338910	Preparer Information	
OHI a	OHI and Field observation			WWII era brick cape cod cottage.	cottage.		Thomas Barrett VRS	
136		Beeler House and Farm	17	Charles	RESIDENTIAL/DOMESTIC	Brick bearing	1870ca. /	
	Lucas	4609 Seaman Road	296940	Beeler	Upright and Wing	Balloon/western/platform fram		
	Oregon	Oregon	4613830		No academic style - Vernacular	Drop or novelty siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338810	Preparer Information	
Field	Field and OHI			Two associated steel pole barns.	e barns.		Thomas Barrett VRS	
135		Segura House	17		RESIDENTIAL/DOMESTIC	Brick bearing	1899ca. /	
	Lucas	149 Lollendorf Road	296060		One-room Schoolhouse	Balloon/western/platform fram	Alteration	
	Oregon	Oregon	4614160			Drop or novelty siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338110	Preparer Information	-
OHI a	OHI and Field observation			The schoolhouse has be additions and alterations.	The schoolhouse has been increasingly obscured over the past 20 years with additions and alterations.	the past 20 years with	Thomas Barrett VRS	
					DEMOLISHED		/ 1996ca.	
							Date demolished	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338710	Preparer Information	
Field								
			17		DEMOLISHED		/ 1996ca. Date demolished	
Additi Field	Additional Sources of Information: Field	rmation:		Further Description		OHI Number: LUC338610	Preparer Information Thomas Barrett VRS	

cer:
Jum
SC P
roie

Project	Project Number:					·		
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
117		Church	17		Church/Religious Structure		1880ca /	
		5224 Bay Shore road	298228					
	Oregon		4617902					
Additio	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC027210	Preparer Information	
				Church			SUV	
							0	
131- 132		Schweizer Fruit Farm	17	Schweizer	RESIDENTIAL/DOMESTIC	Brick bearing	1880ca. <i> </i>	
	Lucas		0/0/67					
	Oregon	Oregon	4613830		Queen Anne	Asbestos/asphalt siding		
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number: LUC338410	Preparer Information	
OHI 15	OHI 1995 RR grade survey; Field	Field					Thomas	
							Barrett VRS	
116,1		Wynn School	17		School		1	
18	Lucas	Unknown address Bay Shore Road	298223					
	Oregon	Oregon	4618011		Gothic Revival			
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							thomas	
							barrett vrs	
129			17	Ţ	RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	3909 Seaman Road	295560		Bungalow	Brick bearing		
	Oregon	Oregon	4613830		Colonial Revival	Brick		
Additio	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338310	Preparer Information	
OHI 15	OHI 1995 RR grade survey			two car garage.			Thomas	
							Barrett	
							VRS	
128		Greenhagen John Smith House	17	Ernest	RESIDENTIAL/DOMESTIC	Brick bearing	1890ca. /	
	Lucas	3856 Seaman Road	295470		Gabled Ell	Balloon/western/platform fram		
	Oregon	Oregon	4613780		No academic style - Vernacular	Wood		
Additid	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338210	Preparer Information	
OHI 1995	<u> 995</u>			This house was moved fr previous research	This house was moved from the property associated with Marathon Oil according to previous research	Marathon Oil according to	Thomas	
							Barrett	
							VRS	

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM .	Owner	Building Type	Wall Construction	Alterations	Elig.
⊇	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
127			17		RESIDENTIAL/DOMESTIC	Brick bearing	1919ca /	
	Lucas	3834 Seaman Road	295389		Bungalow	Brick bearing		
	Oregon	Oregon	4613760		Craftsman/Arts and Crafts	Brick		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC213810	Preparer Information	
RR gra	RR grade crossing survey ASC 1993	SC 1993		Large powerlines overhe	Large powerlines overhead. 3 bay frame garage with pyramidal roof.	amidal roof.	Thomas	
							Barrett VRS	
			17		RESIDENTIAL/DOMESTIC		1945 /	
	Lucas	3431-3535 Seam Road	294597		Bungalow			
	Oregon	Oregon	4614062		No academic style - Vernacular			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas Barrett	
							VRS	
126		Baptist Church	17	American Freewill Baptist	Chapel	Brick bearing	1907 / 1947	
	Lucas	3409 Seaman Road	294558		One-room Schoolhouse	Brick bearing	Alteration	
	Oregon	Oregon	4614042			Brick	Good/Fair	
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC025810	Preparer Information	
Field / OHI	IHO						Thomas	
							Barrett	
							VRS	
122			17		RESIDENTIAL/DOMESTIC	Brick bearing	1920ca /	
	Lucas	1281 N. Stadium Road	299394		American foursquare	Brick bearing		
	Oregon	Oregon	4616676		Bungalow	Brick		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				Light Brick foursquare.			Thomas	
							Barrett	
		WW II era housing development	17		RESIDENTIAL/DOMESTIC		-	[
	Lucas	N. Stadioum Road	299562		Bungalow			
	Oregon	Oregon	4617372					
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				large addtion of wwll hou	large addition of wwll housing approximately 2 miles away from Maumee River east.	y from Maumee River east.	thomas	
							barrett	
							VrS	

Page 8 of 35

- 6
ŏ
_ ⊏
n
Z
- #
ž
.≝
0
<u> </u>

Lujec								
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
			17				/ 2000ca	
	Lucas	5520 Bay Shore Road	298817				Date demolished	
	Oregon	Oregon	4618040					
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC032210	Preparer Information	
				gone			thomas	
							barrett vrs	
72			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1930ca /	
	Lucas	5459 Corduroy Road	298914		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614837		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett	
							VRS	
133		Meyer House	17		RESIDENTIAL/DOMESTIC	Concrete block	1870ca. / 1996ca.	
	Lucas	4209 Seaman / Lollendorf	296140		Upright and Wing	Balloon/western/platform fram	Date moved	
	Oregon	Oregon	4613830		No academic style - Vernacular	Drop or novelty siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC338510	Preparer Information	
OHI ar	OHI and Field observation			Likely moved for Railgrac	Likely moved for Railgrade construciton and outbuildings removed.		Thomas	
							Barrett	
							VRs	
			17		RESIDENTIAL/DOMESTIC	Brick bearing	1880ca / 1960ca	
	Lucas	6011 Corduroy Point Rd.			Gabled Ell			
		Oregon			No academic style - Vernacular		Some alteration	
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number:	Preparer Information	
Field							Thomas	
							Barrett	
78			17		RESIDENTIAL/DOMESTIC	Brick bearing	1920ca. / 1988ca	[
	Lucas	4961 Corduroy Road	297710		American foursquare	Balloon/western/platform fram	Alteration	
	Oregon	Oregon	4614874		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							thomas	
							barrett	
							Vrs	

1		
1	۰.	_
1	2	2
1	u	9
	e	5
-	1	4
1	-	-
	c	-
1	-	=
1		3
÷		-
2	2	-
-		-
4		
2	7	2
1	L	,
	6	h
1	u	,
٠	-	-
	С	3
1	2	-
1	-	-
ſ	٦	

Fosort Name Fosort Name Fosort Name Fosort Name Fosort Name Foreiro Address Um Address Control Fosort Name Address Fosort Las Restriction Manual Address Fosort Las Restriction Manual Address Restriction Manual Addres Manual Addre	Projec	Project Number:							
County build, manual build, manual		Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	
Qued, Name Trophy Paddres Dord. Immetation Resolution Mail Resolution Mail <t< th=""><th>Photo</th><th></th><th></th><th>MTU</th><th>Owner</th><th>Building Type</th><th>Wall Construction</th><th>Alterations</th><th>Eliy.</th></t<>	Photo			MTU	Owner	Building Type	Wall Construction	Alterations	Eliy.
Lumbin Origination Title Secondary rand Origination Title Secondary rand Origination Title Secondary rand Secondary random Title Secondary random Secondary random Unionination	a		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
Itema 2010 contany radii 201830 4614738 Bungalow 4614738 Bungalow 60mpon Bungalow 40mmon viry suffixy Internation: -0mpon 0mpon -0mpon -0mpon -0mmon viry suffixy Internation: -0mpon 2018 -0mpon -0mmon viry suffixy -0mmon viry suffixy Internation: -0mpon 2000 -0mpon -0mmon viry suffixy -0mmon viry suffixy Internation: -0mpon -0mpon -0mmon viry suffixy -0mmon viry suffixy Internation: -0mpon -0mpon -0mmon viry suffixy -0mmon viry suffixy Internation: -0mpon -0mmon viry suffixy -0mmon viry suffixy -0mmon viry suffixy Internation: -0mpon -0mmon viry suffixy -0mmon viry suffixy -0mmon viry suffixy Internation: -0mpon -0mmon viry suffixy -0mmon viry suffixy -0mmon viry suffixy Internation: -0mmon viry suffixy -0mmon viry suffixy -0mmon viry suffixy Internation: -0mmon viry suffixy -0mmon viry suffixy -0mmon viry suffixy Internation:	44-45			17		RESIDENTIAL/DOMESTIC	Unknown	1910ca. / 1990ca.	
Oropon Oropon Oropon Automations Automations Automations Automations Idencial Sources of Informations Total Sources of Informations Further Description Automations		Lucas	7010 corduroy road	301839		Bungalow	Balloon/western/platform fram	Alteration	
Interface Eurlan Eurlan OH Number: Inclusion Today Today Ranch Rest ReTrutuDOMESTIC Interface Inclusion Consumery red 301838 Ranch Rest RetrutuDOMESTIC Interface Inclusion Consumery red 301838 Ranch Rest RetrutuDOMESTIC Unknown Inclusion Consumery red 301838 Ranch Rest RetrutuDOMESTIC Unknown Inclusion Inclusion Inclusion 17 Rest RetrutunuDOMESTIC Unknown Inclusion Inclusion Inclusion Inclusion Rest RetrutunuDOMESTIC Unknown Inclusion Inclusion Inclusion 17 Rest RetrutuuDOMESTIC Inclusion Inclusion Onegoin Onegoin Onegoin Inclusion Rest RetrutuuDOMESTIC Inclusion Inclusion Onegoin Onegoin Onegoin Inclusion Rest RetrutuuDOMESTIC Inclusion Inclusion Inclusion Onegoin Inclusion Rest RetrutuuDOMESTIC Inclusion <td></td> <td>Oregon</td> <td>Oregon</td> <td>4614738</td> <td></td> <td>Craftsman/Arts and Crafts</td> <td>Aluminum or vinyl siding</td> <td>Good/Fair</td> <td></td>		Oregon	Oregon	4614738		Craftsman/Arts and Crafts	Aluminum or vinyl siding	Good/Fair	
Interaction Total Control Protein Essible Fritu.DoMESTIC Result InterAction Interaction Onegon Onegon 46.4738 Panch Panch Panch Interaction Onegon Onegon 46.4738 Panch Panch Panch Panch Interaction Onegon Onegon A6.4738 Panch Panch <t< td=""><td>Additi</td><td>onal Sources of Infor</td><td>rmation:</td><td></td><td>Further Description</td><td></td><td>OHI Number:</td><td>Preparer Information</td><td></td></t<>	Additi	onal Sources of Infor	rmation:		Further Description		OHI Number:	Preparer Information	
Luess 725 Groundy Rd. 013 17 Residential conception Residential conception Oregon Oregon 0								Thomas Barrett	
Lues Torgon Torgon Solds Search Solds Search Solds Search	42			17		RESIDENTIAL/DOMESTIC			
Oregin Oregin Oregin Reface Mathematical Iditional Sources of Information: Further Description Enther Description OH Number: Lucas neth curfie Information: Informatical Oncome Oregon Oregon Neth curfie Informatical Oncome Oregon Oregon Neth curfie Informatical Informatical Lucas Modern Houses cape cod and rach 17 Purther Description Added Ele Lucas Modern Houses cape cod and rach 17 Purther Description Added Ele Lucas Oregon Oregon Oregon 17 Purther Description Oregon Oregon Oregon Oregon 17 Purther Description Added Ele Lucas Oregon Oregon Oregon 17 Purther Description Added Ele Lucas Oregon Oregon Oregon 17 Purther Description Added Ele Lucas Oregon Oregon Oregon Purther Description <t< td=""><td></td><td>Lucas</td><td>7025 Corduroy Rd.</td><td>301839</td><td></td><td>Ranch</td><td></td><td></td><td></td></t<>		Lucas	7025 Corduroy Rd.	301839		Ranch			
Interface of Information: Eurlier Description Other Description Other Description Other Description Loas ordin curries ordin curries 11 Rest Entrancom Uninnom Loas Oregon Oregon Oregon Creation Uninnom Oregon Oregon Oregon Territer Description Rest Entrancom Astest estassing of thinound Loas Modern Houses cape cod and rach 17 Further Description Paranta Astest estassing of thinound Loas Concores of Information: Concores of Information Rest Entranco Paranta Loas Oregon Oregon 17 Rest Entranco Paranta Uninnom: Oregon Oregon 18 Rest Formation Paranta Uninnom: Oregon Oregon 17 Rest Formation Paranta Uninnom Oregon Oregon 17 Rest Formation Paranta Uninnom Oregon Oregon 2000 Rest Formation Oregon Paranta O		Oregon	Oregon	4614738					
Index English Barn with shed lean to shed and concrete foundation Lucas north curfae 17 RESIDENTIALIDOMESTIC Unhown Oregon Oregon Oregon Itelanate Astestossephartiscling Oregon Oregon 17 Further Description Astestossephartiscling Iditional Sources of Information: Further Description RESIDENTIALIDOMESTIC Unhown Iditional Sources of Information: Contromy Road 17 Further Description Iditional Sources of Information: Contromy Road 17 Residentiation Iditional Sources of Information: Oregon Oregon Astestossephartiscling Iditional Sources of Information: Oregon 17 Residentiation	Additi	onal Sources of Infor	rmation:		Further Description	_	OHI Number:	Preparer Information	
Lucas The information The information Information Oregon Oregon Oregon Oregon Assessessephatisting Oregon Oregon Oregon Oregon Assessessephatisting Infinant Sources of Information: Oregon The infinante Assessessephatisting Infinant Sources of Information: Modern Houses cape cod and rach The infinante Perther Description Lucas Modern Houses cape cod and rach The infinante Perther Description Perther Description Lucas Oregon Oregon Oregon Perther Description Perther Description Lucas Oregon Oregon Oregon State Treatment Plant Perther Description Lucas Oregon Oregon Oregon State Treatment Plant Perther Description Lucas Oregon Oregon Oregon State Treatment Plant Perther Description					English Barn with shed le	ean to shed and concrete found	lation	Thomas Barrett	
Indication Cabled Eliminate Unknown Huses cape cod and rach 17 Purther Description Asbestosfasphattsding Huses cape cod and rach 17 RESIDENTIAL/DOMESTIC Albestosfasphattsding Water Treatment Plant 17 Residendia Albestosfasphattsding Water Treatment Plant 17 Residendia Albestosfasphattsding Water Treatment Plant 17 Mater Related Albestosfasphattsding Water Treatment Plant 17 Mater Related Albestosfasphattsding Water Treatment Plant 17 Mater Related Albestosfasphattsding Mater Treatment Plant 17 Mater Related Albestosfasphattsding	41			17		RESIDENTIAL/DOMESTIC	Unknown	1890ca. / 1990ca.	
Image: Normal System Image: Normal System Aspestos(asphalt s(ding Aspestos(asphalt s(ding Aspestos)) Houses cape cod and rach 17 Purther Description Moad 17 ResIDENTIAL/DOMESTIC Moad 17 Rench Moad 17 Rench Mater Treatment Plant 17 Mater Related Mater Related		Lucas	north curtice			Gabled Ell	Unknown	Alteration	
Humber: OH Number: Humber: 17 Residential Humber: 17 Residential Nade 17 Residential Mater Treatment Plant 17		Oregon	Oregon			Italianate	Asbestos/asphalt siding	Deteriorated	
Houses cape cod and rach 17 RESIDENTIAL/DOMESTIC y Road 17 Ranch y Road Ranch Ranch Mater Treatment Plant 17 Nater Related 302556 302556 Mater Related Af 515761 Treatment Plant Nater Related Mater Treatment Plant 17 Mater Related Image: Related Mater Related OHI Number:	Additi	onal Sources of Infor	rmation:		Further Description		OHI Number:	Preparer Information	
Houses cape cod and rach y Road 17 RESIDENTIAL/DOMESTIC y Ranch Ranch Ranch Yater Treatment Plant 17 OHI Number: Water Treatment Plant 17 Water Related 302556 302556 Water Related 4615761 Ther Description								Thomas Barrett	
y Road Hart Treatment Plant i Water Treatment Plant i 302556 4615761 Vater Related i 4615761 Vater Related i 4615761 OH Number: OH Number: OH Number: OH Number:			Modern Houses cape cod and rach	17		RESIDENTIAL/DOMESTIC		1955ca. /	
Water Treatment Plant T Further Description Water Treatment Plant 17 Water Related 302556 4615761 Mater Related 4615761 Eurther Description		Lucas	Corduroy Road			Ranch			
Water Treatment Plant 17 OHI Number: Water Treatment Plant 17 Nater Related 302556 302556 Water Related 302556 4615761 Mater Related 1 17 Mater Related		Oregon	Oregon						
Water Treatment Plant 17 Water Related 302556 302556 4615761 Alther Description	Additi	onal Sources of Infor	rmation:		Further Description		OHI Number:	Preparer Information	
Water Treatment Plant 17 Water Related 302556 4615761 After Description OHI Number:								Thomas Barrett	
302556 4615761 Further Description OHI Number:	39		Oregon Water Treatment Plant	17		Water Related		1966ca. /	
4615761 Further Description OHI Number:		Lucas	Curtice	302556					
Further Description OHI Number:		Oregon	Oregon	4615761					
	Additi	onal Sources of Info	rmation:		Further Description		OHI Number:	Preparer Information Thomas Barrett	

ŝ	
\$	2
ŝ	
	5
2	2
ţ	5
-5	D
5	2
n	

Projec	Project Number:					·		
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM .	Owner	Building Type	Wall Construction	Alterations	Elig.
≘	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
32-36		Bay View Bed and Breakfast	17	Davies	Hotel/Inn/Motel	Brick bearing	1879ca. / 1990ca	
	Lucas	7250 Cedar Point Rd.	302385		I House	Brick bearing	Addition	
	Oregon	Oregon	4616351		itaianate	Brick	Excellent	
Addit	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
Field				Original brick italianate w	Original brick italianate with large modern side-gable addition making it an	dition making it an	Thomas	
				oversized ell.			Barrett	
29-31		Myers Farm	17	Beichter 1898	RESIDENTIAL/DOMESTIC	Brick bearing	1898 /	[
	Lucas	6810 Cedar Point Road	301493			Brick bearing		
	Oregon	Oregon	4616375		Neo-Classical Revival	Brick		
Addit	Additional Sources of Information:	ormation:		Further Description	_	OHI Number:	Preparer Information	_
Field				Beichter 1898 English Ba	Beichter 1898 English Barn; corn crib; several steel outbuildings. House is brick	uildings. House is brick	Thomas	
						ונכוווות מוכא.	Barrett VRS	
			17		Agricultural Outbuildings		_	
	Lucas	6706 Corduroy Road	3011982		English or Three Bay Barn			
	Oregon	Oregon	4614694					
Addit	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
22		Vail Farms	17	Berger	RESIDENTIAL/DOMESTIC		1890ca. / 1970ca.	
	Lucas	6118 Cedar Farms					Addition	
	Oregon	Oregon					Some alteration	
Addit	Additional Sources of Information:	ormation:		Further Description		OHI Number: LUC20310	Preparer Information	_
Orego	Oregon-Jerus. Twp hist. soc. OHI	c. OHI					Thomas	
							Barrett	
47		Simpler Times	17		COMMERCIAL		1949ca. / 2000ca.	
	Lucas	6601 Norden Road	301014				Alteration	
	Oregon	Oregon	4614815			Aluminum or vinyl siding	Excellent	
Addit	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
							Barrett	
							Thomas	
							2	

Table
Documentation
Form
Summary
w Project
S Revie
ion 106
Sect

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM .	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
21			17		COMMERCIAL	Concrete block	1	
	Lucas	5940 Cedar Point Rd.	299707		COMMERCIAL	Concrete block		
	Oregon	Oregon	4616406			Concrete		
Additic	Additional Sources of Information:	rmation:		Further Description	0	OHI Number:	Preparer Information	
Field							Thomaas	
							Barrett	
20			17		RESIDENTIAL/DOMESTIC		1950ca. /	
	Lucas	5824 Cedar Point Road	299494		Cape Cod Cottage/Williamsburg			
	Oregon	Oregon (Township of)	4616419					
Additic	Additional Sources of Information:	rmation:		Further Description	0	OHI Number:	Preparer Information	
							Thomas Barrett	
18-19			17	Ernie Dickens	RESIDENTIAL/DOMESTIC	Brick bearing	1860ca. <i> </i>	
	Lucas	5808 Cedar Point Road			I House	Brick bearing	Alteration	
	Oregon	Oregon (Township of)			Greek Revival	Aluminum or vinyl siding	Good/Fair	
Additic	Additional Sources of Information:	rmation:		Further Description	0	OHI Number: LUC020210	Preparer Information	
Field and OHI	IHO PU			Brick is now clad in vinyl Italianate window details	Brick is now clad in vinyl siding. Window sills are very deep on the core I-house.	ep on the core I-house.	Thomas	
							Barrett	
1			7		COMMEDCIAL	Concrete block	106603 /	
2			-				1.0000	
	Lucas	1200 N. Stadium Road	299442			Concrete block		
	Oregon	Oregon	4616466			Concrete	Good/Fair	
Additic	Additional Sources of Information:	rmation:		Further Description	0	OHI Number:	Preparer Information	
Field							Thomas	
							Barrett	
							VRS	
13-15			17		Agricultural Outbuildings		1	
	Lucas	5741 Cedar Point Road	299352					
	Oregon	Oregon	4616475					
Additic	Additional Sources of Information:	rmation:		Further Description	0	OHI Number:	Preparer Information	
Field							Thomas	
							Barrett	
							VK3	

Table
Documentation
Form
t Summary
Project
Review
106 ו
Sectior

Project Number:	iber:							
Ref	Ref. Number	Dresent Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo Cou	County		UTM .	Owner	Building Type	Wall Construction	Alterations	Elig.
	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
12			17		RESIDENTIAL/DOMESTIC	Concrete block	1930ca. /	
Lucas	as	5604 Cedar Point Rd.	298979			Balloon/western/platform fram		
Oregon	gon	Oregon	4616420		Craftsman/Arts and Crafts	Wood		
Additional 3	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
Field							Thomas	
							uren VRS	
10-11			17		RESIDENTIAL/DOMESTIC		1940ca. /	
Lucas	as	5415 Cedar Point Road	298986		Bungalow	Balloon/western/platform fram		
Oregon	gon	Oregon (Township of)	4616941		Craftsman/Arts and Crafts	Wood	Good/Fair	
Additional 3	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
Field							Thomas Barrett VRS	
ი			17		RESIDENTIAL/DOMESTIC	Unknown	/ 1950 ca.	
Lucas	as	5553 Cedar Point Road	299092		Duplex (side-by-side)	Balloon/western/platform fram	1980 ca.	
Ore	Oregon	Oregon (Township of)	4616409		ranch	Aluminum or vinyl siding	Good/Fair	
Additional :	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
							Thomas Barrett	
							VRS	
8			17		RESIDENTIAL/DOMESTIC	Concrete block	1	
Lucas	as	5306 Cedar Point Road	298376		Gabled Ell	Balloon/western/platform fram	Addition	
Oregon	gon	Oregon (Township of)	4616424		none	Aluminum or vinyl siding	Good/Fair	
Additional :	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
				Modern outbuildings			Thomas	
							Barrett	
-					_		VRS	
26			17		RESIDENTIAL/DOMESTIC	Brick bearing	1900ca. / 1970ca.	
Lucas	as	6310 Cedar Point Rd.	300389		Non-discernable House Type	Brick bearing		
Oregon	gon	Oregon (Township of)	4616404		No academic style - Vernacular	Brick		
Additional	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett	

- 54	_
0	h
2	Ľ
7	2
•	-
2	=
-	
-	2
Z	2
_	-
٠	
۰.	د
2	ī.
	μ
- 2	
5	2
- 5	-
n	
-	-
	Droioct Number:

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM .	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
62			17		RESIDENTIAL/DOMESTIC	Brick bearing	1915ca. /	
	Lucas	5819 Corduroy Road	299456		Bungalow	Brick bearing		
	Oregon	Oregon	4614842		Craftsman/Arts and Crafts	Brick	Excellent	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field							Thomas	
							Barrett VRS	
142			17		RESIDENTIAL/DOMESTIC	Unknown	1870 /	
	Lucas	5150 Seaman Street			Upright and Wing	Balloon/western/platform fram		
		Oregon			No academic style - Vernacular	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field				2 car garage; alterations; additions.	; additions.		Thomas	
							Barrett VRS	
			17		RESIDENTIAL/DOMESTIC	Unknown	1900ca. / 1999ca	
	Lucas	unknown address Corduroy Road			American foursquare	Balloon/western/platform fram	Original/Most significa	
		Oregon			No academic style - Vernacular	Asbestos/asphalt siding	Deteriorated	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett	
			17		RESIDENTIAL/DOMESTIC	Brick bearing	1944 / 1970ca	
	Lucas	5615 Corduroy Road	298982		Cape Cod Cottage/Williamsburg	Balloon/western/platform fram	Alteration	
	Oregon	Oregon	4614870		No academic style - Vernacular	Aluminum or vinyl siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett	
							VRS	
	Lucas	5764 Corduroy Road					/ Date demolished	
		Oregon						
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC025210	Preparer Information	
				Gone			Thomas	
							Barrett	
							2K3	

35
of
2
5
ğ
Ба

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo ID	County Quad. Name	Property Address	UTM Coord.	Owner Information	Building Type Architectural Style	Wall Construction Exterior Wall	Alterations Current Condition	Elig.
69 9	Lucas	5637 Corduroy Road Oregon	17				~	
Additio	Additional Sources of Information:			Further Description Gone		OHI Number:	Preparer Information	
68	Lucas Oregon	5632 Corduroy Road Oregon	17 299186 4614805		RESIDENTIAL/DOMESTIC Upright and Wing		1870ca. / Alteration	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information Thomas Barrett VRS	
67	Lucas Oregon	5722 Corduroy Road Oregon	17 299224 4614777		RESIDENTIAL/DOMESTIC Upright and Wing		1880ca / Good/Fair	
Additio	Additional Sources of Information:			Further Description		OHI Number:	Preparer Information Thomas Barrett VRS	
66	Lucas	unknown address Corduroy Road Oregon	17		RESIDENTIAL/DOMESTIC Cape Cod Cottage/Williamsburg No academic style - Vernacular	Unknown Balloon/western/platform fram Permastone	1945ca /	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information Thomas Barrett VRS	
	Lucas	Corduroy Road Oregon	17		RESIDENTIAL/DOMESTIC Bungalow Craftsman/Arts and Crafts	Unknown Balloon/western/platform fram Aluminum or vinyl siding	1910ca. / 1990ca. Addition Good/Fair	
Additic Field	Additional Sources of Information: Field	rmation:		Further Description Oversized craftsman four	Further Description OHI Number: Oversized craftsman foursquare with side addition and attached modern garage.	OHI Number: attached modern garage.	Preparer Information Thomas Barrett VRS	

- L	_
	ħ.
	,
	2
- 7	=
× ۲	-
_	-
	3
_	5
_	-
_	
	٠
ć	٥
- 2	z
- u	9
- C	3
- 2	1
<u> </u>	

Projec	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
			17		RESIDENTIAL/DOMESTIC		1940ca. /	
	Lucas	5502 Curduroy Road			Cape Cod Cottage/Williamsburg			
		Oregon						
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number: LUC023010	Preparer Information	
				Removed			Thomas Barrett VRS	
73-77			17		RESIDENTIAL/DOMESTIC	Unknown	1880ca /	
	Lucas	5260 Corduroy Road	297855		Gabled Ell	Balloon/western/platform fram		
	Oregon	Oregon	4615091		Queen Anne	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field				Fishcale at gables. Corne across the road with lean	Fishcale at gables. Corner porch with mansard roof. New windows. English Barn across the road with leanto shed and a block garage.	/ windows. English Barn	Thomas Barrett	
			!					
60			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1910cal /	
	Lucas	6050 Corduroy Road	299901		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614781		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field				Three Bay Garage.			Thomas Barrett	
							VRS	
59			17		RESIDENTIAL/DOMESTIC	Brick bearing	1880ca. / 1999cal	
	Lucas	6111 Corduroy Road	300003		Upright and Wing	Balloon/western/platform fram	Addition	
	Oregon	Oregon	4614845		No academic style - Vernacular	Aluminum or vinyl siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	-
Field				detached garage and steel pole barn.	eel pole barn.		Thomas	
							Barrett VRS	
57-58			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	6141 Corduroy Road	300106		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614910		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	_
Field				Gambreil Roof Barn and adjacent milk house.	adjacent milk house.		Thomas	
							Barrett VRS	

Project Number:

Projec	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		NTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
56			17		RESIDENTIAL/DOMESTIC	Unknown	1870ca. / 1990ca.	
	Lucas	6165 Corduroy Road	300151		Non-discernable House Type	Balloon/western/platform fram	Addition	
	Oregon	Oregon	4614835		Federal	Aluminum or vinyl siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				possible partional log cor	possible partional log construction based on massing and depth of sills.	d depth of sills.	Thomas	
							Barrett vrs	
55			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910 / 1990ca	
	Lucas	6209 Corduroy Road	300219		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614847		Craftsman/Arts and Crafts	Aluminum or vinyl siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							Thomas	
							Barrett VRS	
54			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	6315 Corduroy Road	300476		Bungalow	Balloon/western/platform fram		
	Oregon	Oregon	4614806		Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							VRS	
51-53			17		RESIDENTIAL/DOMESTIC	Unknown	1900ca / 1980ca	
	Lucas	6450 Corduroy Road	300684		Gabled Ell	Balloon/western/platform fram		
	Oregon	Oregon	4614752		Neo-Classical Revival	Aluminum or vinyl siding	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				Gambrel Roof English Ba	Gambrel Roof English Barn with brick walk-in and shed lean to.	ean to.	Thomas	
							Barrett VRS	
50			17		RESIDENTIAL/DOMESTIC	Concrete block	19 /	[
	Lucas	6510 norden Road	300849		Non-discernable House Type	Balloon/western/platform fram		
	Oregon	Oregon	4614711		Federal	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett	
							2	

ŝ
f 3
Ö
29
ge
á
Ц.

NRHP Elig. Preparer Information Preparer Information Preparer Information Preparer Information Preparer Information **Current Condition** Year Built/Altered 1949ca. / 1980ca 1860ca. / 1970ca Alterations 1949ca. / Good/Fair Alteration Thomas 1910ca. Barrett VRS VRS Vrs Vrs Vrs LUC025110 Balloon/western/platform fram Balloon/western/platform fram Foundation Material Aluminum or vinyl siding Aluminum or vinyl siding Wall Construction Exterior Wall Concrete block **OHI Number: OHI Number:** Brick bearing Brick bearing **OHI Number: OHI Number: OHI Number:** Unknown Unknown Brick Falsefront core structure, flanked by greenhouse structures. Cape Cod Cottage/Williamsburg Cape Cod Cottage/Williamsburg No academic style - Vernacular Non-discernable House Type RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC House has no significant changes since 1979 OHI. RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC Architectural Style **Building Type** Present use COMMERCIAL group of similar post wwll bungalows. Falsefront Bungalow Further Description Further Description Further Description Further Description Further Description Owner Information 300836 299284 7 4612327 7 17 7 17 4614752 UTM Coord. **Property Address Present Name** 741-730 Stadium road Oregon (Township of) O'Briens Greenhouse 5734 Corduroy Road 7131 Seaman Road 6552 Norden Road Navarre Road Cy;nthia Barclay OHI 1979. Field 2013 Oregon Oregon Oregon Additional Sources of Information: Oregon Additional Sources of Information: Additional Sources of Information: Additional Sources of Information: Additional Sources of Information: Sallee Ref. Number Quad. Name Project Number: Photo County ID Oregon Oregon Lucas Lucas Lucas Lucas Lucas field field 209 192 176 49 65

52
÷
0
σ
-
ge
ă
Δ.

<u> </u>
σ
F
•
tio
Ŧ
σ
=
Φ
Document
$\overline{\mathbf{O}}$
×
2
Form [
5
0
Ъ
~
σ
Ξ
m
Sum
Sum
it Sum
IJ
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
Q
106 Review Projec
Q

NRHP Elig. Preparer Information Preparer Information Preparer Information Preparer Information **Current Condition** Year Built/Altered Alterations 1940ca. / 1910ca. / 1910ca. / 1910ca. / 1910ca Vrs Vrs Vrs Vrs Balloon/western/platform fram Foundation Material Aluminum or vinyl siding Wall Construction ble Exterior Wall Brick bearing OHI Number: **OHI Number: OHI Number:** Brick bearing **OHI Number:** Brick Cape Cod Cottage/Williamsburg RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC Craftsman/Arts and Crafts Craftsman/Arts and Crafts Craftsman/Arts and Crafts Architectural Style American foursquare American foursquare American foursquare **Building Type** Present use Bungalow Further Description Further Description Further Description Further Description Owner Information 299610 299265 17 17 299985 4612307 17 17 7 4612468 4612832 UTM Coord. **Property Address** Navarre Road 6000 Block **Present Name** S Ø 6116 Navarre Road 5929 Navarre Road 6009 Navarre Road 741 Stadium Road Oregon Oregon Oregon Oregon Oregon Additional Sources of Information: Additional Sources of Information: Additional Sources of Information: Additional Sources of Information: Ref. Number Quad. Name Project Number: Photo County ID Oregon Oregon Oregon Lucas Lucas Lucas Lucas Lucas field 206-207 field 208 205 204

Preparer Information

OHI Number:

Further Description

Additional Sources of Information:

VIS

Table
ocumentation
ŭ u
For
Summary
roject
Review P
106
Section

Project	Project Number:	Section 106 Kev	6 Keviev	v Project summ	riew Project Summary Form Documentation Table	ation lable)	
	Ref. Number				Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
197-		Gerald Peach	17	Gerald Peach	RESIDENTIAL/DOMESTIC	Brick bearing	1916 /	
203	Lucas	6113 Navarre Road	29963		American foursquare	Brick bearing		>
	Oregon	Oregon	4612428		Craftsman/Arts and Crafts	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC154110	Preparer Information	
Field; 21.5	correspondence with N	Field; correspondence with Mr. Peach; OHI; ODOT PID: 9159 LUC-2- 21.5	LUC-2-	foursquare considered el constructed in 1908. grar	foursquare considered eligible under Criteria C in 1997 (ODOT IOC). Bank Barn constructed in 1908. granary constructed in 1888; 5-bay garage.	DDOT IOC). Bank Barn jarage.	thomas barrett vrs	
211-			17		RESIDENTIAL/DOMESTIC	Brick bearing	unk. /	
212	Lucas	237 N. Stadium road			Non-discernable House Type	Brick bearing		
		Oregon			No academic style - Vernacular	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							VIS	
193-			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
195	Lucas	6459 Navarre Road	300709		Cape Cod Cottage/Williamsburg	Brick bearing		
	Oregon	Oregon	4612473		Craftsman/Arts and Crafts	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				Mail Pouch Barn associated with this house	ited with this house			
0,0			7			Ductionted Steve wil and steve	VIS	
2		ACON Condition Acco	11				194008. 1	
	Lucas Oregon	IUZ IN. Stadium Ave. Oregon	299338 4614322		bungalow	Brick bearing Brick		
Addit:	Additional Sources of Information			Eurthor Description		OHI Number:	Dranarar Information	
field				Gambrel roof barn with l	Gambrel roof barn with lean to sheds; concrete block building; Granary; pivy	lding; Granary; pivy		
							Vrs	
189-			17		RESIDENTIAL/DOMESTIC		1940ca /	
2	Lucas	Navarre Road n/e corner of Norde Oregon			Cape Cod Cottage/Williamsburg			
171 P	and the second of large			Tthen December 1				
Additi	Additional Sources of Information:	rmation:		Further Description	0	OHI Number:	Preparer Information	
							VrS	

ŝ
ŝ
ð
~
\sim
Ð
ag
ñ
_

Table
Documentation
Form
Summary
Project
Review
106
Section

Project Number:	umber:	-			-			
Ľ	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
Q	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
188			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	6734 Navarre Road	301249		American foursquare	Balloon/western/platform fram		
0	Oregon	Oregon	4612320		Craftsman/Arts and Crafts	Drop or novelty siding		
Addition	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
							SIA	
187			17		RESIDENTIAL/DOMESTIC		1910ca. /	
	Lucas	6824 Navarre Road			Bungalow			
		Oregon			Craftsman/Arts and Crafts			
Addition	Additional Sources of Information:	ermation:		Further Description		OHI Number:	Preparer Information	
							SIX	
			17		RESIDENTIAL/DOMESTIC		1880cal /	
	Lucas	6827 Navarre Road Oregon			Gabled Ell			
Addition	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field				Farmstead: 4 steel silos; garage.	Farmstead: 4 steel silos; gambrel barn with leanto; pole barn mod. Gambrel barn; garage.	barn mod. Gambrel barn;	XIS	
184- 185 L	Lucas	Gobbells Farm- Barkholder 7333 Navarre Road NW Quad. Oregon	17	Barkholder	RESIDENTIAL/DOMESTIC		-	
Addition	Additional Sources of Information:	ormation:		Further Description	-	OHI Number:	Preparer Information	_
182			17		RESIDENTIAL/DOMESTIC		1910ca. /	
_	Lucas	400 N. Curtice Road Oregon			Cape Cod Cottage/Williamsburg			
Addition field	Additional Sources of Information: field	ormation:		Further Description gambrel roof		OHI Number:	Preparer Information	
							VrS	

ŝ
ŝ
đ
22
Ð
ag
à

Projec	Project Number:						-	[
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
Q		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
181		Dwight D. Eisenhower School	17		School	Brick bearing	1959 /	
	Lucas	N. Curtice				Brick bearing		
		Oregon			International	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
				Two industrial size wind t	Two industrial size wind turbines are present on this site.		VIS	
180			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	[
	Lucas	110 N. Curtice Road			Bungalow	Balloon/western/platform fram		
		Oregon			Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							VIS	
140			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1899ca. /	
	Lucas	5128 Seaman Street			I House	Balloon/western/platform fram		
		Oregon			Greek Revival	Drop or novelty siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field				10 over 1 and 6/1 windov	10 over 1 and 6/1 windows on the front; portico hood over the front central door.	er the front central door.	Thomas	
							Barrett VRS	
196			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1912ca. /	
	Lucas	6318 Navarre Road			American foursquare			
		Oregon				Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				pole barn; garage, and sned present.	nea present.			
							VrS	
228			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	3554 Navarre Road			Non-discernable House Type	Balloon/western/platform fram		
	Oregon	Oregon			Dutch Colonial Revival	Asbestos/asphalt siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field								
							VrS	

ŝ
ŝ
ð
23
ge
ă
Д_

	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
Q		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
243			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	1330 Wynn Road			Bungalow	Balloon/western/platform fram		
	Oregon	Oregon			No academic style - Vernacular	Aluminum or vinyl siding		
Additic	Additional Sources of Information:	rmation:		Further Description	_	OHI Number:	Preparer Information	
field								
							VLS	
			17		RESIDENTIAL/DOMESTIC	Concrete block	2000ca. /	
	Lucas	wynn Road			Non-discernable House Type	Balloon/western/platform fram		
	Oregon	Oregon			No academic style - Vernacular	Aluminum or vinyl siding		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				group of modern houses along Wynn Road	along Wynn Road			
							VIS	
241-			11		Agricultural Outbuildings	Brick bearing	1880ca. / 2000ca.	
242	Lucas	Wynn Road			BARN TYPES	Brick bearing	Alteration	
	Oregon	Oregon				Brick	Deteriorated	
Additic	Additional Sources of Information:	rmation:		Further Description	-	OHI Number:	Preparer Information	
field. N	learby powerstation d	field. Nearby powerstation development from 2006 circa.		house removed. Cellar and privy intact	ind privy intact.			
							VIS	
241			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. / 1980ca.	
	Lucas	Navarre Road / at RR crossing			American foursquare	Balloon/western/platform fram	Alteration	
	Oregon	Oregon			Craftsman/Arts and Crafts	Aluminum or vinyl siding	Good/Fair	
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							VIS	
			17		VACANT/NOT IN USE	Brick bearing	1968ca. / 1980ca	[
	Lucas	5370 Navarre Road			COMMERCIAL	Brick bearing	Alteration	
	Oregon	Oregon			Modern Movements	Brick		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				/ bay by 4 bay, tormer a beam porte cocher at the	/ bay by 4 bay, former apartment or small hotel building. Small round concrete 1- beam porte cocher at the center façade. Vacant.	. Small round concrete I-		
							VrS	

S
З
of
24
Ð
ag
Δ.

Liolec								
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		NTM	Owner	Building Type	Wall Construction	Alterations	Elig.
DI		Property Address C	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
238			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	5360 Navarre Road			Bungalow	Balloon/western/platform fram		
	Oregon	Oregon			Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							SIA	
236-			17		RESIDENTIAL/DOMESTIC	Brick bearing	1880ca. / 1980ca.	[
237	Lucas	5332 Navarre Road			Gabled Ell	Balloon/western/platform fram	Alteration	
	Oregon	Oregon			No academic style - Vernacular	Aluminum or vinyl siding		
Addition field	Additional Sources of Information: field	rmation:		Further Description english barn with partial t barn also present. Both ir	Further Description OHI Number: english barn with partial brick ground floor and slate fishscale roof. Smaller two bay barn also present. Both in good condition.	OHI Number: scale roof. Smaller two bay	Preparer Information	
					1		VIS	
			17		RESIDENTIAL/DOMESTIC		1910ca. /	
	Lucas	5300 block of Navarre Road			Bungalow			
	Oregon	Oregon			Craftsman/Arts and Crafts			
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field			0,	grouping of post wwll bungalow houses	ngalow houses			
210			17		RESIDENTIAL/DOMESTIC		1950 /	
	Lucas	N. Stadium Road			Cape Cod Cottage/Williamsburg			
		Oregon			No academic style - Vernacular			
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field			20	WW-II era; cottages; modern r of N. Stadium Road observed	WW-II era; cottages; modern ranches; modern McMansions all along this segment of N. Stadium Road observed .	ons all along this segment	SIX	
232-		Welles Bowen Realtors/ Wiemeyer	17		COMMERCIAL	Brick bearing	1895 / 1980ca.	
233	Lucas	4728 Navarre Road			Gabled Ell	Balloon/western/platform fram	Alteration	
	Oregon	Oregon			Queen Anne	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				English Barn and large gr Est. 1895"; garage and si directly across from Pear	English Barn and large granary behind house sign on granary "Wiemeyer Farms Est. 1895"; garage and steel silo also associated. The former farmstead is located directly across from Pearsons Metropark, a swampland preserve.	anary "Wiemeyer Farms rmer farmstead is located preserve.		
							Vrs	

Page 25 of 35	
Section 106 Review Project Summary Form Documentation Table	

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
175			17		Agricultural Outbuildings	Brick bearing	1880ca. <i> </i>	
	Lucas	7113 Seamand Road			BARN TYPES	Brick bearing		
		Oregon			english	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							VRS	
229-		Bartz viviano	17		COMMERCIAL	Brick bearing	1880ca. / 1975ca.	
231	Lucas	3608 Navarre Road			Gabled Ell	Brick bearing	Addition	
	Oregon	Oregon			classic revival	Brick	Good/Fair	
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				brick classic revival with I have been added to and	brick classic revival with Italianate elements and greek revival elements. have been added to and converted to commercial property circa 1970's.	vival elements. Appears to ty circa 1970's.	SIX	
226			17		RESIDENTIAL/DOMESTIC	Concrete block	1910ca. /	
	Lucas	3536 Navarre Road			Bungalow	Balloon/western/platform fram		
	Oregon	Oregon			Craftsman/Arts and Crafts	Drop or novelty siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				three-bay matching garage with central chimney and pedestrian door at right bay. House current chicken coop behind the garage with shed roof.	three-bay matching garage with central chimney, carriage doors on left two bays and pedestrian door at right bay. House currently for sale. Contemporaneous chicken coop behind the garage with shed roof.	e doors on left two bays . Contemporaneous	SIA	
220-		Erol D. Riza MD Gynecologist	17	Erol Riza	COMMERCIAL	Brick bearing	1880ca. /	
977	Lucas	3465 Navarre Ave.		3465 Navarre Ave.	Gabled Ell	Brick bearing		>
	Oregon	Oregon		Oregon, Ohio	Queen Anne	Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				Excellent example of bric throughout. A brick carria wraparound front porch. (Excellent example of brick queen anne architecture. Ornamentation and corbeling throughout. A brick carriage house is associated. Turret at entrance and wraparound front porch. Corbelled central chimney; fishscale slate roof.	amentation and corbeling at entrance and cale slate roof.	Thomas Barrett VRS	
			17		RESIDENTIAL/DOMESTIC	Concrete block	1950 /	
	Lucas	3600 block of Star Ave.			Ranch	Balloon/western/platform fram		
	Oregon	Oregon				Aluminum or vinyl siding		
Additi	Additional Sources of Information:	rmation:		Further Description	Further Description OHI Number: arouning of post WW II houses consisting of simple cape cods and ranches.	OHI Number: le cods and ranches.	Preparer Information	
TIEIO								
							VrS	

	۰.	_
	6	ħ.
	ч	,
	2	2
	-	-
	È	
	=	-
	-	2
	-	2
	~	
	c	3
	2	5
	ч	,
	-	-
	C	3
	a	-
	-	-
- 1	n	

Project	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	o County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
219			17		RESIDENTIAL/DOMESTIC	Brick bearing	1870ca. / 1990ca.	
	Lucas	3748 Star Ave.			Upright and Wing	Balloon/western/platform fram	Alteration	
	Oregon	Oregon			Greek Revival	Aluminum or vinyl siding	Some alteration	
Additi	Additional Sources of Information:	mation:		Further Description	0	OHI Number:	Preparer Information	
field				deck fron porch and mod	deck fron porch and modern materials throughout.			
							VrS	
218			17		RESIDENTIAL/DOMESTIC	Brick bearing	1890 /	
	Lucas	3833 Eastwood			I House	Balloon/western/platform fram		
	Oregon	Oregon			Greek Revival	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
field				green vinyi siairig.				
							VrS	
217			17		RESIDENTIAL/DOMESTIC	Brick bearing	1890ca. /	
	Lucas	4032 Star Ave.			Gabled Ell	Balloon/western/platform fram		
	Oregon	Oregon				Aluminum or vinyl siding		
Additi	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
field				gabled ell with wing. Circ	gabled ell with wing. Circa mid 20th century3-bay barn behind the house.	ehind the house.		
							VIS.	
216			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	4104 Star Ave.			Bungalow	Balloon/western/platform fram		
	Oregon	Oregon			Craftsman/Arts and Crafts			
Additi	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
field							ŝ	
215			17		RESIDENTIAL/DOMESTIC	Brick bearing	vis 1880ca. /	[
	Lucas	4047 Star Ave.			Upright and Wing	Balloon/western/platform fram		
	Oregon	Oregon			Greek Revival	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	mation:		Further Description	0	OHI Number:	Preparer Information	
field								
							VrS	

ŝ
က
of
27
~
Ð
g
an an
ц.

NRHP Elig.

Section 106 Review Project Summary Form Documentation Table

Preparer Information Preparer Information Preparer Information Preparer Information Preparer Information **Current Condition** Year Built/Altered 1880ca. / 1959ca. Alterations 1920ca. / Good/Fair Alteration Thomas 1910ca. 1880ca. Barrett 1906 VRS VRS Vrs Vrs Rusticated Stone, w/ cut stone Balloon/western/platform fram Balloon/western/platform fram Balloon/western/platform fram classic 1920s cape cod with multicolored shingle roof. Two dormer windows. 1 1/2 story massive chimney teracotta entranceway surround. Atached two bay flat roof garage. Copper gutters and spouts. Screened in porch wing addition. Foundation Material Aluminum or vinyl siding Aluminum or vinyl siding Asbestos/asphalt siding Wall Construction quonset shed; gambrel roof three bay barn. Gray asbestos shingles cover the house. Core Upright part of house features central chimney and decorative bargeboards. Drop or novelty siding Exterior Wall Brick bearing Brick bearing **OHI Number:** Brick bearing **OHI Number:** Brick bearing **OHI Number: OHI Number:** Brick bearing **OHI Number:** Brick Cape Cod Cottage/Williamsburg No academic style - Vernacular RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC RESIDENTIAL/DOMESTIC Craftsman/Arts and Crafts Craftsman/Arts and Crafts Craftsman/Arts and Crafts Architectural Style American foursquare Upright and Wing **Building Type** Upright and Wing Present use Bungalow Further Description Further Description Further Description Further Description Further Description Owner Information Fleitz 7 17 4 7 7 UTM Coord. **Property Address** Present Name 5518 Seaman Street 5210 Navarre Road 349 Stadium Road 229 Stadium Road Fleitz Farm Oregon Oregon Oregon Oregon Additional Sources of Information: Oregon Additional Sources of Information: Additional Sources of Information: Additional Sources of Information: Additional Sources of Information: 7133 Ref. Number Quad. Name Project Number: County Oregon Lucas Lucas Lucas Lucas Lucas Photo ID Field field 235 154 148 177 155

Vrs

of 35	
e 28 c	
Page	

Projec	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	o County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
153		St. Ignatius Roman Catholic Churc	17		RELIGIOUS	Brick bearing	1927 /	
	Lucas	212 N. Stadium Road	299380			Brick bearing		
	Oregon	Oregon	4614210		Romanesque Revival	Brick		
Addit	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC025910	Preparer Information	
							VrS	
152		National Gospel Tabernacle	17		Chapel	Rubble Stone, w/ wood water t	1893 /	
	Lucas	5763 Seaman Street			One-room Schoolhouse	Balloon/western/platform fram		
		Oregon			Greek Revival	Wood		
Addit	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC021710	Preparer Information	
Field							NrS	
151		Parsonage Clay Chapel	17	Full Gospel Tabernacle Pa	Church Related Residence	Rusticated Stone, w/ cut stone	1893 /	
	Lucas	5749 Seaman Street	299380		Upright and Wing	Balloon/western/platform fram		
	Oregon	Oregon	4613810			Drop or novelty siding		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number: LUC021610	Preparer Information	
Field	Field and OHI			wing is located at the rear of this upright	ır of this upright			
							VIS	
		Clay High School Complex	17	Clay High School	School		1930ca. /	
	LUCAS	or etc seaman street Oregon			COMINIERCIAL International	Brick bearing Brick		
Additi	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field				WPA era large garage at massive front additions.	WPA era large garage at the center of the complex. The school is dominated by massive front additions.	e school is dominated by		
							VRS	
150			17		RESIDENTIAL/DOMESTIC		1950ca. <i> </i>	
	Lucas	5557 Seaman Street			Non-discernable House Type			
		Oregon			No academic style - Vernacular			
Addit	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field								
							VIS	

35
<u> </u>
Ö
S.
2
ge
ğ
Δ.

	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address Co	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
157			17		RESIDENTIAL/DOMESTIC		1880ca. /	
	Lucas	37 N. Stadium Road			Upright and Wing	Balloon/western/platform fram		
		Oregon				Asbestos/asphalt siding		
Additio	Additional Sources of Information:	mation:		Further Description	_	OHI Number:	Preparer Information	
							VIS	
			17		RESIDENTIAL/DOMESTIC		1944ca. /	
	Lucas	5540 Seaman Street			Cape Cod Cottage/Williamsburg			
		Oregon						
Additio	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
							VIS	
			17		RESIDENTIAL/DOMESTIC		1	
	Lucas	56 N. Stadium Road			Ranch			
		Oregon						
Additic	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
							VIS	
147			17		RESIDENTIAL/DOMESTIC	Brick bearing	1890ca. /	
	Lucas	5501 Seaman Street			Upright and Wing			
		Oregon				Aluminum or vinyl siding		
Additic	Additional Sources of Information:	mation:		Further Description		OHI Number:	Preparer Information	
ohi field	p			house and modern outb	house and modern outbuildings clad in white siding			
							VrS	
146		Ai Ransom Fassett, Jr. House	17	Dr. William Imen Jr.	RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1910ca. /	
	Lucas	5507 Seaman Road			Gabled Ell	Balloon/western/platform fram		
		Oregon			Queen Anne	Asbestos/asphalt siding		
Additic	Additional Sources of Information:	mation:		Further Description		OHI Number: LUC021510	Preparer Information	
Field a	Field and OHI			Home of local historian . Historical Society; teach History of Oregon and Je	Home of local historian Josephine Fassett; founder of the Oregon and Jerusalem Historical Society; teacher and District Supervisor; auther of two volumes of The Historical of Oregon and Jerusalem Township. House features a sunken summer	e Oregon and Jerusalem ar of two volumes of The ures a sunken summer	Thomas Barrett VDS	
				kitchen/ pantry			CNV	

Table
Documentation
/ Form
ect Summary
/ Proje
Review
106 ח
Sectior

Page 30 of 35

Project	Project Number:	Section 10		w Project Summ	Section 100 Keview Project Summary Form Documentation Table			
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
⊇	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
143-		City of Oregon Municipal Building C	17		Government Office	Concrete block	1964ca. /	
144	Lucas	5330 Seaman Street			Office	Brick bearing		
		Oregon			International	Brick		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field a	Field and City of Oregon website.	bsite.		spralling one-floor mid-ce government/school elem	spralling one-floor mid-century building complex with international government/school elements	srnational		
							VRS	
			17		RESIDENTIAL/DOMESTIC	Concrete block	1942ca. /	
	Lucas	5304 Seaman Street			Bungalow	Brick bearing		
		Oregon (Township of)				Brick		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field							Thomas Barrett VRS	
			17		RESIDENTIAL/DOMESTIC		1942ca. /	[
	Lucas	5248 Seaman Street			Bungalow	Concrete block		
		Oregon						
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Thomas	
							Barrett VRS	
			17		RESIDENTIAL/DOMESTIC		1950 /	
	Lucas	5208- 5240 Seaman Street			Ranch			
		Oregon						
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field				Grouping of common ver	Grouping of common vernacular and heavily altered post WWII houses.	t WWII houses.	Thomas	
							Barrett VRS	
			17		RESIDENTIAL/DOMESTIC		1945ca /	
	Lucas	5206 Seaman Street			Cape Cod Cottage/Williamsburg			
		Oregon						
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field							Thomas Barrett	

Table
Documentation
Form
Summary
Project
Review
106 ו
Sectior

of 35
Page 31

Project	Project Number:	Section 10	16 Reviev	w Project Summ	Section 106 Review Project Summary Form Documentation Table	ation Table))))))	
	Ref. Number	Owen turned			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
₽	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
141		First Baptist Church	17		RELIGIOUS		1945ca. /	
	Lucas	5157 Seaman Street			COMMERCIAL	Brick bearing		
		Oregon			streamline	Brick		
Additi	Additional Sources of Information:	ormation:	_	Further Description		OHI Number:	Preparer Information	
							Thomas Barrett VPS	
244			17		RESIDENTIAL/DOMESTIC	Brick bearing	1930ca. /	[
	Lucas	844 Wynn road			Bungalow	Balloon/western/platform fram		
	Oregon	Oregon			Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	ormation:	_	Further Description		OHI Number:	Preparer Information	
field				6 bay garage.			NIS	
149			17		RESIDENTIAL/DOMESTIC	Brick bearing	1920ca. /	
	Lucas	5537 Seaman Street			Bungalow	Balloon/western/platform fram		
		Oregon			Craftsman/Arts and Crafts	Aluminum or vinyl siding		
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
Field							VRS	
164			17		RESIDENTIAL/DOMESTIC	Poured concrete	1944cal /	
	Lucas	6406 Seaman Street			Cape Cod Cottage/Williamsburg			
	Oregon	Oregon						
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field							VIS	
174			17		RESIDENTIAL/DOMESTIC		1890ca. /	
	Lucas	7000 ? Seaman Road			Gabled Ell			
		Oregon						
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
				6/6 windows and 2 pole barns	barns		5	
							VIS	

ŝ
ŝ
đ
\sim
З
ge
ag
<u> </u>

Project	Project Number:					Ī		
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
Q		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
173			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	6735 Seaman Road			Bungalow			
		Oregon			Craftsman/Arts and Crafts			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							VIS	
172			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1890ca. /	
	Lucas	6733 Seaman Road			Gabled Ell	Balloon/western/platform fram		
		Oregon			No academic style - Vernacular			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
Field							VIS	
171			17		RESIDENTIAL/DOMESTIC	Concrete block	1910ca. /	
	Lucas	6714 Seaman Road			American foursquare			
		Oregon			Craftsman/Arts and Crafts			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							VIS	
170			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	6660 Seaman Rd.			American foursquare			
Additic	Additional Sources of Information:	Uregon rmation:		Further Description		OHI Number:	Preparer Information	
field								
169			17		RESIDENTIAL/DOMESTIC		VIS 2000 /	[
	Lucas	6601 Norden Road			Non-discernable House Type			
		Oregon						
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							VIS	

ŝ	2
0	D
2	2
2	
-	3
Z	2
t	5
0	D
ŝ	2
Ō	

		-	-					
	Ref. Number	Present Name			Present use	Foundation Material	Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	-ing.
₽	Quad. Name	Property Address Coo	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
			17		RESIDENTIAL/DOMESTIC		1970ca. / 2000	
	Lucas	6513-6600 Seaman Road			Ranch		Original/Most significa	
		Oregon						
Additio	Additional Sources of Information:	rmation:	Fun	Further Description	0	OHI Number:	Preparer Information	
field			Secti	on of Seaman Road	Section of Seaman Road comprised of ranches and "Mcmansions".	nansions".	XIS	
168			17		RESIDENTIAL/DOMESTIC		1890ca. /	[
	Lucas	6512 Seaman Road			I House			
		Oregon			Greek Revival			
Additio	Additional Sources of Information:	rmation:	Furt	Further Description		OHI Number:	Preparer Information	
field			rear	rear addition. Two bay garage.	Irage.		XIS	
156			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	334 N. Stadium Road			Bungalow			
		Oregon			Craftsman/Arts and Crafts			
Additio	Additional Sources of Information:	rmation:	Furt	Further Description		OHI Number:	Preparer Information	
							VIS	
			17		RESIDENTIAL/DOMESTIC		/	
	Lucas	6426 Seaman Road						
	Oregon	Oregon			Greek Revival	Permastone		
Additio	Additional Sources of Information:	rmation:	Furt	Further Description	0	OHI Number:	Preparer Information	
field							VIS	
			17		RESIDENTIAL/DOMESTIC		/	
	Lucas	5136-5138 Seaman Street			Cape Cod Cottage/Williamsburg			
		Oregon						
Additio	Additional Sources of Information:	rmation:	Fur	Further Description		OHI Number:	Preparer Information	
				WWII era one and hair cape cod cottages.	ape cod cottages.		Thomas Barrett	
							VRS	
I								

S
ŝ
đ
4
ò
ge
ğ
Δ.

Liojec								
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
٩	Quad. Name	Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
165			17		RESIDENTIAL/DOMESTIC		1	
	Lucas	6405 Seaman Street			Non-discernable House Type	Brick bearing		
	Oregon	Oregon			No academic style - Vernacular	Brick		
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field							VIS	
163			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	[
	Lucas	6316 Seaman Street			American foursquare			
	Oregon	Oregon			Craftsman/Arts and Crafts			
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field				modern Pole Barn associated.	siated.			
							VIS	
			17		RESIDENTIAL/DOMESTIC		1944ca. /	
	Lucas	6103 Seaman Street			Bungalow			
		Oregon			Craftsman/Arts and Crafts			
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field							VIS	
			17		RESIDENTIAL/DOMESTIC		1945ca. /	
	Lucas	60006100 block Seaman Stree			Bungalow			
		Oregon			crat			
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field				a row of approximately 7 Street.	a row of approximately 7 WWII era bungalows along this segment of Seaman Street.	is segment of Seaman		
	-	-				-	VrS	
162			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	5906 Seaman Street			American foursquare	Balloon/western/platform fram		
		Oregon						
Additi	Additional Sources of Information:	ormation:		Further Description		OHI Number:	Preparer Information	
field								
							VrS	

S
З
of
S
ŝ
ge
ğ
Δ.

Froject	Project Number:							
	Ref. Number	Present Name			Present use	Foundation Material	Year Built/Altered	NRHP
Photo	County		UTM	Owner	Building Type	Wall Construction	Alterations	Elig.
Q		Property Address	Coord.	Information	Architectural Style	Exterior Wall	Current Condition	
161			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	5865 Seaman Street			American foursquare	Balloon/western/platform fram		
		Oregon			Craftsman/Arts and Crafts			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							VIS	
160			17		RESIDENTIAL/DOMESTIC	Rusticated Stone, w/ cut stone	1920ca. /	
	Lucas	5860 Seaman Street			American foursquare	Balloon/western/platform fram		
		Oregon			Craftsman/Arts and Crafts			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							VIS	
159			17		RESIDENTIAL/DOMESTIC		1920ca. /	
	Lucas	5844 Seaman Road			American foursquare	Balloon/western/platform fram		
		Oregon				Drop or novelty siding		
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
field							VIS.	
158			17		RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	5808 Seaman Street N. Stadium R Oregon			Bungalow	Aluminum or vinyl siding]
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							VIS	
167					RESIDENTIAL/DOMESTIC	Brick bearing	1910ca. /	
	Lucas	0440 Seaman Ku. Oregon			bungarow Craftsman/Arts and Crafts			
Additic	Additional Sources of Information:	rmation:		Further Description		OHI Number:	Preparer Information	
							Vrs	



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 1. Looking north toward existing power facilities at the intersection of Lollendorf Road and Cedar Point Road.



Photo 2. Looking northeast toward existing refinery at the north terminus of Lollendorf Road, looking eastward along Cedar Point Road.



Photo 3. View from Lollendorf Road along the south side of Cedar Point Road.



Photo 4. Looking east along Cedar Point road from the north end of Lollendorf Road.





Photos 5-6 Industrial facilities north of project site, across Cedar Point Road.



Photo 7. Farmstead located at 5252 Cedar Point Road.



Photo 8. House located at 5306 Cedar Point Road.



Photo 9. Duplex at 5553 Cedar Point Road.



Photo 10. Bungalow at 5415 Cedar Point Road



Photo 11. Two barns associated with bungalow at 5415 Cedar Point Road.



Photo 12. 5604 Cedar Point Road.



Photo 13. 5741 Cedar Point Road



Photo 14. 5741 Cedar Point Road looking northeast at façade.



Photo 15. 5741 Cedar Point Road with industry to the northwest in background.



Photo 16. Looking west from Stadium Road, westward on Cedar Point Road.



Photo 17. 1200 North Stadium Road.



Photo 18. LUC-202-10 5808 Cedar Point Road.



Photo 19. LUC-202-10 Looking northeast toward 5808 Cedar Point Rd.



Photo 20. Cape Cod at 5824 Cedar Point Road.



Photo 21. 5940 Cedar Point Rd. upright and wing and barn in ruin.



Photo 22. LUC-203-10 Vail Horse Farm6118 Cedar Point Road; looking west.



Photo 23. Setting along Cedar Point Road with radio tower, across from Vail Farms.



Photo 24. Looking southwest at outbuildings at 6118 Cedar Point Road.



Photo 25. 1927-built, County-installed, concrete slab culvert, crossing ditch on the east side of Vail Medaows Farm.



Photo 26. Gambrel-roofed house at 6310 Cedar Point Road.



Photo 27. Intersection at Norden Road looking west toward project site at 2 miles.



Photo 28. Setting at Norden Road and Cedar Point intersection, looking west toward project area.



Photo 29. House at Myers Farm 6810 Cedar Point Road.



Photo 30. Outbuildings at Myers farm 6810 Cedar Point Road..



Photo 31. Closer view of granary at 6810 Cedar Point Road.



Photo 32. Rear elevation of Bay View Bed & Breakfast 7250 Cedar Point Rd.



Photo 33. Horse barn at 7250 Cedar Point Rd. Bay View B&B.



Photo 34. Front elevation of 7250 Cedar Point Road.



Photo 35. Northeastern elevation of 6810 Cedar Point Road horse barn.



Photo 36. View toward project area from 6810 Cedar Point Rd. showing radio tower.



Photo 37. North Curtice Road and Cedar Point Road intersection looking west.



Photo. 38. North Curtice Road looking west south of Cedar Point Road intersection.



Photo 39. Oregon Water Treatment Plant, looking west toward the project from North Curtice Road.



Photo 40. North Curtice Road at Corduroy Road, looking west toward project area.



Photo 41. Corduroy Road. Ell with modern bay window, alterations.



Photo 42. 7025 Corduroy Road. English barn with lean-to shed.



Photo 43. 7025 Corduroy Road.



Photo 44. 7010 Corduroy Road.



Photo 45. 7010 Corduroy Road.



Photo 46. Power line looking northwest toward Project.



Photo 47. 6601 Norden Road



Photo 48. Looking west across Norden Road at Corduroy Road.



Photo 49. 6552 Norden Road



Photo 50. 6510 Corduroy Road.



Photo 51. 6450 Corduroy Road.



Photo 52. 6450 Corduroy Road



Photo 53. West view from 6450 Corduroy Road



Photo 54. 6315 Corduroy Road.



Photo 55. 6209 Corduroy Road



Photo 56. 6165 Corduroy Road



Photo 57. 6141 Corduroy Road.



Photo 58. 6141 Corduroy Road associated barn.



Photo 59. 6111 Corduroy Road



Photo 60. 6050 Corduroy Road.



Photo 61. Modern homes along 6000 block of Corduroy Road.



Photo 62. 5819 Corduroy Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 63. Looking west across N. Stadium Road, from Corduroy Road, former 5502 Corduroy Road (LUC-250-10). Note wind turbine.



Photo 64. Looking northwest across N. Stadium and Corduroy Roads at carryout.



Photo 65. 5734 Corduroy Road. LUC-251-10 Navarre House (log interior).



Photo 66. Cape Cod with Permastone exterior, west of Navarre House.



Photo 67. 5722 Corduroy



Photo 68. 5632 Corduroy Road



Photo 69. 5637 Corduroy gone and LUC-252-10 at 5764 also gone.



Photo 70. 5532 Corduroy Road



Photo 71. 5000-block of Corduroy Road on north side.



Photo 72. 5459 Corduroy Road



Photo 73. 5260 Corduroy Road



Photo 74. Barn at 5260 Corduroy Road, showing industry and towers in the background.



Photo 75. TV station towers behind barn at 5260 Corduroy.



Photo 76. Looking northwest toward Project from 5260 Corduroy Road.



Photo 77. View along Corduroy Road from 5000 block, looking west.



Photo 78. 4961 Corduroy Road



Photo 79. 4960 Corduroy Road.



Photo 80. 4920 Corduroy Road, upright and wing.



Photo 81. 4811 Corduroy Road.



Photo 82. 4701 Corduroy Road



Photo 83. 4701



Photo 84. Outbuildings at 4701 Corduroy Road with refineries and power plant in the background.



Photo 85. Cedar Point Development Park. Industrial park southeast of the Project.



Photo 86. Possible altered upright & wing at4560 Corduroy Road.



Photo 87. 3400?? Corduroy Road.



Photo 88. Barn and commercial building at 3400?? Corduroy Road.



Photo 89. 4033 Corduroy Road.



Photo 90. 4011 Corduroy Road. Ackerman Berry farm.




Photo 91. Ackermans Berry Farm. English Barn with rear wing.



Photo 92. Looking northwest from 3935 Johlin winery LUC-249-10 driveay toward LUC-248-10.



Photo 93. Johlin Century Winery house. Note front porch roof missing.



Photo 94. West elevation and winery facility at 3935 Corduroy Road.



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 95. Rear elevation of Johlin Winery house.



Photo 96. Winery at Johlin Century Winery LUC-249-10.



Photo 97. Winery at 3935 Corduroy Road.



Photo 98. Winery facility at 3935 Corduroy Road.



Photo 99. Johlin Winery looking north toward refineries.



Photo 100. Johlin Winery looking north from brick-paver driveway.

Oregon Gas to Electric Power Plant APE Survey

Photo log for the Section 106 Review Project Summary Form Documentation Table

Photo 101. Looking northeast toward Johlin Winery at 3935 Corduroy Road.



Photo 102. South elevation of house at Johlin Winery LUC-249-10.



Photo 103. South elevation of LUC-249-10



Photo 104. LUC-248-10 Johlin Blue Chip Farm at 3825 Corduroy Road



Photo 105. Johlin Blue Chip Farm LUC-248-10



Photo 106. Envirosafe Landfill



Photo 107. LUC-244-10 4516 Bay Shore Road.



Photo 108. View eastward Bayshore Road, toward Bay Shore Station power plant.



Photo 109. LUC-243-10 4516 Bay Shore Road



Photo 110. LUC-243-10 4554 Bay Shore Road

Oregon Gas to Electric Power Plant APE Survey

Photo log for the Section 106 Review Project Summary Form Documentation Table

Photo 111. Looking eastward along Bay Shore Road from 4516.



Photo 112. LUC-245-10 4526 Bay Shore Road looking southeast.



Photo 113. LUC-242-10 4400 Bay Shore Road.



Photo 114. LUC-241-10 4328 Bay Shore Road



Photo 115. Power grid is prevalent throughout the project vicinity.



Power 116. Wynn School. Original portion with castellated roofline and buttress.



Photo 117. LUC-272-10 5224 Bay Shore Road.



Photo 118. Wynn School front addition Bay Shore Road.




Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 119. South of Bay Shore Road toward project showing grid.



Photo 120. Bay Shore Road former sites of LUC-271-10 and LUC-322-10



Photo 121. Modern development along Bay Shore Road near Stadium Rd.



Photo 122. 1281 N. Stadium Road brick four over four with porte-cochere.




Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 123. Intersection of Corduroy and Stadium Road.



Photo 124. Southwest quadrant of Corduroy and N. Stadium Road.



Photo 125. Looking northeast across intersection of Corduroy and Stadium Road.



Photo 126. LUC-258-10 3409 Seaman Road Baptist Church est. 1907.



Photo 127. LUC-2138-10 3834 Seaman Road.



Photo 128. LUC-3382-10 3856 Seaman Road



Photo 129. LUC-3383-10 3909 Seaman Road.



Photo 130. LUC-214-10 3948 Seaman Road.



Photo 131. LUC-3384-10 4114 Seaman Road.



Photo 132. LUC-3384-10 4114 Seaman Road.



Photo 133. LUC-3385-10 4209 Seaman Road at Lollendorf intersection NE.



Photo 134. Former sites of LUC-3386-10 and LUC-3387-10 north side of RR grade.



Photo 135. LUC-3381 149 Lollendorf Road (former schoolhouse).



Photo 136. 3388-10 4609 Seaman Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey_____

Photo 137. LUC-3389-10 4651 Seaman Road



Photo 138. LUC-3389-10 4651 Seaman Road



Photo 139. Johlin log cabin in Pearson Park, relocated from Corduroy Rd.



Photo 140. 5128 Seaman Road



Photo 141. 5157 Seaman Road. First Baptist on Oregon Bay



Photo 142. 5150 Seaman Road



Photo 143. 5330 Seaman Road



Photo 144. 5330 Seaman Road



Photo 145. 5438 Seaman Road



Photo 146. LUC-215-10 5507 Seaman Road Fassett House



Photo 147. 5501 Seaman Road



Photo 148. 5518 Seaman Road



Photo 149. 5537 Seaman Road



Photo 150. 5557 Seaman Road



Photo 151. LUC-216-10 5749 Seaman Road



Photo 152. 5763 Seaman Road. National Gospel Tabernacle



Photo 153. LUC-259-10 212 Stadium Road St. Ignatius



Photo 154. 229 Stadium Road



Photo 155. 349 Stadium Road



Photo 156. 334 Stadium



Photo 157. 37 N. Stadium Road



Photo 158. 5808 Seaman Road at N. Stadium Road intersection.



Photo 159. 5844 Seaman Road



Photo 160. 5860 Seaman Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 161. 5865 Seaman Road



Photo 162. 5906 Seaman Road.



Photo 163. 6316 Seaman Road



Photo 164. 6406 Seaman Road



Photo 165. 6405 Seaman Road



Photo 166. 6512 Seaman Road



Photo 167. 6445 Seaman Road



Photo 168. 6512 Seaman Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 169. 6601 Norden Road N/E corner at Seaman Road.



Photo 170. 6660 Seaman Road. Rusticated block American Foursquare.



Photo 171. 6714 Seaman Road



Photo 172. 6733 Seaman Road



Photo 173. 6735 Seaman Road



Photo 174. Seaman Road south side along 6000 segment.



Photo 175. 7113 Seaman Road



Photo 176. 7131 Seaman Road



Photo 177. 7133 Seman Road Fleitz Farm 1906



Photo 178. Looking northwest from intersection of N. Curtice and Seaman Roads



Photo 179. Northwest view from Curtice and Seman Roads



Photo 180. 110 N. Curtice Road



Photo 181. Dwight D. Eisenhower School on east side of N. Curtice Road with wind turbines.



Photo 182. 400 N. Curtice Road.



Photo 183. House at N. Curtice Road



Photo 184. 7333 Navarre Road on northwest corner of N. Curtice. Goebell's Farm.



Photo 185. 7333 Navarre Road on northwest corner of N. Curtice. Goebell's Farm.



Photo 186. 6824 Navarre Road



Photo 187. 6824 Navarre Road



Photo 188. 6734 Navarre Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 189. NE corner of Navarre Road and Nordern Road.



Photo 190. Barn associated with house at NE corner of Navarre Road and Nordern Road.



Photo 191. Looking east from Norden Road at Navarre intersection.



Photo 192. O'Briens Greenhouse on Navarre Road.



Photo 193. Mail Pouch barn at 6459 Navarre Road.



Photo 194. Mail Pouch barn at 6459 Navarre Road.



Photo 195. 6459 Navarre Road.



Photo 196. 6318 Navarre Road



Photo 197. 6113 Navarre Road. Peach Farm DOE 1996.



Photo 198. 6116 Navarre Road looking southwest



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 199. Peach Farm at 6113 Navarre Road DOE



Photo 200. Peach Farm at 6113 Navarre Road DOE bank barn circa 1908




Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 201. Peach Farm Peach Farm at 6113 Navarre Road DOE



Photo 202. Peach Farm at 6113 Navarre Road DOE granary



Photo 203. Peach Farm at 6113 Navarre Road DOE east elevation of barn



Photo 204. Cape Cod in 6000 section of Navarre Road



Photo 205. 6009 Navarre Road



Photo 206. 5929 Navarre Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 207. 5929 Navarre Road.



Photo 208. 741 Stadium Road



Photo 209. 730 Stadium road



Photo 210. Stadium Road bungalow near 730



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 211. 237 N. Stadium Road



Photo 212. 237 N. Stadium Road closer view.



Photo 213. 102 Stadium Road.



Photo 214. Looking northwest from Starr Ave. toward Pearson Park.



Photo 215. 4047 Starr Ave.



Photo 216. 4104 Starr Ave.



Photo 217. 4032 Starr Ave.



Photo 218. 3833. Starr Ave.




Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 219. 3748 Starr Ave.



Photo 220. 3465 Navarre. Road



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 221. 3465 Navarre Road Dr. Riza Gynecologist.



Photo 222. Looking east from 3465 Navarre Road showing commercialization.




Photo 223. 3465 Navarre Road



Photo 224. Carriage House at 3465 Navarre Road.



Photo 225. 3465 Navarre Road, east elevation.



Photo 226. 3536 Navarre Road



Photo 227. 3536 Navarre Road



Photo 228. 3554 Navarre Road



Photo 229. 3608 Navarre Road.



Photo 230. Looking north toward Project from Navarre Road at 3608.



Photo 231. Navarre Road looking north toward Project from 3608



Photo 232. South side of Navarre Road at 4728, Wells Bowen Realtors' two outbuildings



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 233. 4728 Navarre Road.



Photo 234. Intersection at Navarre Road and Wynn Road showing modern residential development.



Photo 235. 5210 Navarre Road



Photo 236. 5332 Navarre Road



Photo 237. 5332 Navarre Road



Photo 238. 5360 Navarre Road.



Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 239. Unknown address. Navarre Road near RR crossing S/W



Photo 240. Cantilevered concrete T-beam/slab over porte-cochere



Photo 241. Navarre Road adjacent to RR grade southwest quadrant.



Photo 241. Wynn Road abandoned brick building




Photo log for the Section 106 Review Project Summary Form Documentation Table Oregon Gas to Electric Power Plant APE Survey

Photo 242. Wynn Road at southwest corner of Cedar Point Road



Photo 243. 1330 Wynn Road.



Photo 244. 844 Wynn Road



Photo 245. Pearson Park looking northwest toward Johlin Cabin



Photo 246. Johlin Cabin rear (south) elevation at Pearson Park



Photo 247. Johlin Cabin looking west with railroad in background



Photo 248. Johlin Cabin looking west with industrial sites in background.



Photo 249. Johlin Cabin looking southwest in Pearson Park toward RR.




Photo 250. Plaque near Johlin Cabin at Pearson Park



Photo 251. North elevation of relocated Johlin Cabin



Photo 252. Rear elevation of Johlin Cabin




Photo 253. Johlin Cabin placard



Photo 254. Southwest corner of Johlin Cabin showing corner notches and water tower in the background.



Photo 255. Johlin Cabin east elevation




Photo 256. Rear elevation of Johlin Cabin. Note TV/radio towers.



Photo 257. Johlin Cabin rear elevation, looking northwest, with development in the background, across Seaman Road.

Attachment C

Ohio Historic Inventory Forms



. No. 1110-202-10	4. Pres	/ENTORY	
County Lucas	D10	kius, Strie [, Pesidence	
		w Name(s) Neculiough Store, B.	S. Deeler Craw
Location of Negatives T -NWONDO		nos el succestrator control es	a. 100100 20006
Specific Location		16. Thematic Category	28. No. of Stories
5808 Cedar	r stadium 7d	A Detector of Deviced	29. Basement? Yes Li No S
COLDE	T. S.B. (27 TAM)	17. Date(s) or Period C . LAGO	30. Foundation Material
City or Town If Bural,	Township & Vicinity	18. Style or Design	Frick
Oregon	÷	Italianate	St. Wall Construction Stick+omluted
. Site Plan with North Arro	N/P	19. Architect or Engineer	32. Roof Type & Material
		20. Contractor or Builder	1.1.0 Le/道豹和沿法
		a Closed the it meaned	33. No. of Bays Front 2 Side
ian P.I. Rd. ^{EI} di		21. Original Use, it apparent	34 Wall Treatment
0	61	22. Present Use	Tenica neodificiat
		2-Camily redifience 23. Ownership Public C	35. Plan Shape
Conductor		Private	(Explain Altered %)
Lat. Long.		24. Owner's Name & Address,	in #42) Moved []
Lat Long. U.T.M. Reference		" Ernie L. Dickies South Cadar Mint	Interior
12 25 3 5 1 0	46 16 20 0	Confermine, O.	Exterior Control
ione Easting	Northing	25. Open to Yet - Public? No S	38 Preservation Yes □ Underway? No □
0. Site ⊡ Building №	Structure L	26. Local Contact Person or Organization	39. Endangered? Yes
1. On National Yes 🗆	12. Is It Yes	GresCorner. Tep. Mart. Con.	By What? No 🕄
Register? No 🖄	Eligible? No 😳	27. Other Surveys in Which Included	d0 Visible from Yes 2
3. Part of Estab. Yes 🗆	14. District Yes [] Potent17 No [2]		40 Visible from Yes 2 Public Road? No
Hist. Dist.? No E			a law with the local data and th
	strict		41 Distance from and Econtage on Board
	strict		Frontage on Boad
5. Name of Established Dis		a status treitmente add tha	Frontage on Road
 Name of Established Dis Further Description of Ir mont. Enterest. 	mportant Features	a studou trestmente add cha gture. The 2/2 double max	Frontage on Boad
 Name of Established Dis Further Description of Ir hont interesting sindows have of 	mportant Features of Lo this stru-	sture. The 2/2 double hour headmaids that lue sills.	Frontage on Road
 Name of Established Dis Further Description of Ir Mont Interest sindows have of Foese is a dis 	mportant Features	eture. The 2/2 double house headmaids that lum sills. light benesth the essions	Frontage on Road
 Name of Established Dis Further Description of Interest standows have of Face is a cit gamle and. All been realisted 	mportant Features of Lo this stru ordine prick poulte profe lthough the s by chaotents	sture. The 2/2 double man headmaids that lue sills. first beneath the eastern intered on the V. facate bare , he produced are still	Frontage on Road
 Name of Established Dis Further Description of Interest windows have of These is soil gable end. All been realisted present. A We 	mportant Features in to this structures of the point of the structure of the lthough the st by characterite	eture. The 2/2 double note headmalas that lue sills. light benesch the essions intres of the V. facade buye , he produces see still by all to a with stairs to	Frontage on Road
 Name of Established Dis Further Description of Ir mont Enterest stindows have of These is soil genie end. All been replaced present. A we the second stir History and Significance 	mportant Features of Lo this stru ormate brick neulte gable lthough the a by cusetants order the stru order the stru order the stru	sture. The 2/2 double main headmaids that lue sills. light beneath the east in informer of the V. facate bare , he produces are still by all the tite stairs to situated by the V. facate. one area lighters, Thomas T	Frontage on Road
 42. Further Description of Ir mont interval windows have of Force is a cit ganle end. \$1 been realaced present. A we tak second attr 43. History and Significance 	mportant Features	store. The 2/2 double note hoadmalds that lue sills. light beneath the eastern inters of the V. facade bare , he hoodmoids are still by all the with stairs to accord to the V. facade, one area inceres, Thomas T ated this as a store and to	Frontage on Boad
 Name of Established Dis 12. Further Description of M monit intervent windows have of There is a cit ganie end. All been replaced present. A we tak second fits 13. History and Significance Werhallough, bu a forcal round. 	mportant Features of to this structures of bouise gable though the a by characterise of the factors of the back garly Rsy the ailt and of an for the name	store. The 2/2 double man headmains and lue sills. light beneath the eastern inters of the V. facade bave , the producide are still by allithe with stairs to according to the S. facade. one area incerns, "house T ated this as a store and the light of the state. S. T.	Frontage on Boad
 Name of Established Dis 12. Further Description of M monit intervent windows have of There is a cit ganie end. All been replaced present. A we tak second fits 13. History and Significance Werhallough, bu a forcal round. 	mportant Features of to this structures of bouise gable though the a by characterise of the factors of the back garly Rsy the ailt and of an for the name	store. The 2/2 double note hoadmalds that lue sills. light beneath the eastern inters of the V. facade bare , he hoodmoids are still by all the with stairs to accord to the V. facade, one area inceres, Thomas T ated this as a store and to	Frontage on Boad
 Name of Established Dis <pre>Stablished Dis host interest sindows have of Foreve is a cirr ganle end. All been reals ed present. A we the second atr A. History and Significance We fullough, bu s "ocal coint suppe. Time</pre>	mportant Features in Lo this structures the point the structure by characterite order for structure ory had been genly Ray the allt and other for the nerve then, it has	store. The 2/2 double how hoadmales that lue sills. light beneath the eastern interests the 2. facade have , he positions are still by all the the X. facade, ore area increase, Thomas T wild this as a store and the locality. Later, 5. 7. been conversed to a two-	Frontage on Road
 Name of Established Dis Further Description of its hoat interest sindows have of Poeve is a cit gable end. All been reals ed present. A we the second attr 43. History and Significance Werfullough, bu a "ocal coint puble. Tince 44. Description of Environm 	mportant Features in Lo this structures the point of the structure bound the structure bound for the structure only had been for the new then, it has nent and Outbuildings	store. The 2/2 double note hoadmales that lue sills. light beneath the eastern interes of the M. facade have , the positions are still by all the title stairs to <u>situeted be the N. facade</u> . ore area increase, Thomas T miled this as a store and the leconard g. Later, S. T. been conversed to a two-	Frontage on Boad
 Name of Established Distribution of Interest. Further Description of Import Interest. There is a city ganle end. There reals ded present. We the second stricts. History and Significance Schullough, but the second stricts. 	mportant Features in Lo this structures in online gable lthough the a by cusetonts onler for-sto ony has been for the nerv for the nerv then, it has nent and Outbuildings	store. The 2/2 double how hoadmales that lue sills. light beneath the eastern interests the 2. facade have , he positions are still by all the the X. facade, ore area increase, Thomas T wild this as a store and the locality. Later, 5. 7. been conversed to a two-	Frontage on Boad
 Name of Established Dis Further Description of its hoat interest sindows have of There is a cit gable end. All been reals ed present. A we take second attr History and Significance Vehillough, bu a "ocal coint bubbe. Finde Mean coint bubbe. Finde 	mportant Features of Lo this structures of the this structure south seable though the webbe by checkents orly had been genly Ray the allt and other for the nerve then, it has ment and Outbuildings onteronds of a sheriba.	store. The 2/2 double man headmains and lue sills. Hight beneath the eastern inters of the V. facade bave , the producide are still cy all the sith stairs to attend to the V. facade, ore area (tenends, "house T ated this as a store and the lecanded 2. Later, 5. 7. been anothered to 3 the-	Frontage on Boad
 Name of Established Distribution of interest. Further Description of its hont interest. Sindows have of Fnere is a cill ganle end. Senie end. Senie end. Senie second stributes History and Significance Schullough, but a "nocal coint bubble. History of Environm bot of Environm bot of Environments 	mportant Features in Lo this Atru omnate brick bouis gable Ithough the s by cusetents bodes fac-sto ory has been Serly Ray the allt and oran for the new then, it has ongroute of a symposi	store. The 2/2 double how headmains and luw sills. Night beneath the eastern interests the M. facade have , the positions are still by all the tite stairs to <u>situated be the E. facade</u> . ore area itenears, "Bonna T wied this as a store and the lecancel 2. Later, S. F. beam anothered to B two-	Frontage on Road
 Name of Established Dis 2. Further Description of its nonin intervent sindows have of There is a cit gable end. All been reals of present. A we the second atr 3. History and Significance We hallough, bu a "neal coint bubbe. Fince 44 Description of Environm b0 of the city stop thy and a 	mportant Features in Lo this struc- minite brick bouise gable Ithough the a by cusetonts onder for-stro- onder for-stro- onder for-stro- onder for-stro- onder for-stro- ny has been for the nerve then, it has ment and Outbuildings onground of a shoulds.	store. The 2/2 double man headmains and lue sills. Hight beneath the eastern inters of the V. facade bave , the producide are still cy all the sith stairs to attend to the V. facade, ore area (tenends, "house T ated this as a store and the lecanded 2. Later, 5. 7. been anothered to 3 the-	Frontage on Road
 Name of Established Dis 5. Name of Established Dis Mont Enterept sindows have of Toeve is soil ganle end. All been reals ded present. A we tas second attr tas second attr	mportant Features in Lo this struc- minite brick bouise gable Ithough the a by cusetonts onder for-stro- onder for-stro- onder for-stro- onder for-stro- onder for-stro- ny has been for the nerve then, it has ment and Outbuildings onground of a shoulds.	store. The 2/2 double man headmains and lue sills. Hight beneath the eastern inters of the V. facade bave , the producide are still cy all the sith stairs to attend to the V. facade, ore area (tenends, "house T ated this as a store and the lecanded 2. Later, 5. 7. been anothered to 3 the-	Frontage on Road

OHIO HISTORIC INVENTORY

£

Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211

County Jucas	5. Other Name(s)	
Location of Negatives	Jacob W. Borger Residence	
Specific Location	16. Thematic Category	28. No. of Stories 2
6118 Cedar Point 1	(dC	29. Basement? Yes
	17. Date(s) or Period	30. Foundation Material
City or Town If Rural, Township		Brick
City or Town If Rural, Township	Vernacular Greek Revival	31. Wall Construction
. Site Plan with North Arrow	19. Architect or Engineer	- Setek
	20. Contractor or Builder	32 Root Type & Material
	6	133 No. of Bays
PCedar Rt. Rd. 0000	21. Original Use, if apparent	Front D Side 4
	0 0 Recidence	34. Wall Treatment
[]	22 Present Use	35. Plan ShapeRectforguin
	23. Ownership Public	36 Changes Addition to
Coordinates	Private 👳	Explain Altered II in #42) Moved II
Lat. Long.	24. Owner's Name δ Address, il known state of the company of the state of the stat	37 Condition
U.T.M. Reference	- Kenneth O. Berger 6118 Centr Point -	Interior
2 3 0 01 00 4 6 1		Exterior
one Easting Nort	hing 25. Open to Yes U	38 Proservation Yes Underway? No 2
0. Site 🗆 S Building 🖄	ructure 1.1	
1. On National Yes 📋 12. Is II	Yes G Oreg. Jornie, Twp. Hist. 400.	
Register? No E Eligible	? No 27. Other Surveys in Which Included	
3. Part of Estab. Yes 🖂 14. Distric	t Yes 🗇	40. Visible from Yes 🗄
	17 No 🖓	Public Road? No 🗇
5. Name of Established District		Frontage on Road
arched, The front p	one has been enclosed and a one with an virian deck are decire from	
43. History and Significance	form has been identified by local	ateromians and at-
Lases as first belongi family who moved from ten. Inseline, married	for to Robert F. and Catherine Ture Conrow, With. to Oreson c.1850. I Lammert Deverse, the son of Feter or case from Contour to settle in	pr Novarte, a picturer Ine of their 17 rot16 - filmiti Usiriachte
	muldings (1) has been do a parried cond.	
fields. One large ba	on our several another pubbulists	18
45. Sources of Information -	P America and	46. Prepared by
	a second a <u>l'at</u> <u>12</u> <u>Oregan</u> <u>and</u>	The state of the s
lorgaslen <u>Twn</u> , Unsan v norv bilaras.	proved when we are investign or part of	47. Organization
and the H Konk, Astranti	West of the Train way	10 min 100 min 2000
personal services and the solution of		48, Date 49 Revision Date(s)

OHIO HISTORIC INVENTORY Ohio Historical Center Columbus, Ohio 43211 4. Present Name(s) No Luc-215-10 Juc-2 Dr. William Imon, Jr. House 2. County 5. Other Name(s) 3. Location of Negatives Ai Hansom Passett, dr. House 27 6. Specific Location 16. Thematic Category 28. No. of Stories rid C County 29. Basement? Yes K Lucas 5:07 Sesman Rd. No 🖂 17. Date(s) or Period c. 1900 30 Foundation Material ani ex 18. Style or Design 7. City or Town If Rural, Township & Vicinity Oregon Queen Anne Wall Construction 31 Vlum. siling 8. Site Plan with North Arrow 19. Architect or Engineer P Roof Type & Material 9.01 NE the state fp/gsobalt snin 20. Contractor or Builder Stod. No. of Bays 33. t. Frant Side 21. Original Use, If apparent Presen 14 Peridence LESSELS 34. Wall Treatment 22. Present Use COMPAN 35 Plan Shape Policing Reglience Dr. Mr Seamine Kel 23: Ownership Public 36. Changes Addition F Private 12 Explain Altered I 9. Coordinates (0 #42) Moved [111 ans 24. Owner's Name & Address, Long Lat H known Op. Wm. Iman, Jr. U.T.M. Reference 5567 Seawan Rd., Oregon Interior 2 98 2 30 4613830 Excellent Estimior Zone Easting Northing 25. Open to Yest 4,4 Preservation Yes IZ Public? Nor Underway? No il 10 Site [Structure Building § Object 26. Local Contact Person or Organization 24 Endangured? Yes megon- erus, Twn. Hist. Non. By What? No X On National Yes X Yes [] 12 15 11 Register? No M Eligible? No D 27. Other Surveys in Which Included Yes No X Part of Estab. Yes [] District 13 14 Visible from 40. Yes E No M Hist, Dist.7 Potent'l? Fublic Road? Not 15. Name of Established District Distance frum and Epontage on Boad 42. Further Description of Important Features The house http://www.auser.aus 490 Contures. There is an L-shaded versings across the front Fassatt, £7 and eastern facade which has bulking columns and lattickwork down to the ground level. The southern windows ŧ; 1 leave source 1/1 double hung. A two story octagonal ba and an unusual above-ground basement addition are on th eastern facade. The western facane has both an octation SUR 4 one story star called elevation Cont 43. History and Significance Historic documentation is not yet completed. However, known that Ai Panson Rassett, Jr. was born in Wyoming County, M.Y. in 1847 and moved to Oregon by covered wagon with his family is 1852. His father helped clear land and build the first churches and schools and acted as the first school director. A. R. Massett, Mr. continued Low, rewdition of Cont 14 0.0110 44. Description of Environment and Outbuildings Locater adjacent to the Drawon "cuicipt) Revers-- ont complex and 2 houses from Ulas With Webcol. 45 Sources of Information Presionet In CHURCH ST State and the state of the state raight of Omenny and Depugatery Tury, experits, 10 49 Philaton Date(s) 48 Date

Ohio Historic Preservation Office

1

ł

OHIO HISTORIC		/ENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211
No		ent Name(s)	
Luc-216-10 2. County	Vat	ion Full Cospel Tebernacle T	arsonage
Lucas	5. Othe	er Name(s)	
 Location of Negatives L-MACHPO 	Cla	y Chapel Vetrodist Protestar	it Marsonage
. Specific Location		16. Thematic Category	28. No. of Stories 11
5749 Seaman Rd. Gregon, O.		17. Date(s) or Period	29. Basement? Yes 다 No 원
500 001 002 1 000		1893	30. Foundation Material
7. City or Town If Rural, Township 8	S. Vicinity	18. Style or Design wheen Anne Cottage	31. Wall Construction
3. Site Plan with North Arrow	. NA	19. Architect or Engineer	32. Roof Type & Material
2		20. Contractor or Builder	Cable/saphalt shin
Lay Lightsch. D C		21. Original Use, if apparent	33. No. of Bays Front 12 Side
Jay Dighsen DI CU		Pesidence	34. Wall Treatment
		22. Present Use	35 Dian Change
0		23. Ownership Public	35. Plan Shape Bit Shape 36. Ghanges Addition G
. Coordinates		Private Y	(Explain Altered Alter
Lat. Long.	_	24. Owner's Name & Address, if known Conden 4. Roberts	37. Condition
U.T.M. Reference		5703 Adaman Pt.	Interior Exterior 1000
20ne Easting North		Cinecton, Q. 25. Open to Yes C	Exterior TCOC 38. Preservation Yes C
0. Site 🗆 Str	ond ructure [] Object []	Public? No 2 26. Local Contact Person or Organization	Underway? No 11 39 Endangnosd? Yes Li
11 On National Yes 🗆 12 Is It	Yes 🗆	Overon-Arussion Hist. Cov.	By What? No 🕾
Register? No K Eligible?	? No ₩ Yes □	27. Other Surveys in Which Included	40. Visible from Yes:C
	1? No 🗵		Public Road? No D
15. Name of Established District			41. Distance from and Frontage on Road
42 Further Description of Important Fea	tures	e ariginal ya an inne embell	and the second sec
the steep witched reconstructed for any steep witched reconstructed for the second state of the second steep the second state of the second steep the second st	ave be of is h wind roted	en well-minimizined. Someoth a vieweet deble ornemont and ow. The remaining windows are with wooten architraves. The st facture) has an otheractive	• IIIIII
43. History and Significance pige p:	araona	ge has the same history is t	he church beside it.
It was built on the :	seme s	ere of innd which why denote arly concernity church, Chart cent. In. Nev. pavid Calvins	a by Jerendan Clay,
	buildinas	The concerns is positioned	Pour to the abunda
on the corner of Pear the home is the Clay	man an	d provide operation immediated	y to the use t of
45. Sources of Information	in 125	end of the other of the or the	46. Propared by
The uselon Two.			47 Organization
1 (A. 17) (1744) (47) (17) A. 19(2) (44)	·		48 Date 49 Revision Date(s)


OHIO HISTORIC INVENTORY Ohio Historical Center Columbus, Ohio 43211 4. Present Name(s) 1. No. Luc-217-10 Nation Full Gospel Tubernacle 2. County Lucas 5. Other Name(s) 3. Location of Negatives Clay Chapel Wethodist Protestant Church NWOHPO. 16. Thematic Category 6. Specific Location 28. No. of Stories 10 5763 Sesman Rd, N 29. Basement? Conut Yes corner of Stadium Ed. Date(s) or Period No 15 17. 189330. Foundation Material Handom rubble 7. City or Town If Rural, Township & Vicinity 18 Style or Design Rural Greek Revival 31. Wall Construction Orecan Beveled siging 8. Site Plan with North Arrow 19. Architect or Engineer 2 32. Roof Type & Material Goble/ hsphol 20. Contractor or Builder 100 No. of Bays 33 22.4 Sida Front 4 21. Original Use. If apparent Present Relicious in i 34. Wall Treatment 22. Present Use usin' 35 Plan Shaper shape Relifious Jeaman Ha. 23. Ownership Public 36. Changes Addition Private 5: Allored (Exotain 9. Coordinates in #421 Meivers 1 24. Owner's Name & Address, Lat. Long. if known 37 Crindition Mation Will Connel Pober-U.T.M. Reference Interior 5763 Headen Hi., Orefon 121 299440 Externor Lood 4 6 1 3 6 1 0 25. Open to Easting Northing 38 Zone You Preservation Yes Public? No 53 Underway? No 1 10. Site L Structure Building M Object [] 26. Local Contact Person or Organization ád. Endangered? By What? Note 11. On National Yes 🗆 12. Is It Yes D bregon-Jerus. Two. 1996.200 Eligible? No X Register? No Ki 27. Other Surveys in Which Included 13. Part of Estab, Yes I 14. District Yes 46. Visible from Yes N No X Hist. Dist.? No 12 Potent'l? Public Road? No 15. Name of Established District Distance from and Frontage on Road 42. Further Description of Important Features mine church mas a number of inter secting gables that add interest to the single design. The original structure is marked by the square strepled double doorway with transom light. The western addition has a brocketed gabled projection over a sidelicit/branaom doorway. The winnows are tall, narmow 1/1 double-mund. 10 11 8 43. History and Significance the one some lot upon which the church and parsonage were built was donated by the area pioneer, Commish Clay. The buildings were erected and dedicated in 1995. Consists Clay end h. R. Sneeelt. were charler members. 12024 44. Description of Environment and Outbuildings Encate: or a threat certification common cown and the street from the Pennett Home and tast to Disy That Tonadi. 45 Sources of Information 46 Prepaled by Dress finity Clark, 1889. TELLY of Obring and househes were 45 49. Revision Elsions Date

Ohio Historic Preservation Office


Ohio Historic Preservation Office OHIO HISTORIC INVENTORY **Ohio Historical Center** Columbus, Ohio 43211 4. Present Name(s) 1. No. Luc -241-10 -uc - 241 - 10 Wing, Pieldon Nr. Residence 2. County LUCES 5. Other Name(s) 3. Location of Negatives omany, Luis . esidence 16. Thematic Category 28. No. of Stories 6. Specific Location **N3** County 4328 Bay Phore Ed. 10 29. Basement? Yes 🖂 corner Dupont Ed. No 10 17. Date(s) or Period R. DEDM 30. Foundation Material Erick If Rural, Township & Vicinity 18. Style or Design 7. City or Town 31. Wall Construction Clapboard 8. Site Plan with North Arrow 19. Architect or Engineer 32. Roof Type & Material Ν sable/asphalt shin. 20. Contractor or Builder 个 33. No. of Bays 1 Ming, Front 11 Sitte 21. Original Use it apparent Cart Present I Bry Shore Rd. 34. Wall Treatment 22, Present Usc 12 Fielden 35. Plan Shape (products) s N3/750(8) 36. Changes 23. Ownership Public Addition 2 Private V (Explain Altered 1 9. Coordinates in #42) Moved I 24. Owner's Name & Address, Long 24 Lat. 37 Condition U.T.M. Reference Interior Crame, O. 171 2867480 Exterior Good House Zone Easting Northing 25. Open to Ynsi 38 Preservation Yes 🗔 Public? Underway? No v No 10. Site Structure Building Di Object 26. Local Contact Person or Organization 39. Endangered? Yes ! Oreg. - week, wo. dist. Sec. By What? No W 11. On National Yes Yes 🖂 12, Is It Eligible? No X Register? No 1/2 27. Other Surveys in Which Included Yes 13. Part of Estab. Yes 🗆 14. District Visible from 40 Yes C Potent'l? No H No 13 Hist. Dist.? Public Road? No Distance Ironi and 15. Name of Established District Frontage on Read 2512751 42. Further Description of Important Features this structe the there there there Monaty, Ditter. house has 1/1 double ship windows; ty , how enlapped windown on the first story of the R. (h) L. Stides; a new (Name(a popch autrance on the D. elevation: 11 | mie story wdo-080 ition on the f. fact. 43. History and Significance Totals "Omena when we are the transferred settler. House 122 The ", while of Boy Whong Th, is a the two of the transmission of the transmission and Barr Dunnist Hos., worden thom Pusched 51. tavion and the approads to suppor firs. "bonturi fil provine indzie 45. Sources of Information 46. Prepared by 47 Organization 38 Date 142: Newminn Oatem)


OHIO HISTORI	C IN	/ENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211	
Luc. 242-10	4. Pres	ent Name(s) Norm, Netroid T. Residence		
2. County Talens	5. Oth	er Namets)		-15
3. Location of Negatives		mat, Logis Fesidence		12-14
6. Specific Location	COLTAN STORAGE	16. Thematic Category	28. No. of Stories 7	1
4400 Ray Shore Pd	(#)		29. Basement? Yes 🕅	14
		17. Date(s) or Period	30. Foundation Material	SPONT
7. City or Town If Rural, Township	o & Vicinity	18. Style or Design, pho	Bt j.ck 31. Wall Construction	
8. Site Plan with North Arrow		19. Architect or Engineer	Vinyl shindle 32. Roof Type & Material	
Antokae	Ϋ́	20. Contractor or Builder	Hip/nephalt_eningle 33. No. of Bays	1
ALC: N		21. Original Use, if apparent	Front Side 2	2
R T Bay She	N.C. 1707	22. Present Use	34. Wall Treatment	15g
		Maridence	35. Plan Shape (Scotterting	1
3. Coordinates		23. Ownership Public Private S	136. Changes Addition 2 (Explain Allered 2	ng Lourn, nona
Lat. Long.		24. Owner's Name & Address, if known workfild P. Wilburn	in #42) Moved []	212
U.T.M. Reference		Hads Bay Shore Ed.	Interior	1
	-0.90	25. Open to Yes O	Exterior flond.	- 54
0. Site 17 5	rthing Structure 🗆	25. Open to Yes D Public? No Y	38. Preservation Yes : Underway? No ?	action
Building 🔄 11. On National Yes 🗍 12. is It	Object (1) Yes (1)	26. Local Contact Person or Organization Open - Contact, Swp. 1151, Soc.	39 Endangered? Yes By What? Nr. 17	1
3. Part of Estab. Yes D 14. Distri	le7 No 10 lot Yes	27. Other Surveys in Which Included	40. Visible from Yes ∑	1
	1177 No27		Public Road? No 🖾	
15. Name of Established District			41. Distance from and Frontage on Road	
	obtructured		21519.251	L
roof dormers on each and transmy: full for breezeway and attached	na sae nat bar	a three story oneon Anne how N. hum t. Teander; hisped and with restangular windows on with calcans; and a new e on the S. glevetion.	A	u stnor 'quodhr
		, who the person' tacques huse		nouse
		C loop have for 200 in 1851 as we have by this much loo		a
			3	1111
44. Description of Environment and Or 24.05 Forcher View 12.1	utbuildings 01 RSG	loots of a Siy Phone, such by Leaner dotably on the	иј 148 јеленисти Кушев Бауч	are atour fat contr
45. Sources of Information	a start y	er en	46. Prepared by	010
Figure 1. A set of the figure for the set of the set			47 Organization	H.
			48. Digle, 49. Heylsler: Ostolog	1
			a.V. C.	8

OHIO HISTORIC I	NVENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211
	Present Name(s) Durown, Aubrey Peridence	
	Other Name(s) Momenty, Peter Registence	ALCEX.
6. Specific Location 4454 Bay Chore Fd.	16. Thematic Category	28. No. of Stories
	17. Date(s) or Period 0 , 1 a 20	29. Basement? Yes II No II 30. Foundation Material
7. City or Town If Bural, Township & Vice	nity 18. Style or Design Versional Thalianate	Brick and demgnack
8. Site Plan with North Arrow	19. Architect or Engineer	Britick 32. Roof Type & Material
Morrany Morrany	20. Contractor or Builder	33. No. of Bays
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Front 2 Side 5
	22. Present Use	35. Plan Shape Jectangular
9. Coordinates	23 Ownership Public 11 Private ⊠ 24 Owner's Name & Address,	Front Side 34. Wall Treatment 35. Plan Shape 36. Changes Addition (Explain) Altered (Explain) in #42)
Lat. Long. U.T.M. Reference	W known thirtoy Brown worst Buy Faore 3d.	37 Condition
1 7 2 3 6 7 1 0 4 6 1 8 0 - Zone Easting Northing		Exterior Excellent 8
10 Site (1 Structur Building ¥) Objec	Public? No 🕅	Underway? No 🗆
11. On National Yes 12. Is It Ye Register? No Xi Eligible? H	1 - U) -D, -OH 12, TOL, HITE, FOC,	39. Endangered? Yes □ By What? No ⊠
13 Part of Estab Yes II 14. District Ye Hist. Dist.? No II Potent17 N	5.2 Child Strays in Which model	40. Visible from Yes S Public Road? No
15. Name of Established District		41 Distance from and Frontage on Road
perch strached to the 5.	Termental spaces lintels and the life redileting windows, is the for 5. The only in open convolution of local what was on total one is not 5. withounce cord any.	
· DOY 计符 计结合数字 一份总 治生产于 经	they pethled on Grogon with his frace opart to talk Bay Share i. 'n n' with terms, he but	- noted by in the testing
the c. of the house, in	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	induce and incoming note on a line of a state, and
49. Sources of Information Magnetic	ter i si si spontier ve Station de stationer se	46 Prepared by 47 Ordanisation
		48. Date 49. Revision Date(s)




OHIO HISTORIC IN	VENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211	
1. No. Luc-245-10 Pres	ent Name(s) borts, Freeman 7, Besidance		1. No.
2. County LUC35 5. Oth	er Name(s)		10 A 12
	nn, Thomas E. Residence		245-(0
6. Specific Location	16. Thematic Category	28. No. of Stories	N
4526 Eny Chore Ed.	C	29. Basement? Yes 🔿	1 8
next to 3biftheyer mitch	17. Date(s) or Period	30. Foundation Materiai	County
7. City or Town If Bural, Township & Vicinity	18. Style or Design Vernscular Jueen Anne	Brick	
8. Site Plan with North Arrow 37 14	19. Architect or Engineer	31. Wall Construction Wood Shinyle	
NA SI	20 Contractor on Builden	32. Fool Type & Material	
and an ell S	20. Contractor or Builder	33. No. of Bays	
Bay Share Rds. Freicks	21. Original Use, if apparent	Front C Side D	10 9
Carry De Carry	Residence 22 Present Use	34. Wail Treatment	obe
	sesidence	35. Plan Shape Matterre	PTC:
	23. Ownership Public 🖂	36. Changes Addition	Roberts, Fr
9. Coordinates	24. Owner's Name & Address,	(Explain Altered 쐰 In #42) Moved 또	(2) (3)
LatLong	H known Freeman X. Foberis	37. Condition	e(s) Freeman
U.T.M. Reference	4526 Bay Snore Pd. Crezon, O.	Exterior FSIP	5
Zono Easting Northurn	25. Open to Yes	38. Preservation Yes 🖸	
10. Site 1. Structure 1 Building 2. Object 15	Public? No 20 26. Local Contact Person or Organization	Underway? No 39 Endangered? Yes	House
H. On National Yes T 12 In 0 Yes T Register? No D Eligible? No X	DrogJerns.Twp.Nist.Yot. 27. Other Surveys in Which Included	By What? No. 2	đ
13. Part of Estab. Yes 14. District Yes 7 Hist. Dist.2 No.X. Potent17 No.X.	are only surveys in which includes	40. Visible from Yes 2 Public Road? No 🗆	
15. Name of Established District		41. Distance from and Frontage on Road	
42. Further Description of Important Features		2.54 GALOC	
the Tayspe Proof	the flexis Mevarre home (i), noews are 1/1 confidence, light in the F, elevation, M, Secure has columns, when		Dunn, Thomas
43. History and Significance	an apply May Chapa minusay	and neighbor of	191 •
(re" for the the Side 10	of Seter Newspre, and a ver- Som married a complete of Ser Creek Fd. heaste heavily	Sh of both Die 1400	House
44. Description of Environment and Outbuildings	dentes of the Balance of Late	and the second state	1520
$ \begin{array}{c} \Xi (1 \le 0), (1 \le 0) \le (1 \le 0), (1 \le 0), $	IN THE REPORT OF THE PARTY OF T	configuration rec.15: a.15	Bev
46. Sources of Information in the second sec	ed gelena esta l'estanol de Tra-	46. Prepared by	10000
	STANDARD AND A STANDA	Special 6, million	
		47. Organization	皆
		43 Date 49 Revision Date(s)	





OHIO HISTORIC II	VENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211
4. Luc-258-10 2. County Tulesc 5.	Present Name(s) Imerican Freewill Baptist Churc Other Name(s) Homestead School	h
3, Specific Location 3409 Reaman Rd.	16. Thematic Category	28. No. of Stories
corner Yoy 9d.	17. Date(s) or Period 1907	30. Foundation Material Frick/water table
City or Town II Rural, Township & Vicin Opeon Site Plan with North Arrow	18. Style or Design 19. Architect or Engineer	31. Wall Construction Brick/painted
	20. Contractor or Builder Julius Comte	32. Root Type & Material Guble/asphalt shin, 33. No. of Bays
	21. Original Use, if apparent Schoolhouse	Front 3 Side 4
E S	22. Present Use Religious 23. Ownership Public O	35, Plan Shape Rectangula 36, Changes Addition 18
Coordinates Lat. Long. U.T.M. Reference [7] [2] [4] [5] [2] [6] [1] [3] [5] [6] [1] [3] [5] [6] [7] [3] [6] [1] [3] [5] [6] [7]	25. Open to Public? 26. Local Contact Person or Organization Prog Jeros. Twp. Hist. Sec. 27. Other Surveys in Which Included	Interior
school was severely sites Flemish belfry were remove building was purchased by Church. The buttweesed, 9 of its former chars. The plain lug lintels is sil statistics has been struche 3. History and Significance was was	ed when the parapet gables and ed, probably c.1347 when the the American Rumanian Orthodox moned entranceway gives a taste bid doublehung windows have ls. A cement block, one story i to the N. feeste. one of the first brick one room as residential community in wes	schoolhouses built
4. Description of Environment and Outbuilding	95 [costed on the NR corner of]	Seastn and Cov Bands.
two residential derivers.	an konstantistas onta konstru kar materialogo das s	
5. Sources of Information Provide the August 1997		46 Prepared by
		19. (Jate) 19. Revision Detoist



Gone.

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211

orno rnor			oomining, one 45211
1. No. Luc - 250 -11	-	sent Name(s)	
2. County	10	ttry, Bobble G. Mesidence	
Luces	5. Off	er Name(s)	
 Location of Negatives L-NWOHPO 	T the	seett, Ai Pansom Sr. Mesiden	ee; Ered J. Cents
6. Specific Location	the second s	16. Thematic Category	28 No. of Stories
5502 Cordui	oy Rd.	<u> </u>	29. Basement? Yes X
	N CONTRACTOR DE LA CONTRA	17. Date(s) or Period C. 1660	No 🗆
7. City or Town If Rural	. Township & Vicinity	18. Style or Design	30. Foundation Material
Oregon	, rownamp a vicinity	Vernacular Italianate	31. Wall Construction
8. Site Plan with North Arro	w NA	19. Architect or Engineer	=rick/paintod
			32. Roof Type & Material
E. C. J R	Pb-	20 Contractor or Builder	33. Mo. of Bays
Cordinary Rd	and the second se	21 Original Use, if exparent	i ront 3 Side 4
e	11	Substitutions	34. Wall Treatment
2	1 the	22. Present Use	
wahr.	n Shidium	veri ferae	35. Plan Shape meshippe
9. Coordinates	(V)	23. Ownership Public Private 😥	136. Changes Addition □ (Explain Altered □
		24. Owner's Name & Address,	in #42) Moved 🗆
Lat. Long U.T.M. Reference	•	if known	37. Condition Interior
			Exterior Good
Zone Easting	Northing	25. Open to Yes	38. Preservation Yes
10. Site	Structure	Public? No 🕾	Underway? No 🗆
Building X	Object	26. Local Contact Person or Organization	39. Endangered? Yes 🗔
11. On National Yes D Register? No X	12.15.11 Yes Eligible? No El	Gren Caun. Two. Mist. Roc.	By What? No ⊠
13. Part of Estab Yes 🗆	14. District Ves	27. Other Surveys in Which Included	40 Visible from Yes 13
Hist, Dist.? No.g.	Potentin No 2	-	Public Road? No 🗆
15. Name of Established Di-	strict		41. Distance from and Frontage on Road 1251 x 5001
42. Further Description of In	noctant Features		the second se
tels and plain es (on the W. 6	(Pahouse with lug sfile. (Levation) vs	ia is a cimply executed itsl morganized encoded window lin the two scall entrance porch e ione is the used tank i intrieste schollwork.	
43 History and Significant		1	
		t. Tr. nurchesed this proper to cartheolog some war built	
monten. Fastol	with with the left	ly computity leader, and hel	bed build the finat
log achool in 3	OPERASIONE (formard / (english Courses), a	form the land for
the first churr	in another for	se needaank ju queton. ge s	nd turee generations
44. Description of Environm	ent and Outputdings	n Grezog concol development,	bid lived dere.
located abo	ut B th In A.	of the Renter of Cordinary of	Set WEINERSON WARE
ous neerown).	on sentes e se	The with a large barg to	a cala it we take house.
dfi Sources of Information			Lat. Building (4)
1 sources of information	CONTRACT	 	46 Prepared by Theorem in the Contraction you
1.02003 20.000 00.000	12.6	DR. Maan (March 1978), althoughtag	47 Organization
			CHINE OF PD
			48. Date 49. Revision Date(s)

	VENIONI	Ohio Historical Center Columbus, Ohio 43211
Luc-251-10 0	esent Name(s) allee, William T. Desidence	
2. County Litees 5. Of 5. O	the Name(s) avarre, Samuel and Rudolph Res	lience
5. Specific Location	16. Thematic Category	28. No. of Stories 1 16
5254 Corduroy Ed.	0	29. Basement? Yes 🗆
	17. Date(s) or Period entrip 1861*6	No 전 30. Foundation Material
7. City or Town II Rural, Township & Vicinit Operan	y 18. Style or Design LM story framehouse	31. Wall Construction
Site Plan with North Arrow	19. Architect or Engineer	loginum siding
NM	20. Contractor or Builder	32. Roof Type & Material Chicle/1801511 shirt
ordurey Rd. E 11 E 2		33. No. of Bays Front Side
	21. Original Use, It apparent Residence	34. Wall Treatment
	22. Present Use	35 Plan Shann
Ji	Residence 23. Ownership Public []	35. Plan Shaperectisticity at 36. Changes Addition-(1)
9. Coordinates	Private 🕅	(Explain Altered 8 in #42) Moved □
Lat. Long.	24. Owner's Name & Address, if known	37. Condition
U.T.M. Peterence	1	Exterior Fricellent
Zone Easting Northing	25. Open to Yes	38 Preservation Yes
0. Site T. Structure	Public? No 🗹	Underway? No 🗆
Building 5% Object © IT. On National Yes □ 12 Is II Yes □ Register? No 10 Eligible? No 0	The second	39, Endangered? Yes ⊡ By What? No E
3. Part of Estab Yes L 14. District Yes Hist, Dist.? No.2. Potent IV No.5	- Tax, other surveys in which included	40. Visible from Yes S Public Road? No 🗇
15. Name of Established District		41. Distance from and Frontage on Road
log house penaina vis the:		and the
this house in the early 10 this section of refer, in Comencetown Others, its o he and his wife, A site, bo	while and his femily entited of RD's. He was one of the caris i was active in founding and r so, Rutoloh, lived here offer which in to three Preson same free in to three Distance	est cettlers in counting the first close) fied and closeners at a fime.
<pre>this neuse in the early 1%) this section of refer, in 'omencetown Otherol. is in he and his wife, A site, bo 44. Description of Environment and Outbouldings</pre>	The second and the second seco	est cettlers in relating the first stream incd and (income to solve) income from Recky's is a small brack.
<pre>this druge in the early 14) this section of refer, in 'omencetown Otherol. 14, by he and his wife, A site, bo 44. Description of Environment and Outboulding: Threads and Bill's converses</pre>	Fors, le the one of the early i was active in founding and b so, Rutoloh, lived here offer arted up to three Oregon Saint freether to the oregon libe Slub; so 1, we the routh of the bound	est cettlers in relating the first stream incd and (income to solve) income from Recky's is a small brack.
<pre>inis incuse in the early 14) this section of refer, in fomensectors Otherol. 14, in he and his wife, A site, bo 44. Description of Environment and Outbourding Trivers and Bill's converses</pre>	Fors, le wag one of the early i was setive in founding and b so, Runoloh, lived here after arted up to three Operan Early Freet to creson libe Club: ad	est cettlers in relating the first stream incd and (income to solve) income from Recky's is a small brack.
<pre>inis incuse in the early 14) this section of refer, in fomensectors Otherol. 14, in he and his wife, A site, bo 44. Description of Environment and Outbourding Trivers and Bill's converses</pre>	Fors, le the one of the early i was active in founding and b so, Rutoloh, lived here offer arted up to three Oregon Saint freether to the oregon libe Slub; so 1, we the routh of the bound	<pre>46 Prepared by 1923 112 Parts 12 146 Prepared by 1923 112 Parts 12 147 Parts 12 148 Par</pre>

OHIO HISTORIC II	VENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211	
1. No. Luc-252-10	Present Name(s) Dregon Nite Club		Luc-
	Other Name(s) Some neetown Store and Tavern		252-10
6. Specific Location	16. Thematic Category	28. No. of Stories	in
5764 Corduray Ed.	C 17. Date(s) or Period	29. Basement? Yes 🖂 No 🖄	Lucas
corner Stadium Rd.	c.1860's	30. Foundation Material	nty
7. Gity or Town If Rural, Township & Vicir Operion	ity 18. Style or Design	31. Wall Construction	
8, Site Plan with North Arrow .	19. Architect or Engineer	Vinyl eningle	8
Kalin I	20. Contractor or Builder	32. Boof Type & Material Inple/nabout. Entry.	-
C L L is Credwroy	Rd. 21. Original Use, if apparent	33. No. of Bays Front Side	4
	22. Present Use	34. Wall Treatment	Leg.
E	Tavera	35. Plan Shapegert trained 1 an	on Na
	23. Ownership Public C Private %	36. Changes Addition	Cregon Nite
9. Coordinates Lat Long.	24. Owner's Name δ Address. If known	in #42) Moved 🖾	Olub
U.T.M. Reletence		Interior	CE0
12 2 99 3 1 0 96 14 515	U 25. Open to Yes X	Exterior TORD 38. Preservation Yes D	
Zone Easting Northing 10. Site Structure	Public? No 🗆	Underway? No 🕅	
Building & Object 11. On National Yes 12 Is II Yes Register? No 52 Eligible? No	p Oreg, -Jerus, Wp. Hist, Fod.	39. Endangered? Yes □ By What? No 徑	
13. Part of Estan, Yes 💭 14. District - Yes		40. Visible from Yes 51	ĺ.
Hist. Dist.? No S. Potent'l? No 15. Name of Established District	*	Public Road? No 2 41. Distance from and Frontage on Road	
Party and a second s		101x501	
42. Further Description of Important Features	Dilacidated two atory frame ension on the S. facade,		Momeneetown Stor
hereiter nichter und in wenebel	ing had served the small rural store, bayers and meeting hull Fuos Momence, central figure	. community of since e.1860. 15 in Domonectowy Mar-	re and Tavern
44 Description of Environment and Outbuilding	99 Stitusto, is the SW corner of	Zarearay stat	III
11 - 12 - 13 - 201 - 151 -			191.4
45 Sources of Information Brackets L. 112	t. Transministration and deputer for	46. Prepared by	Corduroy
And a reaction of the second		47 Organization	UTOJ
			nd.
×			5


ы 1

ŀ

OHIO HISTORIC	IN	/ENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211
1. No. L.u.c 253-10 2. County	4. Pres	ent Name(s) 5 Marine, Inc.: Mina Shermon,	
hucso	5. Othe	er Name(s)	
3. Location of Negatives	Eci	cville School	0110
6. Specific Location		16. Thematic Gategory	28. No. of Stories
6601-6603 Corduroy serner Norden Ed.	₩ā.	17. Date(s) or Period	29. Basement? Yes T No 29 30. Foundation Material
7. City or Town If Bural, Township & V	/icinity	18. Style or Design	Brick 31. Wall Construction
8. Site Plan with North Arrow	NA	19. Architect or Engineer	32. Roof Type & Material
CI RI E E		20. Contractor or Builder	
Carowrey Ma. O.		21. Original Use, if apparent	33. No. of Bays Front Side
Seeding The		Stehan) house	34. Wall Treatment
o-d		22. Present Use	35. Plan Shape],-15118100
2		23. Ownership Public 🗇	36. Changes Addition 10
9. Coordinates		Private X 24. Owner's Name & Address,	(Explain Altered 2 in #42) Moved □
Lat. Long.		if known	37. Condition
U.T.M. Reference	10 00		Exterior Good
1 7 5 0 1 0 0 0 4 6 1 4 6 Zone Easting Northing		25 Openito Yes X	1
10. Site Struc	ture 🗆	Public? No D	Underway? No 🗇 💦
11. On National Yes 112. Is It	Yes 1	26. Local Contact Person or Organization Opents schemes , ones (101, 100,	39. Endangered? Yes □ By What? No 2 13
Register? No £ Eligible? No ½ 13. Part of Estab. Yes [] 14. District Yes [] Potent17 No ?] Hist. Dist.? No ? Potent17 No ?] Potent17 No ?] 15. Name of Established District Potent17 No ?] Potent17 No ?]		27. Other Surveys in Which Included	40. Visible from Yes Σ Public Boad? No □
			Public Road? No D and A1. Distance from and Frontage on Road A1. D' x 50'
A second story with shee been added, as have blo on the S. elevation, a	d dog tutle onc	is has toon quartly altered, mer on the star close has windows and a ultrance borch story office close is astrong any of the 7. Iscade too been	¢ C P
43. History and Significance Tente 1+ 1.	n 136	79 ns a one roos schoolasuse,	this building way
later converted by John			
44. Description of Environment and Outbuild	ldings ,	boart.h. to the "S corner of "	terniurov und Pornier
Sueda in an accountance			teriuroy and "conten.
45. Sources of Information	3. at 1	-1 Course	46. Prepared by
45. Sources of Information Inc. Statts -	W.	The second second second second second	CV DATE MENSION
			47. Organization
			43. Date 49. Revision Date(s)

Luc- 254-10		VENTORY	
2. County	(\$¢)	huidt, "ear) Wesidehee	
Lucas		er Name(s)	
3. Location of Negatives	50	midt, Joseph Cr. Sesidence	
6. Specific Location		16. Thematic Category	28. No. of Stories
910 N. Talle	ndorf #d.	0	29. Basement? Yes
		17. Date(s) or Period c. 185301 H	No ⊠ 30. Foundation Material
. City or Town If Rural, To	winship & Vicinity	18. Style or Design	Brick
Orecon			31. Wall Construction
. Site Plan with North Arrow	N-> O	19. Architect or Engineer	32. Roof Type & Material
Lallendort Rd. 15	Mat 11 Mare	20. Contractor or Builder	Dable/asposit entra
	- Ku		33. No. of Bays Front Side
Carduran Rd	12 El 12	21. Original Use, if apparent Vesidence	34. Wall Treatment
5 ×	2	22. Present Use	
	2:	Pesidence	35. Plan Shape 1035
. Coordinates	5	23. Ownership Public 🖂 Private 🖾	36. Changes Addition (Explain Altered
		24. Owner's Name & Address,	in #42) Moved-D
Lat. Long. U.T.M. Reference		if known Peserl Schmidt S13 V. Lellendorf	37. Condition Interior
7 296170 4	6115740	Oregon, 0,	Exterior
one Easting	Northing	25. Open to Yes C Public? No Vi	38. Preservation Yes
0. Site ⊡ Building ⊕	Structure Object	Public? No ½ 26. Local Contact Person or Organization	Underway? No 🖸 39. Endangered? Yes 🗆
	. Is It Yes □ Eligible? No ᡚ	Oreg, -Jerus, Two, Hist, Soc,	By What? No E
	District Yes □ Potent'1? No ₱	27. Other Surveys in Which Included	40. Visible from Yes C. Public Road? No
15. Name of Established Distric	at the second		41. Distance from and
			Frontage on Road
		6	Z D X Z M (I)
2. Further Description of Impo	rtant Features	Lawren Parma Complemente 1/1	N /
		Common frame farmhouse. 1/1 story dependency on S. fucado	
	ows. dae	story dependency on S. facade	
double buog wind 43. History and Significance of	lows. dae f	idt, fr. was sorn in Sermany	
double twom wind 3. History and Significance of along with the W Land on the W. F	lows, Che focerh Schr. foch family	idt, fr. wir born in Sermany (neighborn on York St.) c.1) lendorf St., und later expen	and come to Company and come to Company bables. He performant
double tung wind 3. History and Significance of along with the W Land on the W. p to the other sid	Togeth Schr. Togeth Schr. Togh family Tide of Jul	idt, fr. wid Sorn in Sermany (neighbord on York St.) c.)	and come to Company and come to Company bables. He performant
double buog wind 3. History and Significance of along with the y Land on the W. g to the offer sid the book for his 4. Description of Environment	Tozeph Schr Tozeph	idt, "r. wid form in Sermany (neighbors on York Sk.) c.1) lendorf Sd., uni later expen- ond. One pricipal homesterd ph Jr., when he way morpied.	and come to Correct and come to Correct addies fore veneral was moved second
double twos wind 3. History and Significance of along with the Y Land on the W. S to the other sid the book for his 4. Description of Environment	Togeth Schr Togeth Schr Togeth Schr Toget family Tide of Tol Te of the re Toget and Outbuildings	idt, fr. was born in Sevanny (neighbors on York St.) c.)) lendorf Sd., und later exampled, one original homester ond. One original homester oh fr., when he way marpied. functionally open form file duarrie, router. Several se	and come to Correct and come to Correct addies fore veneral was moved second
double buog wind 3. History and Significance of along with the w land on the W. p to the other sid the bood for his 34. Description of Environment from the Matin are still on still	Togeth Schm Togeth Schm Toget family Tide of Tol Toget family and Outbuildings and Outbuildings	idt, fr. wid born in Sermany (neighbors on York Dt.) c.1) lemiouf Ed., und later exam- oad. One original homesterd ph. fr., when he way marpied. Cherochies by oden form file dustrie, retuiner. Several at	and come to Control and come to Control addies fore control was moved screet
double buog wind 3. History and Significance of along with the W land on the W. p to the other sid the bood for his 14. Description of Environment from the Matin are still on st	Togeth Schm Togeth Schm Togeth Schm Toget family tide of family tide of family tide of the re and Outbuildings and Outbuildings that with the tal with the tal with the tal with the tal with the	idt, fr. wid born in Sermany (neighbors on York Sk.) c.1) lendorf Sd., und later excen- ond. One optical homesterd ph Jr., when he way marpied. Cheronalist by open form file dustrial container. Several st	and come to Coston bable, He performent ted is fore stored was moved screet

1. No. ,		Luc-		
2. County	_ Cook (Noch), Scorge Residence			
Luces	5. Other Name(s)		261-1	
3. Location of Negatives T→NA CHPO	Koch, John Trederick Vesidenc	(och, John Trederick Vesidence		
6. Specific Location	16. Thematic Category	28. No. of Stories		
3516 York St.	17. Date(s) or Period.	29. Basement? Yes □ No □	Lucas	
		30. Foundation Material	in a	
7. City or Town If Rural, Township &	Vicinity 18. Style or Design Bungaloid	31. Wall Construction		
Site Plan with North Arrow	-3 19. Architect or Engineer	britoria [0	1	
	SC 20. Contractor or Builder	52. Roof Type & Material Hin/asthelt shinele		
D'OYorKS	4. 1	33. No. of Bays Front 5 Side		
S M O	-6 Residence	34. Wall Treatment	lool	
1 1 C C C C	22. Present Use Renidence	35. Plan Shape gamena	C.	
0	22. Present Use Renidence 23. Ownership Public CI	35. Plan Shape Container 36. Changes Addition □	Cook (Koch),	
9. Coordinates	Private M 24. Owner's Name & Address.	(Explain Altered □ in #42) Moved □	÷.	
Lat. Long.	If known	37. Condition		
U.T.M. Reference		Exterior COLT	OFRe	
Zone Easting North		38. Preservation Yes 🗆	121	
10. Site 🗆 Str	Ucture D Public? No fill Object D 28. Local Contact Person of Organization	Underway? No 🖾 39. Endangered? Yes 🗆	ouse	
11. On National Yes 🗇 12. Is It	Yes D OregJerus, Twp. Hist. Soc.	By What? No C	1	
Register? No XI Eligible? 13. Part of Estab. Yes II 14. District	ar, other curreys in trinen included	40. Visible from Yes D		
Hist. Dist.? No for Potent'	? No 🙊	Public Road? No		
15. Name of Established District		Frontage on Road		
to Fully Description of Important For	ture	25'x150'	{—	
42. Further Description of Important Fea	tures & series of rooflines, two of the ends, crests a pagoda effect		- Mar - C	
on this home. There	are hipped roof dormers on the	with the second second	Koch.	
our rout slopes. ""	ie winiows are 1/1 touble hung. Geouted with rouch ashlar.		. Johr	
The second	Constants and		11	
ally that fordy is ef		and the second sec	1.25	
a frait horda is e.			1.	
43. History and Significance Tohn	7. Koch settled on this form in 18		1.	
43. History and Significance .Tohn	of his neighbors of this time Inti	· · · · · · · · · · · · · · · · · · ·	- House	
43. History and Significance .Tohn	2. Roch settled on this form in 18 of his neighbors of this time, form Be and his family cleared the is	· · · · · · · · · · · · · · · · · · ·	1.	
43. History and Significance .Tohn 1 Freder Growing, Most r lensely wooded area.	of his neighbors of this time Inti	· · · · · · · · · · · · · · · · · · ·	1.	
 43. History and Significance	buildings	ting the home have	- House	
 43. History and Significance	buildings Decision of the second tensor sec	tine the home have seen of the home have seen of the home have	House 3516	
 43. History and Significance	buildings	tine the home have seen of the home have seen of the home have	House 3516	
 43. History and Significance John 1 Code Greening, Most in Lencely wooded area, epult comband, 44. Description of Environment and Out back contacted by oil Course and beauty equit 45. Sources of Information Property 	buildings buildings storage tanks. Yosk Ot. is a the inment in the immersion surround (Mist. of Orono, and Service of the	tine the home home suction to the home spectrum form the the state of spectrum.	- House 3516 York	
 43. History and Significance	buildings buildings storage tanks. Yosk Ot. is a the inment in the immersion surround (Mist. of Orono, and Service of the	tans flyton in the and one through a time the home haves spectral one for the the of coverant	House 3516	



OHIO HISTORIC IN	VENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211	
	ent Name(s) Bay Shore Church		Luc 2
	er Name(s)	3	72-10
6. Specific Location	16. Thematic Calegory	28. No. of Stories	1
5224 Bay Shore Ed.	C. N	29. Basement? Yes 🖂	1
Fe-	17. Date(s) or Period C . 1010	30. Foundation Material	Lucas
7. City or Town If Rural, Township & Vicinity	18. Style or Design Queen Anne/Eranziticnal	31. Wall Construction	
8. Site Plan with North Arrow	19. Architect or Engineer	32 Root Type & Material	
Bay Shore Hd.	20. Contractor or Builder	33. No. of Bays	-
	21. Original Use, if apparent 같은 1 등 1 이미다	Front 5 Side 4 34. Wall Treatment	Albin .
	22. Present Use	1	1
	23. Ownership Public	35. Plan Shapepart http://www.	(OP)
9. Coordinates	23 Ownership Public Private 20 24. Owner's Name & Address,	36: Changes Addition □ (Explain Altered □ in #42) Moved □	Hay Shore Church
Lat. Long. U.T.M. Reference	il known	37. Condition Interior	2011
17298150 4617830		ExteriorGood	1
Zone Easting Northing	25. Open to Yes J Public? No X	38. Preservation Yes 앞 Underway? No □	10000
Building M Object I) 11. On National Yes II 12 Is It Yes II	26. Local Contact Person or Organization Oregon-lends. Twp. Sist. 200.	39. Endangered? Yes ⊟ By What? No ½	
Register? No (2) Eligible? No (2) 13. Part of Estab. Yes III 14. District Yes III Hist. Dist.? No El Potent'I7 No El	27. Other Surveys in Which Included	40. Visible from Yes 2	
15. Name of Established District		Public Road? No 41. Distance from and Frontage on Road 251 x 251	
features conservative "tick ed in a contracting color. aten with a gable onnament tow with tracery. How to shingle accent topped with ment. All of the 4/4 doub	ned styles. The Forth facto s articulation which is using The exposed gable is leader and a delicate situation who he decrease is a rectangler a semi-elliptical for some- lebung windows are triared ?		
 History and Significance The M servic Thomas Lynn, with the speci religious purposes. 	armeb arougryy was menated by ification that the property (- Bry Shope bloneer. Swize be used for	
44. Description of Environment and Outbuildings Located M mile eact of sign Thomas Locate Wynn,	n Mand, next va inne fainsi -	slow with mamped road	2224 3ay
46. Sources of Information Observentions	$\operatorname{Might} = \operatorname{Might} (p_{1}, \dots, p_{n})$	46 Prepared by	PLADE 1
$d_{i}^{*}(\mathbf{G}_{i}) = \left\{ \mathbf{f}_{i}^{*} \in \mathcal{I}(\mathbf{f}_{i}) : i \in \mathcal{I}(\mathbf{f}$		the second se	
neloz Trwhwor		45. Date 49. Revision Date(s)	87.
		1 Martin	

OHIO HISTORIC	INVENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211
Contraction of the local distance of the loc	4. Present Name(s)	n
$\frac{L_{UC} = 9dO = 10}{2. \text{ County}}$	Fokerman, Craig Residence	
Lucas	5 Other Name(s)	
3. Location of Negatives L-NWOHPO		
6. Specific Location	16 Thematic Category	28 No. of Stories
5424 Bay Shore Rd.	17 Date(s) or Period	28 No. of Stories
	c,1940	ad roundation onatema
7 City or Town If Rural, Township & V Oregon	Bungaloid	Brick 31. Wall Construction
8 Site Plan with North Arrow Mannie	Bay 19 Architect or Engineer	Alum. siding
E TLATED	erk.]]et 20. Contractor or Builder	32 Root Type & Material Gable/asph.shin.
Piny Shore Rd.		33 No of Bays Front 3 Side
2 E E E E	21 Original Use of apparent Residence	34 Wall Treatment
n n n n n n n n n n n n n n n n n n n	22 Present Use Residence	The filling Change
× ·	K AN 23 Ownership Public X	34 Wall Treatment 35 Plan Shape Trregular 30 Changes Addition (Figure Addition
9 Coordinates	24. Owner's Name & Address.	(Explan) Altered to #4, Micked
Lat Long	d known Craig Eckerman	in 84, Mirsed 37 Condit -n Interage
17 298670 46/78	5424 Bay Shore Rd, Oregon, Ohio 43618	Externe Excellent
Zone Easting Northing	25 Open to Yes	38. Preservations Yes X
10. Site Struct Building X Obj		Underway? No T
11. On National Yes 12. Is It	Yes Oregon-Jerus. Hitts.Soc. No ✓ 27. Other Surveys in Which Included	39 Endangered? Yes By What? No X
13. Part of Estab. Yes 14. District Hist Dist.? No X Potent'!?	Yes	40 Visible from Yes X
15. Name of Established District		Public Road? No 7
		Frontage on Road 501 x 2001
12 Further Description of Important Seature	es A lelightful bungalow which	1 30 1 200
uses the characteristic	front entranceway pillars. The	Example
43 History and Significance in hous	e stands out as the finest exam	ole of Bungaloid
style in Oregon, which i farmhouses.	s generally a community of 19th	century vernacular
44. Description of Environment and Outbuil	diegs Located in a mixed residentia	11-arrienttural area
on a road which follows	the Maumee Bay shoreline. A two is across the road from In Taber	C CHP CAPAGE DIUS
45 Sources of Information Observatio	on. Toledo City Directoriu.	46 Prepared by Cynthia W. Eardian
		an Organization
		12 - Ch OH FO (6 Date 49 Revision Dates)
18		12 August 10 manager (12 august)

4 P	IVENTORY esent Name(s)	
Luc - 321-10	rdmann, Fred Residence	
. County	ther Name(s)	
Location of Negatives		
. Specific Location	16 Thematic Category	28 No. of Stories 1 1/2
5452 Bay Shore Rd.	C	29 Basement? Yes
Sale pay anote no.	17 Date(s) or Period	No X
	c. 1870	30. Foundation Material
. City or Town II Rural, Township & Vicinit Oregon	y 18 Style or Design Italianate Vernacular	Stone & cement blk.
Site Plan with North Arrow Maumer Be		Clapboard
Land Manual I	Y	32 Boof Type & Material
- Loto been	12 20 Contractor of Builder	Gable/asph.shingle
	21 Original Use it apparent	33 No. of Bays Front Side 3
Claim Ra	- Residence	34 Wall Treatment
Пад	22 Present Use	
Pu	Residence	35 Plan Shape CROSE
	23 Oweerstep Public Private X	36 Champers Add tools X
Coordinates	24. Owner's Name & Address	Historia Altered m.#3, Mound
Lat. Long.	" known Fred Erdmann	37 Condut in
U.T.M. Beference	5452 Bay Shore Rd.	b) type i ge
7 298730 4617820	0regon, 0. 43618	Litrone Excellent
ne Easting Northing	Public? Yes	38 Preser at the Yes X
Building X Object		Underway? No
On National Yes 12. Is It Yes 1	26 Local Contact Person or Organization Oregon-Jerusalem Twp.His.Soc	39. Endangered? Yes ≺ By What? No
Register? No X Eligible? No X	27. Other Surveys in Which Included	Demolition
Hist Dist.? No X Potent 12 No 3		40 Visible from Yes X
5. Name of Established District	<u>.</u>	Public Road? No
J. Hante of Established District		Frontage on Road
		50' x 75'
2. Further Description of Important Ceatures m	his Italianate cottage is sim-	
	It has 1/1 windows with ar-	The states
ple in design and scale.	To dos TAT attaches aton on-	
tablatures and shed roofe	d additions attached to the	THE REPORT
tablatures and shed roofe E and S facades. The sma	d additions attached to the 11 gambrel roofed barn behind	
tablatures and shed roofe	d additions attached to the 11 gambrel roofed barn behind	THE BELLEVILLE
tablatures and shed roofe E and S facades. The sma	d additions attached to the 11 gambrel roofed barn behind	
ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in	d additions attached to the 11 gambrel roofed barn behind excellent shape.	
tablatures and shed roofe E and S facades. The sma it is eye-catching and in History and Significance The home is	d additions sttached to the 11 gambrel roofed barn behind excellent shape. significant because there are	e not many Italian-
ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in A History and Significance The home is ate style cottages in Ore	d additions stached to the 11 gambrel roofed barn behind excellent chape. significant because there are gon. The barn is one of few y	which is still stand-
tablatures and shed roofe E and S facades. The sma it is eye-catching and in History and Significance The home is ate style cottages in Ore ing in this area which wa	d additions stached to the 11 gambrel roofed barn behind excellent chape. significant because there are gon. The barn is one of few y s predominantly agricultural.	Unfortunately, the
ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in History and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be	d additions stached to the 11 gambrel roofed barn behind excellent chape. significant because there are gon. The barn is one of few y	Unfortunately, the than 20' from the
 ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in History and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which i 	d additions stached to the 11 gambrel roofed barn behind excellent shape. significant because there are gon. The barn is one of few s predominantly agricultural. torn down because it is less s in violation of a new Oregon	Unfortunately, the than 20' from the n ordinance,
 ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in Mistory and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which is Description of Environment and Outbuildings road which follows the Man 	d additions stached to the 11 gambrel roofed barn behind excellent chape. significant because there are gon. The barn is one of few y s predominantly agricultural. torn down because it is less s in violation of a new Oregon Located on a mixed resident mee Bay shoreline. It is our	Unfortunately, the than 20' from the n ordinance, ial/agricultural
 ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in History and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which is Description of Environment and Outbuildings 	d additions stached to the 11 gambrel roofed barn behind excellent chape. significant because there are gon. The barn is one of few y s predominantly agricultural. torn down because it is less s in violation of a new Oregon Located on a mixed resident mee Bay shoreline. It is our	Unfortunately, the than 20' from the n ordinance, ial/agricultural
 ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in History and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which i Description of Environment and Outbuildings road which follows the Mat A small, gambrel roofed ba 	d additions stached to the 11 gambrel roofed barn behind excellent shape. significant because there are gon. The barn is one of few y s predominantly agricultural. torn down because it is less s in violation of a new Oregon Located on a mixed resident mee Bay shoreline. It is opp arn is south of the house.	Unfortunately, the than 20' from the n ordinance, ial/agricultural
 ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in Mistory and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which i Description of Environment and Outbuildings road which follows the Man A small, gambrel roofed ba Sources of information Observation. 	d additions stached to the 11 gambrel roofed barn behind excellent shape. significant because there are gon. The barn is one of few y s predominantly agricultural. torn down because it is less s in violation of a new Oregon Located on a mixed resident mee Bay shoreline. It is opp arn is south of the house.	Unfortunately, the than 20' from the n ordinance, ial/agricultural
 ple in design and scale, tablatures and shed roofe E and S facades. The sma it is eye-catching and in Mistory and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which i Description of Environment and Outbuildings road which follows the Mat A small, gambrel roofed ba 	d additions stached to the 11 gambrel roofed barn behind excellent chape. significant because there are gon. The barn is one of few y s predominantly agricultural. torn down because it is less s in violation of a new Oregon Located on a mixed resident mee Bay shoreline. It is our	Anich is still stand Unfortunately, the than 20' from the c ordinance. isl/agricultural osite La Tabernilla.
 a Mistory and Significance The home is ate style cottages in Ore ing in this area which wa house is scheduled to be neighboring home, which i follows the Mat A small, gambrel roofed back. b. Sources of Information Observation. 	d additions stached to the 11 gambrel roofed barn behind excellent shape. significant because there are gon. The barn is one of few y s predominantly agricultural. torn down because it is less s in violation of a new Oregon Located on a mixed resident mee Bay shoreline. It is opp arn is south of the house.	Anich is still stand Unfortunately, the than 20' from the c ordinance. isl/agricultural osite La Tabernilla.

OHIO HISTORIC	INVENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211	
t. Mei	4. Present Name(s)		15-
2. County		C NO	
Lucas	5. Other Name(s)		322
3. Location of Negatives	Tompkins, Thomas Parm		2-10
6. Specific Location	16. Thematic Calegory	28. No. of Stories 2	1 .
5520 Bay Shore Rd.	С.	29. Basement? Yes 🖂	
	17 Date(s) or Period c. 1860	No.R	Lucas
7. City or Town If Rural, Township & V		30. Foundation Material Brick	
Oregon	Upright with ell	31. Wall Construction	1
8. Site Plan with North Arrow (2	19. Architect or Engineer	Alum. siding	
Mannee Ba	20. Contractor or Builder	32. Roof Type & Material Gable/asph.shin≋le	
C)Latabera	la 20. Contractor of Builder	33 No. of Bays	-
Bay Shure Rd.	-d 21. Original Use. it apparent	Front 4 Side	- 3
22 D B M	Residence	34. Wall Treatment	Norden, How
Myan Ed.	Residence	35 Plan Shape Trreg.	der
4	C A Public C	36 Changes Addition	1, Van
9. Coordinates	Private 52	(Explain Altered 39	Hours
Lat Long.	24. Owner's Name & Address,	in #42) Moved 🖂	hard
U.T.M. Reference	Wildred Erdmann 23 Dakeview	37 Condition Interior	£
117 298800 46178	a 0 Oregon, 0. 43618	Exterior Good	Res
Zone Easting Northing	25. Open to: Yes 🗇	38. Preservation Yes 🗇	idenc
10. Site El Struc Building M Ob		Underway? No 🗆	ne
	Yes Coregon-Jerus, Hist, Soc.	39. Endangered? Yes □ By What? No S(0
Register? No.20 Eligible?	No 27. Other Surveys in Which Included		
13. Part of Estab. Yes Li 14. District Hist. Dist ? No 2 Potent'l?	Yes No 2,	49. Visible from Yes. K Public Road? No	1
15 Name of Established District		41 Distance from and	1
		Frontage on Boad 501 x 2001	8
42. Further Description of Important Feature	1	<u></u>	
farmhouse with many sma is typical of Oregon ag It has been refaced in	ller one-story additions which ricultural architectural heritag aluminum aiding.		Tompkins, Thoma
"gentleman farmer", rai stand of trees just ent is significant in this	Compkins arrived in Oregon from E ad this slready established farm. Using deer and peacocks. Tompkins at of the home which was left to area which was cleared for farmi	He was known as a Woods is a virgin harbor wildlife. It ng more than a cen-	s Farm 55
44. Description of Environment and Outbuil	dings Located in " mixed residenti	31/agricultural area	- AL
on a toad mulcu tollows	the Maumee Bay shoreline. It is almilkhouse and tool shed sit n	S ACTOSS From La	Ey.
45. Sources of Information 1 stronger of	with members of the Erdmann	46. Prepared by	nor
family.	s are en incluration of due andmouth	Cantinia 2 Borrows	fr g
	gon and Jerusales Pwp; pp.242,26		Shore Kd.
And happing the constraint with the	The second se		1
Lucas County Atlasas,	1013110331	48 Pexision Dates)	1

OHIO HISTORIC	INVENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211
1. No. Luc - 323-10	4. Present Namc(s)	
2. County	Condon, Mabel J. Residence	
Incas	5. Other Name(s)	
3. Location of Negatives L-NWOHFO		
6. Specific Location	16. Thematic Category	28. No. of Stories 11/2
5637 Corduroy Rd.	17. Date(s) or Period	29. Basement? Yes L No D
	c, 1860	30. Foundation Material
7. City or Town II Rural, Township &	Vicinity 18. Style or Design Ttalianate Vernacular	Brick 31. Wall Construction
Oregon 8. Site Plan with North Arrow	19. Architect or Engineer	31. Wall Construction Clapboard
	20. Contractor pr Builder	32. Roof Type & Material Gable/asph.shingle
Sta D D and Card	01	33. No. of Bays Front 4 Side 5
	- r=γ Rd. 21. Original Use. If apparent Residence	Front 4 Side 2 34. Wall Treatment
2	22. Prozent Use Residence	
	N 1 23. Ownership Public II,	35. Plan Shape L+Shape 36. Changes Addition □
9. Coordinates	Private	(Explain Altered E in #42) Moved E
LatLong	24. Owner's Name & Address, if known Mribel J. Condon	37. Condition
U.T.M. Reference	5637 Corduroy Rd. Cregon, 0. 43616	Interior Fair
17 299180 46141 Zone Easting Northing	- I Martin Company and the second	Exterior PBLP 38. Preservation Yes
10. Site Stro	icture T Public? No X	Underway? No 것
Building C 11. On National Yes C Register? No X Eligible?	Ves X Qregon-Jerus. Hist. Soc. Yo 27. Other Surveys of Which Included	39. Endangered? Yes □ By What? No 🕱
13. Part of Estab. Yes 11 14. District Hist. Dist.? No X Potent17	Yes	40 Visible from Yes ⊠ Public Road? No □
15. Name of Established District		41. Distance from and Frontage on Road 501 x 2001
42. Further Description of Important Feat	ures This is an attractive frame	N
cottage with 1/1 double	e hung windows hav ing simple en- haped windows decorate the gable	
	has turned pillars, and follows	
the L-shape plan of the	e house.	- Linner -
		A ROTE AT
43. History and Significance The nm	esent owner is a third generation	Condon. Patrick
Condon was an Trich im	migrant who settled 70 acres at t	he corner of Wynn
farm property sometime	, Michael, purchased 5637 Corduro before 1900. The 1875 stlas sho	y and surrounding
property of Michael De	Bolt, the pioneer after whom DeB	lolt's Corner was
44 Description of Environment and Outh	s changed to Comincetown.	/ appicultural area
in old Memineetown. I durpy intersection.	t is the third property west of t	he Stadium and Cor-
	wite Atlance 1975 and tube	46 Prepared by
45 Sources of Information 1 mages into	ALL	is contracted by
49 Sources of Information Luchs (10) Fessiett, <u>History of</u> Or	eron and Jerusalem Pup.; p. 241.	Ovnthia W. Popelay 42 Organization
45 Sources of Information Luchs (D) Fessett, <u>History of</u> (D)	eron and Jerusalem Twp.: p. 241.	Ownehia W. Bonelay 42 Organization 1WOIPO 48 Date 49 Revision Date(s)

The second secon

OHIO HISTORI	C INV	/ENTORY	Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211	
1. No.	4 Pres	ent Name(s)		Lu
Luc - 324-10 2. County	Wita	onke, Earl Fanm		we-324-10
Incas	5 Othe	r Name(s)		14-
3. Location of Negatives L-NWOHLPO			-	
6. Specific Location		16. Thematic Category B. (1	28 No of Stories 1 79 Basement? Yes I	
938 Norden Rd.		17 Datetsi ol Perios C. 1360	30 Foundation Material	Lucas
7. City of Town II Rural, Townshit	o & Vicinity	18 Style of Design	Rubble stone	
8. Site Plan with North Arrow Bay Shere Plan		19 Architec) of Engineer	Claphoand	
5		20 Contractor of Boilder	Cable/asph.shingle	-
- Per	a 20	21 Original Use & articlem Residence	33 Val of Hays Front Enter	Warnke,
Cedar Ft Rd.	2	Residence	35 Mue Shio Pectangular	nke
Φ _N		23 Cramerster, Public, Private,	36 strangen Addition	1
9 Coordinates		24 Owner's Name's Address.	$\frac{\chi}{m + 1} = \frac{10 r_{1}}{m + 1} = \frac{\Lambda den_{1}}{Metand}$	Eatl
Lat Long U.T.M. Reference		" snows Earl Weenke	37 frondst m Reterior	Farm
17 300960 461	5410	958 Norden Rd. Oregon, 0. 4361a	Latena Foor	1
Zone Easting No	rttunic Structure	Public 7 Yes Public 7 70	38 Presar above Yes (1)	
Building 🗙	Object	26 Local Contact Pomeo in Organization	39 Endangered Yes	
Register? No X Eligit	uen No X	Orenon-Jerusalam Twp.His. 27 Other Survive of	Soc. White	
13 Part of Estab Yes 14 Distr Hist Dist. ? No X Pote	ies Yes nt'17 No X	Miles a	40 Visible from Yes X Public Boad? No	
15. Name of Established District			41 Distance from and Frontage on Road	
42 Further Description of Important 5	eatures g	small frome form dwelling.		1
possibly having origi	nal log	construction beneath. Whe design and propertion.		
43 History and Significance This nificant because it o tury or more ago.	primit locument	ive form dwelling and acc a the early settlement as	ompanying barn is sig- ttern in Oregon a cen-	938 Not
44 Description of Concomment and C midway between Ray 5 west side of Mordon.	lique su	Small fride least dorab of d Tedar (11) 02, 11 is		Norden Rd.,
45 Sources of Information Observined	ntion.	tadens former () lasser, ho	$\tau_{\mathcal{T}} = \begin{bmatrix} s_{b_1} \stackrel{\text{Prepared}}{=} p_{t_1} \\ \forall T T T^{t_1} \\ \exists T T T^{t_1} \\ \exists T T T^{t_1} \end{bmatrix} p_{t_1} \\ = \mathbb{P} \cup \mathbb{P} \mathbb{C} \begin{bmatrix} s_{t_1} \\ s_{t_2} \end{bmatrix} = p_{t_2}$	Dragan
stad by	C32.4		47ataioation	an.
			Hy My 49 Revision Dates	0


Ohio Historic Preservation Office

1992) Verma Auertua Consertanti Ordio 4 2011 644 - 466 - 1530



OHIO HISTORIC INVENTORY 4. Present Name(s) 1. No. LUC - 1285 - 10

	4. Present Name(s) Bay Shore Generating	7 Plant
2. County Lucas	5. Other Name(s)	and the second sec
3. Location of Negatives	None	
6. Specific Location	16. Thematic Category	28. No. of Stories 12
	Electric generating plant	29. Basement? Yes 🖄
4701 Bay Shore Road	17. Date(s) or Period	No 🗇
	September, 1955	30. Foundation Material
7. City or Town If Rural, Township &	Vicinity 18. Style or Design	Concrete
Orecon	Indoor	31. Wall Construction
8. Site Plan with North Arrow	19. Architect or Engineer	Brick & Alum, Sidin
	G.W. Saathoff/Gibbs & Hill	32. Roof Type & Material
See Say Shore Station	20. Contractor or Builder	Felt, Tar, Stone
sketch attached	A. Bentlley & Sons Co.	33. No. of Bays Front 16 Side 18
	21. Original Use, if apparent	designed in the second data and
	Generate electricity 22. Present Use	34. Wall Treatment Brick & Alum, didin
	Same	
		35. Plan Shape 社会合作。 136. Changes Addition 团
	23. Ownership Public Director Edison Co. Private(C)	(Explain Altered C
	24. Owner's Name & Address,	in #42) Moved 🗆
	if known	37. Condition
9. U.T.M. Referance	Toledo Edison Company	Interior excellent
지정 [기억역성원] [미당기회	APT/ 300 Madison Ave.	Exterior Excellent
Zone Easting Northi	nd 25. Open to Yes 🕮	38. Preservation Yes 🗆
	acture Z Public? By appointment No D	Underway? No 🕅
Building 🗆 🛛	Object 26. Local Contact Person or Organization	39. Endangered? Yes 🖂
11 On National Yes [] 12: Is It	Yes J Lemoyne B. Mercer	By What? No 🖸
Register? NoXi Eligible?	Er oner ourreys in triter menued	
Hist, Dist 2 No 7 Potent's	Yes No E None	40. Visible from Yes 20
	AGHe AGHe	Public Road? No 🗆
15 Name of Established District		41. Distance from and Frontage on Road
		325 Ft. /ELOO Ft.
42. Further Description of Important Feat	ures (Continue on reverse if necessary)	N
LEATT THE STRVICE KE	A PRIME MOVER RETIRED	
1 Sent. 1955 110	,000 2,000 psi Steam	
2 Feb., 1959 100	,000 2,000 nsi Steam ,000 2,400 nsi Steam	Photo
	,000 2,400 msi Steam	Photo
3 May, 1963 140	,000 2,400 msi Steam	
4 June, 1966 215	1 is the second s	
11 June, 1960 213	,000 Gas turbine	
07 1 Aug., 1967 16	,000 Gas turbine	
11 June, 1960 213 GT 1 Aug., 1967 16	,000 Gas turbine	
43. History and Significance This generating clent	,000 Gas turbine	te Toledo Sdiach
43 History and Significance This generating clent	,000 Gas turbine	te Toledo Adiaca re of Roumee Day.
43 History and Significance This generating clent	,000 Gas turbine	te Toledo Sdiacn re of Houmee Soy.
43. History and Significance This generating clent	,000 Gas turbine	te Toledo Sdiach re of Houmee Soy.
43 History and Significance This generating clant Company customers sinc	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho	te Toledo Sdiach re of Houmee Boy.
43 History and Significance This generating clant Company customers sinc	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho	re of Hourse Boy.
44 Description of Environment and Outp	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho willings rn coal. Unit 37 1 burns oil. Coc	re of Hourse Boy.
 44 Description of Environment and Outb Units (1 through) h bu from Asumes Env and is 	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho willings rn coal. Unit ST 1 burns oil. Coc returned to the bay. There is a	re of Hourse Boy.
 43 History and Significance 43 History and Significance 44 Description of Environment and Outh Units #1 through (h bu from Asumes Bay and is Office Building, The s 	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho willings rn coal. Unit 37 1 burns oil. Coc	re of Haumee Day. ling water is taken separate construction
 If June, 1966 215 GT 1 Aug., 1967 16 43 History and Significance This generating clant Company customers since 44 Description of Environment and Outb Units #1 through 14 bu From Saumee Pay and is Office Bullfing. The a 45 Sources of Information 	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho winnings rn coal. Unit 37 1 burns oil. Coc returned to the bay. There is a lant complys with EPA Standards.	re of Haumee Day. ling water is taken separate construction 46. Prepared by
 44 Description of Environment and Outb Units (1 through) h bu From Saumes Env and is Office Bullding. The s 45 Scorces of Information Visual observation and 	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho willings rn coal. Unit ST 1 burns oil. Coc returned to the bay. There is a	re of Haumee Day. ling ester is taken separate construction 46. Prepared by
 If June, 1966 215 GT 1 Aug., 1967 16 43 History and Significance This generating clant Company customers since 44 Description of Environment and Outb Units #1 through 14 bu From Saumee Pay and is Office Bullfing. The a 45 Sources of Information 	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho winnings rn coal. Unit 37 1 burns oil. Coc returned to the bay. There is a lant complys with EPA Standards.	re of Haumee Day. ling water is taken separate construction 46. Prepared by 2 Gissee 47. Organization
 41 June, 1960 215 GT 1 Aug., 1967 16 43 History and Significance This generating clant Company customers since 44 Description of Environment and Outb Units #1 through /h bu From Saumae Bay and is Office Hullding. The m 45 Sources of Information Visual observation and 	,000 Gas turbine has supplied 60 cycle electricity e 1955. It is situated on the sho winnings rn coal. Unit 37 1 burns oil. Coc returned to the bay. There is a lant complys with EPA Standards.	re of Haumee Day. ling ester is taken separate construction 46. Prepared by



Ohio Historic Preservation Office

OHIO HISTORIC INVENTORY




1. No	a Countri	A Broen	nt Name(s)		
	2. County		ra House	Coder	
LUC-3381-10 3 Location of Negative	Lucas	- segu	La Donog		Coden
	78	5 Histor	ic or Other Name(s)		
ASC, Inc. Roll No. F			olhouse at the cor	ner of Corduroy	and Lallendorf
	2: 22-24				
6. Specific Address or	Location		16. Thematic Association(s)		28. No. of Stories 1 1/2
149 Lallendor	f Road		Education		29. Basement? Yes x
	- sector - toss.		17. Date(s) or Period	17b. Alteration Date(s)	No LI
6a. Lot, Section or VM	D Number		ca. 1875-1899		30. Foundation Material
Section 34			18. Style or De⊴gn	Elements	Brick; concrete block
7. City or Village	RRural Townshi		Vernacular Li Elements 18a. Style of Addition or Element(s)		31 Wall Construction
Oregon Twp. 8. Site Plan with North	Toledo	VIC.	ride style in meaning of the	(1000(14:34)	Wood frame 32 Root Type & Material
		12	19. Architect or Engineer		Front gable: asph. sh.
1 1	< LINITAL CH	142.	NEW DOCTOR OF A DOCTOR OF A		33 No of Bays
	2		19a. Design Suizilles		From 2 Side 3
N	MAN				34. External Wall Material(s)
11.1	The start		20. Contractor or Budder		Drop siding
	NUSSICK				35 Plan Shape Rectangular
SEMMIN T	Ser.		21. Building Type or Plan		36 Changes Addition 🔀
	and the second	Sec.	One-room schoolho	diadeolgi-	(Explain Alternet 🗙
0.11 T.11 Participation		Y	22. Original Use d'Apparent		in #42) Moved x/ 37 Window Type(s)
9. U.T.M. Reference	Oregon, Ohio-Mi	ch	Schoolhouse 23 Present Use		G over 6 C 2 over 2
172960			Residence		□ + ever 4 k Other modern
	Isting Nort		24. Ownership	Public L.	38. Building Dimensions 6x13m
	the second s	uture 🗔		Frivate X	39 Endangered? Yes x
Buildin	ig 😿	ibjøet 🖯	25. Owner's Name & Addres	is d known	By What? No
11: On Mational Ve	95 [] 12 N.A	Yps []	Segura Same		insensitive alteration
	In XI Potential?	No 🗆	Same		40 Chimney Placement
	HI 14 District	99rs 1			Center ridge interior
ALL AND	ia 🐮 Ententiary		26. Property Acreage		<1. Distance from and
15. Nanie of Establish	ed District (N.R. & Local	1. S	27. Other Surveys in Which	() Onder	Frontage on Road Distance 16m (51 ft)
					Frontage approx. 31m
This was rep totally alte addition is building, co Bay windows of the window	ortedly a one-r red scale conve on a concrete b ncrete block re were added to t ws are modern r	com sch rbuch in lock fo places he nort eplacem	Features (Contrue on Levens toolhouse that now to a residence. A bundation. At the the original brick the and south elevat tents. Drop siding the south elevation	has been A modern front rear of the & foundation. tions and all g covers the	Alenarity they
The current one-room sch Corduroy and There were o which was co	oolhouse and wa Lallendorf. I riginally three nverted into a	ura, st s moved t is no school church,	stary) ated that this was here from the con t known when it was houses in the vict now at the corner ng the remodelling	cner of as moved. inity, one of c of Seaman and	A MILLION AND AND AND AND AND AND AND AND AND AN
	vironment and Outbuildin		STARLER MALE AND A CONTRACT OF A DESCRIPTION OF A DESCRIPA DESCRIPTION OF A DESCRIPTION OF A DESCRIPTION OF		46 Pro
There are a few mature trees on th					L.O.
	Southern Railroad is situated imme a concrete pad at the rear (covers		s well?). A two-car garage and		47 Organization ASC, Inc.
Southern Rai a concrete p storage build	ding has a hip	storage building has a hip roof an extension of the north elevation h			
Southern Rai a concrete p storage build extension of	ding has a hip the north elev	ation h	as wood frame(co	ont'd #43 over)	45 Date Recorded in Field
Southern Rai a concrete po storage buil extension of 45 Sources of Inform	ding has a hip the north elev mater	ation h	as wood frame(co	ont'd #43 over)	15 May 1995
Southern Rai a concrete p storage built extension of 45 Sources of Inform Field observa- Maumee Bay 14	ding has a hip the north elev ation ation. Andreas 899 15' USCS to	& Bask pograph	in 1875 atlas. Un tin 1875 atlas. Un tic map. Cultural Gibbs, et al., 19	nt'd #43 over) n1 1/00 atlas. Resource	15 May 1995 49 Revised by 50a. Date Revised
Southern Rai a concrete p storage built extension of 45 Sources of Inform Field observa- Maumee Bay 14	ding has a hip the north elev ation ation. Andreas 899 15' USCS to	& Bask pograph	in 1875 atlas. Un tin 1875 atlas. Un tic map. Cultural	nt'd #43 over) n1 1/00 atlas. Resource	15 May 1995

£

Ť

1. No. 2. County		nt Name(s)	Cotted		
LUC-3437-10 Lucas 3. Location of Negatives	Ge	orge and Valarie	Everts	i Couco	LUC-
0.D.O.T.	5. Histor	ic or Other Name(s)			34
Roll No. Picture No.(s)				5	3437
6. Specific Address or Location		16. Thematic Association(s	5)	28 No. of Stories 2	0
b. openic risulties of ascenion				29. Basement? YesXX	0 LUCA
4120 Navarre Road		17. Date(s) or Period	17b. Alteration Date(s)	No L	UC
6a. Lot, Section or VMD Number		1913 . 18. Style or Design	L] High Style	30 Foundation Material	AS
Section 10 7 City or Village If Bural, 1	ownship & Vicinity	Dutch Colonial B		Rock faced Concrete Blk.	ł
	on Twp.	18a. Style of Addition or E		Wood Frame	
8. Site Plan with North Arrow	50_1×p			32 Root Type & Material	1
	기간 위 : :	19. Architect or Engineer		Gambrel/Imbricated Asp.	1
HEARS	ON DE PARK	19a. Design Sources		35 No of Bays Shingles Front Varies Side Four	
/FIS	Non V Cours	19a. Design adurces		34 Extenor Wall Material(s)	
	Contract S	20. Contractor or Builder		Wood/Alum. Siding	4120 Nava
NT V	2019.			35 Plan Shape Irregular	
······································	5 m ·	21. Building Type or Plan		36 Changes Addition	
T		22. Original Use, it appare	ont	(Explain Alter#dx/x) in #421 Moved	E.
9. U.T.In supervised		Residence		37 Window Type(s)	õ
Quadrangle NameOregon,	0Mich.	23. Present Use		6 over 6 2 over 2	EN
17 295960 46				38. Building Dimensions1.0 + v 20 +	a
Zong Easting	Structure	24 Ownership	Public Povate x	39 Engangered? Yes	5
10. Site L. Building [x]	Object	25 Owner's Name & Adde		By What? Novy	Nea
11. On National Yes 1 12 N					6
Register? No [x] Po	rential? No 🔀			40. Chimney Placement	10
13 Part of Estab. Yes 1 14. De				Interior Ridge	1
Hist, Dest ? No XI Po	iontiaté No 🔽	26. Property Acreage 27. Other Surveys in Whit	340 acres	Frontage on Boad	13
13. Name of Establishod Shard (N.Y.		1987 Report by Listed as Parce	H. Murphy ODOT	70'	
42 Further Description of Important In				\square	T
steps; a second story si hipped roof rear additio approach steps. The win 43 History and Significance (Continue The 1875 atlas associate indicated. The 1900 15'	bay window h six windo de shed roo n with a mo dows featur on reverse i nece s Jacob Yol U.S.G.S. M of Lucas C ated. The ucture in a ubuildings (See # recent comme west quadran l company, um complex cords for Pa arry Kaczal.	on the second st ws, a side entran f dormer and a fi dern storm door, e plain wood trim essary) in with the area. ap (Naumee Bay) i ounty, Ohio 1940 1965 & 1965 Phote similar location i2) ercial developmen nt of Navarre Roa law office, credi are located in th arcel #44-25064; a December 3, 199	ory gable end; a tee with an awning rst story bay win evenly spaced win A structure and ndicates a struct associates 0.J. 4 (Revised 1980 U.3 (Ourbuildings of t. The structure d (SR2) and t union, drive-in c vicinity. 4120 Navarre Rd. 7), 1875 atlas	hipped partial width and three Wood approach adow; and a one story adows and two wood d acreage are not thre in thermoto \$ 25 acres with the area. \$ d.s. 7.5' MapS(Oregon, are not indicated. 46 Prepared by 5.Gasbarro 47 Organization	X

LUC-3437-10



This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

2/15/2013 3:59:00 PM

in

Case No(s). 12-2959-EL-BGN

Summary: Correspondence Transmitting OPSB Staff Requested Documents electronically filed by Teresa Orahood on behalf of Sally Bloomfield for Oregon Clean Energy, LLC