



















- Survey Corridor
- Sampling Point
- Culvert Inlet/Outlet
- Culvert Pipe
- Stream

	PEM
	PFO
	PSS
	PUB

- PEM
- PFO
- PSS
- PUB

A map showing a network of roads and a highlighted red square labeled "Road 1 map". The map includes a grid of streets and a complex network of black lines representing a road network. A red square highlights a specific area, and a red line points to it with the label "Road 1 map".



**FIGURE 4-15
AQUATIC RESOURCE LOCATION MAP
SENECA WIND PROJECT**

**SENECA WIND LLC
SENECA COUNTY, OHIO**



Notes:
1) Aerial photograph provided by ESRI's ArcGIS Online World Imagery map service (© 2015 ESRI and its data suppliers).

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

12/3/2018 2:24:35 PM

in

Case No(s). 18-0488-EL-BGN

Summary: Correspondence of Seneca Wind, LLC Submitting Aquatic Resource Report, Part 4 of 12 electronically filed by Teresa Orahod on behalf of Dylan F. Borchers