















-  Study Area
-  Sampling Point
-  Culvert Inlet/Outlet
-  Culvert Pipe
-  Stream

**Wetland Continuation**

- PEM
- PFO
- PSS
- PUB




**FIGURE 4-19  
AQUATIC RESOURCE LOCATION MAP  
SENECA WIND PROJECT**

**SENECA WIND LLC  
SENECA COUNTY, OHIO**




Notes:  
1) Aerial photograph provided by ESRI's ArcGIS Online World Imagery map service (© 2015 ESRI and its data suppliers).









**This foregoing document was electronically filed with the Public Utilities**

**Commission of Ohio Docketing Information System on**

**12/3/2018 2:25:51 PM**

**in**

**Case No(s). 18-0488-EL-BGN**

Summary: Correspondence of Seneca Wind, LLC Submitting Aquatic Resource Report, Part 5 of 12 electronically filed by Teresa Orahod on behalf of Dylan F. Borchers