










| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | E |
| Water Width at Crossing (ft) | 20 |
| Water Depth at Crossing (ft) | 2 |
| Top of Bank Width (ft) | 25 |
| Left Bank Height (ft) (Looking Downstream) | 12 |
| Right Bank Height (ft) (Looking Downstream) | 10 |
| OHWM Width (ft) | 20 |
| OHWM Height (ft from substrate) | 6 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Pools and Runs |
| Substrate | Sand |









WC-04





| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Intermittent |
| Direction of Flow (Direction Downstream) | N |
| Water Width at Crossing (ft) | 2 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 8 |
| Left Bank Height (ft) (Looking Downstream) | 4 |
| Right Bank Height (ft) (Looking Downstream) | 6 |
| OHWM Width (ft) | 7 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Pools, Riffles, Runs |
| Substrate | Silt |



WC-04-B





WC-04-B




WC-04-B





WC-04-B




| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | E |
| Water Width at Crossing (ft) | 20 |
| Water Depth at Crossing (ft) | 2 |
| Top of Bank Width (ft) | 35 |
| Left Bank Height (ft) (Looking Downstream) | 9 |
| Right Bank Height (ft) (Looking Downstream) | 8 |
| OHWM Width (ft) | 25 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Sand |




WC-04-C



WC-04-C





WC-04-C





| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | E |
| Water Width at Crossing (ft) | 20 |
| Water Depth at Crossing (ft) | 3 |
| Top of Bank Width (ft) | 35 |
| Left Bank Height (ft) (Looking Downstream) | 9 |
| Right Bank Height (ft) (Looking Downstream) | 10 |
| OHWM Width (ft) | 25 |
| OHWM Height (ft from substrate) | 7 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |


WC-05





WC-05



WC-05





WC-05





| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Intermittent |
| Direction of Flow (Direction Downstream) | E |
| Water Width at Crossing (ft) | 2 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 13 |
| Left Bank Height (ft) (Looking Downstream) | 7 |
| Right Bank Height (ft) (Looking Downstream) | 7 |
| OHWM Width (ft) | 6 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |



WC-05d





WC-05d



WC-05d




WC-05d





| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Intermittent |
| Direction of Flow (Direction Downstream) | N |
| Water Width at Crossing (ft) | 3 |
| Water Depth at Crossing (ft) | 1 |
| Top of Bank Width (ft) | 11 |
| Left Bank Height (ft) (Looking Downstream) | 6 |
| Right Bank Height (ft) (Looking Downstream) | 5 |
| OHWM Width (ft) | 6 |
| OHWM Height (ft from substrate) | 4 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |

WC-06




WC-06






WC-06




| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | E |
| Water Width at Crossing (ft) | 4 |
| Water Depth at Crossing (ft) | 1 |
| Top of Bank Width (ft) | 10 |
| Left Bank Height (ft) (Looking Downstream) | 5 |
| Right Bank Height (ft) (Looking Downstream) | 5 |
| OHWM Width (ft) | 8 |
| OHWM Height (ft from substrate) | 4 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |


WC-06b




WC-06b



WC-06b






WC-06b





| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Intermittent |
| Direction of Flow (Direction Downstream) | SE |
| Water Width at Crossing (ft) | 2 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 10 |
| Left Bank Height (ft) (Looking Downstream) | 6 |
| Right Bank Height (ft) (Looking Downstream) | 7 |
| OHWM Width (ft) | 6 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |

WC-07






WC-07





WC-07




| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | No |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Intermittent |
| Direction of Flow (Direction Downstream) | N |
| Water Width at Crossing (ft) | 1 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 5 |
| Left Bank Height (ft) (Looking Downstream) | 3 |
| Right Bank Height (ft) (Looking Downstream) | 3 |
| OHWM Width (ft) | 5 |
| OHWM Height (ft from substrate) | 3 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |

WC-08







WC-08




WC-08







| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | No |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Ephemeral |
| Direction of Flow (Direction Downstream) | N |
| Water Width at Crossing (ft) | 2 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 8 |
| Left Bank Height (ft) (Looking Downstream) | 6 |
| Right Bank Height (ft) (Looking Downstream) | 5 |
| OHWM Width (ft) | 5 |
| OHWM Height (ft from substrate) | 4 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Sand |







WC-09








| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | NE |
| Water Width at Crossing (ft) | 7 |
| Water Depth at Crossing (ft) | 2 |
| Top of Bank Width (ft) | 25 |
| Left Bank Height (ft) (Looking Downstream) | 10 |
| Right Bank Height (ft) (Looking Downstream) | 9 |
| OHWM Width (ft) | 13 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Pools and Runs |
| Substrate | Sand |


WC-09-B








WC-09-B




| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | NE |
| Water Width at Crossing (ft) | 3 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 13 |
| Left Bank Height (ft) (Looking Downstream) | 8 |
| Right Bank Height (ft) (Looking Downstream) | 7 |
| OHWM Width (ft) | 9 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Pools and Runs |
| Substrate | Sand |


WC-10




WC-10



WC-10





WC-10







| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | NE |
| Water Width at Crossing (ft) | 12 |
| Water Depth at Crossing (ft) | 3 |
| Top of Bank Width (ft) | 30 |
| Left Bank Height (ft) (Looking Downstream) | 8 |
| Right Bank Height (ft) (Looking Downstream) | 9 |
| OHWM Width (ft) | 20 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |

WC-10-B




WC-10-B







WC-10-B





| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Perennial |
| Direction of Flow (Direction Downstream) | NE |
| Water Width at Crossing (ft) | 10 |
| Water Depth at Crossing (ft) | 3 |
| Top of Bank Width (ft) | 25 |
| Left Bank Height (ft) (Looking Downstream) | 9 |
| Right Bank Height (ft) (Looking Downstream) | 9 |
| OHWM Width (ft) | 12 |
| OHWM Height (ft from substrate) | 4 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Runs |
| Substrate | Silt |



WC-11





WC-11




WC-11





WC-11



| Attributes | |
|---|---------------------------------------|
| Defined Bed and Bank | Yes |
| Waters of the US | Yes |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | Intermittent |
| Direction of Flow (Direction Downstream) | N |
| Water Width at Crossing (ft) | 4 |
| Water Depth at Crossing (ft) | 0.5 |
| Top of Bank Width (ft) | 10 |
| Left Bank Height (ft) (Looking Downstream) | 6 |
| Right Bank Height (ft) (Looking Downstream) | 8 |
| OHWM Width (ft) | 7 |
| OHWM Height (ft from substrate) | 5 |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | Clear, Natural Line Impressed on Bank |
| Pools, Riffles, Runs Present? | Pools and Runs |
| Substrate | Silt |





NW-01





| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-02






NW-02



| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |


NW-03






| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-04




NW-04





| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-05





NW-05





| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-06







NW-06



| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-07





| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-08



NW-08



| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

NW-09



NW-09



| Attributes | |
|---|--------------------------|
| Defined Bed and Bank | No |
| Waters of the US | No |
| Mapped on NHD | Yes |
| Mapped on NWI | No |
| Investigator | MCV |
| Flow Characteristics | No Evidence of Flow |
| Direction of Flow (Direction Downstream) | No Discernable Direction |
| Water Width at Crossing (ft) | No Water Noted |
| Water Depth at Crossing (ft) | No Water Noted |
| Top of Bank Width (ft) | N/A, No Defined Bank |
| Left Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| Right Bank Height (ft) (Looking Downstream) | N/A, No Defined Bank |
| OHWM Width (ft) | N/A, No OHWM Noted |
| OHWM Height (ft from substrate) | N/A, No OHWM Noted |
| Evidence of Scour or Erosion | No |
| OHWM Criteria | None Noted |
| Pools, Riffles, Runs Present? | None Noted |
| Substrate | Vegetated |

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

5/3/2021 12:06:36 PM

in

Case No(s). 20-0417-EL-BGN

Summary: Application - 17 of 40 (Exhibit L – Part 3 of 3 - Water Resources Delineation Report) electronically filed by Christine M.T. Pirik on behalf of Grover Hill Wind, LLC