CY

PRICE HILL "42"
STA. 5 (3)

FERGUSON "41"
STA. 285 (3)

* SUPERVISORY CONTROLLED

REPEATER

3

Automated switch 9481 opened and locked out at 13:18.
1,027 customers out for 66 min.
Switch 9481 closed at 14:24.

4

184 customers served from pole K8-487 out for 144 minutes until repair complete at 15:42.

1

Defective L.A. on pole K8-487 caused a fault here on 9/4/2009 at 13:18

2

Ferguson Sub CB 111 operated out-and-in due to the faulted arrester above on 9/4/2009 at 13:18.
3,369 customers out momentarily.

Kleeman "43"

NORM OPEN 10878

NORM OPEN 4818

Brighton "43"

9286

DJ-35

4461

36953 140A

NORM OPEN 11759

J9-137

11744

9481

NORM OPEN 31791

3242

Ferguson "42"

47018

65T

K9-1

COPPERED

6889

K8-42

K8-519

K8-512

5369

26465

HMO-7314

NORM OPEN 3479

Queensgate "41"

HMO-7318

8515 28810

L8-362

Queensgate "41"

29800

9342

Price Hill "43"

NORM OPEN 9341

9191 NORM OPEN

NORM OPEN 8180

Ferguson "42"

NORM OPEN 3396

Ferguson "43"

6113 NORM OPEN

Ferguson "44"

NORM OPEN 4266

Price Hill "43"

4861

2644

NORM OPEN 10340

Price Hill "41"

4828 NORM OPEN

Price Hill "43"

1292

3842 NORM OPEN

Price Hill "41"

CADD DRG. pricehi42.dgn & pricehi42.tif

PRICEHI42.DGN 9/15/2009 9:25:28 AM