



COLUMBUS | CLEVELAND
CINCINNATI | DAYTON
MARIETTA

BRICKER & ECKLER LLP
100 South Third Street
Columbus, OH 43215-4291
MAIN: 614.227.2300
FAX: 614.227.2390

www.bricker.com
info@bricker.com

Devin D. Parram
614.227.8813
dparram@bricker.com

April 24, 2018

Via Electronic Filing

Ms. Barcy McNeal
Administration/Docketing
Ohio Power Siting Board
180 East Broad Street, 11th Floor
Columbus, Ohio 43215-3793

**Re: Dominion Energy Ohio Letter of Notification for PIR 782
Case No. 18-560-GA-BNR**

Dear Ms. McNeal:

Attached is a copy of Dominion Energy Ohio's responses to the Ohio Power Siting Board Staff's first set of data requests.

Please feel free to contact me if you have any questions.

Sincerely,

Devin D. Parram

Attachment

cc: Ashton Holderbaum (w/Attachment)

**Dominion Energy Ohio Construction Notice for PIR 782 Pipeline Replacement Project
Case No. 18-560-GA-BNR**

Responses to Staff's First Data Request

1. Please confirm the existing line has no protective coating.

RESPONSE:

Year Installed	Pipeline Number	Distance of Pipeline Segment to be Replaced (Ft.)	Existing Size and Type	Coating	Disposition
1942	L#2468	188	8", 0.322W, steel (Grade B)	None	To be retired
1968	L#2468	5	8", 0.188W, steel (Grade B)	Tarred & wrapped	To be retired
1968	L#2468	133	8", 0.188W, steel (Grade B)	Tarred & wrapped	To be retired
1942	L#12100	1541	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1942	L#12100	150	8", 0.322W, steel (unknown)	None	To be retired
1942	L#12100	615	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1942	L#2468	988	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1972	L#12100	91	8", 0.322W, steel (Grade B)	Tarred & wrapped	To be retired
1942	L#12100	80	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1942	L#12100	248	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1942	L#12100	220	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1942	L#2468	682	8", 0.322W, steel (unknown)	Tarred & wrapped	To be retired
1942	L#2468	5	8", 0.322W, steel (Grade B)	None	To be retired

2. Is the existing line rectified?

RESPONSE: *No, the existing line is not rectified (installed before July 31, 197 – PHMSA requirement).*

3. Does the pipe-to-be-abandoned have leakage history?

RESPONSE:

4. Is DOE facing a compliance deadline on an active leak?

RESPONSE: *No, there is no compliance date.*

5. What is the percent capacity the current pipe operates at on peak day?

RESPONSE:

**Dominion Energy Ohio Construction Notice for PIR 782 Pipeline Replacement Project
Case No. 18-560-GA-BNR**


Responses to Staff's First Data Request

6. What percent capacity will the proposed pipe operate at on peak day?

RESPONSE:

7. The 2370 foot section off Sherman Church Ave SW is being abandoned in place, and the new pipe will be installed slightly offset from the other section, however I am not clear on if you are also abandoning the remaining pipe to be replaced or if after construction those will be taken out of service and removed? Can you please clarify this small question for me?

RESPONSE: *No pipe will be removed – the pipe will only be abandoned where specified*



**Dominion Energy Ohio Construction Notice for PIR 782 Pipeline Replacement Project
Case No. 18-560-GA-BNR**

Responses to Staff's First Data Request

8. Is DOE experiencing any immediate adverse operating conditions due to the current 8" pipe such as downstream delivery pressure issues or active corrosion?

RESPONSE: *DEO is not aware of any current issues with downstream delivery pressure or corrosion.*

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

4/24/2018 4:26:24 PM

in

Case No(s). 18-0560-GA-BNR

Summary: Response to OPSB Staff Data Request electronically filed by Teresa Orahod on behalf of Devin D. Parram