

Case No. 14-0995-EL-REN
Pedlar, Mike Residence - M Pedlar
Staff Interrogatories - Initial Set

Question 1: In Sections A through D of the facility application, the facility address is listed as "1493 Co Rd 57 W Bellefontaine, OH 43311." According to a search conducted on the usps.com website, the United States Postal Service does not recognize this address as one they serve; mail sent to the address may be returned. Please verify that this is the correct address of the facility, and if the address is not set up to receive mail, please provide an address that is.

**Answer 1: The mailing address for this facility has been confirmed as :
1493 Co Rd 57 W Bellefontaine, OH 43311**

Question 2: In Section A of the facility application, the coordinates of the facility are listed as "40.4171, -83.7672." These coordinates are not near a residence, though the image included in the application shows a residential rooftop solar facility. Please provide more accurate coordinates for the facility.

Answer 2: The correct GPS coordinates for this facility should be; 40.417335, -83.716893

Question 3: In Sections B through D of the facility application, the street address is listed in the "city" field. Please verify that "Bellefontaine" was the intended entry for "city" in those three sections.

Answer 3: Bellefontaine is the correct entry for the city fields.

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

7/14/2014 4:14:30 PM

in

Case No(s). 14-0995-EL-REN

Summary: Response Staff Interrogatories - Initial Set electronically filed by Mr. Steven Eisenberg on behalf of Mike Pedlar