



(PHOTOS 24 AND 25)



SCALE IN FEET

LEGEND



IMPACTED AREA A

Hull
& associates, inc.

ENGINEERS | GEOLOGISTS | SCIENTISTS | PLANNERS

6397 EMERALD PARKWAY
SUITE 200
DUBLIN, OHIO 43016

PHONE: (614) 793-8777
FAX: (614) 793-9070
www.hullinc.com

© 2012 HULL & ASSOCIATES, INC.

ROUTE EVALUATION STUDY
BUCKEYE II WIND FARM
CONSTRAINTS MAP, FIGURE 12
S.R.36 & BULLARD RUTAN RD
CHAMPAIGN COUNTY, OHIO

PROJECT NO.: EVP010

CAD DWG FILE: FIG 12

PLOT DATE: FEBRUARY-29-12



(PHOTOS 26 AND 27)



SCALE IN FEET

LEGEND



IMPACTED AREA A

Hull
& associates, inc.

ENGINEERS | GEOLOGISTS | SCIENTISTS | PLANNERS

6397 EMERALD PARKWAY
SUITE 200
DUBLIN, OHIO 43016

PHONE: (614) 793-8777
FAX: (614) 793-9070
www.hullinc.com

© 2012 HULL & ASSOCIATES, INC.

ROUTE EVALUATION STUDY
BUCKEYE II WIND FARM
CONSTRAINTS MAP, FIGURE 13
S.R.36 & N. PARKVIEW RD
CHAMPAIGN COUNTY, OHIO

PROJECT NO.: EVP010

CAD DWG FILE: FIG 13

PLOT DATE: FEBRUARY-29-12



(PHOTOS 28, 29, 30 AND 31)



SCALE IN FEET

LEGEND



IMPACTED AREA A

Hull
& associates, inc.

ENGINEERS | GEOLOGISTS | SCIENTISTS | PLANNERS

6397 EMERALD PARKWAY
SUITE 200
DUBLIN, OHIO 43016

PHONE: (614) 793-8777
FAX: (614) 793-9070
www.hullinc.com

© 2012 HULL & ASSOCIATES, INC.

ROUTE EVALUATION STUDY
BUCKEYE II WIND FARM
CONSTRAINTS MAP, FIGURE 14
N. PARKVIEW RD & URBANA WOODSTOCK PK
CHAMPAIGN COUNTY, OHIO

PROJECT NO.: EVP010

CAD DWG FILE: FIG 14

PLOT DATE: FEBRUARY-29-12



(PHOTOS 32 AND 33)



SCALE IN FEET

LEGEND



IMPACTED AREA A

Hull
& associates, inc.

ENGINEERS | GEOLOGISTS | SCIENTISTS | PLANNERS

6397 EMERALD PARKWAY
SUITE 200
DUBLIN, OHIO 43016

PHONE: (614) 793-8777
FAX: (614) 793-9070
www.hullinc.com

© 2012 HULL & ASSOCIATES, INC.

ROUTE EVALUATION STUDY
BUCKEYE II WIND FARM
CONSTRAINTS MAP, FIGURE 15
S.R.36 & N. MUTUAL UNION RD
CHAMPAIGN COUNTY, OHIO

PROJECT NO.: EVP010

CAD DWG FILE: FIG 15

PLOT DATE: FEBRUARY-29-12



(PHOTOS 34 AND 35)

LEGEND



IMPACTED AREA A

Hull
& associates, inc.

ENGINEERS | GEOLOGISTS | SCIENTISTS | PLANNERS

6397 EMERALD PARKWAY
SUITE 200
DUBLIN, OHIO 43016

PHONE: (614) 793-8777
FAX: (614) 793-9070
www.hullinc.com

© 2012 HULL & ASSOCIATES, INC.

ROUTE EVALUATION STUDY
BUCKEYE II WIND FARM
CONSTRAINTS MAP, FIGURE 16
S.R.36 & S. MUTUAL UNION RD
CHAMPAIGN COUNTY, OHIO

PROJECT NO.: EVP010

CAD DWG FILE: FIG 16

PLOT DATE: FEBRUARY-29-12



(PHOTOS 36 AND 37)



SCALE IN FEET

LEGEND



IMPACTED AREA A

Hull
& associates, inc.

ENGINEERS | GEOLOGISTS | SCIENTISTS | PLANNERS

6397 EMERALD PARKWAY
SUITE 200
DUBLIN, OHIO 43016

PHONE: (614) 793-8777
FAX: (614) 793-9070
www.hullinc.com

© 2012 HULL & ASSOCIATES, INC.

ROUTE EVALUATION STUDY
BUCKEYE II WIND FARM
CONSTRAINTS MAP, FIGURE 17
S. MUTUAL UNION RD & STRINGTOWN RD
CHAMPAIGN COUNTY, OHIO

PROJECT NO.: EVP010

CAD DWG FILE: FIG 17

PLOT DATE: FEBRUARY-29-12

PHOTOS 19-37

Existing Conditions for Conceptual Improvements



Photo 19 – Supplement to Figure 10: Intersection S.R.56 & S.R.29 (Facing East)



Photo 20 – Supplement to Figure 10: Intersection S.R.56 & S.R.29 (Facing Southeast)



Photo 21 – Supplement to Figure 10: Intersection S.R.56 & S.R.29 (Facing East)



Photo 22 – Supplement to Figure 11: Intersection S.R.161 & S. Parkview (Facing South)



Photo 23 – Supplement to Figure 11: Intersection S.R.161 & S. Parkview (Facing East)



Photo 24 – Supplement to Figure 12: Intersection S.R.36 & Bullard Rutan Rd. (Facing Northeast)



Photo 25 – Supplement to Figure 12: Intersection S.R.36 & Bullard Rutan Rd. (Facing Southeast)



Photo 26 – Supplement to Figure 13: Intersection S.R.36 & N. Parkview Rd. (Facing Northeast)



Photo 27 – Supplement to Figure 13: Intersection S.R.36 & N. Parkview Rd. (Facing East)



Photo 28 – Supplement to Figure 14: Intersection N. Parkview Rd. & Urbana Woodstock Pk (Facing Northeast)



Photo 29 – Supplement to Figure 14: Intersection N. Parkview Rd. & Urbana Woodstock Pk (Facing Southeast)



Photo 30 – Supplement to Figure 14: Intersection N. Parkview Rd. & Urbana Woodstock Pk (Facing Southwest)



Photo 31 – Supplement to Figure 14: Intersection N. Parkview Rd. & Urbana Woodstock Pk (Facing South)



Photo 32 – Supplement to Figure 15: Intersection S.R.36 & N. Mutual Union Rd (Facing North)



Photo 33 – Supplement to Figure 15: Intersection S.R.36 & N. Mutual Union Rd (Facing Northeast)



Photo 34 – Supplement to Figure 16: Intersection S.R.36 & S. Mutual Union Rd (Facing Northeast)



Photo 35 – Supplement to Figure 16: Intersection S.R.36 & S. Mutual Union Rd (Facing Southeast)



Photo 36 – Supplement to Figure 17: Intersection S. Mutual Union Rd & Stringtown Rd (Facing North)



Photo 37 – Supplement to Figure 17: Intersection S. Mutual Union Rd & Stringtown Rd (Facing East)

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

12/22/2017 4:11:02 PM

in

Case No(s). 17-2516-EL-BGA, 17-2517-EL-BGA

Summary: Application Exhibit K Part 2 electronically filed by Mr. Ryan D. Elliott on behalf of
Buckeye Wind LLC and Champaign Wind LLC