

## **2973 Garford, Shawnee Twp, Ohio – Excavation Damage Summary**

### **Background**

On 8/25/2021 at approximately 2 PM, Dominion Energy Ohio (DEO) received a notice of a damaged service line at 2973 Garford Av, Shawnee Twp, Ohio.

### **Damage Description**

DEO generated an emergency excavation notice (A123702398) at 2:04 PM on 8/25/021 and responded to the reported address to investigate. Upon arrival, DEO found an unmarked damaged one (1) inch service line and initiated the repair.

Dominion Energy Ohio's emergency ticket for this repair is listed below:

ORIGINAL STREAMS:

----- stream 0 -----

Ticket Revision : 0  
Creation Date : Wed Aug 25 14:08:23 EDT 2021  
Transmission Date : Wed Aug 25 14:08:15 EDT 2021  
Data Type : 1  
Data Source : OUPS  
Mime Type : text  
Decoder Class : com.cssgroup.product.locate.tickets.parsers.OHOCARSTicketHandler  
Recorded flag : true  
Sequences :

Recipient: LCLS1a Seq: 619

LCLS1 00619 OUPSa 08/25/21 14:08:15 A123702398-00A EMER NEW POLY LREQ

Ticket : A123702398 Rev: 00A Taken: 08/25/21 02:04 PM Channel: OPR

State: OH Cnty: ALLEN Place: SHAWNEE TWP

Address : 2973 Street: GARFORD AV

Cross 1 : HERMAN ST

Rail/Hwy: Milemarker(s):

Where : FRONT OF PROPERTY & BOTH SIDES OF ROAD & INCLUDING THE ROAD

: FARTHEST POINT OFF ROAD: LESS THAN 200 FT

: DISTANCE FROM CROSS STREET: APPROX 400FT SOUTH OF

WorkType: HIT AND BLOWING GAS LINE REPLACEMENT

Done for: DOMINION ENERGY OHIO

Done by : DOMINION ENERGY OHIO

Whitelined: N Blasting: N

Means of Excavation: BACKHOE

Work date: 08/25/21 02:07 PM

Start by : 09/09/21 02:07 PM Response Due: 08/27/21 02:07 PM

Best Fit: 40.698022/-84.122363 40.697563/-84.120579

: 40.696932/-84.122643 40.696473/-84.120860

Comments: CREW IS EN ROUTE

Caller : DENISE WILLIAMS

Phone: 800-521-2600

Company : DOMINION ENERGY OHIO

Type: MEMB

Co addr : 1201 E 55TH ST

City : CLEVELAND

St: OH Zip: 44103

Alt Tel#: 800-521-2600

Alt cont: TONY REINDEL

Phone: 419-233-5978

Email: ASKED

Members:

AEPP =AEP OHIO (USIC)

BUCP =BUCKEYE PIPELINE

LIM =LIMA - CITY OF

MAAP =MARATHON PIPE LINE - LIMA

SXCP =ENERGY TRANSFER

WOG =DOMINION ENERGY OHIO -W OH DIV

## Damage Investigation

The damage investigation revealed that Cornerstone Basement Solution generated an excavation ticket the day prior but failed to wait the required 48 hours before excavating. Listed below is the excavation one call notice Cornerstone Basement Solution generated on 8/24/21 at 9:56 AM.

```
ORIGINAL STREAMS:
----- stream 0 -----
    Ticket Revision    : 0
    Creation Date      : Tue Aug 24 09:58:44 EDT 2021
    Transmission Date  : Tue Aug 24 09:58:42 EDT 2021
    Data Type          : 1
    Data Source        : OUPS
    Mime Type          : text
    Decoder Class      : com.cssgroup.product.locate.tickets.parsers.OHOCARSTicketHandler
    Recorded flag      : true
    Sequences          :
                        Recipient: LCLS1a Seq: 210
LCLS1 00210 OUPSa 08/24/21 09:58:42 A123600923-00A ROUT NEW POLY LREQ

Ticket : A123600923 Rev: 00A Taken: 08/24/21 09:56 AM Channel: OPR

State: OH Cnty: ALLEN Place: SHAWNEE TWP

Address : 2973 Street: GARFORD AV
Cross 1 : HERMAN ST
Rail/Hwy: Milemarker(s):
Where   : FRONT AND BOTH SIDES OF PROPERTY
         : FARTHEST POINT OFF ROAD: 150 FT
         : DISTANCE FROM CROSS STREET: SOUTH OF

WorkType: WATER LINE INSTALLATION
Done for: HOMEOWNER
Done by :
Whitelined: N Blasting: N
Means of Excavation: MINI EXCAVATOR

Work date: 08/26/21 09:58 AM
Start by : 09/08/21 09:58 AM Response Due: 08/26/21 10:11 AM

Best Fit: 40.697841/-84.122201 40.697733/-84.120766
         : 40.696749/-84.122283 40.696641/-84.120848

Comments:

Caller   : ELDON BEAR Phone: 419-234-6703
Company  : CORNERSTONE BASEMENT SOLUTIONS Type: CONT
Co addr  : 4655 N KEMP RD
City     : LIMA St: OH Zip: 45807
Alt Tel# : 419-234-6703
Alt cont : SAME AS ABOVE Phone:
Email    : CORNERSTONEBASEMENTSOLUTIONS@GMAIL.COM

Members:
AEPP    =AEP OHIO (USIC) BUCP    =BUCKEYE PIPELINE
LIM     =LIMA - CITY OF MAAP    =MARATHON PIPE LINE - LIMA
SXCP    =ENERGY TRANSFER WOG     =DOMINION ENERGY OHIO -W OH DIV
```

The pictures below detail the damaged service line along the driveway at 2973 Garford Street in Shawnee Twp, Ohio.







The picture below details the repaired service line 2973 Garford Av, Shawnee Twp, Ohio on 8/25/2021.



## Conclusions

Cornerstone Basement Solution failed to generate an excavation one call ticket and wait the required 48 hours prior to excavating, as required by section 3781.28 of the Ohio Revised Code (below). This failure resulted in an unmarked service line being damaged.

### **3781.28 [Effective 3/27/2013] Excavator notifying protection service or pipeline owner**

(A) Except as otherwise provided in divisions (C), (D), (E), and (F) of this section, at least forty-eight hours but not more than ten working days before commencing excavation, the excavator shall notify a protection service of the

location of the excavation site and the date on which excavation is planned to commence.