COLUMBUS I CLEVELAND CINCINNATI-DAYTON

BRICKER & ECKLER LLP 100 South Third Street Columbus, Ohio 43215-4291 MAIN: 614.227.2300 FAX: 614.227.2390

www.bricker.com info@bricker.com

Christopher L. McCloskey 614.227.2385 cmccloskey@bricker.com 06-1142-GA-BIN

March 14, 2008

Kimberly D. Bose, Secretary Federal Energy Regulation Commission 888 First St., N.E., Room 1A Washington, D.C. 20426

Re:

**REX-East** 

CP07-208-00

Request for Re-survey of Property



## Dear Secretary Bose:

I am writing in regards to Rockies Express' response to the February 25, 2008 data request. Specifically, Rockies Express submitted Table 4.3.1-1, which identifies springs located within 150 feet of the REX East Proposed Pipeline Route a. That table, however, does not identify the springs located on the property owned by my clients, Mr. and Mrs. Scothorn.

The springs located on my clients' property are located at approximately half way between mile marker 521 and 522 of the pipeline, in Pickaway County, Ohio, and the proposed pipeline will track directly through, and most likely destroy, the springs.

These springs were apparently not identified by the civil surveyor retained by Rockies Express to survey my clients' property, although my clients have not been provided with a copy of that survey, despite a number of requests submitted to Rockies Express representative, Tom Kenney. Accordingly, my clients respectfully request that FERC require Rockies Express to have the property resurveyed, or, at a minimum, include the springs in the above table.

Sincerely,

Christopher McCloskey

2440773v1

This is to certify that the images appearing are an accurate and complete reproduction of a case file document delivered in the regular course of business rechnician \_\_\_\_\_\_ Date Processed 3.7 CV