

NC
FILE

EASTMAN & SMITH LTD.

ATTORNEYS AT LAW

Established 1844

D. Casey Talbott
Attorney at Law
Direct Dial: 419-247-1845
dctalbott@eastmansmith.com

6

One SeaGate, 24th Floor
P.O. Box 10032
Toledo, Ohio 43699-0032
Telephone: 419-241-6000
Facsimile: 419-247-1777

May 25, 2011

The Public Utilities Commission of Ohio
Docketing Division
180 East Broad Street
Columbus, Ohio 43215-3793

11-3182-RR-RCP

**Re: In the Matter of the Request of Norfolk Southern Railway
Company to Modify Warning Devices at the Seneca County Line
Road Grade Crossing (472394U) in Seneca County, Ohio
PUCO Case No.
Our File No: N1432/176814**

Dear Docketing Clerk:

Enclosed for filing are an original and seven (7) copies of a Request to Modify Warning Devices. Please file this pleading and then return a date-stamped copy to me via the enclosed, stamped envelope.

Please call me – at (419) 241-6000 – if you have any questions or concerns.

Thank you.

Very truly yours,

EASTMAN & SMITH LTD.


D. Casey Talbott

DCT/kml
Enclosures

cc: Leah Thomas Dalton (w/enc.)
Susan J. Kirkland (w/enc.)
Mark R. Zimmerman (w/enc.)

This is to certify that the images appearing are an accurate and complete reproduction of a case file document delivered in the regular course of business.
Technician TM Date Processed MAY 26 2011

RECEIVED-DOCKETING DIV
2011 MAY 26 AM 11:49
PUCO

Columbus • Toledo • Findlay • Novi

2011 MAY 26 AM 11:48

[illegible][illegible]


Attorneys for Norfolk Southern
: Railway Company

[illegible]

A memorandum in support is attached.

Respectfully submitted,

EASTMAN & SMITH LTD.



D. Casey Talbott
Mark W. Sandretto
One SeaGate, 24th Floor
P.O. Box 10032
Toledo, Ohio 43699-0032
Telephone: (419) 241-6000
Fax: (419) 247-1777

Attorneys for Norfolk Southern
Railway Company

MEMORANDUM IN SUPPORT


The signalization at the above-referenced crossing includes a "No Turn" signal located on the west side of the crossing.

This signal was directed toward a driveway which formerly entered the roadway from a private property. The driveway has since been relocated, further west, thereby obviating the need for the "No Turn" signal.

For the foregoing reasons, Norfolk Southern respectfully requests the Commission's authority to remove the "No Turn" signal. (See attached color-copies of two photographs of the involved crossing, including the signal to be removed.)

PROOF OF SERVICE

A copy of the foregoing *Request to Modify Warning Devices* was e-mailed this 25th day of May, 2011, to: **Leah Thomas-Dalton**, Transportation Department, Railroad Commission, Public Utilities Commission of Ohio, 180 East Broad Street, Columbus, Ohio 43215; **Susan J. Kirkland**, Manager, Grade Crossing Safety Programs, Ohio Rail Development Commission, 1980 West Broad Street, 2nd Floor, Columbus, Ohio 43223; and **Mark R. Zimmerman**, Seneca County Engineer, 3300 South Township Road 151, Tiffin, Ohio 44883.



Attorneys for Norfolk Southern
Railway Company



