

September 9, 2014

**Case No. 14-1206-EL-REN
Camp-Darrell-OH-PV-6.72kW Residence
Staff Interrogatories – Initial Set**

Question 1: In Section N of the facility application, an image of the meter used to measure the facility output is required. An image is attached to the application, but the image is blurry, making it impossible to verify the other information listed in Section N. Since the facility is over the 6 kW threshold, verification of the use of a utility grade meter is necessary. Please provide a new image of the facility meter.

Answer 1:



Please let me know if you have any further questions and thank you for your cooperation.

Best,

Anna Nocas
Senior Associate
Sol Systems, LLC

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

9/9/2014 11:48:25 AM

in

Case No(s). 14-1206-EL-REN

Summary: Reply reply to staff interrogatory electronically filed by Ms. Anna Noucas on behalf of Camp, Darrell