

Figure 22. Fieldwork results and photo orientations for Sheet 14.




Figure 23. Fieldwork results and photo orientations for Sheet 15.




Figure 24. Fieldwork results and photo orientations for Sheet 16.




Figure 25. Fieldwork results and photo orientations for Sheet 17.




Figure 26. Fieldwork results and photo orientations for Sheet 18.




Figure 27. Fieldwork results and photo orientations for Sheet 19.



Figure 28. View of the disturbed existing drive on sheet 4.



Figure 29. View of the disturbed existing drive south of Township Road 179.



Figure 30. View of the disturbed existing drive north of Township Road 187 on sheet 9.



Figure 31. View of the surface collected cornfield on sheet 10.



Figure 32. View of the surface collected cornfield on sheet 10.



Figure 33. View of the disturbed existing access west of Bennington Eastern Road.



Figure 34. View of the disturbed access road east of Township Road 188.



Figure 35. View of the disturbed existing access at the station within the eastern end of the project.

This foregoing document was electronically filed with the Public Utilities

**Commission of Ohio Docketing Information System on** 

9/26/2016 2:01:39 PM

in

Case No(s). 16-1531-EL-BLN

Summary: Letter of Notification Part 14 electronically filed by Mr. Hector Garcia on behalf of AEP Ohio Transmission Company