

**Duke Energy Ohio
OPSB Case No. 20-1392-GA-BTA
STAFF Second Set of Data Requests
Date Received: November 13, 2020**

STAFF-DR-02-005

REQUEST:


Please provide before and after site condition photographs for test boring site 20-2.

RESPONSE: Before and after site condition photographs for test boring site 20-2 are provided as STAFF-DR-02-005 Attachment.

PERSON RESPONSIBLE: James Olberding

CENTRAL CORRIDOR PIPELINE - Soil Boring 20-2

Before Boring Advanced



After Completion

