2011 JAN 31 AM 11: 47



# PUCO EXHIBIT FILING

Date of Hearing: January 13, 2011
Case No. 10-2459-TR-CVF
PUCO Case Caption: In the Matter of the Request of Fastrack LLC for an Administrative Hearing.
List of exhibits being filed:
Staff Exhibit 2 - Driver/Vehicle Examination Report Staff Exhibit 2 - Two photographs
Staff Exhibit 3- Driver/Vehicle Examination Report
Staff Exhibit 5- Photocopy of page 190 from Out of Service manal
Reporter's Signature: <u>Carolyn M. Burke</u> Date Submitted: <u>Ganuary</u> 26, 2011

This is to certify that the images appearing are an accourate and complete reproduction of a case file document delivered in the regular course of business.

Technician Date Processed 444 3 1 7011

•	
1	BEFORE THE PUBLIC UTILITIES COMMISSION OF OHIO
2	<b>-</b>
3	
4	In the Matter of the : Request of FasTrack LLC : Case No. 10-2459-TR-CVF
5	for an Administrative : Hearing.
6	
7	
8	PROCEEDINGS
9	before Mr. Henry H. Phillips-Gary and Ms. Mandy
10	Willey, Hearing Examiners, at the Public Utilities
11	Commission of Ohio, 180 East Broad Street, Room 11-D,
12	Columbus, Ohio, called at 10:10 a.m. on Thursday,
13	January 13, 2011.
14	
15	
16	
17	
18	
19	
20	
21	ARMSTRONG & OKEY, INC. 222 East Town Street, 2nd Floor
22	Columbus, Ohio 43215-5201 (614) 224-9481 - (800) 223-9481
23	Fax - (614) 224-5724
24	
25	
I	

### Staff Exhibit No. 1

#### DRIVER/VEHICLE EXAMINATION REPORT

## **Public Utilities** Commission

Transportation Department Phone: (614) 466-0429 Fax: (614) 752-9274

Report Number: OH3258002245

Inspection Date: 7/9/2010

Certification Date: 07/20/2010 Time Started: Time Ended: 14:20 13:20

Inspection Level: II - Walk-Around HM inspection Type: No HM inspection

FASTRACK LLC

8671 CRABB RD

TEMPERANCE, MI 48182

Phone #: (419)215-5142

**ERIE STEEL TREATING LLC** 

Fax #:

MC/MX#: 560135

Driver: License#: HOFFERT, RICHARD A

RR725056

State: OH

Date of Birth:

08/17/1972

State #:

Shipper:

Location: ROADSIDE

USDOT#: 1487384

Highway: IR 475 County: LUCAS MilePost: Origin:

TOLEDO, OH

Destination: NAPOLEON, OH Bill of Lading: 2019-3

Cargo: GENERAL FREIGHT

VEHICLE IDENTIFICATION:

GVMR Unit Type Make Year State License# Company # Unit VIN Issued Decal# Existing Decal# OOS Stkr.# KW 2000 MI RA26376 F7 1XKWDR9X3YR849599 ST STOU 2001 MI 1DW1A48231B488715 0 C124318 1

BRAKE ADJUSTMENTS: No brake measurements recorded.

**VIOLATIONS:** 

Section Code Unit oos Lvi 6 Citation # Verify\* Crash Violation Description Inspection, repair and maintenance of parts & accessories -396.3(a)(1) N LF tire making contact with pitman arm. N N Ν Retroreflective material not affixed as required for trailers 393.11RT 2 N manufactured after December 1993 - No refelctive tape on lower rear of trailer.

' U - Unknown; N - Non-OOS or Driver OOS Violation

Charle	Chec	· La

HazMat:

No HM Transported.

Traffic Enforcement

Cargo Tank: Post Crash Inspection

Alcohol/Controled Substance Check

Conducted by Local Jurisdiction Size and Weight Enforcement

PASA Conducted Inspection **Drug Interdiction Search** 

PBBT inspection

Arrests:

Placard: NA

Inspection Notes: Driver confirmed current address on DL.

Escorted truck to xpress and placed OOS.

Special Study Fields:

Special Study1:

Special Study2:

Special Study3: Special Study4:

Special Study5:

Special Study6: Special Study7:

Special Study8:

Special Study9: Special Study10:

Locally Defined Fields:

For-Hire Carrier: Y; Driver Address: 1717 TALBOT ST; Driver City: TOLEDO; Driver State: OH; Driver Zip: 43613; Photos Taken (Y/N): Y; Reason Code: ISSS;FMCSA Credentials Verified-Y/N: Y;CDL Verified (Y/N): Y;FMCSA OOS Order Issued(Y/N): N

Pursuant to authority contained in Title 49, Code of Federal Regulations, Section 398.9, I hereby declare vehicles with defects followed by an "Y" in the "Out of Service" column in the violations discovered section of this report OUT OF SERVICE. No person shall remove the out of service stickers applied to these vehicles, or operate such vehicles until the out of service defects have been repaired and the vehicles have been restored to safe operating condition.

Report Prepared By:

M Kurtz

Badge #: 3258

Copy Received By: HOFFERT, RICHARD A



### DRIVER/VEHICLE EXAMINATION REPORT

## **Public Utilities** Commission

Transportation Department Phone: (614) 456-0429 Fax: (614) 752-9274

Report Number: OH3258002245

inspection Date: 7/9/2010

Certification Date: 07/20/2010 Time Started: Time Ended: 14:20 13:20

Inspection Level: II - Walk-Around HM Inspection Type: No HM Inspection

HOFFERT, RICHARD A

License #:

RR725056

State: OH

Date of Birth:

06/17/1972

**FASTRACK LLC** 

8671 CRABB RD

TEMPERANCE, MI 48182 Phone #: (419)215-5142

USDOT#: 1487384

Fax #:

MC/MX#: 560135

State #:


All violations of the FHMR and FMCSR or Title 49 of the Ohio Revised Code will be reviewed by the PUCO's Transportation Department to determine whether civil forfeitures should be assessed against any responsible parties in accordance with the penalty provisions of Title 49 of the Ohio Revised Code. If civil forfeitures are assessed, you will receive a separate notice by mail. These penalties may be assessed to motor carriers, shippers, and/or drivers.

ATTENTION DRIVER: This report must be sent to the motor carrier whose name appears at the top of this inspection report within 24 hours. If the inspection report cannot be delivered within 24 hours the driver must mail or fax the inspection report to the motor carrier.

ATTENTION MOTOR CARRIER: The motor carrier must examine this report and repair all the vehicle defects/violations noted above. -AND- The motor carrier must sign the Certification of Repairs below and Jeturn the signed form to: Public Utilities Commission of Ohio-TASD; 180 E. Broad St.; Columbus, Oh; 43215-3793 -OR- Fax (614) 752-9274 within 16 days of the inspection. If "No Violations Were Discovered" then you do not need to return this report. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

MOTOR CARRIER CERTIFICATION OF COMPLETED REPAIRS: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety & Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. A false certification of repairs is required to be prosecuted with penalties up to \$10,000.

Signature of Carrier Official:	X	Title:	Date:	
Signature of Repairer:	X	Facility:	Date:	





Report Prepared By:

DRIVER/VEHICLE SAMINATION REPORTS

Report No. OHIO STATE HIGHWAY PATROL MOTOR CARRIER ENFORCEMENT DISTRICT 1 HEADQUARTERS 200 JUL 20 AN 18: 33 TELEPHONE: (419) 423-1414

Report Number: OH3258002245 Inspection Date: 07/09/2010

Start Time: 01:20 PM End Time: 02:20 PM

Inspection Level; II - Walk-Around

			HM	inspection Type: h	ione
FASTRACK LLC 8671 CRABS RD TEMPERANCE, MI 48182 USDOT#: 91487384 MC/MX#: 580135 State#: Location: ROADSIDE Highway: IR 475 County: LUCAS, OH	Phone#: (419)215-5 Fax#:	MilePost: 9.6 Orlgin: TOLEDO	License#: RR7; Date of Birth: 0 CoDriver: License#: Date of Birth: Shipper:	6/17/1972 ERIE STEEL TRE Bill of Lading: 201	9-3
,	m+ + + + + + + + + + + + + + + + + + +	Destination: NAF	OLEON, OH	Carpo: GENERAL	FREIGHT
VEHICLE IDENTIFICATION Unit Type Make Year State				Maria di Angela di A	In constitution of the second
1 TT KW 2000 MI 2 ST STOU 2001 MI	Piete# Con RA26975 C124318		<u>VIN</u> <u>GV</u> R9X3YR849599 462318488715	WR CVSA# CVSA	issued # OOS Sticker
BRAKE ADJUSTMENTS: N	o Brake Measurements	Required For Level 2		. · ·	
VIOLATIONS	prometered (E.I. g. v. ma		• • •	र कर्र १६६ वडी <del>प्रतीय र</del>	•
Section Code Type Unit Of 396.3(a)(1) F 1	OS Citation # Verify V V N	N Inspection, making cor N Retroreflecti	itaci with pitman or ve meterial not affix		ers manufeatured after
Special Checks: No Date in State Information: FMCSA Credentials Verified-Y/Driver Address: 1717 TALBOT  *Pressure to subority contained in Title	N. Y. CDL Verified (Y/r 9T; Driver City; TOLEI	DO: Driver State: OH	i; Driver Zip: 43613; Sectors vehicles with defect	Photos Taken (Y/N):	Ni; Out of Sociou" column is the
violations discovered section of this representation defects have been regulard and	of OUT OF SERVICE. No sain	PLO STAIL FRANCISE HAS OUT OF	Minico stipkera applied to t L	Meno white at a parage and	ols vesticitus until (har put cd
Signatury Of Repute 7	1/10		FIDEN:	8 TRUCK SERVICE, I	Octor 7/4/0
All violations of the FHMR and FACSR a supersed against any responsible partie notice by wall. Those punalties may be	s in secondary with the penel teasured to motor content, whi	ly provincions of 1766 49 of th popula, endfor drivens.	e Ohio Revised Gude, if ch	ill forelitende die vereinskier i	Cit will facility & puppings
ATTENTION CRIVER: The report must within 24 hours the driver (Hugel must or to			о ст. ине мересии-тероп v	HARRIE DA RIGILLY. A THU CORPAC	odni sehrut omassit bit dilitikladisid
ATTENTION MOTOR CARRIER: The r Cuminosition of Repairs betwee und return 15 days of the inspection. If "No Volution of up to \$690.	the tioned turn to Public Utili	ties Commission of Obju-T.	450: 180 ff. Broad St., Col	umbun, On: 43215-3793 -OF	t: Figs (614) 752:0374 within
MOTOR CARRIER CERTIFICATION OF compliance with the Federal Apole Carrier required to be prospected with penalties	CONFLETED REPAIRS, The or Salary & HIZZERDO & MISSERS IN THE STORY & THE STORY IN T	Undersigned centries that a he Regulations Inspire as the	ii violotions noted on livių s ny era applicoble to moter o	port bave been corrected to acriers and drivers. A false	al action taken to assure cartification of repairs is
Signature Of Motor Cerrier X:	luci-stoism	DL		1CLV	. Date: 11 (2)110
•		. · ·	*		

M9 05:86:1 0105/71/7 sate()

Copy Received By

Badge #

Page: 177

3638748467 :mon?

## 10. TIRES




a. (1) Less Than 2/32 Inch (1.6mm) Tread Measured Any Two Adjacent Grooves



a. (1) Less Than 2/32 Inch (1.6mm) Tread Measured Any Two Adjacent Grooves



a. (1) Less Than 2/32 Inch (1.6mm) Tread Measured Any Two Adjacent Grooves



a. (2) Exposed Cord in Tire



a. (2) Exposed Cord in Tire



a. (7) Tire in Contact With Any Part of the Vehicle