

FILE

PUCO EXHIBIT FILING

4

Date of Hearing: 11/7/13

Case No. 13-1580-TR-CVF

PUCO Case Caption: ITMO the Request of Thomas L.  
Vannmeter for an Administrative Hearing

RECEIVED-DOCKETING DIV  
2013 NOV 22 PM 2:14

PUCO

List of exhibits being filed:

Staff Exhibit 1

This is to certify that the images appearing are an accurate and complete reproduction of a case file document delivered in the regular course of business. Technician MA Date Processed NOV 22 2013

Reporter's Signature: Karen Sue Gibson  
Date Submitted: 11/19/13

BEFORE THE PUBLIC UTILITIES COMMISSION OF OHIO

- - -

In the Matter of the :  
Request of Thomas L. :  
Vanmeter for an : Case No. 13-1580-TR-CVF  
Administrative Hearing. :  
- - -

PROCEEDINGS

before Mr. Bryce McKenney, Attorney Examiner, at the  
Public Utilities Commission of Ohio, 180 East Broad  
Street, Room 11-C, Columbus, Ohio, called at 10 a.m.  
on Thursday, November 7, 2013.

- - -

ARMSTRONG & OKEY, INC.  
222 East Town Street, Second Floor  
Columbus, Ohio 43215-5201  
(614) 224-9481 - (800) 223-9481  
Fax - (614) 224-5724

- - -

## DRIVER/VEHICLE EXAMINATION REPORT

**Ohio**

Report Number: OH1191008678  
 Inspection Date: 12/7/2012 Certification Date:  
 Time Started: 09:58 Time Ended: 10:21  
 Inspection Level: III - Driver-Only Inspection  
 HM Inspection Type: No HM Inspection

GREAT LAKES PETROLEUM CO  
 4500 RENAISSANCE PKWY  
 CLEVELAND, OH 44128  
 USDOT #: 977498 Phone #: (216)478-0501  
 MC/MX #: Fax #:  
 State #:

Driver: VANMETER, THOMAS L  
 License #: RS112718 State: OH  
 Date of Birth: 05/22/1964

Location: ROADSIDE  
 Highway: IR80  
 County: LORAIN  
 Shipper: CARRIER

MilePost: 139  
 Origin: AKRON, OH.  
 Destination: SANDUSKY, OH.

Bill of Lading: NONE  
 Cargo: EMPTY

## VEHICLE IDENTIFICATION:

Unit	Type	Make	Year	State	License#	Equipment ID	Unit VIN	GVWR	CVSA #	CVSA Issued #	OOS Stkr.#
1	TR	FORD	1992	OH	PVM7185	8226900A	1FTZY90R4NVA04694	58,000	15980487		

BRAKE ADJUSTMENTS: No brake measurements recorded.

## VIOLATIONS:

Vio Code	Section	Unit	OOS	Citation #	Verify*	Crash	Violation Description
392.16	392.16	D	N		N	N	Failing to use seat belt while operating CMV, did not have on as he passed patrol car, white shirt, black seat belt.

\* N - Non-OOS or Driver OOS Violation

HazMat: No HM Transported.

Placard: NA Cargo Tank:

## Special Checks:

<input type="checkbox"/> Alcohol/Controlled Substance Check	<input checked="" type="checkbox"/> Traffic Enforcement	<input type="checkbox"/> Post Crash Inspection
<input type="checkbox"/> Conducted by Local Jurisdiction	<input type="checkbox"/> PASA Conducted Inspection	<input type="checkbox"/> PBET Inspection
<input type="checkbox"/> Size and Weight Enforcement	<input type="checkbox"/> Drug Interdiction Search	Arrests:

Inspection Notes: Medical 11-7-14.

## Special Study Fields:

Special Study1:  
 Special Study2:  
 Special Study3:  
 Special Study4:  
 Special Study5:

Special Study6:  
 Special Study7:  
 Special Study8:  
 Special Study9:  
 Special Study10:

## Locally Defined Fields:

For-Hire Carrier: Y; Driver Address: 4231 KIOWA RD.; Driver City: RICHFIELD; Driver State: OH; Driver Zip: 44286; Photos Taken (Y/N): N; Reason Code: TRAF; FMCSA Credentials Verified-Y/N: Y; CDL Verified (Y/N): Y; FMCSA OOS Order Issued(Y/N): N

All violations of the FHMR and FMCSR or Title 49 of the Ohio Revised Code will be reviewed by the PUCO's Transportation Department to determine whether civil forfeitures should be assessed against any responsible parties in accordance with the penalty provisions of Title 49 of the Ohio Revised Code. If civil forfeitures are assessed, you will receive a separate notice by mail. These penalties may be assessed to motor carriers, shippers, and/or drivers.

ATTENTION DRIVER: This report must be sent to the motor carrier whose name appears at the top of this inspection report within 24 hours. If the inspection report cannot be delivered within 24 hours the driver must mail or fax the inspection report to the motor carrier.

ATTENTION MOTOR CARRIER: The motor carrier must examine this report and repair all the vehicle defects/violations noted above -AND- The motor carrier must sign the Certification of Repairs below and return the signed form to: Public Utilities Commission of Ohio, T ASD - 4th floor, 180 E Broad St, Columbus, OH 43215-3793 -OR- Fax (614) 752-9274 within 15 days of the inspection. If "No Violations Were Discovered" then you do not need to return this report. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000. If you have any questions, please contact (614) 466-0429.

MOTOR CARRIER CERTIFICATION OF COMPLETED REPAIRS: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety & Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. A false certification of repairs is required to be prosecuted with penalties up to \$10,000.

Report Prepared By:  
 R Kisner

Badge #:  
 1191

Copy Received By:  
 VANMETER, THOMAS L

Page 1 of 2



OH1191008678

# DRIVER/VEHICLE EXAMINATION REPORT

# Ohio

Report Number: OH1191008678  
 Inspection Date: 12/7/2012 Certification Date:  
 Time Started: 09:58 Time Ended: 10:21  
 Inspection Level: III - Driver-Only Inspection  
 HM Inspection Type: No HM Inspection

GREAT LAKES PETROLEUM CO  
 4500 RENAISSANCE PKWY  
 CLEVELAND, OH 44128  
 USDOT #: 977498 Phone #: (216)478-0501  
 MC/MX #: Fax #:  
 State #:

Driver: VANMETER, THOMAS L  
 License #: RS112718 State: OH  
 Date of Birth: 05/22/1964

Signature of Carrier Official: X Title: \_\_\_\_\_ Date: \_\_\_\_\_

Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

Signature of Repairer: X Facility: \_\_\_\_\_ Date: \_\_\_\_\_

Report Prepared By:  
 R Kisner

Badge #:  
 1191

Copy Received By:  
 VANMETER, THOMAS L

Page 2 of 2



OH1191008678