



March 24, 2014

Case No. 14-0176-EL-REN
Good To U Auto Center, LLC-PA-PV-39kW Facility
Staff Interrogatories – Initial Set

Question 1: According to the application, the facility has a placed-in-service date of 11/14/13, yet the picture provided appears to be that of a drawing produced with a 3D CAD program. Please submit at least one digital photograph that depicts an accurate characterization of the renewable generating facility.

Answer 1: Please find below a photo of the modules taken this morning (3/24/14)



Please let me know if you have any further questions and thank you for your cooperation.

Best,

Anna Nocas
Senior Associate
Sol Systems, LLC

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

3/24/2014 10:02:36 AM

in

Case No(s). 14-0176-EL-REN

Summary: Reply reply to staff interrogatory electronically filed by Ms. Anna Noucas on behalf of Good, Dean