

June 9, 2014

Case No. 14-0612-EL-REN Feeney-James-PA-PV-4.8KW Residence Staff Interrogatories – Initial Set

Question 1: In Section A of the facility application, its coordinates are listed as latitude 40.1919 and longitude -75.0261. However, the facility appears to be at latitude 40.196323 and longitude -74.977085. Please verify the correct coordinates.

Answer 1: The proper coordinates are latitude 40.196323 and longitude -74.977085. Apologies for the confusion.

Question 2: In Section L of the facility application, it is listed as eligible to meet another state's RPS. In Section L.1, under "State Certification Agency," the State Certification Number is listed. Please list the correct State Certification Agency (most likely the District of Columbia Public Service Commission).

Answer 2: We have received the following state certification numbers for this facility:

| PA | PA-391625-SUN-I |
|----|-----------------|
| DC | DC-101126-SUN-I |
| IL | IL-09384-SUN-I |

Question 3: In Section N.1.b of the facility application, the serial number of the facility's utility grade meter is listed as 64 80 222. On the picture, the serial number appears to be 64 808 222. Please verify the correct serial number.

Answer 3: The correct serial number is 64 808 222.

Please let me know if you have any further questions and thank you for your cooperation.

Best,

Anna Noucas Senior Associate Sol Systems, LLC This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

6/9/2014 10:04:27 AM

in

Case No(s). 14-0612-EL-REN

Summary: Reply reply to staff interrogatory electronically filed by Ms. Anna Noucas on behalf of Feeney, Barbara