

November 24, 2015

Mahila Christopher,

With regard to the following case:

Case No. 15-1695-EL-REN
SMITH-DONNIE-OH-PV-15.6kw Residence
Staff Interrogatories – Initial Set

## **Question 1:**

In Section N.1 of the application, you have submitted the following:

N.1.a Manufacturer: Solar Edge

However, the manufacturer name that is visible in the Section N.1.e photograph does not match the name submitted. Please clarify the manufacturer of the meter submitted under Section N.

## Answer 1:

Both meters are GE i-70-s. One has the serial number 83 111 881 and the other has a serial number 89 331 572. Photographs attached below were taken today 11/24/2015.

## Question 2:

In your application, you have submitted details for two meters with the following serial numbers:

N.1.a Manufacturer: Solar Edge

N.1.b Serial Number: 89 331 572, 83 111 831

**N.1.c Type:** i-70-s, i-70-s

- a. Please provide a photograph of the meter, as well as other Section N details, for the meter with serial number 83 111 831.

  Please find photographs attached below.
- b. Please indicate how many of the 60 panels submitted in Section G are connected to each meter? Also, indicate the location of the two sets of panels and, if needed, submit a hand drawn indication on the photograph or a row X column location mention.

The panels are split evenly 30 and 30. All panels are located on the roof.

## Answer 2:









Best,

Bridget Callahan SREC Operations Analyst This foregoing document was electronically filed with the Public Utilities

**Commission of Ohio Docketing Information System on** 

11/24/2015 4:39:11 PM

in

Case No(s). 15-1695-EL-REN

Summary: Answer to staff interrogatory electronically filed by Ms. Bridget Callahan on behalf of Donnie Smith