

July 26, 2016

Mahila Christopher,

With regard to staff interrogatories for the following case:

Case No. 16-1392-EL-REN Williams-Arlie-IN-PV-14.82kW Residence Staff Interrogatories – Initial Set

Question 1: In Section N of the application you have submitted the following:

N.a The meter(s) that are measuring output from the facility are:

No Inverter Meter(s)

Yes Utility Grade Meter(s) (Must meet ANSI 12.1, or demonstrate an accuracy level of $\pm 2\%$)

N.1 Please provide the following information for each meter used in your system.

N.1.a Manufacturer: GE

N.1.b Serial Number: 10277781

The manufacturer name submitted does not match the manufacturer name visible in the Section N meter photograph submission. Please clarify the manufacturer of the meter.

Answer 1: The correct manufacturer is GE, model kv2.

Question 2: In Section N.1.e of the application you have submitted the following:

Attach a photograph of the meter(s) with date image taken. The meter reading(s) must be clearly visible in the photograph.

N.1.e Report the total meter reading number at the time the photograph was taken and specify the appropriate unit of generation (e.g., kWh): 0kWh

The meter reading number that is visible in the Section N meter photograph does not match the meter reading number submitted. Please clarify the meter reading number.

Answer 2: The correct meter reading in the photograph is 9 KWH.

Best, Jessica Cowan

This foregoing document was electronically filed with the Public Utilities

Commission of Ohio Docketing Information System on

7/26/2016 5:30:51 PM

in

Case No(s). 16-1392-EL-REN

Summary: Reply to staff interrogatories electronically filed by Ms. Bridget Callahan on behalf of Arlie Williams