Duke Energy Ohio OPSB Case No. 20-1392-GA-BTA STAFF Second Set of Data Requests Date Received: November 13, 2020

**STAFF-DR-02-001** 

# **REQUEST:**

In the section of the Geotechnical Engineering Report entitled "Photographs of Site Conditions," photographs 48 through 70 do not seem to correspond with test borings sites. Please mark on a map where these photographs were taken relative to the Central Corridor Pipeline and if it was a corresponding test boring site.

**RESPONSE:** Photographs 1 through 47 were standard geotechnical test bores and were shown on the map. However, photographs 48 through 70 were actually environmental sample sites, which were performed with a geoprobe rig that takes tubular samples of the soil. STAFF-DR-02-01 Attachment is a map showing the locations of those environmental sample sites.

**PERSON RESPONSIBLE:** James Olberding

Page 1 of 4 OPSB Case No. 20-1392-GA-BTA STAFF-DR-02-001 Attachment

GeoReport

# **EXPLORATION PLAN**

November 18, 2020 - Terracon Project No. N1175384 Duke C350V Pipeline - Cincinnati, OH






DIAGRAM IS FOR GENERAL LOCATION ONLY, AND IS NOT INTENDED FOR CONSTRUCTION PURPOSES

Page 2 of 4

Duke C350V Pipeline ■ Cincinnati, OH






Page 3 of 4
GeoReport

# **EXPLORATION PLAN**

Duke C350V Pipeline ■ Cincinnati, OH

November 18, 2020 Terracon Project No. N1175384




# **EXPLORATION PLAN**

Duke C350V Pipeline ■ Cincinnati, OH

November 18, 2020 ■ Terracon Project No. N1175384





This foregoing document was electronically filed with the Public Utilities

**Commission of Ohio Docketing Information System on** 

11/19/2020 9:52:18 AM

in

Case No(s). 20-1392-GA-BTA

Summary: Correspondence Duke Energy Ohio, Inc.'s Response to Staff Data Request 02-001 electronically filed by Carys Cochern on behalf of Duke Energy Ohio, Inc.