FILE

21.0263 TR CVF

Public Utilities Commission 180 East Broad Street Columbus Ohio 43215-3793

Attention: Ron Mosher

Case number: OH3207302892D

OH320730289D

To Whom It May Concern:

I would like to formally contest the violation via a Administration Hearing. Thank you for your time in this matter.

David Osburn

2411 Olde Falls Rd Zanesville Ohio 43701

740-705 -6610

1000

ARCENTED OF DAILO: OF

This is to certify that the images appearing are an accurate and complete reproduction of a case file document delivered in the regular course of business.

Technician Date Processed 3.34.21

State: OH

State:

'ublic Utilities Commission of Ohio

Fransportation Department **180 East Broad Street** 

Columbus, Ohio 43215

hone #: (614)466-0429 Fax #: (614)752-9274

AID STATE SYSTEMS INC

10 BOX 926

2

SB

HOLATIONS

**IEBRON. OH 43025** 

ISDOT#: 00214896

**IC/MX#: 153267** 

itate#:

.ocation: ROADSIDE

lighway: SR 79 Sounty: LICKING, QH Phone#: (740)928-1115

Fax#:

MilePost: 5.71

Origin: HEATH, OH

Destination:FRIENDLY, WV

Report Number: OH3207302892

Inspection Date: 12/22/2020

Start: 10:24 AM ET End: 10:59:33 AM ET

Inspection Level: II - Walk-Around HM Inspection Type: Bulk

Driver: OSBURN, DAVID L

License#: RJ015111

Date of Birth: 10/06/1973

CoDriver: License#:

Date of Birth:

Shipper: KAISER ALUMINUM & CHEMICAL CORE

Bill of Lading: MSO#00696 Cargo: HAZ MAT (ALL)

'EHICLE IDENTIFICATION

Jnit Type Make Year State Plate # TT FRHT 2012 OH

UNK 2012 OH

PWM2726 TQT5824

Equipment ID 314 DT185

GVWR CVSA# CVSA Issued# OOS Sticker 1FUJGEDR6CSBR5550 48,000 4C9D43625C5071138

VIN

68,000

3RAKE ADJUSTMENTS: No Brake Measurements Required For Level 2

HOEA HONS								
Jio Code	Section	Unit (	<u> 200</u>	Citation#	Verify C	rash	<u>Violations Discovered</u>	
192.10A3	392.10(a)(3)	D	N		N	N	Failure to stop at railroad crossing - CMV requiring display of HM placards: Failed to stop at Track on SR 79 near N. Maple Dr.	
196.17C	396.17(c)	1	N		N	N	Operating a CMV without proof of a periodic inspection: Expired end of November 2020 on tractor	
72.602C1	172.602(c)(1)	1	N		N	N	Maintenance/accessibility of Emergency Response information: In compartment in center upper console with a door - driver had to search to locate	
196.17C	396.17(c)	2	N		N	N	Operating a CMV without proof of a periodic inspection: Expired end of November 2020 on trailer	
77.817A	177.817(a)	1	N		N	N	No or improper shipping papers (carrier): Shipping sequence is incorrect and additional wording in between proper shipping name - Carrier	
72.201A4	172.201(a)(4)	1	N		N	N	Additional information not after Hazardous Materials basic description: Shipper violation	
72.202A3	172.202(a)(3)	1	N		N	N	No or improper Hazard Class or Division number.: Shows hazard	

lazMat: 4.3 Dangerous wn/wet

Special Checks: Traffic Enforcement

Placard: Yes

class 4 should show 4.3 in proper shipping description

Cargo Tank:

itate Information:

MCSA Credentials Verified-Y/N: Y: CDL Verified (Y/N): Y; FMCSA OOS Order Issued(Y/N): N; For-Hire Carrier: Y; Reason Code: OBVI; Priver Address Verified (Y/N): Y; Driver Address: 2411 OLDE FALLS RD; Driver City: ZANESVILLE; Driver State: OH; Driver Zip: 43701; 'hotos Taken (Y/N): Y; HM Safety Permit Verified(Y/N): N; Loaded by Shipper (Y/N): Y; Ship Doc Prep by Shipper (Y/N): Y; Haz Class A; .3; ID # A: UN3170; Packing Group A: II; Gross Weight A: 15,820;

Report Prepared By: V T FORBES

Badge #: 3207

Copy Received By: DAVID OSBURN




DRIVER/VEHICLE EXAMINATION REPORT Aspen 3.0.0.17 **Public Utilities Commission of Ohio** Report Number: OH3207302892 **Transportation Department** Inspection Date: 12/22/2020 180 East Broad Street Start: 10:24 AM ET End: 10:59:33 AM ET Columbus, Ohio 43215 Inspection Level: II - Walk-Around Phone #: (614)466-0429 HM Inspection Type: Bulk Fax #: (614)752-9274 MID STATE SYSTEMS INC Driver: OSBURN, DAVID L PO BOX 926 License#: RJ015111 State: OH HEBRON, OH 43025 Date of Birth: 10/06/1973 USDOT#: 00214896 Phone#: (740)928-1115 CoDriver: MC/MX#: 153267 Fax#: License#: State: State#: Date of Birth: Location: ROADSIDE MilePost: 5.71 Shipper: KAISER ALUMINUM & CHEMICAL CORF Highway: SR 79 Origin: HEATH, OH Bill of Lading: MSO#00696 County: LICKING, OH Destination:FRIENDLY, WV Cargo: HAZ MAT (ALL) ATTENTION DRIVER: This report must be sent to the motor carrier whose name appears at the top of this inspection report within 24 hours. If the inspection report cannot be delivered within 24 hours the driver must mail or fax the inspection report to the motor carrier. POSSIBLE CDL DISQUALIFICATION If this roadside inspection identified an alleged violation of one or more of the below noted regulations, your CDL may be disqualified. If the PUCO finds you committed a violation of any of these regulations, the violation will be treated as a conviction for the purposes of federal and state law and notice of such conviction will be forwarded to the Ohio Bureau of Motor Vehicles (BMV). The BMV may disqualify you from operating a commercial motor vehicle for a minimum of 60 days. Any BMV sanction is in addition to sanctions imposed by the Public Utilities Commission of Ohio (PUCO). 177.804(b)(1), 177.804(b)(2), 177.804(b)(3), 177.804(c), 4901:2-5-07D, 383.23(a)(2), 383.51(a), 383.51A-NSIN, 383.51A-NSOUT, 383.51A-SOUT, 383.51A-SOUT, 383.93(b)(5), 383.93(b)(5), 391.15(a), 391.15 MOTOR CARRIER CERTIFICATION OF COMPLETED REPAIRS: The findersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety & Hazartious Material Regulations insofar as they are applicable to motor carriers and drivers. If false certification of repairs is required to be prosecuted with penalties up to \$10,000. Signature Of Repairer X: Facility

All violations of the FHMR and FMCSR or Title 49 of the Ohio Revised Code will of reviewed by the PUCO's Transportation Department to determine whether civil forfeitures should be assessed against any responsible parties in accordance with the penalty provisions of Title 49 of the Ohio Revised Code. If civil forfeitures are assessed, you will receive a separate notice by mail. These penalties may be assessed to motor carriers, shippers, and/or drivers.

ATTENTION MOTOR CARRIER: The motor carrier must examine this report and repair all the vehicle defects/violations noted above -AND- The motor carrier must sign the Certification of Repairs below and return the signed form to: Public Utilities Commission of Ohio, TASD- 4th floor, 180 E Broad St, Columbus, OFF-3215-3789 OR- Fair (614) 752-9274 within 15 days of the inspection. If "No Violations West Discovered" then you do not need to return this report. Fallure to return this report with the equires certification can result in penalties up to \$1,000 per day for each day the violation pointings, up to a total of \$10,000 at you have any questions, sheave contact (614) 486-9429.

Signature Of Motor Carrier X:\_

Title



Badge #: 3207 Copy Received By: DAVID OSBURN Pane 2 of 2





Lawrence K. Friedeman Dennis P. Deters Daniel R. Conway

December 24, 2020

OSBURN, DAVID L 2411 OLDE FALLS RD ZANESVILLE, OH 43701

RE: Notice of Apparent Violation

And Intent to Assess Forfeiture

Case No. OH3207302892D

OH3207302892 PIN #: U9jkrDAV

Dear Sir or Madam:

On 12-22-2020, a vehicle operated by MID STATE SYSTEMS INC and driven by, OSBURN, DAVID L was inspected in the State of Ohio, resulting in the discovery of the following apparent violation(s) of the Commission's rules. The Commission intends to assess a civil forfeiture against DAVID L OSBURN in the following amount:

Code	<u>Group</u>	Description	<u>Crash</u>	State Citation	<u>Forfeiture</u>
392.10A3	4	Failure to stop at railroad crossing - CMV requiring display of HM placards	N		\$ 500.00
				Total Amount Due:	\$ 500.00

Within 30 days of this notice you must either; 1) pay the assessed civil forfeiture or, 2) submit a written Request for Conference to present mitigating circumstances. \* Violations with a "Y' in the "crash" column or any text in the "State Citation" column are not assessed a civil forfeiture. Further, because these offenses are primarily under the jurisdiction of local courts, these violations are not available for a conference.

Failure to comply with either option above shall constitute a waiver of your right to further contest the violation(s) and will conclusively establish the occurrence of the violation(s). Such failure shall also constitute a waiver of your right to further contest liability to the State of Ohio for the civil forfeiture described in the notice and will result in the forfeiture amount being referred to the Ohio Attorney General's Office for collection. In addition, your Ohio operating authority (CPCN) may be sanctioned as permitted by law.







Lawrence K. Friedeman Dennis P. Deters Daniel R. Conway

OSBURN, DAVID L **2411 OLDE FALLS RD** ZANESVILLE, OH 43701

Invoice #: 20-00048627

Date:

12/24/2020

Due Date: 01/23/2021

PIN #:

U9jkrDAV

Case #:

OH3207302892D

## 2020

Item#	Туре	Description	Amount Due		
INVD- 0121612	Civil Forfeiture HazMat	Failure to stop at railroad crossing - CMV requiring display of HM placards	\$ 500.00		
	Payments Received				
	Total Amount Due				

Please visit https://www.puco.ohio.gov/sc/mcos/ to make your online payments.

Questions concerning this invoice should be addressed to our call center at 1-800-686-7826.

(Remittance for mailed check payment)

Please make checks payable to:

**Public Utilities Commission of Ohio** 

PO BOX 715343

Cincinnati, OH 45271-5343

OSBURN, DAVID L 2411 OLDE FALLS RD ZANESVILLE, OH 43701

Invoice #: 20-00048627

Date:

12/24/2020

Due Date: 01/23/2021

