

DRIVER/VEHICLE EXAMINATION REPORT



Public Utilities Commission of Ohio
180 East Broad Street
Transportation Department
Columbus, OH 43215
Phone #: (614)466-0429 Fax #: (614)752-9274

Report Number: OH3225014232
Inspection Date: 8/17/2020 Certification Date:
Time Started: 09:25 Time Ended: 09:50
Inspection Level: III - Driver-Only Inspection
HM Inspection Type: No HM Inspection

MCJUNKIN ROLL OFFS INC
2064 PERRY HWY
FREDONIA, PA 16124

Driver: PEARSON, RICHARD A
License #: [REDACTED] State: PA
Date of Birth: [REDACTED]

USDOT #: 01371622 Phone #: (724)475-2170
MC/MX #: 00654255 Fax #:
State #:

Location: ROAD SIDE US MilePost: 19
Highway: US 422 Origin: HUBBARD, OH Bill of Lading: NONE
County: MAHONING Destination: HILLSVILLE, PA Cargo: GARBAGE, REFUSE, TRASH
Shipper: CARRIER

VEHICLE IDENTIFICATION:

Unit	Type	Make	Year	tate	License#	Equipment ID	Unit VIN	GVWR	CVSA #	CV	A Issued #	OO	tkr #
1	TR	FRHT	1999	PA	[REDACTED]	17	1FV4TEDB5XHA05988	80,000					

BRAKE ADJUSTMENTS: No brake measurements recorded.

VIOLATIONS :

Vio Code	Section	Unit	OOS	State Citation Number	Verify*	Crash	Violation Description
392.16	392.16(a)	D	N		N	N	Failing to use seat belt while operating a CMV: Viewed driver from red light (616) left turn on to US (422), sunny, clear view to driver, driver not wearing seat belt as designed.
392.2UCR	392.2	1	N		N	N	Failure to pay UCR Fee: No 2020 UCR paid up to date.

* N - Non-OOS or Driver OOS Violation

HazMat: No HM Transported. **Placard:** NA **Cargo Tank**

Special Checks:

<input type="checkbox"/> Alcohol/Controlled Substance Check	<input type="checkbox"/> Traffic Enforcement	<input type="checkbox"/> Post Crash Inspection
<input type="checkbox"/> Conducted by Local Jurisdiction	<input type="checkbox"/> PASA Conducted Inspection	<input type="checkbox"/> PBBT Inspection
<input type="checkbox"/> Size and Weight Enforcement	<input type="checkbox"/> Drug Interdiction Search	Arrests:
<input type="checkbox"/> ESscreening		

Inspection Notes Driver wearing flourescent yellow/green safety vest, black/gray belt, viewed driver not wearing belt while I was stationary at red light driver making a left turn onto us 422, clear view into drivers front and side window. drivers side window down. seat belt not worn as designed. no shoulder harness coming across drivers shoulder/chest.

when I approached driver. driver was wearing seat belt as designed.

Driver commented and showed that he was wearing seat belt under his left arm pit.

Special Study Fields:

Special Study1:	Special Study6:
Special Study2:	Special Study7:
Special Study3:	Special Study8:
Special Study4:	Special Study9:
Special Study5:	Special Study10:

Locally Defined Fields:

For-Hire Carrier: Y;Fatalities (Y/N): N;Driver Address: 3423 SANDY LAKE, NEW LEBANAON ;Driver City: SANDY LAKE;Driver State: PA;Driver Zip: 16145;Photos Taken (Y/N): Y;Supplemental Report #: N;Co-Investigator #: N;Reason Code: OBVI;FMCSA Credentials Verified-Y/N: Y;CDL Verified (Y/N): Y;FMCSA OOS Order Issued(Y/N): N;Crash Report #: N;Driver Address Verified (Y/N): Y;ISS Score: 44

Report Prepared By:
John Brayer

Badge #:
3225

Copy Received By:
PEARSON, RICHARD A

Page 1 of 2



OH3225014232

X

X

DRIVER/VEHICLE EXAMINATION REPORT



Public Utilities Commission of Ohio
180 East Broad Street
Transportation Department
Columbus, OH 43215
Phone #: (614)466-0429 Fax #: (614)752-9274

Report Number: OH3225014232
Inspection Date: 8/17/2020 Certification Date:
Time Started: 09:25 Time Ended: 09:50
Inspection Level: III - Driver-Only Inspection
HM Inspection Type No HM Inspection

MCJUNKIN ROLL OFFS INC
2064 PERRY HWY
FREDONIA, PA 16124

Driver: PEARSON, RICHARD A
License #: [REDACTED] State: PA
Date of Birth: [REDACTED]

USDOT #: 01371622 Phone #: (724)475-2170
MC/MX #: 00654255 Fax #:
State #:

All violations of the FHMR and FMCSR or Title 49 of the Ohio Revised Code will be reviewed by the PUCO's Transportation Department to determine whether civil forfeitures should be assessed against any responsible parties in accordance with the penalty provisions of Title 49 of the Ohio Revised Code. If civil forfeitures are assessed, you will receive a separate notice by mail. These penalties may be assessed to motor carriers, shippers, and/or drivers.

ATTENTION MOTOR CARRIER: The motor carrier must examine this report and repair all the vehicle defects/violations noted above -AND- The motor carrier must sign the Certification of Repairs below and return the signed form to: Public Utilities Commission of Ohio, T ASD - 4th floor, 180 E Broad St, Columbus, OH 43215-3793 -OR- Fax (614) 752-9274 within 15 days of the inspection. If "No Violations Were Discovered" then you do not need to return his report. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000. If you have any questions, please contact (614) 466-0429.

Signature of Carrier Official: X Date: _____

ATTENTION DRIVER: This report must be sent to the motor carrier whose name appears at the top of this inspection report within 24 hours. If the inspection report cannot be delivered within 24 hours the driver must mail or fax the inspection report to the motor carrier.

***** POSSIBLE CDL DISQUALIFICATION *****

If this roadside inspection identified an alleged violation of one or more of the below noted regulations, your CDL may be disqualified. If the PUCO finds you committed a violation of any of these regulations, the violation will be treated as a conviction for the purposes of federal and state law and notice of such conviction will be forwarded to the Ohio Bureau of Motor Vehicles (BMV). The BMV may disqualify you from operating a commercial motor vehicle for a minimum of 60 days. Any BMV sanction is in addition to sanctions imposed by the Public Utilities Commission of Ohio (PUCO).

177.804(b)(1), 177.804(b)(2), 177.804(b)(3), 177.804(c), 4901.2-5-07D, 383.23(a)(2), 383.51(a), 383.51A-NSIN, 383.51A-NSOUT, 383.51A-SIN, 383.51A-SOUT, 383.91(a), 383.93(b)(1), 383.93(b)(2), 383.93(b)(3), 383.93(b)(4), 383.93(b)(5), 391.15(a), 391.15A-NSIN, 391.15A-NSOUT, 391.15A-SIN, 391.15A-SOUT, 392.10(a)(1), 392.10(a)(2), 392.10(a)(3), 392.10(a)(4), 392.11, 392.12, 392.4(a), 392.5(a)(2), 392.5A2-UI, 392.5(c)(2), 392.80(a), 392.82(a)(1), 395.13(d), 396.9(c)(2).

MOTOR CARRIER CERTIFICATION OF COMPLETED REPAIRS: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety & Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. A false certification of repairs is required to be prosecuted with penalties up to \$10,000.

Signature of Repairer: X Facility: _____ Date: _____

Report Prepared By:
John Brayer

Badge #:
3225

Copy Received By:
PEARSON, RICHARD A

Page 2 of 2



X

X

OH3225014232

**This foregoing document was electronically filed with the Public Utilities
Commission of Ohio Docketing Information System on**

2/28/2022 10:37:11 AM

in

Case No(s). 20-1684-TR-CVF

Summary: Exhibit State's Exhibit 2 electronically filed by Mr. Ken Spencer on behalf of Armstrong & Okey, Inc.