

DRIVER/VEHICLE EXAMINATION REPORT



Public Utilities Commission of Ohio
180 East Broad Street
Transportation Department
Columbus, OH 43215
Phone #: (614)466-0429 Fax #: (614)752-9274

Report Number: OH1575002638
Inspection Date: 3/4/2021 Certification Date: 04/13/2021
Time Started: 07:35 Time Ended: 08:25
Inspection Level: II - Walk-Around
HM Inspection Type Bulk Inspection

MCCUTCHEON ENTERPRISES INC

250 PARK ROAD
APOLLO, PA 15613

USDOT #: 00265293

Phone #: (724)568-3623

MC/MX #: 00178688

Fax #:

State #:

Driver: OHARRA, MAX H

License #:

State: PA

Date of Birth:

Location: ROADSIDE

MilePost: 52

Highway: IR270

Origin: INDIANAPOLIS, IN

Bill of Lading: 018984996

County: FRANKLIN

Destination: GREENSBURG, PA

Cargo: HAZ MAT (ALL)

Shipper: EASTERN GAS TRANSMISSION & STORAGE

VEHICLE IDENTIFICATION:

Unit	Type	Make	Year	tate	License#	Equipment ID	Unit VIN	GVWR	CVSA #	CV A Issued #	OO	tkr #
1	TT	PTRB	2016	PA	AG20498		1XPBDP9X1GD297156	52,000				
2	ST	TRLR	1992	PA	PT7593V		1S9T24228N0017141	68,000				

BRAKE ADJUSTMENTS: No brake measurements recorded.

VIOLATIONS :

Vio Code	Section	Unit	OOS	State Citation Number	Verify*	Crash	Violation Description
172.516C6	172.516(c)(6)	2	N		N	N	Placard damaged, deteriorated, or obscured: 2 of 4 placards (left and right side) faded to bright pink coloration

* N - Non-OOS or Driver OOS Violation

HazMat: 3 Flammable,

Placard: Yes Cargo Tank 306

Special Checks:

<input type="checkbox"/>	Alcohol/Controlled Substance Check	<input checked="" type="checkbox"/>	Traffic Enforcement	<input type="checkbox"/>	Post Crash Inspection
<input type="checkbox"/>	Conducted by Local Jurisdiction	<input type="checkbox"/>	PASA Conducted Inspection	<input type="checkbox"/>	PBBT Inspection
<input type="checkbox"/>	Size and Weight Enforcement	<input type="checkbox"/>	Drug Interdiction Search	Arrests:	
<input type="checkbox"/>	EScreening				

Inspection Notes: Residue - en route to company in PA from place of disposal in IN. Placards at front and rear of trailer bright red, like new. Placards at trailer sides worn and faded to a pink coloration.

Special Study Fields:

Special Study1:

Special Study6:

Special Study2:

Special Study7:

Special Study3:

Special Study8:

Special Study4:

Special Study9:

Special Study5:

Special Study10:

Locally Defined Fields

HM Incid/Crash w/release(Y/N): N;Placards Displayed (Y/N): Y;Placards Offered (Y/N): Y;Loaded by Carrier (Y/N): Y;Loaded by Shipper (Y/N): N;Ship Docs Prep by Carrier(Y/N): Y;Ship Doc Prep by Shipper(Y/N): N;Haz Class A: 3;ID # A: UN1268;Packing Group A: II;Gross Weight A: RLC;For-Hire Carrier: Y;Driver Address: 184 POST OFFICE RD;Driver City: SAGAMORE;Driver State: PA;Driver Zip: 16250;Photos Taken (Y/N): Y;Reason Code: OBVI;FMCSA Credentials Verified-Y/N: Y;CDL Verified (Y/N): Y;FMCSA OOS Order Issued(Y/N): N;HM Safety Permit Verified(Y/N): Y;Shipper 1 Name: EASTERN GAS TRANSMISSION & STO;Shipper 1 Street Address: 925 WHITE OAK RD;Shipper 1 City: BRIDGEPORT;Shipper 1 State: WV;Shipper 1 Zip Code: 26330;Driver Address Verified (Y/N): Y;ISS Score: 27

Report Prepared By:

Badge #:

Copy Received By:

Page 1 of 2

T J MULARCIK

1575

OHARRA, MAX H



X

X

OH1575002638

DRIVER/VEHICLE EXAMINATION REPORT



Public Utilities Commission of Ohio
180 East Broad Street
Transportation Department
Columbus, OH 43215
Phone #: (614)466-0429 Fax #: (614)752-9274

Report Number: OH1575002638
Inspection Date: 3/4/2021 Certification Date: 04/13/2021
Time Started: 07:35 Time Ended: 08:25
Inspection Level: II - Walk-Around
HM Inspection Type Bulk Inspection

MCCUTCHEON ENTERPRISES INC

250 PARK ROAD
APOLLO, PA 15613

USDOT #: 00265293

Phone #: (724)568-3623

MC/MX #: 00178688

Fax #:

State #:

Driver: OHARRA, MAX H

License #:

State: PA

Date of Birth:

All violations of the FHMR and FMCSR or Title 49 of the Ohio Revised Code will be reviewed by the PUCO's Transportation Department to determine whether civil forfeitures should be assessed against any responsible parties in accordance with the penalty provisions of Title 49 of the Ohio Revised Code. If civil forfeitures are assessed, you will receive a separate notice by mail. These penalties may be assessed to motor carriers, shippers, and/or drivers.

ATTENTION MOTOR CARRIER: The motor carrier must examine this report and repair all the vehicle defects/violations noted above -AND- The motor carrier must sign the Certification of Repairs below and return the signed form to: Public Utilities Commission of Ohio, T ASD - 4th floor, 180 E Broad St, Columbus, OH 43215-3793 -OR- Fax (614) 752-9274 within 15 days of the inspection. If "No Violations Were Discovered" then you do not need to return his report. Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000. If you have any questions, please contact (614) 466-0429.

Signature of Carrier Official:

X

Date:

ATTENTION DRIVER: This report must be sent to the motor carrier whose name appears at the top of this inspection report within 24 hours. If the inspection report cannot be delivered within 24 hours the driver must mail or fax the inspection report to the motor carrier.

***** POSSIBLE CDL DISQUALIFICATION *****

If this roadside inspection identified an alleged violation of one or more of the below noted regulations, your CDL may be disqualified. If the PUCO finds you committed a violation of any of these regulations, the violation will be treated as a conviction for the purposes of federal and state law and notice of such conviction will be forwarded to the Ohio Bureau of Motor Vehicles (BMV). The BMV may disqualify you from operating a commercial motor vehicle for a minimum of 60 days. Any BMV sanction is in addition to sanctions imposed by the Public Utilities Commission of Ohio (PUCO).

177.804(b)(1), 177.804(b)(2), 177.804(b)(3), 177.804(c), 4901.2-5-07D, 383.23(a)(2), 383.51(a), 383.51A-NSIN, 383.51A-NSOUT, 383.51A-SIN, 383.51A-SOUT, 383.91(a), 383.93(b)(1), 383.93(b)(2), 383.93(b)(3), 383.93(b)(4), 383.93(b)(5), 391.15(a), 391.15A-NSIN, 391.15A-NSOUT, 391.15A-SIN, 391.15A-SOUT, 392.10(a)(1), 392.10(a)(2), 392.10(a)(3), 392.10(a)(4), 392.11, 392.12, 392.4(a), 392.5(a)(2), 392.5A2-UI, 392.5(c)(2), 392.80(a), 392.82(a)(1), 395.13(d), 396.9(c)(2).

MOTOR CARRIER CERTIFICATION OF COMPLETED REPAIRS: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with the Federal Motor Carrier Safety & Hazardous Materials Regulations insofar as they are applicable to motor carriers and drivers. A false certification of repairs is required to be prosecuted with penalties up to \$10,000.

Signature of Repairer:

X

Facility:

Date:

Report Prepared By:

T J MULARCIK

Badge #:

1575

Copy Received By:

OHARRA, MAX H

Page 2 of 2



OH1575002638

X

X



Not For Court Display

+ - ◂ ◃ ↶ ↷


KILOGRAMS / POUNDS				SUITABLE TIRE - RIM CHOICE			
MANUFACTURED BY	GVWR	24132.0	53200	TIRE SIZE	RIM SIZE	KPA	COLD PSI
PETERBILT MOTORS CO.	FR. GAWR	5987.5	13200	295/75R22.5H	22.5X8.25	830	120
DIVISION OF PACCAR INC.	2ND. GAWR	9072.0	20000	295/75R22.5F	22.5X8.25	660	95
	3RD. GAWR	9072.0	20000	295/75R22.5F	22.5X8.25	660	95
DATE MFG.	05/2015	4TH. GAWR	0.0	0			

LABEL 22-01467

Not For Court Display




Not For Court Display



Not For Court Display



Not For Court Display





Not For Court Display



Not For Court Display (2-pitch typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number PAD081045107	2. Page 1 of 1	3. Emergency Response Phone (800) 424-0300	4. Manifest Tracking Number 018984-00 JJK			
5. Generator's Name and Mailing Address Eastern Gas Transmission & Storage, Inc. 825 White Oak Rd. Bridgeport, WV 26330 Generator's Phone: (724) 653-1801		Generator's Site Address (If different than mailing address) Eastern Gas Transmission & Storage, Inc. 6814 RT 22, Greensburg, PA 15601						
6. Transporter 1 Company Name McCutcheon Enterprises Inc		U.S. EPA ID Number PAD012828847						
7. Transporter 2 Company Name		U.S. EPA ID Number						
8. Designated Facility Name and Site Address Heritage Environmental Service 7901 West Morris Street Indianapolis, IN 46201 Facility's Phone: (317) 243-4380		U.S. EPA ID Number IND093210901						
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
		No.	Type					
	1. X UN1268, Waste Petroleum distillates, n.o.s. 3. PG II	1	TT	5200	G	D601	D610	
	2.							
	3.							
4.								
14. Special Handling Instructions and Additional Information 121199-3 ERG# 128 WDR 20210216004854 Profile 121199-3 TV-33								
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.								
Generator's/Offor's Printed/Typed Name L. J. M...		Signature L. J. M...		Month 03			Day 02	Year 01
16. International Shipments <input type="checkbox"/> Shipped to U.S. <input type="checkbox"/> Export from U.S. <input type="checkbox"/> Shipped to foreign								

Indianapolis, IN 46201
Fax (317) 243-4380

Not For Court Display

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))
X	1. UN1268, Waste Petroleum distillates, n.o.s. 3, PG II
	2.
	3.
	4.
14. Special Handling Instructions and Additional Information	
121199-3 ERGS 128	

Not For Court Display

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number PAD081045107
5. Generator's Name and Mailing Address Eastern Gas Transmission & Storage, Inc. 925 White Oak Rd. Bridgeport, WV 26330		
Generator's Phone: (724) 953-1801		
6. Transporter 1 Company Name McCutcheon Enterprises Inc		
7. Transporter 2 Company Name		
8. Designated Facility Name and Site Address Heritage Environmental Service 7901 West Morris Street Indianapolis, IN 46201		
Facility's Phone: (317) 243-4380		
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	
	1. X UN1208 Waste Petroleum	

Not For Court Display

Form Approved. OMB No. 2050-0039

Page 1 of 1	3. Emergency Response Phone (800) 424-9300	4. Manifest Tracking Number 018984996 JJK
Generator's Site Address (if different than mailing address) Eastern Gas Transmission & Storage, Inc 8814 RT 22, Greensburg, PA 15601		
		U.S. EPA ID Number PAD0013820847
		U.S. EPA ID Number
		U.S. EPA ID Number IND093210901
10. Containers	11. Total	12. Unit
13. Waste Codes		

Consent.
(if I am a small quantity generator) is true.

Not For Court Display

Month Day Year

03 02 21

Port of entry/exit: _____

Date leaving U.S.: _____

Month Day Year

03 02 21

Month Day Year

☐ Residue

☐ Partial Rejection

☐ Full Rejection

Manifest Reference Number: _____

U.S. EPA ID Number

|

Month Day Year



1268

3



**This foregoing document was electronically filed with the Public Utilities
Commission of Ohio Docketing Information System on**

3/1/2022 1:05:10 PM

in

Case No(s). 21-0492-TR-CVF

Summary: Exhibit Staff Exhibit 1 electronically filed by Mr. Ken Spencer on behalf of
Armstrong & Okey, Inc. and Spencer, Michael O. Mr.