FILE

PUCO EXHIBIT FILING

2023 NOV 22 PM 2: 09

Date of Hearing: 11/14/2023 Case No. 20-1288 - EL-B&N PUCO Case Caption: In the Matter of the application List of exhibits being filed: document deli Reporter's Signature:

Date Submitted:

BEFORE THE OHIO POWER SITING BOARD

- - -

In the Matter of the : Application of Hecate : Energy Highland 4 LLC for :

a Certificate of : Case No. 20-1288-EL-BGN

Environmental : Compatibility and Public : Need. :

PROCEEDINGS

before Mr. Nicholas Walstra and Mr. Jesse Davis,
Administrative Law Judges, at the Public Utilities
Commission of Ohio, 180 East Broad Street, Room 11-D,
Columbus, Ohio, called at 10:05 a.m. on Tuesday,
November 14, 2023.

ARMSTRONG & OKEY, INC.
222 East Town Street, Second Floor
Columbus, Ohio 43215-5201
(614) 224-9481

505 Ghibit

CHANGES IN ROBERT HOLDERBAUM'S WRITTEN TESTIMONY

	November 9, 2023 Written Testimony	November 7, 2023 Written Testimony
5A	I served as the overall Staff Project	I served as the overall Staff Project Lead
571	Lead for the investigation that resulted	for the investigation that resulted
	in the Staff Report of Investigation	in the Staff Report of Investigation (Staff
	1	1 ,
	(Staff Report) that was filed in this	Report) that was filed in this docket on
	docket on January 4, 2021. I managed	January 4, 2021. I managed the Staff
	the Staff investigation and preparation	investigation and preparation of the Staff
	of the Staff Report in this case. As a	Report in this case
	result of that investigation, I testified	
	in support of the Joint Stipulation	
	and Recommendation that was filed	
	in the case on January 22, 2021, and	
	ultimately adopted by the Board on	
	March 18, 2021. Further, I	
	participated in the compliance	
	investigation that resulted in the	
	Compliance Inquiry Report that was	*
	filed in the case on October 18, 2022.	
6A	Originally, the Board approved,	The Applicant proposed to construct a new
OIL	subject to stipulated conditions, the	110 MW Solar Generation Facility in
	Applicant's proposed construction of	
		Highland County
	a 100 MW Solar Generation Facility	
	(Facility) in Highland County. As	
	part of that approval, the Board	
	required that the Facility be installed	
	with property setbacks of at least 100	
	feet from all property lines, including	
	public roads. This setback limitation	
	was described throughout the course	
	of the Board's record, including (1)	
	as part of the application (page 22),	
	(2) as part of the Applicant's	
	supplemental filings (see, Data	
	Response on December 23, 2020,	
	which is attached to my testimony),	
	and (3) as adopted by the Board (see,	
	Opinion, Order and Certificate	
	(March 18, 2021)). This case results	
	from the Applicant's failure to	
	construct the Facility in recognition	
7.4	of the 100-foot setback requirement.	C4-C2-1
7A	Staff's original investigation included	Staff's investigation included reviewing
	reviewing the application, conducting	the application, conducting site visits to the
	site visits to the proposed facility	proposed facility location, acquiring

location. acquiring additional additional information from the Applicant, obtaining input from other relevant state information from the Applicant, and federal agencies, and preparing a Staff obtaining input from other relevant state and federal agencies, Report of Investigation that presents preparing the Staff Report that Staff's analysis, conclusions. presented Staff's analysis, conclusions, recommendations. As a result of Staff's and recommendations. As a result of investigation. Staff recommended that the Staff's investigation, the Board Board approve the application, subject to the 23 conditions that are presented in the adopted Staff recommendation to approve the application, as modified Staff Report, as modified within the within the Stipulation. Stipulation. conducted additional an investigation of this case in response to the certificate holder's selfreported construction violations on September 12, 2022. In that selfreport, the Facility described 39 locations within the Facility where installation equipment occurred within the designated 100-foot setback. As a result of that selfreport, Staff conducted a site inspection on September 30, 2022, which demonstrated that 38 of the 39 self-reported construction setback violations were valid. 8Q describe Staff's review when Please describe Staff's review of the Please engineering drawings receiving the final engineering drawings submitted to Staff as required by submitted to Staff as required by Condition Condition 8 in the Opinion and 8 in the Opinion and Order issued for the Order issued for the project on project on March 18, 2021. March 18, 2021. 8A Consistent with its practices, Staff Staff reviews the final engineering final engineering reviewed the drawings to verify the drawings were drawings to verify that the drawings created by a professional engineering firm. Staff keeps a record of the drawings for were created by a professional engineering firm and in a format unforeseen future circumstances, and as a that the public could access on the record in the case docket for the public to case docket. Staff's treatment of this have access to. filing (verification of formatting consistent with filing on the case docket) is consistent with treatment of the numerous other condition compliance filings that occurred in this case between March 19 and April 14, 2021. Further,

Staff's treatment of this filing is consistent with its protocol as to all engineering drawings that are filed in satisfaction of a certificate	
holder's condition compliance. Please describe Staff's review when receiving the final engineering	Please describe the basis for Staff's review protocol as to the final engineering
drawings submitted to Staff as required by Condition 8 in the Opinion and Order issued for the project on March 18, 2021.	drawings.
As the Applicant is limited by the conditions set forth in the certificate, there is no added benefit to Staff performing an independent technical review of the final engineering drawings. Further, such a duplicative review would require Staff to retain expert consultant services that are not cost justified.	The Applicant stated they would abide by this setback requirement on page 22 of the Application filed in the case docket on September 2, 2020. Additionally, on December 14, 2020, the Applicant responded to a data request from Staff confirming their commitment to abide by the 100-foot setback. A record of the Applicant's data request response is attached to my testimony.



EXHIBIT 8




EXHIBIT 8

EXHIBIT 8




EXHIBIT 9




EXHIBIT 9







EXHIBIT 9



NMS EXHIBIT 20





From: Gagliardi, Danelle M. <danelle.gagliardi@squirepb.com>

Sent: Tuesday, March 23, 2021 8:48 PM **To:** robert.holderbaum@puco.ohio.gov

Cc: Patti Shorr <PShorr@hecateenergy.com>; Jared Wren <jwren@hecateenergy.com>; Winters, Karen A.

<karen.winters@squirepb.com>; Sean Fairfield <Sean.Fairfield@algonquinpower.com>
Subject: RE: Hecate Energy's New Market Solar Project - Case No. 20-1288-EL-BGN

Ashton,

As you may have seen, we made several filings on the docket today regarding compliance with Conditions 8, 12, 14, 15, 16, and 23 of the Certificate for New Market Solar I. We have uploaded the relevant shapefiles and other associated documentation to the OPSB sharefile site, as well as courtesy copies of the corresponding documents for New Market Solar II.

Please let us know if you have any questions or trouble accessing the documents.

Thank you, Danelle



Danelle M. Gagliardi Associate T +1 614 365 2820 danelle.gagliardi@squirepb.com

From: Gagliardi, Danelle M.

Sent: Friday, March 19, 2021 4:48 PM

To: 'robert.holderbaum@puco.ohio.gov' <robert.holderbaum@puco.ohio.gov>

Cc: Patti Shorr <PShorr@hecateenergy.com>; 'Jared Wren' <jwren@hecateenergy.com>; Winters, Karen A. <karen.winters@squirepb.com>; 'Sean.Fairfield@algonquinpower.com' <Sean.Fairfield@algonquinpower.com>

Subject: Hecate Energy's New Market Solar Project - Case No. 20-1288-EL-BGN

Ashton,

Please see the attached Preconstruction Notice letter, sent on behalf of Patti Shorr. We have uploaded the relevant shapefiles and other documentation to the OPSB sharefile site.

Please let us know if you have any questions or trouble accessing the documents.

Thank you, Danelle



Danelle M. Gagliardi

Associate Squire Patton Boggs (US) LLP 2000 Huntington Center 41 South High Street Columbus, Ohio 43215 T +1 614 365 2820 F +1 614 365 2499 danelle.gagliardi@squirepb.com

Linked in mother

45 Offices in 20 Countries

This message is confidential and may be legally privileged or otherwise protected from disclosure. If you are not the intended recipient, please telephone or email the sender and delete this message and any attachment from your system; you must not copy or disclose the contents of this message or any attachment to any other person.

For information about how Squire Patton Boggs processes UK and EU personal data that is subject to the requirements of applicable data protection laws, please see our Privacy Notice regarding the processing of UK and EU personal data about clients and other business contacts at www.squirepattonboggs.com.

Squire Patton Boggs (US) LLP is part of the international legal practice Squire Patton Boggs, which operates worldwide through a number of separate legal entities. Please visit www.squirepattonboggs.com for more information.

New Market Solar Measurement Table September 30, 2022

Measurement 39 100'1" 100 0 Measurement 11 97'2" 97 3 Measurement 24 96'5" 96 4 Measurement 17 94'4" 94 6 Measurement 2 91'2" 91 9 Measurement 35 89'9" 90 10 Measurement 26 89'10" 89 11 Measurement 27 88'10" 89 11 Measurement 27 88'10" 89 11 Measurement 16 86'9" 87 13 Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 23 85'7" 85 15 Measurement 23 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 34 83'8" 84 16 <th>Measurement</th> <th>Feet from Road Center Line</th> <th>]</th> <th></th>	Measurement	Feet from Road Center Line]	
Measurement 24 96'5" 96 4 Measurement 17 94'4" 94 6 Measurement 2 91'2" 91 9 Measurement 35 89'9" 90 10 Measurement 26 89'10" 89 11 Measurement 27 88'10" 89 11 Measurement 16 86'9" 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 3 84'1" 84 16 Measurement 4 83'8" 84 16 Measurement 3 82'11" 83 17	Measurement 39	100'1"	100	0
Measurement 17 94'4" 94 6 Measurement 2 91'2" 91 9 Measurement 35 89'9" 90 10 Measurement 26 89'10" 89 11 Measurement 27 88'10" 89 11 Measurement 16 86'9" 87 13 Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85'7" 85 15 Measurement 29 85'5" 85 15 Measurement 3 84'1" 84 16 Measurement 3 84'1" 84 16 Measurement 3 82'1" 84 16 Measurement 25 82'1" 83 17	Measurement 11	97'2"	97	3
Measurement 2 91'2" 91 9 Measurement 35 89'9" 90 10 Measurement 26 89'10" 89 11 Measurement 27 88'10" 89 11 Measurement 16 86'9" 87 13 Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 3 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 35 82'1" 83 17 Measurement 30 82'11" 83 17 Measurement 25 82'3" 82 18	Measurement 24	96'5"	96	4
Measurement 35 89'9" 90 10 Measurement 26 89'10" 89 11 Measurement 27 88'10" 89 11 Measurement 6 86'9" 87 13 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85'7" 86 14 Measurement 23 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 34 83'8" 84 16 Measurement 35 82'1" 83 17 Measurement 20 82'1" 83 17 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 <	Measurement 17	94'4"	94	6
Measurement 26 89"10" 89 11 Measurement 27 88'10" 89 11 Measurement 16 86'9" 87 13 Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 4 84'1" 84 16 Measurement 5 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 5 78'9" 79 21 Measurement 16 76'9" 79 21	Measurement 2	91'2"	91	9
Measurement 27 88'10" 89 11 Measurement 16 86'9" 87 13 Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 34 83'8" 84 16 Measurement 4 83'1" 83 17 Measurement 5 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 5 78'9" 79 21	Measurement 35	89'9"	90	10
Measurement 16 86'9" 87 13 Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 4 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 18 76'1" 76 24	Measurement 26	89'10"	89	11
Measurement 4 86' 86 14 Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 28 77'11" 77 23 Measurement 10 76' 76 24	Measurement 27	88'10"	89	11
Measurement 6 85'9" 86 14 Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 8 75'8" 78 22 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24	Measurement 16	86'9"	87	13
Measurement 7 85'7" 86 14 Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 33 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 4 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 6 78'9" 79 21 Measurement 7 77'8" 78 22 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 19 76'5" 76 24 Measurement	Measurement 4	86'	86	14
Measurement 31 85'9" 86 14 Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 5 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 2 77'8" 78 22 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 19 76'5" 76 24 Measurement 9 75'5" 75 25	Measurement 6	85'9"	86	14
Measurement 32 85'7" 86 14 Measurement 3 84'7" 85 15 Measurement 29 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 35 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 75'5" 75 25 <	Measurement 7	85'7"	86	14
Measurement 3 84'7" 85 15 Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 37 75'5" 75 25 Measurement 20 73'2" 75 25 Measureme	Measurement 31	85'9"	86	14
Measurement 23 85' 85 15 Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 13 75'2" 75 25 Measurement 20 73'2" 75 25	Measurement 32	85'7"	86	14
Measurement 29 85'5" 85 15 Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 37 75'5" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 3	84'7"	85	15
Measurement 1 84'1" 84 16 Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 4 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 23	85'	85	15
Measurement 34 83'8" 84 16 Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 14 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 71 29 Measurement 38 71'2" 71 29	Measurement 29	85'5"	85	15
Measurement 15 83'1" 83 17 Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 14 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 1	84'1"	84	16
Measurement 30 82'11" 83 17 Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 14 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 37 75'5" 75 25 Measurement 20 73'2" 75 25 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 34	83'8"	84	16
Measurement 22 82'10" 82 18 Measurement 25 82'3" 82 18 Measurement 14 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 36 76' 76 24 Measurement 36 76' 76 24 Measurement 20 75'5" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 15	83'1"	83	17
Measurement 25 82'3" 82 18 Measurement 14 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 9 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 30	82'11"	83	17
Measurement 14 81'1" 81 19 Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 20 73'2" 75 25 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 22	82'10"	82	18
Measurement 5 78'9" 79 21 Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 25	82'3"	82	18
Measurement 12 77'8" 78 22 Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 14	81'1"	81	19
Measurement 28 77'11" 77 23 Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 71 29 Measurement 38 71'2" 71 29	Measurement 5	78'9"	79	21
Measurement 8 75'8" 76 24 Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 12	77'8"	78	22
Measurement 10 76' 76 24 Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 28	77'11"	77	23
Measurement 18 76'1" 76 24 Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 8	75'8"	76	24
Measurement 19 76'5" 76 24 Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 10	76'	76	24
Measurement 36 76' 76 24 Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 18	76'1"	76	24
Measurement 9 75'5" 75 25 Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 19	76'5"	76	24
Measurement 13 75'2" 75 25 Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 36	76'	76	24
Measurement 20 73'2" 73 27 Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 9	75'5"	75	25
Measurement 21 71'2" 71 29 Measurement 38 71'2" 71 29	Measurement 13	75'2"	75	25
Measurement 38 71'2" 71 29	Measurement 20	73'2"	73	27
	Measurement 21	71'2"	71	29
Measurement 37 68'7" 69 31	Measurement 38	71'2"	71	29
	Measurement 37	68'7"	69	31
Measurement 33 67'11" 68 32	Measurement 33	67'11"	68	32

From:

Kristy Ramkissoon < Kristy. Ramkissoon@algonquinpower.com>

Sent:

Fri 4/09/2021 7:15 PM (GMT-00:00)

To: Cc: Yuri Otarov <Yuri.Otarov@algonquinpower.com>
Gary Newton <Gary.Newton@algonquinpower.com>;Sean Fairfield

<Sean.Fairfield@algonguinpower.com>;Homer Lensink

<Homer.Lensink@algonquinpower.com>

Bcc:

Subject: RE: Highland - Pre-construction meeting debrief

Yuri - Below are my rough notes. Feel free to edit as you see fit.

- Confirmed tree clearing was completed on April 1 with no hiccups.
- OPSB staff (Ashton) has no concerns/objections to start of construction/this being the final preconstruction conference provided that we will comply with the stipulation conditions prior to the applicable construction activity
- Ashton requested a high level schedule with key activities and milestones Yuri to provide.
- Staff may visit the site during construction depending on the nature of public/local complaints.
- · Yuri/Jared to be the primary point of contacts with OPSB staff.

Regards,

Kristy

From: Yuri Otarov

Sent: Friday, April 9, 2021 2:05 PM

To: Kristy Ramkissoon < Kristy.Ramkissoon@algonquinpower.com > Cc: Gary Newton < Gary.Newton@algonquinpower.com >; Sean Fairfield

<Sean.Fairfield@algonquinpower.com>; Homer Lensink <Homer.Lensink@algonquinpower.com>

Subject: RE: Highland - Pre-construction meeting debrief

Thanks Kristy,

Yes, very happy with the way that meeting went. Ashton seems very reasonable

Yuri Otarov, M.Eng, P.Eng | Liberty Power | Senior Project Manager P: 905-465-4531 | C: 416-270-1334 | E: Yuri.Otarov@algonquinpower.com 354 Davis Road, Suite 100, Oakville, ON L6J 2X1

From: Kristy Ramkissoon < Kristy.Ramkissoon@algonquinpower.com>

Sent: Friday, April 9, 2021 1:45 PM

To: Yuri Otarov < Yuri. Otarov@algonquinpower.com>

Cc: Gary Newton < Gary.Newton@algonquinpower.com >; Sean Fairfield

<Sean.Fairfield@algonquinpower.com>; Homer Lensink <Homer.Lensink@algonquinpower.com>

Subject: Highland - Pre-construction meeting debrief

Yuri — Excellent news...no additional preconstruction meetings needed. I will send out my rough notes shortly.